

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-534F-1RF

PROPELLER S/N FP4924B

LOGBOOK # 1

PROPELLER MAINTENANCE RECORD

Position SINGLE

Propeller Model PHC-33K-1RF

Propeller S/N FP4924 B

Blade Design F7392-1

Blade S/N's

No. 1 K41713

No. 2 K41714

No. 3 K41717

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____

Reverse _____

Aircraft Manufacturer Cirrus Design

Aircraft Model SR-20

S/N 20-1720

Registration N6255F



d/b/a MILLION AIR - RICHMOND
CRS VXWR051W


Manufacturer:	Hartzell	Date	8/20/2008
Model:	PHC-J3YF-1RF	W.O.:	M080806
S/N:	FP4924B	Reg #:	N625SF
TTP:	675.3	ACTT:	675.3
		Flight Hobbs:	675.3

PROPELLER LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service for the work performed. Pertinent details of this work order are on file at this repair station..

The Hartzell PHC-J3YF-1RF S/N FP4924B propeller was inspected I/A/W current maintenance rules of the Federal Aviation Regulation for an Annual Inspection using the Cirrus Design SR20 current inspection guide and is approved for return to service. The following items were serviced, repaired and/or inspected as noted.

Researched propeller logbook for AD 2007-26-09 and found that it does not apply by propeller blade serial numbers installed: K41713, K41714 and K41717.

Signed: 
Print: John T. Gardner
for

COMMONWEALTH AVIATION SERVICE, INC.
F.A.A. Approved Repair Station No. VXWR051W

ption of all operations pertaining to Airworthiness Directives,
Documents, Overhaul, Major or Minor Repair, and Inspections.

Heart of Virginia Aviation
11152 Airpark Rd
Ashland, VA 23005



Phone: 804-798-6500
Fax: 804-798-6544
WO # A10-0249

N625SF

June 9, 2010

Aircraft Hobbs: 1288.1
Prop Total Flight Time: 993.7

I certify this prop has been inspected in accordance with a 100 hour inspection was determined to be in airworthy condition

Daniel McSherry AP31103001A 

LEADING EDGE

AVIATION SERVICES, INC.

Tampa, FL



AUTHORIZED SERVICE CENTER

Date: 5/16/2011; Aircraft: N625SF; Type: CIRRUS; S/N: 1720; Hobbs: 1420.30; Total Time: 1093.40; Prop - Type: PHC-J3YF-1RF, S/N: FP4924B, Time: 1093.40, SMOH: 1093.40

- Complied with Cirrus 100 hour inspection checklist.
- Inspected Propeller for cracks, leaks, and abrasions.
- Dressed leading edges of blades and lubed hub.
- Verified AD compliance through Bi-weekly issue 2011-09.

The above work was performed in accordance with current regulations of the Federal Aviation Administration and is approved for return to service pertaining to work performed.

Jonathan Bennett

A&P 3026634

6582 Eureka Springs Rd. Tampa, FL 33610
Tampa Executive Airport (KVDF) 813 626 1515

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
------	----------------------	------------	-----------------------------------------------------------------------------------------------------------------------------------------------

LEADING EDGE 

AVIATION SERVICES, INC.

Tampa, FL



AUTHORIZED SERVICE CENTER

Date: 7/27/2011; Aircraft: N625SF; Type: CIRRUS; S/N: 1720; Hobbs: 1463.00; Total Time: 1125.64; Prop - Type: PHC-J3YF-1RF, S/N: FP4924B, Time: 1125.27, SMOH: 1125.27

- Inspected Propeller for cracks, leaks, and abrasions.
- Dressed leading edges of blades and lubed hub.
- Verified AD compliance through bi-weekly issue 2011-14.

I certify this propeller has been inspected in accordance with a 100hour inspection with reference to Cirrus AMM and is found to be in airworthy condition at this time.

Paul Stern  A&P 3078823IA
 6582 Eureka Springs Rd. Tampa, FL 33610
 Tampa Executive Airport (KVDF) 813 626 1515

LEADING EDGE

AVIATION SERVICES, INC.

Tampa, FL



AUTHORIZED SERVICE CENTER

Date: 12/09/2011; Aircraft: N625SF; Type: CIRRUS; S/N: 1720; Hobbs: 1574.80; Total Time: 1212.50; Prop - Type: PHC-J3YF-1RF, S/N: FP4924B, Time: 1212.50, SMOH: 1212.50

- Complied with Cirrus 100 hour inspection checklist.
- Inspected Propeller for cracks, leaks, and abrasions.
- Verified AD compliance through Bi-weekly issue 2011-23.

The above work was performed in accordance with current regulations of the Federal Aviation Administration and is approved for return to service pertaining to work performed.

Jonathan Bennett

A&P 3026634

6582 Eureka Springs Rd. Tampa, FL 33610
Tampa Executive Airport (KVDF) 813 626 1515

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		

LEADING EDGE 
AVIATION SERVICES, INC.
Tampa, FL



Date: 3/22/2012; Aircraft: N625SF; Type: CIRRUS; S/N: 1720; Hobbs: 1701.50; Total Time: 1708.30; Prop - Type: PHC-J3YF-1RF, S/N: FP4924B, Time: 1313.60

- Inspected Propeller for cracks, leaks, and abrasions.
- Dressed leading edges of blades and lubed hub.
- Verified AD compliance through Bi-weekly issue 2012-03.

I certify this propeller has been inspected in accordance with a 100 hour inspection with reference to Cirrus AMM and is found to be in airworthy condition at this time.

Paul Stern  A&P 3078823IA
 6582 Eureka Springs Rd. Tampa, FL 33610
 Tampa Executive Airport (KVDF) 813 626 1515

LEADING EDGE

AVIATION SERVICES, INC.

Tampa, FL



AUTHORIZED SERVICE CENTER

Date: 5/24/2012; Aircraft: N625SF; Type: CIRRUS; S/N: 1720; Hobbs: 1830.70; Total Time: 1827.80; Prop - Type: PHC-J3YF-1RF, S/N: FP4924B, Time: 1411.54, SMOH: 1411.54

- Complied with Cirrus 100 hour inspection checklist.
- Inspected Propeller for cracks, leaks, and abrasions.
- Dressed leading edges of blades and lubed hub.
- Verified AD compliance through Bi-weekly issue 2012-09.

The above work was performed in accordance with current regulations of the Federal Aviation Administration and is approved for return to service pertaining to work performed.

Jonathan Bennett

A&P 3026634

6582 Eureka Springs Rd. Tampa, FL 33610
Tampa Executive Airport (KVDF) 813 626 1515

LEADING EDGE

AVIATION SERVICES, INC.

Tampa, FL



AUTHORIZED SERVICE CENTER

Date: 1/15/2013; Aircraft: N625SF; Type: CIRRUS; S/N: 1720; Hobbs: 2106.8; Total Time: 1616.3; Prop - Type: PHC-J3YF-1RF, S/N: FP4924B, Time: 1616.3, SMOH: 1616.3

- Complied with Cirrus 100 hour inspection checklist.
- Inspected Propeller for cracks, leaks, and abrasions.
- Dressed leading edges of blades and lubed hub.
- Verified AD compliance through Bi-weekly issue 2012-26.

I certify this propeller has been inspected in accordance with a 100 hour inspection with reference to Cirrus AMM and is found to be in airworthy condition at this time.

Jonathan Bennett 

A&P 3026634 IA

6582 Eureka Springs Rd. Tampa, FL 33610
Tampa Executive Airport (KVDF) 813 626 1515

Seller
TSO

A/C
Hrs

Description of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspections.



Make: CIRRUS DESIG

Model: SR20

Reg. No.: N625SF

Order No.: 81569

Completed: 02/01/14

S/N: 20-1720

Tach Time: 1746.10

TTAF: 1746.10

Propeller Log

Type: Hartzell_PHCJ3Y

S/N: FP4924B

I certify that this propeller has been inspected in accordance with a 100 hour
inspection and was determined to be in airworthy condition.

Sean M. Passinault A&P2806728





Propeller

8191 N Tamiami Trail
Sarasota, FL 34243
www.AEROMx-srq.com
(941) 360-9074

Date: 02/27/2015

**Make: Hartzell
S/N: FP4924B**

**Model: PHC-J3YF-RF
FT: 1807.6**

**REG #: N635SF
TTAF: 1807.6**

I certify that this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.


William Reppond

AP#3476478

Belle Aircraft Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 828-684-9191
Date **6/2/17** **N625SF** **PHC-J3YF-1RF** **S/N:FP4924B** **Hobbs: 71.5**
Total Time: 2478.4

Dressed, painted blades as needed and lubed hub.

I certify that this propeller was inspected IAW a 100HR/Annual Inspection and was approved for return to service.




A&P3038109IA

Belle Aircraft Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 828-684-9191
7/19/18 **N625SF** **PHC-J3YF-1RF** **S/N:FP4924B** **Hobbs: 117.5**
Total Time: 2478.4

Dressed blades as needed.

I certify that this propeller was inspected IAW a 100HR/Annual Inspection and was approved for return to service.



A&P3038109IA



Propeller

8191 N Tamiami Trail
Sarasota, FL 34243
www.AEROMx-srq.com
(941) 360-9074

Date: 06/01/2016

Make: Hartzell
S/N: FP4924B

Model: PHC-J3YF-RF
Hobbs: 2406.9

REG #: N625SF
TTAF: 2406.9

I certify that this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.

Nicholas J. Ranaldo

A&P#3653259

A handwritten signature in black ink, appearing to read "N.J. Ranaldo", with a long horizontal flourish extending to the right.

Belle Aircraft Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 828 684-9191
8/1/19 N625SF PHC-J3YF-1RF SN:FP4924B Hobbs:183.0
Prop Total Time: 2589.9

Dressed Propeller as needed.

*I certify that this Propeller has been inspected in accordance with an Annual inspection
and was approved for return to service.*

David G. Phillips A&P 3598992 IA
David G. Phillips



Propeller

Sarasota, FL 34243
www.AEROMx-srq.com
(941) 360-9074

Date: 10/02/2020

Model: PHC-J3YF-1RF
Hobbs: 204.0

REG #: N625SF
SMOH: 0.0

Make: Hartzell
S/N: FP4924B

Removed Propeller and sent to Aircraft Propeller Works Inc. Reinstalled Propeller P/N# PHC-J3YF-1RF S/N# FP4924B with a NEW Flange O-ring P/N# C-3317-228 and NEW alternator belt P/N# 15395 IAW Cirrus Aircraft SR20 Maintenance Manual, Chapter 61, Section 61-10, Paragraph 2.

Performed operational check no faults were found.

Miguel L. Vicente A&P#3954737

ons pertaining to Airworthiness, overhaul, Major or Minor Repair, and Inspections.



Propeller

8191 N Tamiami Trail
Sarasota, FL 34243
www.AEROMx-srq.com
(941) 360-9074

Date: 12/01/2020

Make: Hartzell
S/N: FP4924B

Model: PHC-J3YF-RF
Hobbs: 204.0

REG #: N625SF
TTAF: 2610.9
SMOH: 0.0

I certify that this Propeller has been inspected in accordance with a 100 hour Inspection and was determined to be in airworthy condition.

Nicholas J. Ranaldo

IA# 3653259

Belle Aircraft Maintenance 20 Lindbergh Ln, Fletcher, NC 28732 828 684-9191
1/28/22 N625SF PHC-J3YF-1RF SN:FP4924B Hobbs:215.8
Prop Total Time: 2622.7

Dressed Propeller as needed.

*I certify that this Propeller has been inspected in accordance with an 100 hr. inspection
and was approved for return to service.*

David G. Phillips A&P 3598992 IA
David G. Phillips