

Propeller Service & Maintenance Record

Date	Total Time	Time Since Last Overhaul	Installations, Inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins.
------	------------	--------------------------	---

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-534F-1RF

PROPELLER S/N FP5272B

LOGBOOK # _____

PROPELLER MAINTENANCE RECORD

Position _____

PITCH RANGE

Propeller Model PHC-534F-1RF

High/Feather _____

Propeller S/N FP5272B

Start Lock _____

Blade Design F76930FB

Low _____

Blade S/N's

Reverse _____

No. 1 K46017

No. 2 K46015

Aircraft Manufacturer Cessna Design

No. 3 K46023

Aircraft Model SR22

No. 4 _____

S/N 2288


No. 5 _____

Registration N335A

No. 6 _____

Spinner Assembly Part No. _____

Propeller Service & Maintenance Record

Date	Total Time	Time Since Last Overhaul	Installations, Inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins.
12-05-06	.0	N/A 1.2	<p>I have Dynamically Balanced Propeller IAW Hartzell Propeller Owner's Manual 115N Rev. 12 dated April/05 Section: 61-00-15 on <u>12-05-06</u> (DATE). The location of the Weight(s) are <u>N/A</u> degree And are <u>N/A</u> gram(s).</p> <p><u>Dean Shyer</u> (Sign/Stamp)  MFG 517 Cirrus Design Corporation, PC 338CE</p>



AVIATION SERVICES

469 Airport Road, Johnstown PA 15904
 Phone: 814-361-3500 Fax: 814-361-3498

Registration: N335A	Time: TT 306.9	W/O: 0712-4	Date: 12-14-2007
Hartzell PHC-J3YF-1RF, S/N FP5272B		Flight Hobbs: 194.7, Hobbs: 424.4	

Performed Annual Inspection IAW Cirrus Inspection guide 05-20. and Hartzell M/M. AD's C/W thru 2007-24 Biweekly. Compliance record provided in aircraft logs. Lubricated propeller assembly. FOD, leak and functional checks - good.

This Propeller has been inspected in accordance with an Annual inspection and is approved for return to service. Further details are on file under work order referenced above.

Signature: [Signature] Certificate: CRS # N64R483Y

PROP MODEL:
 PHC-J3YF-1RF
 PROP S/N: FP5272B
 REG. NO: N335A
 WORK ORDER: 782

Advanced Aircraft Services LP

500 Airport Rd. Suite D
 Lititz, PA 17543
 Phone: 717-735-5179

DATE: 11/7/2008
 A/C TSN: 518.5
 PROP TT: 518.5
 HOBBS: 658.4

Work Entries

Completed an Annual Inspection using the Cirrus AMM check/list ch. 5-20.... C/W AD 08-13-28 Prop Hub Lube Holes, N/A by design/part number.... Dressed all prop blades and serviced hub. All AD's current thru 08-22.-END-

I certify that this PROPELLER has been inspected IAW an Annual inspection and was found to be in Airworthy condition.

DATE: 11/7/2008

SIGNED

[Signature]
 Richard A. Barnhart II, IA: 3124994

Work Order: 782

Printed by EBIS 3 (datcomedia.com)

Propeller Service & Maintenance Record

Date	Total Time	Time Since Last Overhaul	Installations, Inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins.
			<p style="text-align: center;">SENENICH PROPELLER SERVICE, INC.</p> <p>DATE: <u>11-10-08</u> CRS: QV9R194N Hobbs/Time: <u>576.9</u> A/C Reg: <u>N335A</u> Hub Model: _____ Hub S/N: _____ Propeller TTSN: _____ Propeller TTSO: _____</p> <p style="text-align: center;"><small>Summary of work performed</small></p> <p style="text-align: center;"><i>Dynamic Balanced Propeller IAW. Chadwick Helmoth Smooth Propeller A. Starting IPS. 21 at 2500rpm. Adjusted static balance weights. Ending IPS. 02 at 2500rpm. End</i></p> <p><small>Pertinent details of this repair or overhaul are on file at this repair station under work order # <u>19707</u> Signed: <u>[Signature]</u> for Sensenich Propeller Service, Inc., 519 E. Airport Rd. Lititz, PA 17543 *This signature constitutes approval for return to service of this aircraft ONLY FOR THE WORK WE HAVE PERFORMED. We have not performed nor been authorized to perform any inspection of this aircraft nor have we reviewed or been authorized to review the maintenance records, including Part 39 compliance.</small></p>

<p>PROP MODEL: PHC-JSYF-1RF PROP S/N: FP5272B REG. NO: N335A WORK ORDER: 1012</p>	<p>Advanced Aircraft Services LP</p> <p>500 Airport Rd. Suite D Lititz, PA 17543 Phone: 717-735-5179</p>	<p>DATE: 7/30/2009 A/C TSN: 593.7 PROP TT: 593.7 HOBBS: 755.5</p>
<p>Prop Entries</p> <p>Completed an Annual Inspection using the Cirrus AMM check list ch. 5-20.... Dressed all prop blades and serviced hub. All AD's current thru 09-15.-END-</p> <p>I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.</p>		
DATE: 7/30/2009	SIGNED: <u>[Signature]</u> Richard A. Barnhart II, IA: 3124994	Work Order: 1012 Printed by EBis 3 (datcomedia.com)

<p>PROP MODEL: PHC-JSYF-1RF PROP S/N: FP5272B REG. NO: N335A WORK ORDER: 1385</p>	<p>Advanced Aircraft Services LP</p> <p>500 Airport Rd. Suite D Lititz, PA 17543 Phone: 717-735-5179</p>	<p>DATE: 23 July, 2010 A/C TSN: 1018 PROP TT: 745 FLIGHTTIME: 939</p>
<p>Prop Entries</p> <p>Completed an Annual Inspection using the Cirrus AMM check list ch. 5-20. Dressed all blades and serviced hub. All AD's current thru 2010-15.</p> <p>I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.</p>		
DATE: 23 July, 2010	SIGNED: <u>[Signature]</u> Richard A. Barnhart II, IA: 3124994	Work Order: 1385 Printed by EBis 3 (datcomedia.com)

Propeller Service & Maintenance Record

Date

Total Time

Time Since Last Overhaul

Installations, Inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins.

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP5272B
REG. NO. N335A
WORK ORDER:
1891-08-2011

Advanced Aircraft Services

530 Airport Rd.
Lititz, PA 17543
Phone: 717-735-5179

DATE: 9/15/2011
A/C TSN: 1082.1
PROP TT: 1082.1
HOBBS: 1304.6


Prop Entries

Cirrus Propeller Annual Inspection completed using the Cirrus AMM check list ch. 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2011-19 Ops check good.

I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.

DATE: 9/15/2011

SIGNED:



Work Order: 1891-08-2011

Richard A. Barnhart II, IA: 3124994AP

Printed by EBis 3 (datcomedia.com)

8/8/12

Broughtt
Forward

N/A

REMOVED CYLINDER, FLUSHED FOR
CONTAMINATION, RESEALED CYLINDER,
CHECKED ANGLES AND TRACK

THIS IS NOT AN OVERHAUL
AND CANNOT BE CONSIDERED AS SUCH

WORK ORDER L23937

C. Ray Hush
Sensenich Propeller Service
Repair Station #QV9R194M

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP5272B
REG. NO. N335A
WORK ORDER:
2336-06-2012

Advanced Aircraft Services

530 Airport Rd.
Lititz, PA 17543
Phone: 717-735-5179

DATE: 10/9/2012
A/C TSN: 1302.5
PROP TT: 1302.5
HOBBS: 1551.5


Prop Entries

Cirrus Propeller Annual Inspection completed using the Cirrus AMM check list ch. 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2012-19 Ops check good.

I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.

DATE: 10/9/2012

SIGNED:



Work Order: 2336-06-2012

Richard A. Barnhart II, IA: 3124994AP

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP5272B
REG. NO. N335A
WORK ORDER:
3082-10-2013



Advanced Lancaster LP

530 Airport Rd.
Lititz, PA 17543
Phone: 717-735-5179

DATE: 10/10/2013
A/C TSN: 1462.8
PROP TT: 1462.8
HOBBS: 1732.6


Prop Entries

Cirrus Propeller Annual Inspection completed using the Cirrus AMM check list ch. 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2013-20 Ops check good.

I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.

DATE: 10/10/2013

SIGNED:



Work Order: 3082-10-2013

Richard A. Barnhart II, IA: 3124994AP

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
HC-J3YF-1RF
PROP S/N: FP5272B
REG. NO: N335A
WORK ORDER:
659-11-2014

ADVANCED Lancaster LP
530 Airport Rd.
Lititz, PA 17543
Phone: 717-735-5179

DATE: 11/12/2014
A/C TSN: 1689.7
PROP TT: 1689.7
HOBBS: 1984.8

Prop Entries

Cirrus Propeller Annual Inspection completed using the Cirrus AMM check list ch 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2014-22.

I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.

DATE: 11/12/2014

SIGNED:

Richard A. Barnhart II, IA: 1124994AP

Work Order: 3659-11-2014

Printed by EBis 3 (datcomedia.com)

nce Record

Business
Modifications and

Date

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP5272B

ADVANCED Fly Advanced
530 Airport Rd.

DATE: 1/7/2016
A/C TSN: 1824.5
PROP TT: 1689.7

MAINTENANCE RELEASE

Part No: PHC-J3YF-1RF Description: HARTZELL PROPELLER Serial No: FP5272B
was REPAIRED (describe) Removed and installed new alcohol feed shoes on all three blades per Hartzell manual 183 R3

OVERHAULED per the following documents (include revision levels):
Manuals
Service Bulletins
Service Letters
Service Instructions
Service Advisories

**THIS IS NOT AN OVERHAUL
AND CANNOT BE CONSIDERED AS SUCH**

The following Airworthiness Directives have been complied with:

A.D. Method of Compliance: Recurs at: Date or Hours

Time Since New: 1856.4 Time Since Overhaul/Major: N/A
The item(s) identified above were repaired or overhauled (as indicated) and inspected in accordance with current FAA regulations and are approved for return to service. Pertinent details of this repair or overhaul are on file at this repair station under work order # L27282

Date: January 5, 2016 Signed: *[Signature]*
For Repair Station #QV9R194N
SENENICH PROPELLER SERVICE, INC.

FORM 004

519 East Airport Road, Lititz, PA 17543

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP5272B
REG. NO: N335A
WORK ORDER:
4920-01-2017

ADVANCED Fly Advanced
Repair Station No. 5T2R901C
530 Airport Rd.
Lititz, PA 17543
Phone: 717-735-5179

DATE: 1/18/2017
A/C TSN: 2174.9
PROP TT: 2174.9
HOBBS: 2328.3

Prop Entries

Annual Propeller Inspection completed IAW FAR 91.409 and the requirements outlined in FAR 43 App. D. with reference to the Cirrus AMM check list ch 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2017-01.

I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.

DATE: 1/18/2017

SIGNED:

Joel A. Glover
Certified Repair Station No. 5T2R901C

Work Order: 4920-01-2017

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP5272B
REG. NO: N335A
WORK ORDER:
5569-01-2018

ADVANCED Fly Advanced
Repair Station No. 5T2R901C
530 Airport Rd.
Lititz, PA 17543
Phone: 717-735-5179

DATE: 1/12/2018
A/C TSN: 2270.4
PROP TT: 2270.4
HOBBS: 2435.9

Prop Entries

Annual Propeller Inspection completed IAW FAR 91.409 and the requirements outlined in FAR 43 App. D. with reference to the Cirrus AMM check list ch 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2018-01.

I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.

DATE: 1/12/2018

SIGNED:

Derrick S. Miller
Certified Repair Station No. 5T2R901C

Work Order: 5569-01-2018

Printed by EBis 3 (datcomedia.com)

Propeller Service & Maintenance Record

Date	Total Time	Time Since Last Overhaul	Installations, Inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins.
------	------------	--------------------------	---

PROP MODEL:
PHC-J3YF-1RF
PROP S/N FP5272B
REG NO N335A
WORK ORDER:
6133-10-2018

ADVANCED Fly Advanced

Repair Station No. 5T2R901C
530 Airport Rd
Litz, PA 17543
Phone 717-735-5179

DATE: 2/13/2019
A/C TSN 2314
PROP TT 2314
HOBSBS 2486

Prop Entries

Annual Propeller Inspection completed IAW FAR 91.409 and the requirements outlined in FAR 43 App. D with reference to the Cirrus AMM check list ch 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2019-03.

I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.

DATE: 2/13/2019

SIGNED: 
Josh Ferry
Certified Repair Station No. 5T2R901C

Work Order: 6133-10-2018

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-1RF
PROP S/N FP5272B
REG NO N335A
WORK ORDER:
7079-02-2020

ADVANCED Fly Advanced

Repair Station No. 5T2R901C
530 Airport Rd
Litz, PA 17543
Phone 717-735-5179


DATE: 2/19/2020
A/C TSN 2339 9
PROP TT 2339 9
HOBSBS 2523.1

Prop Entries

Annual Propeller Inspection completed IAW FAR 91.409 and the requirements outlined in FAR 43 App. D with reference to the Cirrus AMM check list ch 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2020-04.

I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.

DATE: 2/19/2020

SIGNED: 
Joshua J. Ferry
Certified Repair Station No. 5T2R901C

Work Order: 7079-02-2020

Printed by EBis 3 (datcomedia.com)

PROPELLER ENTRY

"N" #: N335A	Make: CIRRUS	Model: SR22	Serial #: 2288	Total Time: 2347.4	Date: 08/20/2020
-----------------	-----------------	----------------	-------------------	-----------------------	---------------------

- Description
1. COMPLIED WITH PRELIMINARY INSPECTION IN ACCORDANCE WITH 14 CFR 145.211(c)(ii).
 2. COMPLIED WITH ANNUAL INSPECTION IAW CIRRUS SR22 MM APPLICABLE SECTION OF CH 05-20. GROUND RAN, OPERATIONAL AND LEAK CHECKS GOOD. WORK PERFORMED IAW CIRRUS SR22 MM APPLICABLE SECTION OF CH 12-10.

*****MAINTENANCE RELEASE*****

THE AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER WORK ORDER NO. 96601.



SIGNED BY:  FOR
EAGLE AVIATION, INC., 2861 AVIATION WAY, WEST COLUMBIA, SOUTH CAROLINA 29170
FAA APPROVED REPAIR STATION NO. FEHR859D

S&S AVIATION



N335A Prop Logbook Entry

Make: Hartzell Model: PHC-J3YF-1RF S/N PF5272B
TTSN: 2420.2 TTSN: 2420.2

ce Record

Date

The following work was completed in accordance with the PA-28 service manual, the Hartzel Compact Hub Propeller Service Manual and all applicable FAR's unless otherwise noted.

1. Annual Inspection completed.
2. There are no new or recurring AD's at this time.

I certify that I have inspected this propeller as indicated above and find it to be in an airworthy condition.

Signed *M. Hees* Cert. No. A&P2739898IA Date 15 Sept., 2021

ness
fications and