

# PROPELLER LOGBOOK

PROPELLER S/N TM51

LOGBOOK # 1

ED REL  
130-3, AIRWO

34

9. Qu

-----END

# PROPELLER MAINTENANCE RECORD

Position one

PITCH RANGE

Propeller Model 4C1-F650A1

High/Feather \_\_\_\_\_

Propeller S/N TM51

Start Lock \_\_\_\_\_

Blade Design 76C04B-0.6

Low \_\_\_\_\_

Blade S/N's

Reverse \_\_\_\_\_

No. 1 C7713

Aircraft Manufacturer Cirrus Design Corp.

No. 2 C7746

Aircraft Model SR22T

No. 3 C7747

No. 4 C7767

No. 5 \_\_\_\_\_

No. 6 \_\_\_\_\_

Spinner Assembly Part No. \_\_\_\_\_

S/N 2308

Registration N356

aircraft maintenance

airworthiness and  
aircraft engine(s)

ally constitute

Installer R

14	14
14	14

14

14

on, and pitch  
ork was performed  
Form # 25. Per  
END

34

9. Q

130-3, AIRW

[illegible]

PROP MODEL  
4C1-F650A1  
PROP S/N TM51  
REG NO N356  
WORK ORDER  
8585-05-2021

### Kalamazoo Aircraft, Inc.

Repair Station No K9AR289N  
2729 E Milham Rd  
Kalamazoo, MI 49002  
Phone (269) 381-0790

DATE 10/12/2021  
A/C TSN 10 9  
PROP TT 10 9  
FLIGHT TIME 10 9

### Prop Entries

REMOVED HARTZELL PROPELLER P/N 4C1-F650A1, S/N TM51, AND SENT TO HARTZELL PROPELLER FOR FLUSH  
REINSTALLED REPAIRED PROPELLER WITH NEW O-RING AND HARDWARE, TORQUED, RAN, LEAK AND OPS CHECKED  
GOOD.

The above work was performed in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Details are on file at this certified repair station.

DATE: 7/22/2021

SIGNED:

James R Michalka  
Certified Repair Station No. K9AR289N

Work Order 8585-05-2021

Printed by EBis 3 (datcomedia.com)

PROP MODEL: 4C1-F650A1  
PROP S/N: TM51  
REG NO N356  
WORK ORDER: KTYS26148-10-2021



### CIRRUS Cirrus Factory Service Center

Repair Station No 9B0R988C  
114 Cirrus Landing  
Alcoa, TN 37701  
Phone: 865-980-8702

DATE 10/12/2021  
A/C TSN 99 9  
PROP TT 99 9  
TSPCH  
TACH 99 9

### Prop Entries

(18) Inspected Propeller IAW Hartzell Propeller Owner's Manual 61-00-80.

The aircraft, airframe, aircraft engine, propeller or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of this work order are on file at this Certified Repair Station CRS 9B0R988C

DATE: 10/12/2021

SIGNED:

John Goebel  
Certified Repair Station No. 9B0R988C

Work Order: KTYS26148-10-2021

Printed by EBis 3 (datcomedia.com)

Description of all operations pertaining to Airworthiness Directives,  
Service Documents, Overhaul, Major or Minor Repair, and Inspections.

**fly/ADVANCED**

Make: Hartzell  
Model: 4C1-F650A1  
S/N: TM51

1501 Narcissa Road Blue Bell, Pa 19422 (215) 646-0400

Date: 05/12/2022  
N356  
Hobbs: 130.8  
Flight: 101.6  
Prop. TT: 101.6

**Propeller Entry:**  
Performed an Annual inspection IAW FAR 43 Appendix D and Cirrus MM Chapter 5-20. AD's current through 2022-10 bi-weekly. Details of this inspection are on file at this facility under work order #LWO-15418. END.

I certify that this PROPELLER has been inspected IAW an Annual inspection and was found to be in airworthy condition.

This aircraft and/or component(s) was repaired in accordance with the current rules and regulations of Title 14 of the Federal Aviation Regulations, was found to be Airworthy, and returned to service.

Joseph DiSipio  
A&P3953685IA

