

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HC-C2YR-1BFP/F7497

PROPELLER S/N NS6537B

LOGBOOK # _____

ATION
RCRA

...times. When equipment is
...ained concurrently with and become a

PROPELLER MAINTENANCE RECORD

Position _____

Propeller Model HC-C2YR-1BFP

Propeller S/N NS6537B

Blade Design F7497

Blade S/N's

No. 1 L15957

No. 2 L15950

No. 3 _____

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____

Reverse _____

Aircraft Manufacturer _____

Aircraft Model _____

S/N _____

Registration _____

ATIONS &
RCRAFT

ite TSN TSO Hrs

HARTZELL SERVICE CENTER

One Propeller Place
Piqua, Ohio 45356 U.S.A



May 25, 2023

W/O:22768 S/N: NS6537B TSN: Not Provided TSO: 0.0

Pertinent details of the work performed are specified on the provided FAA Form 8130-3, Tracking Number MQ38660, Dated 5-25-23.

Dan Davis Repairman #
Repair Station # SJ3R843L

wo: WO_248
Steel Aviation · 53 North Street Ext · Phillipsburg, Ohio 45354 · 937 332 7587
Hartzell, HC-C2YR-1BFP, S/N: NS6537B
inspected in accordance with FAR 43 Appendix D using - Diamond DA40 ASMA and Hartzell
Propeller - [unclear] July 18, 2023

wo: WO_248



Propeller - page 1 of 1

Steel Aviation · 53 North Street Ext · Phillipsburg, Ohio 45354 · 937 332 7587

N889DS

Hartzell, HC-C2YR-1BFP, S/N: NS6537B

July 18, 2023

TACH: 2998.5

1. C/W Annual Inspection in accordance with FAR 43 Appendix D using - Diamond DA40 AMM and Hartzell 115N Manual as a guide.
2. Removed prop and sent out for overhaul. Installed same prop after overhaul from Hartzell. Prop model HC-C2YR-1BFP S/N: NS6537B.

I certify that this Propeller has been inspected in accordance with an (annual) inspection and was determined to be in airworthy condition. Details of work performed are on file with Steel Aviation under work order: WO_248.

Jeff Pleiman A/P I/A 3304319