




Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
10-19-17	0.0	N/A	0.0	<p>I have Dynamically Balanced Propeller IAW Hartzell Propeller Owner's Manual 115N Rev. 22 dated Jul/16 Section: 61-00-45 on OCT 19 2017 (DATE). The location of the Weight(s) are <u>190</u> degree And are <u>16.7</u> gram(s).</p> <p>  (Sign/Stamp) Cirrus Design Corporation, PC 338CE</p>



Registration: N226RG Date: 9 Jan. 18 Flight: 28.7 TT
Make: Cirrus Model: PHC-J3Y1F-1RF S/N: Prop S/N: FP9116B

Blended propeller blades in accordance with Hartzell Manual 115N. Touched up prop paint. Performed a Dynamic balance check, vibration reading is 0.03 IPS. Results Satisfactory.

This work has been performed in accordance with Federal Aviation Regulations and is hereby approved for return to service.
(Reference work order: 1050)


Alexander J. Silva.:  Certificate #: A&P 3804642








Registration: N1RG Date: 17 Jul. 18 Flight: 93.2 TT
Make: Cirrus Model: PHC-J3Y1F-1RF S/N: Prop S/N: FP9116B


Inspected the propeller per Cirrus AMM Manual Chapter 61-10. Performed a 100 hour inspection Cirrus Service Instructions. The propeller was serviced with Aeroshell #6 grease per the Hartzell service manual 61-00-45 Rev. 13 dated Oct. 2013.

This work has been performed in accordance with Federal Aviation Regulations and is hereby approved for return to service.
(Reference work order: 1180)


Alexander J. Silva.:  Certificate #: A&P 3804642

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
				Registration: N73CC Date: 09/18/19 Flight: 208.7 TT Make: Hartzell Model: PHC-J3YF-1 RF S/N: FP9116B
<p>Inspected the propeller per Cirrus AMM Manual Chapter 61-10. Performed a 100 hour inspection per Cirrus Service Instructions 5-20. Lubricated the propeller with Aeroshell #6 grease.</p> <p>This propeller has been inspected in accordance with Federal Aviation Regulations and is hereby approved for return to service. (Reference work order: 1534)</p> <p> Jordan Mitchell McCoy Certificate #: 4222530 <u>A&P</u></p>				

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
				Registration: N1RG Date: 13 Nov. 2018 Flight: 125.7 TT Make: Hartzell Model: PHC-J3YIF-1RF S/N: FP9116B
<p>Inspected the propeller per Cirrus AMM Manual Chapter 61-10. Performed a 100 hour inspection per the scope and detail of FAR 43 Appendix D and Cirrus Service Instructions.</p> <p>(Reference work order: 1278)</p> <p>I certify that this propeller has been inspected in accordance with a 100 hour/annual inspection as per the scope and detail FAR43 Appendix D and Cirrus AMM date June 2010 and was determined to be in an airworthy condition.</p> <p>Jeremy A. Greene.:  Certificate #: <u>AP36662931A</u></p>				
<p>and detail of FAR 43 Appendix D and Cirrus Service Instructions.</p> <p>(Reference work order: 1585)</p> <p>I certify that this propeller has been inspected in accordance with a 100 hour/annual inspection as per the scope and detail FAR43 Appendix D and Cirrus AMM date June 2010 and was determined to be in an airworthy condition.</p> <p>Scott P. Reilly.:  Certificate #: <u>A&P 33618011A</u></p>				

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
				Registration: N73CC Date: 16 Nov 2020 Flight: 309.4 TT Make: Hartzell Model: PHC-J3YIF-IN S/N: FP9116B
	<p>Inspected the propeller per Cirrus AMM Manual Chapter 61-10. Performed a 100 hour inspection per the scope and detail of FAR 43 Appendix D and Cirrus Service Instructions.</p> <p>(Reference work order: 1840)</p> <p>I certify that this propeller has been inspected in accordance with a 100 hour/annual inspection as per the scope and detail FAR43 Appendix D and Cirrus AMM and was determined to be in an airworthy condition.</p> <p>Scott P. Reilly.: <u>Scott P. Reilly</u> Certificate #: <u>A&P 3361801IA</u></p>			

wo: 2113 Propeller · page 1 of 1


 Elite Aircraft Maintenance · 707 Rod Sullivan Rd · Sanford, NC 27330 · 9196651233

N73CC	January 04, 2022
Flight: 333.9	

1. Inspected the propeller per Cirrus AMM Manual Chapter 61-10. Performed a 100 hour inspection per the scope and detail of FAR 43 Appendix D and Cirrus Service Instructions. The propeller was serviced with Aeroshell #6 grease per the Hartzell service manual 61-00-45.

I certify that this aircraft has been inspected in accordance with an annual inspection as per the scope and detail FAR43 Appendix D and was determined to be in an airworthy condition. Details of work performed are on file with Elite Aircraft Maintenance under work order 2113.

Scott Reilly A&P 3361801IA Scott P. Reilly

