


**MCCAULEY™**

**PROPELLER  
OPERATOR'S  
MANUAL  
&  
LOG**



**MPC-10, MPC-11, MPC-12,  
MPC-13, MPC-14, MPC-15,  
CMM500-1**

# PROPELLER ASSEMBLY LOG

PAGE NUMBER	Date	Total Time	Time Since Overhaul	Aircraft Model & Registration Number	Maintenance Service History	Signature & Certificate Number
	12/3/15	8	5	2A37C223-C	<b>THIS PROPELLER WAS MANUFACTURED NEW AT McCauley Propeller Systems. INSPECTED AND FOUND TO BE AIR- WORTHY ON THIS DATE.</b>	 60150
			512	150525		

**PROP MODEL:**  
**PROP S/N:**  
**REG. NO.:** 9774Y  
**WORK ORDER:** 15127



**Mangon Aircraft, Inc.**  
 501 Sky Ranch Drive  
 Petaluma, CA 94954-3908  
 Phone: (707) 765-1848

**DATE:** 12 February, 2016  
**A/C TSN:** 5394.44  
**PROP TT:**  
**TACH:** 5394.44

**Prop Entries**

Propeller completed a 100 Hour inspection to complete Annual Inspection requirements of FAR 91.409 (a)(1), using Beechcraft / Raytheon Service Manual 35-590086B, Reissue, Nov. 15, 1960, Revised 35-590096B20, Dtd. Sep. 03, 2001.... Propeller Pn.2A36C23/PCEG removed from service 2/2016. Propeller replaced with new model Pn.2A37C223/90RB-6. Installed with new "O" ring and nuts lube-torqued to 50 ft. lbs. No leaks noted. Ops check good.

PROPELLER GROUND OPERATED. ALL FUNCTIONS CHECKED NORMAL  
 I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH THE REQUIREMENTS OF A 100-HOUR INSPECTION FOR AN ANNUAL CERTIFICATION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION

**DATE:** 12 February, 2016      **SIGNED:**

  
 Michael Tillman, A&P: 2845176 IA

**Work Order:** 15127  
 Printed by EBis 3 (datamedia.com)







