
## HARTZELL

## PROPELLER LOGBOOK

PROPELLER MODEL PHC- J3YF-IRF/F7694

PROPELLER S/N FP21.116

LOGBOOK #\_1\_




Position	PITCH RANGE
Propeller Model PHC-J3YF-IRF/F7694	High/Feather 35.0
Propeller S/N FPAIIIB	Start Lock
Blade Design	Low_14.1
Blade S/N's	Reverse
No. 1 584227	
No. 2 <u>58 4226</u>	Aircraft Manufacturer
No. 3 <del>18 4128</del> 575799	Aircraft Model
No. 4	S/N_
No. 5	Registration
No. 6	
Spinner Assembly Part No	verhault Major or Minor Rapay, ar dargue a same

Date	Prop	eller	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
-7-03	0.2			I have Dynamically Balanced Propeller IAW Hartzell Propeller Owner's Manual 115N Rev. 7 dated Oct/02 Section: 61-00-15 on

Insp. Sig / Louis Airport  Spirit of St Louis Airport  Chesterfield, MO. 63005  FAA Certificated Repair Sta	aft STL Inc. t532 Beechcraft Dr. (636)532-4800
347.3 PROP REMOVED FOR REPAIR	AFTER PROP STRIKE WITH OBJECT
1	Insp. Sig/(Mal/) October Executive Beechcra  Spirit of St Louis Airport  Chesterfield, MO, 63005

MID AMERICA PROPELLER, INC.  FAA REPAIR STATION M3PR527J  DATE @ 21 05 MODEL PHC- T3YF-1RF  TOTAL TIME SIN F POLITIB  Propeller Overhaul:  Disasser bled, cleaned, inspected,  Overhauled, reader moled, and  tested Hendrich Dieses  MID AMERICA PROPELLER, INC.  FAA RS#M3PR527J	Propeller TSN TSO	A/C Hrs  Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
		FAA REPAIR STATION M3PR527J  DATE 02/21/05 MODEL PHC-J3YF-IRF  TOTAL TIME S/N FP2111B  Propeller Overhaul:  Disassenbled, aleaned, inspected,  Overhauled, reassembled, and  tosted Henderk Macs  MID AMERICA PROPELLER, INC.
Form 47118-ST <del>k</del> R		Form 47118-ST*R



Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
			OZARK AIRCRAFT MAINTENANCE LLC
			CAPE GIRARDEAU REGIONAL AIRPORT  CAPE GIRARDEAU MO
	May 5, 2006	6 N1039	Cirrus SR22 S/N 470
	Hartzell PH	IC-J3YF-	-1RF S/N FP2111B
	Hobbs 585.	7 Total to	time 585.7  TSO $H = 218.0$ lades greased hub
	Filed and pa	iintea, oi	I certify that this propeller has been inspected IAW
		V	With a 100 hour inspection and was determined
-		t	to be in an airworthy condition.
			Brian J Ozark AP041640790IA
		AND DESCRIPTION OF THE PERSON	

## OZARK AIRCRAFT MAINTENANCE LLC CAPE GIRARDEAU REGIONAL AIRPORT CAPE GIRARDEAU MO June 12, 2007 N1039 Cirrus SR22 S/N 470 Hartzell HC-E3YR-1RF S/NFM1155A EPZ 11113 Hobbs 703.6 Total time 703.6 Filed and painted blades, check attach torque. I certify that this propeller has been inspected IAW With a 100 hour inspection and was determined to be in an airworthy condition. Brian J Ozark AP041640790IA OZARK AIRCRAFT MAINTENANCE LLC CAPE GIRARDEAU REGIONAL AIRPORT CAPE GIRARDEAU MO August 20, 2008 N1039 Cirrus SR22 S/N 470 Hartzell HC-E3YR-1RF S/N FM1155A FP2111B Hobbs 920.7 Total time 920.7 TSOH 553.4 Filed and painted blades, check attach torque. Greased blades I certify that this propeller has been inspected IAW With a 100 hour inspection and was determined to be in an airworthy condition. Zark AP041640790IA Page 3

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
t	September 4, Hartzell HC- Hobbs 993.5 Filed and pair I certify that the FAR 43 App ( be in an airy	2009 E3YR-1 Total tin ted black his prop d) a 100 vorthy c	OZARK AIRCRAFT MAINTENANCE LLC CAPE GIRARDEAU REGIONAL AIRPORT CAPE GIRARDEAU MO N1039 Cirrus SR22 S/N 470 RF S/N FM1155A FPAUB me 920.7 TSOH 553.4 des, check attach torque. Greased blades eller has been inspected IAW hour inspection and house in the second sec

## OZARK AIRCRAFT MAINTENANCE LLC CAPE GIRARDEAU REGIONAL AIRPORT CAPE GIRARDEAU MO September 27, 2010 N1039 Cirrus SR22 S/N 470 Hartzell HC-E3YR-1RF S/N FM1155A Hobbs 1072.9 Total time 1072.9 TSOH 632.8 Filed and painted blades, check attach torque. Greased blades I certify that this propeller has been inspected IAW FAR 43 App (d) a 100 hour inspection and was determined to be in an airworthy condition. Brian & Ozark AP0416407901 Dan's Prop Hobbs time 1547.1 Cirrus SR22 SN 470 Prop Time 1179.8 HartzellPHC-J3YF S/N FP211B I certify that this prop has been inspected in accordance with and annual inspection and was determined to be in airworthy condition. Roland Bronsor 2333210IA Date, 9/24/2015

Page 4

Date	Propelle TSN T	er A/C SO Hrs		Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.	
		Hobbs Ti		nat this prop has been inspeted in accordance with inspection and was determined to be airworthy condition  Roland Bronson  2333210IA  Date/108/2016	
		Prop i	inspe	TSOH 160.4 Total Time 318.0  Sected in accordance With chapter 5-20 New Overhaul  Sthat this Prop has been inspected inaccordance with and pection and was determined to be in airworthy condition  Roland Bromson 2333210IA  Date Sept, 22, 2019	

Date	Hartzell HC-E3Y Hobbs 1201.6 T Filed and painted I certify that this	Dank	es, etions.
7			

	OZARK AIRWORKS, INC.
	185 Taxiway Place Midway, AR. 72651
Date: 12/12/12 Propeller: Hartzell	(870) 481-5456
Model: PHC-J3YF Series Serial No. FP2111B	
SMOH: 916.9	ed this date. This inspection procedure meets the requirements of FAR 43.13 appendix
(d) and Hartzell Propeller ma	intenance and service data. All AD notes pertinent to this propeller have been complied
with and are listed in the Cor OZA-2886.	mpliance Report. Details of this inspection are on file at this agency under work order No.
	eller has been inspected in accordance with an annual inspection and has
been determined to be in	
	Les Ives, A/P 489486318 I/A

Hobbs time 1498.3 Cirrus SR22 SN 470 Prop Time 1131.0  HartzellPHC-J3YF S/N FP211B  I certify that this prop has been inspected in accordance with and annual inspection and was determined to be in airworthy condition.  Roland Bronson 2333210IA Oct,7,2014  3/25/2017  Ib59.6 1292.3 1659.6 ON This Date Prop Removed for overhaul @ NE Propelle (Sulpen)  1659.6 OO.0 1659.6 ON This Date Remistalled propelled on N83886 after overhaul by New England Propelled Service. Grand Ran England no Leader and Medical Noted.	Date	Prop	peller	A/C	Description of all operations pertaining to Airworthiness Directives,  Service Documents, Overhaul, Major or Minor Repair, and Inspections
6/21/2017 00.0 1659.6 ON This Date Reinstalled propeller on N8388G Atter overhist by NEW England Propeller Service. Ground Ran Engine No Les				Ha I an	rtzellPHC-J3YF S/N FP211B certify that this prop has been inspected in accordance with d annual inspection and was determined to be in airworthy ndition.  Roland Bronson 2333210IA
6/21/2017 00.0 1659.6 ON This Date REINSTAILED PROPEller ON N8388G After overhist by Now England Propeller Service. Ground RAN Engine No Les	5/25/2	17			
6/21/2017 00.0 1659.6 ON This Date REINSTAILED PROPEller ON N8388G After overhis by Now England Propeller Service. Ground RAN Engine No Les		1659.6	1292.3	1659.6	on This Date Prop Removed for overhaul a NE Propeller
	6/22/20	1659.6	00.0	1659.6	ON This Date Reinstalled propeller on N8388G Atter overhauc
or defected Noted. (M. Hooveln Att 3191938					
					or defected Noted. In Propolly Att 3191938

A

Approving Civil Aviation Authority/Country: FAA/United States  AUTHORIZED R FAA Form 8130-3, AIR	ELEASE CERT RWORTHINESS A	PPROVAL TAG	3. Form Tracking Number:  43667  5. Work Order/Contract/Invoice Number	7
4. Organization Name and Address:  New England Propeller Service, Inc  FAA RSN RC2R130L	6 Matthews Driv East Haddam, (860) 873-1494	ve	CR-43667	
EASA 145.5972	9. Quantity:		11. Status/Work:	
HARTZEU PHC JAYF-IRF	1		DUELHAUCED 202A VIR55	1
12. Remarks THIS PROPELLER WAS REPAIRED IN ACCORDANCE WITH MANUFACTURER'S I	MANUALS:	V F C V V F 7 0	V6R34 V7R44	1
		V8R32 V10R34		1
Total Time: LINKNOWH'S  Time Since Overhaul: OC  Details of work performed are on file at New England Propeller Service, Inc.	c. under Repair Static	on Work Order Number: CRY	3667	1
Details of work performed are on file at New Eligiand 1 Topological The following work was performed:	HALL BLADES REF	INISHED. PARTS FLORESCENT		
PENETRANTI	INSPECTED, MAGN	AFLUXED, & REPLACED WHEHE		
DECILIBED	DEICER BOOTS	INSTALLED. PROP TRACKED, NGLES & PAINTED. COMPLIES		
HING 1 A BIO 0	OBIC LICTED ON R	ISUTA FILIRIN INDIANCE		
OVERH	AULED BU	ADESINJ 1999	.28.	
	3.)	4.) 5.)	6.)	
Blade Serial #'s: 384227 584220	J 75/	77		

	S.B. & Subject	@ Compliance	Method of Compliance	one-time	recurr.	Next Comp.
						hrs./date
""CU).	for safe operation.  13c. Approval/Authorization No.:  13e. Date (dd/mmm/yyyy):	Certifies that unle 11 and described of Federal Regular for return to service 14b. Authorized Signate 14d. Name (Typed or Parthur D'On Arthur D'On PENETRANT INSPENDENTANT INSPENDENT INSPENDENT INSPENDENT INSPENDENT INSPENDENT INSPENDENT INS	Printed): ECTED, MAGNAFLUX ER BOOTS INSTAL ASED, SET ANGLES	ed in Block 12, the wood in accordance respect to that work, the RC2	proval/Certificate No.  2R130L  (dd/mmm/yyyy):  HERE  CKED,  PLIES	ck Code ved
		AUTHORIZI	ED BY	M/si	#64360 d	7
		NEW ENGL	AND PROPELLI EAST HADDAI EPAIR STATION 1-800-878-6	ER SERVICE, IN M, CT V# RC2R130L		
Date TSN TSO	High Service	e Documents, Or	enous peneral			


				ENTOT AND
Date	Prop	peller	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
				Hobbs Tane 1919 S Proposite log Total Term MAIS The Samuran A Samu
				DAN T Cirrus 22 Prop
		i cer	ed and tify the linsp	1419.5 Propeller Log Total Time 1419.5 Time SMOH 979.4 dressed prop blades and visual inspection of propeller . hat this propeller has been inspected in accordance with and ection and was determined to be in airworthy condition 2013  Roland Bronson 2333210IA
				WASTEDNIE TO THE TOTAL TO THE STORE STATE OF THE STATE OF
			Hob Prop I, cert	bs 1678.0 TSOH 18.4 Total Time 167.0 inspected in accordance With chapter 5-20 New Overhaul rify that this Prop has been inspected inaccordance with and inspection and was determined to be in airworthy condition inspection and was determined to be in airworthy condition.
			ammua	Roland Bronson 2333210IA Date Sept, 27, 2017
				TSOH 78.9 Total Time 236.5

	bbc 1679 0 TCOU 10 1
	obbs 1678.0 TSOH 18.4 Total Time 167.0 — inspected in accordance With chapter 5-20 New Overhaul
	rtify that this Prop has been inspected inaccordance with and
annu	al inspection and was determined to be in sirworthy condition
	Seffel Mour
	Roland Bronson 2333210IA
	Date Sept, 27, 2017
	Hobbs 1738.5 TSOH 78.9 Total Time 236.5
	Prop inspected in accordance With chapter 5-20 New Overbaul
	Tyce cardence that this Prop has been inspected insecondence
	annual inspection and was determined to be in airworthy condition
	1/
	Roland Bronson 2333210IA
	Date Sept, 20, 2018
	SEPT 22, 2019 ANNUAS Truspection SEE page #5 for Sticker
	Hobbs 1874.6 TSOH 132.9 Total Time 290.5
	Prop inspected in accordance With chapter 5-20 Now Overband
	Literative that this Prop has been inspected inserted.
	annual inspection and was determined to be in airworthy condition
180	Roland Bronson 2333210IA
200 / 10 / 10 / 10 / 10 / 10 / 10 / 10 /	Date Sept, 21, 2020

Date	merson fiviation .
	LACONIA MUNICIPAL AIRPORT  118 KIMBALL ROAD
	GILFORD, NH 03249 603-293-0800 PROPELLER ENTRY
	REMOVED SPINNER, INSPECTED PROPELLER IAW AN APPROVED 100HR I NSPECTION CHECKLISTAND FAR 43 APPENDIX D; DRESSED AND PAINTED BLADES; REINSTALLED SPINNER; RETURN THIS PROPELLER TO SERVICE IN REGUARDS TO THE WORK PERFORMED.
	CHRISTIAN CLAYTON A&P3474976
	PROPELLER ENTRY N8388G S/N: FP2111B HOBBS: 1912.9 PTT: 171.2 SEPTEMBER 13, 2021
	I CERTIFY THAT I HAVE INSPECTED THIS PROPELLER IN ACCORDANCE WITH AN ANNUAL INSPECTION AND HAS BEEN FOUND TO BE AIRWORTHY AND RETURN IT TO SERVICE.  3474976IA  CHRISTIAN CLAYTON

Comerson Tviation
LACONIA MUNICIPAL AIRPORT
118 KIMBALL ROAD GILFORD, NH 03249
603-293-0800
N8388G S/N: FP2111B HOPPG 1076
N8388G S/N: FP2111B HOBBS: 1956.4 PTT: 214.7 SEPTEMBER 14, 2022  REMOVED SPINNER, INSPECTED PROPELLER IAW AN APPROVED 100HR I NSPECTION CHECKLISTAND FAR 43 IN REGUARDS TO THE WORK PERFORMED.
CHRISTIAN CZAYTON  A&P3474976
N8388G S/N: FP2111B HORRS: 105C 4 PTT
N8388G S/N: FP2111B HOBBS: 1956.4 PTT: 214.7 SEPTEMBER 14, 2022
I CERTIFY THAT I HAVE INSPECTED THIS PROPELLER IN ACCORDANCE WITH AN ANNUAL INSPECTION AND HAS  BEEN FOUND TO BE AIRWORTHY AND RETURN IT TO SERVICE.
CHRISTIAN CLAYTON 3474976IA

1	December 100 December 110
Date	LACONIA MUNICIPAL AIRPORT  118 KIMBALL ROAD  GILFORD, NH 03249  603-293-0800
	N8388G S/N: FP2111B HOBBS: 1994.3 PTT: 252.6 SEPTEMBER 1, 2023  REMOVED SPINNER, INSPECTED PROPELLER IAW AN APPROVED 100HR I NSPECTION CHECKLISTAND FAR 43 IN REGUARDS TO THE WORK PERFORMED.
	CHRISTIAN CLAYTON A&P3474976
	PROPELLER ENTRY  N8388G S/N: FP2111B HOBBS: 1994.3 PTT: 252.6 SEPTEMBER 1, 2023  I CERTIFY THAT I HAVE INSPECTED THIS PROPELLER IN ACCORDANCE WITH AN ANNUAL INSPECTION AND HAS BEEN FOUND TO BE AIRWORTHY AND RETURN IT TO SERVICE.
	CHRISTIAN CLAYTON 3474976IA



I	Drandlar	NO	Description of all operations pertaining to Airworthiness Directives,				
Date			Totation tions.				
			LACONIA MUNICIPAL AIRPORT				
			118 KIMBALL ROAD				
			GILFORD, NH 03249				
			603-293-0800				
			PROPELLER ENTRY				
	DEMONED CONT		88G S/N: FP2111B HOBBS: 1994.3 PTT: 252.6 SEPTEMBER 1, 2023				
			CTED PROPELLER IAW AN APPROVED <u>100HR I</u> NSPECTION CHECKLISTAND FAR 43 D PAINTED BLADES; REINSTALLED SPINNER; RETURN THIS PROPELLER TO SERVICE				
			RK PERFORMED.				
	1						
	66	1	_A&P3474976				
	CHRISTIAN CLA	YTON					
		NIO	PROPELLER ENTRY 888G S/N: FP2111B HOBBS: 1994.3 PTT: 252.6 SEPTEMBER 1, 2023				
		1103	000G S/N: FF2111B HODDS: 1994.5 F11: 252.0 SEFTENIDER 1, 2025				
	I CERTIFY THAT	T I HAVE IN	SPECTED THIS PROPELLER IN ACCORDANCE WITH AN ANNUAL INSPECTION AND HAS				
	BEEN FOUND TO BE AIRWORTHY AND RETURN IT TO SERVICE.						
	11/1	9-	247407(14				
	CHRISTIAN CLA	A VTON	3474976IA				
	CHROSTIAN CLA	TITON					

	LACONIA MUNICIPAL AIRPORT  118 KIMBALL ROAD  GILFORD, NH 03249  603-293-0800  PROPELLER ENTRY  N8388G S/N: FP2111B HOBBS: 2030.5 PTT: 288.8 OCTOBER 2, 2024  REMOVED SPINNER, INSPECTED PROPELLER IAW AN APPROVED 100HR I NSPECTION CHECKLISTAND FAR 43  APPENDIX D; DRESSED AND PAINTED BLADES; REINSTALLED SPINNER; RETURN THIS PROPELLER TO SERVICE IN REGUARDS TO THE WORK PERFORMED.	
	PROPELLER ENTRY  N8388G S/N: FP2111B HOBBS: 2030.5 PTT: 288.8 OCTOBER 2, 2024  I CERTIFY THAT I HAVE INSPECTED THIS PROPELLER IN ACCORDANCE WITH AN ANNUAL INSPECTION AND HAS BEEN FOUND TO BE AIRWORTHY AND RETURN IT TO SERVICE.  3474976IA  CHRISTIAN CLAYTON	
Date   FSI	No TSO Hrs Service Documents, Overhauf, Major or Minor Repair, and Inspections.	