

**N108EZ**

Propellor Log



## SENENICH PROPELLER SERVICE, INC.

## Propeller Logbook

- |                   |                                     |
|-------------------|-------------------------------------|
| McCauley          | <input type="checkbox"/>            |
| Hartzell          | <input checked="" type="checkbox"/> |
| MT                | <input type="checkbox"/>            |
| Sensenich         | <input type="checkbox"/>            |
| Dowty             | <input type="checkbox"/>            |
| Hamilton Standard | <input type="checkbox"/>            |

INSTALLING AGENCY PLEASE NOTE:  
Recording of Propeller Total Time Since New (TTSN)  
is Required Per F.A.R. 91.417

FP4944B

Lancaster Airport, 519 East Airport Road, Lititz, PA 17543 (800) 462-3412 (717) 560-3711 Fax: (717) 560-4354 FAA Certified Repair Station #QV9R194N

Lee Gilmer Memorial Airport, 1245 Palmour Place, Suite A, Gainesville, GA 30501 (800) 791-7767 (770) 538-0444 Fax: (770) 538-0117 FAA Certified Repair Station #S46R346N

Windham County Airport, 21 Airport Road, North Windham, CT 06256 (877) 456-7944 (860) 456-7944 Fax: (860) 456-0410 FAA Certified Repair Station #Q0PR011X

The manufacturers' FAA approved overhaul period for this propeller is 6 years/months or 2400 hours, whichever occurs first.

Limiting factors affecting time between overhaul (TBO)

Corrosion, internal

- Directly proportional to calendar time
- Unseen and potentially catastrophic

Corrosion-erosion, external

- Calendar time and operating environment
- Visible and easily corrected

Wear, Internal/External

- Function of hours in operation and types of flying, i.e., aerobatic much higher wear rates than pleasure.

Seal Life

- Deterioration and loss of resiliency affecting sealing property is proportionate to calendar time in service.
- Wear rates are commensurate to hours flown.

**IT IS STRONGLY RECOMMENDED ALL PROPELLERS MINIMUMLY RECEIVE AN INTERNAL CORROSION INSPECTION AND NEW SEALS AT INTERVALS NOT TO EXCEED SIX YEARS.**

INSTRUMENTATION  
Propeller Model PHC-J3YF-1N

Blade Model N7605B

Hub Serial No. FP4944B

Blade Serial No. 1 A0001

2 A0002

3 A0005

4 \_\_\_\_\_

5 \_\_\_\_\_

6 \_\_\_\_\_



# SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
------	----------------------	---------------------	---------------------	-----------------------

PROP MODEL:  
PROP S/N:  
REG. NO: 108EZ  
WORK ORDER: 11533



## Lincoln Park Aviation

Repair Station No. LKPR101K  
425 Beaverbrook Road  
Lincoln Park, NJ 07035  
Phone: 973-633-0450

DATE: 4/12/2017  
A/C TSN: 1037.3  
PROP TT: 523.6  
HOBBS: 1037.3

### Prop Entries

(3) 100HR/ANNUAL/PROP - INSPECTED PROPELLER IN ACCORDANCE WITH 100/ANNUAL INSPECTION... (10) INSTALLED OVERHAULED PROP. MODEL PHC-J3YF-1N, S/N: FP4944B. TEST RUN AND OPS CHECK OK.

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.

DATE: 4/12/2017

SIGNED:

Frank R Galella  
Certified Repair Station No. LKPR101K

Inspector #2

Work Order: 11533

Printed by EBis 3 (datcomedia.com)

CRS# LKPR101K

PROP MODEL:  
PROP S/N:  
REG. NO: 108EZ  
WORK ORDER: 11890



## Lincoln Park Aviation

Repair Station No. LKPR101K  
425 Beaverbrook Road  
Lincoln Park, NJ 07035  
Phone: 973-633-0450

DATE: 4/26/2018  
A/C TSN: 1059.6  
PROP TT: 545.9  
HOBBS: 1059.6

### Prop Entries

(3) 100HR/ANNUAL/PROP - INSPECTED PROPELLER IN ACCORDANCE WITH 100/ANNUAL INSPECTION

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.

DATE: 4/26/2018

SIGNED:

Frank R Galella  
Certified Repair Station No. LKPR101K



Inspector #2

Work Order: 11890





Printed by EBis 3 (datcomedia.com)

CRS# LKPR101K

# SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
	PROP MODEL: PROP S/N: REG. NO. N108EZ WORK ORDER: 5202-09-2019	<b>Waterford Aviation, Inc.</b> 6548 Highland Rd Suite 900 Waterford, MI 48327 Phone: 248-724-2400		DATE: 15 October, 2019 A/C TSN: 1120.7 PROP TT: 6070 TSPCH: FLIGHTTIME: 1120.7
	<b>Prop Entries</b>			
	Completed Annual Inspection in scope & detail of FAR 43 Appendix D and using the SR22 Annual Checklist as a guide. Researched AD's thru bi-weekly 2019-19 - none due at this time. I certify that this Propeller has been inspected in accordance with an Annual Inspection and has been found to be in Airworthy Condition.			
	DATE: 15 October, 2019	SIGNED:  Luke Hall, IA 3695185		Work Order: 5202-09-2019 Printed by EBis 3 (datcomedia.com)
	PROP MODEL: PHC-J3YF-1N PROP S/N FP4944B REG. NO. N108EZ WORK ORDER: 6080-10-2020	<b>Waterford Aviation, Inc.</b> 6548 Highland Rd Suite 900 Waterford, MI 48327 Phone: 248-724-2400		DATE: 06 November, 2020 A/C TSN: 1136.6 PROP TT: 622.9 TSPCH: FLIGHTTIME: 1136.6
	<b>Prop Entries</b>			
	Completed Annual Inspection in scope & detail of FAR 43 Appendix D and using the SR22 Annual Checklist as a guide. Researched AD's thru bi-weekly 2020-20. I certify that this Propeller has been inspected in accordance with an Annual Inspection and has been found to be in Airworthy Condition.			
	DATE: 06 November, 2020	SIGNED:  Dan Lynch, IA 3624030		Work Order: 6080-10-2020 Printed by EBis 3 (datcomedia.com)

# SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
			<p>  <b>Waterford Aviation, Inc.</b>                      6548 Highland Rd                      Suite 900                      Waterford, MI 48327                      Phone: 248-724-2400                 </p>	<p>                     DATE: 20 April, 2022                      A/C TSN: 1218 4                      PROP TT: 704.7                      TSPCH:                      FLIGHTTIME: 1218 4                 </p>
			<p> <b>Prop Entries</b>                      Completed Annual Inspection in scope &amp; detail of FAR 43 Appendix D and using the SR22 Annual Checklist as a guide. Researched AD's thru bi-weekly 2022-06 - none due at this time. I certify that this Propeller has been inspected in accordance with an Annual Inspection and has been found to be in Airworthy Condition.                 </p>	
			<p>                     DATE: 20 April, 2022      SIGNED:                       Dan Lynch, A&amp;P 2824030 <i>LA</i> </p>	<p>                     Work Order: 7775-03-2022                      Printed by EBis 3 (datcomedia.com)                 </p>
			<p>  <b>Waterford Aviation, Inc.</b>                      6548 Highland Rd                      Suite 900                      Waterford, MI 48327                      Phone: 248-724-2400                 </p>	<p>                     DATE: 20 April, 2022                      A/C TSN: 1218 4                      PROP TT: 704.7                      TSPCH:                      FLIGHTTIME: 1218 4                 </p>
			<p> <b>Prop Entries</b>                      Performed dynamic prop balance using Aces Systems 2021 Cobra II Prop Balance Analyzer S/N 2021T2203-007. Prop balanced to 0.03 IPS by adding 9.0 grams at 245 degrees.                 </p>	
			<p>                     DATE: 20 April, 2022      SIGNED:                       Sean Farrelly, A&amp;P 3890041                 </p>	<p>                     Work Order: 7775-03-2022                      Printed by EBis 3 (datcomedia.com)                 </p>



**HARTZELL**

# PROPELLER LOGBOOK

*Closed*

PROPELLER MODEL PHC-J3YF-1N

PROPELLER S/N FP4944B

LOGBOOK # 1

*Cirrus P/N 18975-003*

## PROPELLER MAINTENANCE RECORD

Position One

PITCH RANGE

Propeller Model PHC-J3YF-1N

High/Feather 35.1 $\frac{1}{4}$  / 35.3 $\frac{1}{4}$

Propeller S/N FP4944B

Start Lock \_\_\_\_\_

Blade Design N7605B

Low 12.4 / 12.5

Blade S/N's

Reverse \_\_\_\_\_

No. 1 \_\_\_\_\_

Aircraft Manufacturer \_\_\_\_\_

No. 2 \_\_\_\_\_

Aircraft Model \_\_\_\_\_

No. 3 \_\_\_\_\_

S/N \_\_\_\_\_

No. 4 \_\_\_\_\_

Registration \_\_\_\_\_

No. 5 \_\_\_\_\_

No. 6 \_\_\_\_\_

Spinner Assembly Part No. \_\_\_\_\_











PROP MODEL:  
PROP S/N:  
REG. NO: 108EZ  
WORK ORDER: 8261



### Lincoln Park Aviation

Repair Station No. LKPR101K  
425 Beaverbrook Road  
Lincoln Park, NJ 07035  
Phone: 973-633-0450

DATE: 1/21/2009  
A/C TSN: 160.1  
PROP TT:  
HOBBS: 201.7

#### Prop Entries

(3) ANNUAL/PROP -Inspected propeller in accordance with 100/annual inspection.

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.

DATE: 1/21/2009

SIGNED:

Inspector 2

Work Order: 8261

Frank R Galella  
Certified Repair Station No. LKPR101K

Printed by EBis 3 (datcomedia.com)



N 108EZ A/C S/N 2037 DATE 8/7/2009

PROPELLER LOG INSPECTION

Tach time: 207.3

*81N FP4544X*

Engine TSN 207.3

Prop time since new: 207.3

Aircraft total time:

Cleaned, and painted the prop Checked all A.D's through 2009-14. I certify that this propeller has been inspected I.A.W. CIRRUS M/M 100 HOUR INSPETION and was determent to be in airworthy condition end.

NAME JOHN SESKUS

A&P 81626791



PROP MODEL:  
PROP S/N:  
REG. NO: 108EZ  
WORK ORDER: 9308



### Lincoln Park Aviation

Repair Station No. LKPR101K  
425 Beaverbrook Road  
Lincoln Park, NJ 07035  
Phone: 973-633-0450

DATE: 2/10/2011  
A/C TSN: 321  
PROP TT:  
HOBBS: 321

#### Prop Entries

(3) ANNUAL/PROP -Inspected propeller in accordance with 100/annual inspection.

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Detailed details of the repair are on file at this repair station under work order listed below.

DATE: 2/10/2011

SIGNED:

Frank R Galella  
Certified Repair Station No. LKPR101K

Inspector 2

Work Order: 9308

Printed by EBis 3 (datcomedia.com)

# TEAM

### Travel Express Aviation Maintenance, Inc

DuPage Airport, West Chicago, IL 60185


Aircraft: N108EZ Date: 3/11/12 Invoice: 4027

TT AF 893.3 HOBBS: 733.7 TT PROP: 893.3

This propeller has been given an annual inspection in accordance with the aircraft manufacturer's instructions and the propeller manufacturer's instructions. Cleaned, inspected, dressed and lubricated prop.

The current status of applicable ADs was researched through 2012-04.

I certify that this PROPELLER has been inspected in accordance with an annual inspection, and was determined to be in AIRWORTHY condition.

  
Sean Blumenschein, AP 3331960 IA

End

Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.

Date Propeller TSN TSO A/C Hrs

DATE 6/20/13 TACH 890.7 FLIGHT HOBBS

I CERTIFY THAT THIS propeller Annual INS HAS BEEN INSPECTED AND DETERMINED TO BE IN WORTHY CONDITION.

Frank R. Galella LIC # STATE LI

PROP MODEL:  
PROP S/N:  
REG. NO: 108EZ  
WORK ORDER: 10889



**Lincoln Park Aviation**  
Repair Station No. LKPR101K  
425 Beaverbrook Road  
Lincoln Park, NJ 07035  
Phone: 973-633-0450

DATE: 5/14/2015  
A/C TSN: 982.2  
PROP TT: 468.5  
HC BBS: 982.2

**Prop Entries**

(3) COMPLIED WITH 50 HOUR PROP INSPECTION I/A/W 50 HOUR CHECKLIST

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.

PROP MODEL:  
PROP S/N:  
REG. NO: 108EZ  
WORK ORDER: 10553



DATE: 5/14/2015

SIGNED:

Frank R. Galella  
Certified Repair Station No. LKPR101K

Inspector #2

Work Order: 10889

CRS# LKPR101K

Printed by EBis 3 (datcomedia.com)

**Prop Entries**

(3) 100HR/ANNUAL/PROP - INSPECTED PROPELLER IN ACCORDANCE WITH 100/ANNUAL INSPECTION

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.

DATE: 6/27/2014

SIGNED:

Frank R. Galella  
Certified Repair Station No. LKPR101K

INSPECTOR #2  
FRG M

Work Order: 10553

Printed by EBis 3 (datcomedia.com)

PROP MODEL:  
PROP S/N:  
REG. NO: 108EZ  
WORK ORDER: 11116



### Lincoln Park Aviation

Repair Station No. LKPR101K  
425 Beaverbrook Road  
Lincoln Park, NJ 07035  
Phone: 973-633-0450

DATE: 1/1/2016  
A/C TSN: 1199.2  
PROP TT: 685.5  
HOBBS: 1199.2

#### Prop Entries

(3) 100HR/ANNUAL/PROP - INSPECTED PROPELLER IN ACCORDANCE WITH 100/ANNUAL INSPECTION

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.

DATE: 1/1/2016

SIGNED: *[Signature]*

CRS# LKPR101K

Work Order: 11116

Frank R Galella  
Certified Repair Station No. LKPR101K

Printed by EBis 3 (datcomedia.com)

MAKE: Cirrus  
MODEL: SR22  
S/N: 2037  
REG. NO: N108EZ  
PROP MAKE: HARTZELL  
PROP MODEL: PHC-J3YF-1N  
PROP 1 SN: FP4944B



**Waterford Aviation, Inc.**  
6548 Highland Rd  
Suite 900  
Waterford, MI 48327

W/O #: PTK-10219-08-2024  
DATE: 05-16-2025  
A/C TT: 1367.1  
Prop TT: 853.4

### Propeller Entries

- Complete Annual Inspection in scope & detail of FAR 43 App. D using Cirrus SR22 AMM ch 5-20 "Traditional Program" Checklist. Researched AD's thru bi-weekly 2025-09. I certify that this Propeller has been inspected in accordance with an Annual Inspection and has been determined to be in Airworthy condition.

DATE: 05-16-2025

SIGNED:

Dan Lynch  
IA Number: 3624030

WORK ORDER: PTK-10219-08-2024

Printed by EBIS (EBISCloud.com)







