

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HC-I3YR-1E

PROPELLER S/N HK1437B

LOGBOOK # 1

PROPELLER MAINTENANCE RECORD

Position _____

PITCH RANGE

Propeller Model _____

High/Feather _____

Propeller S/N _____

Start Lock _____

Blade Design _____

Low _____

Blade S/N's

Reverse _____

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

Aircraft Manufacturer PIPER



Aircraft Model PA-46-350T


S/N 4692060

Registration ~~N6104A~~ N179BL

OCT 16, 2008


Page 1


Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
<div style="text-align: center;">  <p>JD'S PLANE REPAIR, LLC 12106 FM 400, SLATON, TX 79364 HANGER #10 PH: 432-788-7137 WWW.JOPLANEREPAIR.COM</p> </div>			
4-4-17			N7198L
Tach time 815.6			
Performed annual inspection on prop. Serviced prop with aeroshell 6 grease. no defects noted at this time			
			 Jonathan Siemens, A&P IA 3288274
11-7-2018			removed cylinder + cleaned, installed new piston seal & re-installed cylinder + torqued. <i>Don't Huskack</i> <i>Aug. 125PR181Y</i>

<div style="text-align: center;">  <p>JD'S PLANE REPAIR, LLC 12106 FM 400, SLATON, TX 79364 HANGER #10 PH: 432-788-7137 WWW.JOPLANEREPAIR.COM</p> </div>			
3-21-18			N7198L
Tach time 970.0			TT 970.0
Performed annual inspection on prop. Serviced prop with aeroshell 6 grease. no defects noted at this time			
			 Jonathan Siemens, A&P IA 3288274

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	SUN AVIATION, INC., Vero Beach, FL (VRB) Date: 12/21/20 Hobbs: 1160.0 Prop TT: 1160.0 ACTT: 1160.0	PROPELLER LOG Model: HC-I3YR-1E Hub SN: HK1437B	N179BL Aircraft SN: 4692060 Accomplished an Annual Prop Inspection IAW FAR 43, appendix "D" using the Piper PA46R-350T 100 hour inspection report as a guide Replaced terminal to deice wire. MAINTENANCE RELEASE: This aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. All work was performed in accordance with applicable aircraft, engine and or appliance maintenance manuals and instructions. Pertinent details are on file at the repair station office, WO #S004422 A.D.'s researched through Rev. 2020.25 Signature <u>[Signature]</u> CRS # ECWR470D Sun Aviation, Inc, Municipal Airport, Vero Beach, FL 32961 (772) 562-9257

SUN AVIATION, INC., Vero Beach, FL (VRB) Date: 03/10/22 Hobbs: 1236.0 Prop TSO: 0.0 ACTT: 1236.0	PROPELLER LOG Model: HC-I3YR-1E Hub SN: HK1437B	N179BL Aircraft SN: 4692060 Accomplished an Annual Prop Inspection IAW FAR 43, appendix "D" using the Piper PA46R-350T 100 hour inspection report as a guide Accomplished 6 year prop overhaul by removing propeller and sent to Aircraft Propeller Works, installed overhauled P/N HC-I3YR-1E SN HK1437B per Piper PA46R-350T MM 61-10-00. MAINTENANCE RELEASE: This aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. All work was performed in accordance with applicable aircraft, engine and or appliance maintenance manuals and instructions. Pertinent details are on file at the repair station office, WO #S004862 A.D.'s researched through Rev. 2022.04 Signature <u>[Signature]</u> CRS # ECWR470D Sun Aviation, Inc, Municipal Airport, Vero Beach, FL 32961 (772) 562-9257

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
<p>SUN AVIATION, INC., Vero Beach, FL (VRB)</p> <p>Date: 04/03/23 PROPELLER LOG N179BL</p> <p>Hobbs: 1325.8 Model: HC-I3YR-1E Aircraft SN: 4692060</p> <p>Prop TSO: 89.8 Hub SN: HK1437B</p> <p>ACTT: 1325.8</p> <p>Accomplished an Annual Prop Inspection IAW FAR 43, appendix "D" using the Piper PA46R-350T 100 hour inspection report as a guide.</p> <p>MAINTENANCE RELEASE: This aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. All work was performed in accordance with applicable aircraft, engine and or appliance maintenance manuals and instructions. Pertinent details are on file at the repair station office, WO #S005307. A.D.'s researched through Rev. 2023.07.</p> <p>Signature  CRS # ECWR470D</p> <p>Sun Aviation, Inc, Municipal Airport, Vero Beach, FL 32961 (772) 562-9257</p>			

<p>SUN AVIATION, INC., Vero Beach, FL (VRB)</p> <p>Date: 04/26/24 PROPELLER LOG N179BL</p> <p>Hobbs: 1529.6 Model: HC-I3YR-1E Aircraft SN: 4692060</p> <p>Prop TSO: 293.6 Hub SN: HK1437B</p> <p>ACTT: 1529.6</p> <p>Accomplished an Annual Prop Inspection IAW FAR 43, appendix "D" using the Piper PA46R-350T 100 hour inspection report as a guide.</p> <p>MAINTENANCE RELEASE: This aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. All work was performed in accordance with applicable aircraft, engine and or appliance maintenance manuals and instructions. Pertinent details are on file at the repair station office, WO #S005698. A.D.'s researched through Rev. 2024.07</p> <p>Signature  CRS # ECWR470D</p> <p>Sun Aviation, Inc, Municipal Airport, Vero Beach, FL 32961 (772) 562-9257</p>			

