

HARTZELL

PROPELLER LOGBOOK

CIRRUS-N219CP

OWNER = JOHN KIRIAZE
(858) 229-3406

PROPELLER MODEL PHC-334F-1RF

PROPELLER S/N FP5217B

LOGBOOK # 1

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

PROPELLER MAINTENANCE RECORD

Position _____	PITCH RANGE
Propeller Model <u>PHC-334F-1RF</u>	High/Feather _____
Propeller S/N <u>FP 5217B</u>	Start Lock _____
Blade Design _____	Low _____
Blade S/N's	Reverse _____
No. 1 _____	
No. 2 _____	Aircraft Manufacturer <u>Cimms Design</u>
No. 3 _____	Aircraft Model <u>SR-20</u>
No. 4 _____	S/N <u>20-1750</u>
No. 5 _____	Registration <u>N219CP</u>
No. 6 _____	
Spinner Assembly Part No. _____	

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
	Reg: N219CP			PROPELLER LOG
	Make: Hartzell			Date: 02-10-2010
	Model: PHC-J3YF-1			Tach: 339.0
	Ser. No. 991191			TS New: 339.0
				Hobbs: 416.2
	Southern Cal Aircraft Inc. 1880 Joe Crosson Drive El Cajon, Ca. 92020 619-448-5010			
	I certify that this Propeller has been inspected in accordance with 100 Hr./Annual Inspection procedure and <u>determined airworthy this date.</u> Inspected propeller for leaks and security, Blended nicks in blades and painted blade faces flat black. <u>No new applicable Ads this date.</u>			
	Except as stated above, no other work, inspection, corrective action or determination of airworthiness was made at this time. Edward Q Hazlewood A&P 1655569 Insp. Auth.			
	Date: 02-10-2010			

N219CP TACH-422.5 TSN-422.5 MODEL- PHC-J3YF1RF S/N-FP5217B		AeromechaniX 2898 MONTECITO ROAD - RNM/MYF - CA
I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION, AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.		
FRANCISCO JIMENEZ A&P3230538IA		DATE: 03/09/2011
N219CP TACH-460.9 TSMO-460.9 MODEL- PHC-J3YF-1RF S/N-FP5217B		AeromechaniX 2898 MONTECITO ROAD - RNM/MYF - CA
I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION, AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.		
FRANCISCO JIMENEZ A&P3230538IA		DATE: 06/01/2012

N219CP TACH-474.9 TSN-474.9
MODEL- PHC-J3YF-1RF S/N-FP5217B

Aeromechanix

2898 MONTECITO ROAD - RIVINGTON, CA

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION, AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

FRANCISCO JIMENEZ A&P3230538IA

DATE: 07/22/2013

Business Directives,
air, and Inspections.

5/27/14	TACH 478.1	TACH 478.1	PERFORMED ANNUAL/100HR INSPECTION IAW
400BS	5655	5655	HARTZELL INSPECTION GUIDE. DRESSED PROP. CK AD'S
			THROUGH BI-WEEKLY & FAA ALL UP TO DATE.
			I CERTIFY THAT THIS PROPELLER HAS BEEN
			INSPECTED IAW AN ANNUAL/100HR INSPECTION
			AND HAS BEEN DETERMINED TO BE IN AIRWORTHY
			CONDITION. Dated 2753847 A&P IA.

7 JUL 15	TACH	TSN	PERFORMED ANNUAL/100HR INSPECTION IAW HARTZELL
	484.8	484.8	INSPECTION GUIDE. DRESSED PROP. CK'D AD'S THROUGH
400BS	572.1	572.1	BI-WEEKLY & FAA ALL UP TO DATE. I CERTIFY THAT
			THIS PROPELLER HAS BEEN INSPECTED IAW AN
			ANNUAL/100HR INSPECTION AND HAS BEEN DETERMINED
			TO BE IN AIRWORTHY CONDITION.
			Dated A&P 2753847 IA

Date: 8/19/16	Prop Model PHC-J3YF-1RF	TSN: 501 2	TSO: N/A	ACTT: 501 2	TACH TIME N/A
AC S/N 1750	PROP S/N FP5217B	CSN N/A	CSO N/A	ACTL N/A	Reg # N219CP


PROPELLER:

- 1) C/W 100HR INSPECTION USING CIRRUS SCHEDULED TRADITIONAL INSPECTION PROGRAM AS A GUIDE IN SR20 AMM CH 05-20. DRESSED BLADE LEADING EDGES IN ACCORDANCE WITH HARTZELL C M M. LUBRICATED WITH AEROSHELL 6 GREASE.

I CERTIFY THIS PROPELLER WAS INSPECTED IN ACCORDANCE WITH A 100 HR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION AD'S REVIEWED THROUGH BI-WEEKLY 2016-16

END

EDWARD TILLIT JR.
A&P 3329150

Date	Pr TSN		
		Advanced Aircraft Service 8622 Gibbs Dr. San Diego, CA. 92123 858-560-7599 Fax 858-560-7507	S.
		CESSNA \ BEECHCRAFT SERVICE CENTER Date 04-16-19 N# :N219CP S/N:FP5217B Hobbs:632.2 FLT:547.8	
		Reinstalled propeller after overhaul from Ameritech Industries dba American Propeller Service.	
		 -----END----- AP 3841036	
		PROP MODEL PNO-J3YF-1N PROP S/N FP5217B REG NO 219CP WORK ORDER 3637  Chuck's Aircraft, LLC. 6200 Aviation Dr AC101 Austin Executive Airport Pflugerville, TX 78660 Phone 512-610-3111 DATE 2/1/2020 A/C TSN 572 2 PROP TT 572 2 TSPOH 24 4 TACH 572 2	
		Prop Entries Inspected hub, blades, spinner and backplate	
		Technicians Who Worked On The Items Listed Above Manny Hudson	
		This propeller has been inspected in accordance with a 100-hour inspection and is approved for return to service	
		DATE 2/1/2020 SIGNED 	Work Order: 3637
		Zach Young A&P 4063779	Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-1N
PROP S/N: FP5217B
REG. NO. 219CP
WORK ORDER: 4143

Chuck's Aircraft, LLC.

6200 Aviation Dr AC101
Austin Executive Airport
Pflugerville, TX 78660
Phone: 512-610-3111

DATE: 3/26/2021
A/C TSN: 615 6
PROP TT: 615 6
TSPOH: 67 8
TACH: 615 6

Prop Entries

Inspected hub, blades, spinner and backplate. Lubed hub.

Technicians Who Worked On The Items Listed Above:
Danny Huchton

This propeller has been inspected in accordance with a 100-hour inspection and is approved for return to service.

DATE: 3/26/2021

SIGNED:

Work Order: 4143

Danny Huchton, A&P 3098167

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP5217B
REG. NO. 219CP
WORK ORDER: 4705

Chuck's Aircraft, LLC.

6200 Aviation Dr AC101
Austin Executive Airport
Pflugerville, TX 78660
Phone: 512-610-3111

DATE: 4/22/2022
A/C TSN: 626 7
PROP TT: 626 7
TSPOH: 78 9
TACH: 626 7

Prop Entries

Inspected hub, blades, spinner and backplate. Lubed hub.

This propeller has been inspected in accordance with a 100-hour inspection and is approved for return to service.

DATE: 4/22/2022

SIGNED:

Work Order: 4705

Robert McBride, Jr., A&P 2710158

Printed by EBis 3 (datcomedia.com)

