HARTZELL N811JM

## PROPELLER LOGBOOK

PROPELLER MODEL PHC-J3YF-1N

PROPELLER S/N FP6896B

LOGBOOK #\_\_\_\_

# PROPELLER MAINTENANCE RECORD

PositionONE	PITCH RANGE
Propeller Model PHC -13 YF-ZN	High/Feather
Propeller S/N FP6896B	Start Lock
Blade Design	Low
Blade S/N's No. 1 <i>A 21 23</i>	Reverse
No. 2 <u>A 2169</u> No. 3 <u>A 2145</u>	Aircraft Manufacturer <u>CINAYS DOSIGN</u> Aircraft Model <u>SR 22</u>
No. 4	S/N 3/27
No. 5	Registration N8/11/X
No. 6	
Spinner Assembly Part No	

Date	Pro TSN	peller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.		
I C Bed	n Inspec h <del>/00 //</del>	it This cted in Insp	26.2 Pension A Accorda	nce // A A		

			<b>(3)</b>
PLATIN	М	1635 NW 51 PLACE HANGAR 31-A FORT LAUDERDALE, FL 33309 (954) 771-1288	
259.1	SR22T Serial: 3127 Regis	stration: N811JM Tach: 199.9 Hobbs:	
W/O: 09-164 Date 1-MAY 2009 Humphrey Lemmers	H Guy	AP2010282	

Date	Proj TSN	peller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.		
	PL	47//	IJИ	1635 NW 51 PLACE HANGAR 31-A FORT LAUDERDALE, FL 33309 (954) 771-1288		
Mak	e: CIRRI	JS Model	: SR22T	Serial: 3127 Registration: N811JM Tach: 246.1 Hobbs: 320.7		
				HOUR INSPECTION. COMPLIED WITH HARTZELL SERVICE IAL FP6896B).		
I CE	RTIFY TH	IAT THIS	PROPELL S DETER	ER HAS BEEN INSPECTED IN ACCORDANCE WITH 100 HOUR WINED TO BE IN AIRWORTHY CONDITION.		
W/O: Date	: 09-212 : 20-JUL	Y 2009	$\mathcal{J}_{k}$	AP2010282		
	- 1		l'			
		- No.			makkan e memilikahan menendan badan di penda di penda da da	

## **PLATINM**Service

1635 NW 51 Place Hangar 31-A Fort Lauderdale, FL 33309 (954) 771-1288

### **Propeller Logbook Entry**

Name: Stratus Air LLC	Tail = N811JM	Tach: 345.2
W O., 15	Serial #: FP6896B	Total time: 345.2
Date: 12 3 2009	Model: SR22	ISPOH: N.A

Completed 100Hr inspection IAW Cirrus SR22 MM & MM checklist, Lubricated w Aeroshell -6, dressed leading edges. Leartify this propeller has been inspected IAW a 100Hr inspection and is found to be airworthy at this

Signature:

Glenn Juber A&P IA 40600028

PROP MODEL. PHC-J3YF-1N PROP S/N FP6896B REG NO N811JM WORK ORDER 0156 PLATINIA Service Platinum Aviation Service

1635 NW 51st Place - Hangar 31 Fort Lauderdale, FL 33309 Phone (954) 771-1288

DATE: 07 June: 2010 A/C TSN 453 4 PROP TT: 453 4 FLIGHTTIME: 453 4

#### **Prop Entries**

Completed annual propeller inspection IAW Cirrus SR22 MM & MM checklist. AD's current through issue 2010-14. Lubricated with Aeroshell #6.

I certify that this airframe has been inspected IAW an Annual

at this time

DATE: 07 June, 2010


SIGNED.

Work Order: 0156

Glenn Juber A&P 3438378

Printed by EBis 3 (datcomedia.com)

Propeller TSN TSO	A/C Description of all operations pertaining to Airworthiness Directives, Hrs Service Documents, Overhaul, Major or Minor Repair, and Inspections					
PROP MODEL PHC-J3YF-1N PROP S/N FP68 REG NO N811 IN WORK CRDER O	96B	PLATINUM Platinum Aviation 1635 NW 51st Place - His Fort Lauderdale, FL 3330 Phone: (954) 771-1288	angar 31 A/C TSN 584 5 PROP TT 564 5			
Prop Entries Completed 100H Aeroshell #6.	lr propeller	inspection IAW Cirrus SR22 MM & MM checklist. AD's o	current through issue 2010-15. Lubricated with			
		1771				
DATE: 13 August	, 2010	SIGNED: That Gitted	Work Order: 0216			
i i i i i i i i i i i i i i i i i i i	1	Alberto Wolfang Ameon Verachecnes A&P 3186786	Printed by EBis 3 (datcomedia.com)			
PROP MODEL: PHC-J3YF-1N/N70 PROP S/N: FP889 REG. NO: N811JT WORK ORDER: 2	6 <b>B</b>	AAM American	n Aircraft Maintenance, Inc. DATE: 3/7/2014 A/C TSN: 1425.7 PROP TT: 1425.7 PROP TT: 1425.7 PROP TT: 1425.7 FLIGHTTIME: 1425.7			
PHC-J3YF-1N/N70 PROP S/N: FP689 REG. NO: N811JT WORK ORDER: 2	6B 6854	Repair Station 19711-B Cam Santa Ana, C Phone: (949)	n Aircraft Maintenance, Inc. DATE: 3/7/2014 A/C TSN: 1425.7 n No. Z5SR421Y PROP TT: 1425.7 npus Drive FLIGHTTIME: 1425.7 A 92707 B 852-8420			
PHC-J3YF-1N/N76 PROP S/N: FP689 REG. NO: N811JT WORK ORDER: 2  Prop Entries Complied with an A section 05-20 as a	68 6854 Annual/100 H guide. All Air	AAM Americar Repair Station 19711-B Cam Santa Ana, C	n Aircraft Maintenance, Inc.  DATE: 3/7/2014 A/C TSN: 1425.7 PROP TT: 1425.7 PROP TT: 1425.7 PLIGHTTIME: 1425.7 PS2707 R52-8420  Sing Cirrus Airplane Maintenance Manual Model SR22 bi-weekly issue 2014-04 Repainted propeller blades face.			
PHC-J3YF-1N/N76 PROP S/N: FP689 REG. NO: N811JT WORK ORDER: 2  Prop Entries Complied with an A section 05-20 as a	6B 6854 Annual/100 H guide. All Air DR COMPON ULES OF 14	Repair Station 19711-B Car Santa Ana, C Phone: (949)  R inspection in accordance with FAR Part 43, Appendix D, us worthiness Directives are in compliance at this time through	n Aircraft Maintenance, Inc. DATE: 3/7/2014 A/C TSN: 1425.7 n No. Z5SR421Y PROP TT: 1425.7 npus Drive FLIGHTTIME: 1425.7 852-8420  sing Cirrus Airplane Maintenance Manual Model SR22 bi-weekly issue 2014-04 Repainted propeller blades face.			



Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspection		
	REG. NO: WORK OR	-1N : FP6896B N811JT DER: 114937	Clear Star Aviation  Repair Station No. 5CSR009B 4765 Frank Luke Dr Addison, TX 75001 Phone: 972-267-2376  DATE: 2/11/2015 A/C TSN: 1506 4 PROP TT: 1506 4 PROP TT: 1506.4		
+	Re-installe	propeller 100 d propeller p/l	OHR inspection in accordance with current Cirrus Design Aircraft Maintenance Manual 5-20 and 5-30 In PHC-J3YF-1N s/n 6896B and prop governor p/n C290D3R/T23 s/n 072030 after prop overhaul by ices and governor overhaul by Quality Aircraft Accessories.		
	accordance w	vith a 100HR ins orms. The aircr of the Federal A 009B.	weekly issue of this date, all AD's are in compliance at this time. I certify that this propeller has been inspected in spection and was determined to be in airworthy condition. I have reviewed the file on this aircraft and the accompanying aft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair SIGNED:		
			May, Kevin Certified Repair Station No. 5CSR009B  Printed by EBis 3 (datcomedia.com)	d J	
+-					

.

E Malebrasis - F Appropriate -	Propeller	ero Inc. 285 S/N <i>FP689</i> less Directiv	<i>6B</i> N	Blvd. Abilene TX 79601 Meter: <u>1628.8</u> Ih <u>2015-04</u>	WO# <u>13919</u> Total Time: <u>1628.</u>	Registration# <u>N811JT</u> B TSMOH: <u>122.4</u>	Date: <u>3/2/16</u>
					ppendix D 100 hour ins	spection and found to be in an	A
H	Painted bl	ades. Lube	d hub with	Aeroshell #6 grease.	ppondix D Too nodi ins	specifor and found to be in an	Airworthy condition.
199				•			
Î					-		
H					-	Approved for return to service	
						Nathan Loflin AP3669831	
1		1		1			
<u></u>							
			1				
<u> </u>		<del></del>	-	<u> </u>			
		1					
├		<del> </del>					
		l	l 1				