



PROPELLER LOGBOOK

PROPELLER MODEL PHC-53YF-1RF/F7693DFB

PROPELLER S/N FP 3260 B

LOGBOOK # _____

PROPELLER MAINTENANCE RECORD

Position _____

PITCH RANGE

Propeller Model PHC-33YF-1RF/F7693DFB

High/Feather _____

Propeller S/N FP3260B

Start Lock _____

Blade Design _____

Low _____

Blade S/N's

Reverse _____

No. 1 K14172

No. 2 K14174

Aircraft Manufacturer Cirrus Design

No. 3 K14169

Aircraft Model SR22

No. 4 _____

S/N _____

No. 5 _____

Registration _____

No. 6 _____

Spinner Assembly Part No. _____

te	Propeller		A/C Hrs
	TSN	TSO	
504	.1	N/A	.1

Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.

I have Dynamically Balanced Propeller IAW Hartzell
Propeller Owner's Manual 115N Rev. 11 dated Dec/04
Section: 61-00-15 on 12-15-04 (DATE).
The location of the Weight(s) are 70 degree
And are 6.9 gram(s).

Matt Miesman



(Sign/Stamp)

Cirrus Design Corporation,

PC 338CE

PROP MODEL:
PROP S/N:
REG NO: 281CD
WORK ORDER: 5967

Lincoln Park Aviation

Repair Station No. LKPR101K
425 Beaverbrook Road
Lincoln Park, NJ 07035
Phone: 973-633-0450

DATE: 1/12/2006
A/C TSN: 50
PROP TT: 50
HOBBS: 242.4

Prop Entries

(3) ANNUAL/PROP -inspected propeller in accordance with 100/annual inspection.

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.

DATE: 1/12/2006

SIGNED:

Frank R Galella, IA: 2784795

[Signature]
Inspector 2

Work Order: 5967

Printed by EBis 3 (datamedia.com)


AOA Maintenance LLC
319 N Crystal Lake Drive
Orlando Florida 32803

Monday, 23 October, 2006

N 281CD S/N 1253

TYPE 5R22 TACH 1068

CW 140 2005 14-11 NO HISTORY OF SOUTHERN CALIFORNIA
PROPPELLER SERVICE REPAIR OR OVERHAUL.


RICK A. MARK
APR07786666

PROP MODEL:
PROP S/N:
REG. NO: 281CD
WORK ORDER: 7042



Lincoln Park Aviation

Repair Station No. LKPR101K
425 Beaverbrook Road
Lincoln Park, NJ 07035
Phone: 973-633-0450

DATE: 4/30/2007
A/C TSN: 409.1
PROP TT:
HOBBS: 409.1

Prop Entries

(3) ANNUAL/PROP - Inspected propeller in accordance with 100/annual inspection.

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Details of the repair are on file at this repair station under work order listed below.

DATE: 4/30/2007

SIGNED:

Frank R Galella
Certified Repair Station No. LKPR101K


Inspector 2

Work Order: 7042

Printed by EBis 3 (datamedia.com)

PROP MODEL:
PROP S/N:
REG NO: 361JB
WORK ORDER: 7649



Lincoln Park Aviation

Repair Station No. LKPR101K
425 Beaverbrook Road
Lincoln Park, NJ 07035
Phone: 973-633-0450

DATE: 2/4/2008
A/C TSN: 458.6
PROP TT:
HOBBS: 458.6

Prop Entries

(3) ANNUAL/PROP -inspected propeller in accordance with 100/annual inspection.

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.

DATE: 2/4/2008

SIGNED:

Frank R. Galella
Certified Repair Station No. LKPR101K

1 of 1

Inspector 2

Work Order: 7649

Printed by EBis 3 (datcomedia.com)

RONSON AVIATION, INC

CRS EHHR538D
(609) 771-9500

TRENTON-MERCER AIRPORT
FAX (609) 771-0651

TRENTON, NJ 08628

REG #	N361JB	DATE:	2/2/2009
MAKE:	HARTZELL	W/O #:	24646
MODEL:	PHC-J3YF-1RF	HM	499.3
S/N:	FP3260B	TT:	499.3

PROPELLER LOG

1. PERFORMED ANNUAL INSPECTION AS PER CIRRUS SR-22 M/M CHAPTER 5.
2. LUBRICATED HUB.

MAINTENANCE RELEASE

I certify that this aircraft has been inspected in accordance with an ANNUAL and was inspected and approved for return to service.

Pertinent details of the inspection are on file at this agency under the work number shown above.
I certify that the article described above has been inspected and approved for return to service.

Signed


RONSON AVIATION, INC

CRS EHHR538D
(609) 771-9500


for RONSON AVIATION, INC. □ CRS EHHR538D

TRENTON-MERCER AIRPORT
FAX (609) 771-0651

TRENTON, NJ 08628

NO	AC His	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.																
		RONSON AVIATION, INC. CRS EHHR538D TRENTON MERCER AIRPORT TRENTON, NJ 08628 (609) 771-9500 FAX (609) 771-0551																
		<table border="1"> <tr> <td>REG #</td> <td>N361JB</td> <td>DATE</td> <td>5/21/2019</td> </tr> <tr> <td>MAKE</td> <td>HARTZELL</td> <td>VNO #</td> <td>25158</td> </tr> <tr> <td>MODEL</td> <td>PHC-J3YF-1PF</td> <td>HIA</td> <td>555.1</td> </tr> <tr> <td>S/N</td> <td>FP3260B</td> <td>TT</td> <td>555.1</td> </tr> </table>	REG #	N361JB	DATE	5/21/2019	MAKE	HARTZELL	VNO #	25158	MODEL	PHC-J3YF-1PF	HIA	555.1	S/N	FP3260B	TT	555.1
REG #	N361JB	DATE	5/21/2019															
MAKE	HARTZELL	VNO #	25158															
MODEL	PHC-J3YF-1PF	HIA	555.1															
S/N	FP3260B	TT	555.1															
		PROPELLER LOG 1. PERFORMED ANNUAL INSPECTION AS PER CIRRUS SR-22 MM CHAPTER 5 2. DRESSED BLADES 3. LUBRICATED HUB																
		MAINTENANCE RELEASE I certify that this aircraft has been inspected in accordance with an ANNUAL and was inspected and approved for return to service. Pertinent details of the inspection are on file at this agency under the work number shown above. I certify that the article described above has been inspected and approved for return to service.																
		Signed  for RONSON AVIATION, INC. CRS EHHR538D RONSON AVIATION, INC. CRS EHHR538D TRENTON MERCER AIRPORT TRENTON, NJ 08628 (609) 771-9500 FAX (609) 771-0551																

• Jet East Corporate Aviation, LLC • CRSJ21R713Y • TRENTON-MERCER AIRPORT • TRENTON, NJ 08628 • Phone (215)-937-9020 • Fax (609)-600-1718



PROP LOG BOOK

REG #	N361JB	DATE:	6/20/11
MAKE:	HARTZELL	W/O #:	11TR62160
MODEL	PHC-J3YF-1RF	Hobbs:	608.8
S/N:	FP3260B	TT:	608.8

1. COMPLIED WITH PROPELLER INSPECTION IAW CIRRUS SR20 MM CH 5.
2. DRESSED PROP AS REQUIRED.

I certify that this PROPELLER has been inspected in accordance with an ANNUAL inspection, determined to be in airworthy condition and return to service. Pertinent details of the inspection are on file at this agency under the work number shown above.

Signed [Signature] for Jet East Corporate Aviation, LLC CRS J21R713Y

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP3260B
REG. NO: N361JB
WORK ORDER:
2367-07-2012

Advanced Aircraft Services

530 Airport Rd.
Littitz, PA 17543
Phone: 717-735-5179

DATE: 8/2/2012
A/C TSN: 672
PROP TT: 672
HOBBS: 672

Prop Entries

Cirrus Propeller Annual Inspection completed using the Cirrus AMM check list ch. 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2012-15. Ops check good. AD 2007-26-09 Blade Inspection, N/A by S/N.

I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.

DATE: 8/2/2012

SIGNED

Work Order: 2367-07-2012

Richard A. Bamhart II, IA: 3124994AP

Printed by EBis 3 (datcomedia.com)

MAINTENANCE RELEASE

Make Hartzell

Model PHC-J39F-1RF/F7693DFB

Serial No. FP 3260B

The component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and was found airworthy for return to service for work performed. Pertinent details of the repair are on file at this agency under Work Order No. ER-11050 and complies with Airworthiness Directives and Service Bulletins listed here.

Removed and replaced alcohol shoes Repainted propeller,
checked angles, track, and static balanced.

Manual No. 113BR41, 202A &
latest revisions

Total Time Brought forward

Total Time Since O/H

Brought forward

Date 3-10-15

Signed [Signature]

EAST COAST PROPELLER SERVICE INC.

propeller
N TSO

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP3260B
REG. NO: N361JB
WORK ORDER:
3030-08-2013



Advanced Lancaster LP

530 Airport Rd.
Lititz, PA 17543
Phone: 717-735-5179

DATE: 9/10/2013
A/C TSN: 723.7
PROP TT: 723.7
HOBBS: 723.7

Prop Entries

Cirrus Propeller Annual Inspection completed using the Cirrus AMM check list ch. 5-20. Cleaned and dressed blades.
Serviced hub. All ADs current through 2013-17. Ops check good.

I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.

DATE: 9/10/2013

SIGNED:

Richard A. Barnhart II, IA 3124994AP

Work Order: 3030-08-2013

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP3260B
REG. NO: N361JB
WORK ORDER:
3594-09-2014



Advanced Lancaster LP

530 Airport Rd.
Lititz, PA 17543
Phone: 717-735-5179

DATE: 10/21/2014
A/C TSN: 797.1
PROP TT: 797.1
HOBBS: 797.1

Prop Entries

Cirrus Propeller Annual Inspection completed using the Cirrus AMM check list ch. 5-20. Cleaned and dressed blades.
Serviced hub. All ADs current through 2014-21.

I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.

DATE: 10/21/2014

SIGNED:

Milan Jovanovic, IA: 3164117AP

Work Order: 3594-09-2014

Printed by EBis 3 (datcomedia.com)

atives,
pections.

MODEL: PHC-J3YF-18F **N361JB**
SN: FP32606
WO#150202 AC: N361J DATE: 2/19/15
REMOVED PROP FROM ENGINE
AP: 3412280 *Ryan McEwen*

MODEL: PHC-J3YF-18F SN: FP32606 **N361JB**
WO#150202 AC: N361J DATE: 3/12/15
REINSTALLED IAW HARTZELL PROP
MANUAL 115N. CHECK BLADE TRACKING
SATISFACTORY. *Ryan McEwen*
AP: 3412280 *Ryan McEwen*

PROP MODEL:
PHC-J3YF-18F
PROP S/N: FP32606
REG. NO: N361JB
WORK ORDER:
4211-11-2015

ADVANCED Advanced Lancaster LP
530 Airport Rd.
Lititz, PA 17543
Phone: 717-735-5179

DATE: 11/6/2015
A/C TSN: 840.2
PROP TT: 840.2
HOBBS: 840.2

Prop Entries

Cirrus Propeller Annual Inspection completed using the Cirrus AMM check list ch 5-20. Cleaned and dressed blades.
Serviced hub. All ADs current through 2015-22.

I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.

DATE: 11/6/2015

SIGNED: *Richard A. Barnhart II*

Richard A. Barnhart II, IA: 3124994AP

Work Order: 4211-11-2015

Printed by EBis 3 (datcomedia.com)