## AIRCRAFT TECHNICAL RECORD

Section 4. PROPELLER LOG



## **PROPELLER LOG**

1. Make:

MT-Propeller Entwicklung GmbH

2. Model:

MTV-6-R-C-F/CF194-80

3. Specification Number:

P19NE

4. Date of Manufacture:

05 JUNE 2019

5. Hub Serial Number:

190633

6. Blades:

a. Design Number:

b. Blade Serial Numbers:

AKC-75227 AKC-75228 AKC-75229

ii. iii.

iii. iv.

i.

c. Pitch Setting

i. Basic:

ii. High:

iii. Low:

iv. Reverse:

٧.

@coTRANSPORT® Publications www.aerotransport.com



Section AA: Propeller Service and Maintenance Record    Section AA: Propeller Service   Archive   Archive	
DIAMOND AIRCRAFT INDUSTRIES INC. AC Serial Number: RH Engine Serial Number: RH Engine Serial Number: RH Prop Serial Number:	
RH Propeller Insurance  The following STC's are incorporated:  No STC's incorporated  Bi-weekly AWD check carried out to current revision 2020-02 all applicable AD's complied with, see  Bi-weekly AWD check carried out IAW the applicable Standard of Airworthiness.  The work described above was carried out IAW the applicable Standard of Airworthiness.  JAN 2 7 2020  date    JAN 2 7 2020	-
No STC's incorporated     No STC's incorporated      Bi-weekly AWD check carried out to current revision 2020-02 all applicable AD's complied with, see      Bi-weekly AWD check carried out to current revision 2020-02 all applicable AD's complied with, see      Interventional to the applicable Standard of Airworthiness.      Interventional to the applicable Standard of Airworthiness.      JAN 2 7 2020      date    JAN 2 7 2020	- 1
Bi-weekly AWD check carried out to current revision 2020-02 all applicable AC 5 complete attached.  The work described above was carried out IAW the applicable Standard of Airworthiness.  JAN 2 7 2020  date  Inspector  (Intentionally left blank below this point)  Premier Aircraft Service, Inc.  3804 Falcon Way W Hangar 18S Fort Worth, Tx 76106 Phone: 562.881.5345  Ight Prop Entries  Performed 100 Hour Inspection using DA62 AMM as a guide  Printed by EBis 3 (date of the control of t	_
The work described above was carried out IAW the applicable Standard of American  JAN 2 7 2020  date    Company   Co	_
Action (Intentionally left blank below this point)    Company   Co	_
ROP MODEL (R):  TITL'S R-C-F/CF194-80 ROP SM (R): 190633 EG. NO: N868AR ORK ORDER: 0259  Aircraft Service  Aircraft Service  Fort Worlt, TX 76106 Phone: 562.881.5345  Performed 100 Hour Inspection using DA62 AMM as a guide  Performed 100 Hour Inspection using DA62 AMM as a guide  Performed 100 Hour Inspection using DA62 AMM as a guide  Performed 100 Hour Inspection using DA62 AMM as a guide  Performed 100 Hour Inspection using DA62 AMM as a guide  Performed 100 Hour Inspection using DA62 AMM as a guide  Performed 100 Hour Inspection using DA62 AMM as a guide  Performed 100 Hour Inspection using DA62 AMM as a guide  Performed 100 Hour Inspection using DA62 AMM as a guide  Performed 100 Hour Inspection using DA62 AMM as a guide  Performed 100 Hour Inspection using DA62 AMM as a guide  Performed 100 Hour Inspection using DA62 AMM as a guide  Performed 100 Hour Inspection using DA62 AMM as a guide  Performed 100 Hour Inspection using DA62 AMM as a guide  Performed 100 Hour Inspection using DA62 AMM as a guide  Performed 100 Hour Inspection using DA62 AMM as a guide  Performed 100 Hour Inspection using DA62 AMM as a guide	-
Promiter Aircraft Service 3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345  Ight Prop Entries  Terrify this propeller has been inspected IAW an Annual Inspection and was determined to be in airworthy condition.  TE: 1/20/2021  David Seastead, License: AP3492477 IA  Printed by EBis 3 (date in the control of the con	:. <del></del>
Promiter Aircraft Service 3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345  Ight Prop Entries  Terrify this propeller has been inspected IAW an Annual Inspection and was determined to be in airworthy condition.  TE: 1/20/2021  David Seastead, License: AP3492477 IA  Printed by EBis 3 (date in the control of the con	
ROP MODEL (R): TV6-R-C-F/CF194-80 ROP S/N (R): 190633 G. NO: N66AR DRK ORDER: 0259 Aircraft Service Aircraft Service Fort Worth, TX 76106 Phone: 562.881.5345  ght Prop Entries erformed 100 Hour Inspection using DA62 AMM as a guide  rtify this propeller has been inspected IAW an Annual Inspection and was determined to be in airworthy condition.  TE: 1/20/2021 SIGNED: David Seastead, License: AP3492477 IA Printed by EBis 3 (date)	
David Seasteed, License: AP3492477 IA Printed by EBis 3 (da	
Frinted by Ebis 3 (us	Vork Order.
	datcomedia.
DUS TOTAL	

Secuon :		
DATE	A/D, S/B, S/I, MODS	DETAILS OF WORK OR INSPECTION PERFORMED
	Diamond AIRCRAFT  DIAMOND AIRCRAFT INDUSTRIES INC. O.T. APPROVED MANUFACTURER #161	Registration: N66AR  -93 AC Serial Number: 62.C021 LH Engine Serial Number: E4P-C-00261 RH Engine Serial Number: E4P-C-00262 LH Prop Serial Number: 190627 RH Prop Serial Number: 190633 Airframe Total Time: 6.9 HRS
1	Propeller installed new on DA 62, S/I Prop Dynamic Balance performed:  o 0.0g located @ 0.0°  o Balanced to 0.184 IPS  Bi-weekly AWD check carried out to crattached.  The work described above was carried or DA  Q 8	Production Test Flight Journey Log (DAI - Form Q-224): 6.9 HRS N: 62.C021  urrent revision 2020-02 all applicable AD's complied with, see at IAW the applicable Standard of Airworthiness.  JAN 2 7 2020  date  v left blank below this point)
1		
1		
2-1		
1		
1 2		