


SOUTH COAST PROPELLER SERVICE, INC.



FAA Approved Repair Station
S6PR302X

STARTED
6/16/23

PROPELLER LOGBOOK

PROPELLER MODEL PHC-J3Y1F-1N


PROPELLER S/N NJ 405 B

LOG BOOK # 2

SOUTH COAST PROPELLER SERVICE, INC.
5750 DUROSE DRIVE, BESSEMER, AL 35022
205-426-7022
REPAIR STATION #S6PR302X

MAJOR OVERHAUL. BLADES REFINISHED. PARTS DYE PENETRANT
INSPECTED, MAGNAFLUXED, REPLATED & REPLACED WHERE REQUIRED. DEICER
BOOTS INSTALLED. PROPELLER TRACKED, BALANCED, SET ANGLES, GREASED AND PAINTED.
COMPLIES WITH AD'S & SB'S LISTED ON 8130-3 FORM.
BLADE S/N#'S INSTALLED ARE: A4378, A4380, A4379
NOTE: BLADES OVERHAULED BY HARTZELL PROPELLER UNDER WO#22797


WORK ORDER # SR-15509
MODEL #PHC-J3Y1F-1N
BLADE MODEL #N7605B
HUB SN #NJ405B
DATE: 14 JUNE 2023

A handwritten signature in black ink, appearing to read 'J-M Gaither', is written over the printed name and title.

JAMES M GAITHER,
GENERAL MANAGER

MAJOR OVERHAUL. BLADES REFINISHED. PARTS DYE PENETRANT
INSPECTED, MAGNAFLUXED, REPLATED & REPLACED WHERE REQUIRED DEICER
BOOTS INSTALLED PROPELLER TRACKED, BALANCED, SET ANGLES, GREASED AND PAINTED.
COMPLIES WITH AD'S & SB'S LISTED ON 8130-3 FORM.
BLADE S/N#S INSTALLED ARE: A4378, A4380, A4379
NOTE BLADES OVERHAULED BY HARTZELL PROPELLER UNDER WO#22797

WORK ORDER # SR-15509
MODEL #PHC-J3Y1F-1N
BLADE MODEL #N7605B
HUB SN #NJ405B
DATE: 14 JUNE 2023



JAMES M GAITHER,
GENERAL MANAGER

Tail # N322PB Champion Flyers of Alabama – Shelby Co. Airport (KEET)
DATE: 06/16/2023 TACH/FLT HRS: 1247.1 HOBBS: 1596.4 PropTT: 1596.4 SMOH: 0.0

Performed ANNUAL inspection IAW AC43.13-1B, appendix "D" inspection check list as a guide. Remove spinner, inspect bulkheads & safety wires. Reinstalled spinner. See AD list dated 06/2023 for compliance.

- Removed propeller, sent to South Coast Propeller Service, Inc., major overhaul performed (details under WO# SR-15509), and blades overhauled, balance, and inspected by Hartzell Service Center (WO# 22797). Reinstalled on airframe and torque to spec.

I certify this PROPELLER has been inspected IAW an ANNUAL inspection and is airworthy at this time.

Michael Carpenter A&P/IA 3260064

m HA 3260064 Ap/Id

Description of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspections.



d/b/a MILLION AIR - RICHMOND
Cirrus Design Service Center
CRS VXWR051W

Aircraft		Engine		Propeller			
Manufacturer:	Cirrus	Date:	6/19/2024	Manufacturer:	Continental	Manufacturer:	Hartzell
Model:	SR22T	W.O.:	M240519	Model:	TSIO-550-K	Model:	PHC-JEY1F-1
S/N:	0065	FHM:	1410.7	S/N:	1003148	S/N:	NJ405B
Reg #:	N322PB	Hobbs:	1791.8	TSN:	1410.7	TSN:	1416.7
TAT:	1410.7						

PROPELLER LOGBOOK INSERT

The propeller identified above was repaired and/or inspected in accordance with current Federal Aviation Regulations. Pertinent details of this maintenance are on file at this repair station.

Inspections

100 Hour/Annual Propeller Inspection and Prop Lube Requirement REF: Cirrus SR22T AMM 05-20 (revised 12/20/2023)

The above inspection was accomplished in accordance with the Cirrus SR22 Airplane Maintenance Manual and/or vendor manuals as required by 14 CFR 91.409(a)(1). With regard to the work performed, I certify that this propeller is in airworthy condition.

Signed:

Print:

for
COMMONWEALTH AVIATION SERVICE, INC.
d/b/a MILLION AIR - RICHMOND
F.A.A. Approved Repair Station No. VXWR051W

wo: WO_6816

Propeller - page 1 of 1



Heck Air LLC · 1389 General Aviation Dr. · Melbourne, FL 32935 · 3212559155

N322PB

Air Time: 1469.4

Hobbs: 1861.1

June 04, 2025

Performed annual inspection. Serviced prop with NYCO GN3058. I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

Phillip Scrivner A&P IA 2724196

Phillip M. Scrivner