# AIRCRAFT TECHNICAL RECORD

Section 4. PROPELLER LOG



### PROPELLER LOG

1.	Mal	ke	MT-Propeller Entwicklung GmbH				
2.	Mod	del	MTV-6-R-C-F				
3.	Spe	cification Number	PI9NE  180214				
4.	Date	e of Manufacture					
5.	Hub	Serial Number					
6.	Bla	des					
	(a)	Design No.					
	(b)	Blade Serial Numbers:					
		(1)	AJA - 68994				
		(2)	AJA-68995				
		(3)	AJA- 6899 6				
		(4)					
		(5)					
	(c)	Pitch Settings					
		(1) Basic	AIA				
		(2) High					
		(3) Low	130				
		(4) Reverse FEATHER	80°				

#### Section 4A: Propeller Service and Maintenance Record TOTAL TIME TIME RUN DATE SINCE OVERHAUL INSTALLATIONS, INSPECTIONS, REPAIRS, ADJUSTMENTS, MODIFICATE MIN HOURS 1 MIN HOURS BROUGHT DIAMOND AIRCRAFT IND D.O.T. APPROVED MAINTENANCE ORGANIZATION161-93 N649DA AC Serial Number 42 N334 Work Order: Prop RH TT: SO 071857 31.08 Airframe Total Time 31.08 180214 Prop RH SN: Propeller MTV-6-R-C-F/CF 190-69, S/N: 180214, installed on Aircraft DA 42 S/N: 42.N334, RIGHT Total Time Prop brought forward: 31.08 hrs Prop and documentation inspected for Major Mod's and/or STC's incorporated, none found. All applicable Airworthiness Directives, Service Bulletins complied with. AWD Bi-weekly checked thru 2018-13 Next overhaul due at 2400 hrs OR May, 2024 whichever occurs Next inspection due: 100 hr inspection The Maintenance Described performed IAW the Applicable Standard of niness JUL 0 3 2018 *EMBRY-RIDDLE* A/C TOTAL TIME: 97.8 AERONAUTICAL UNIVERSITY ENG TOTAL TIME: 97.8 ENG T.S.M.O.H.: N/A I certify that this RIGHT PROPELLER-DA 42NG (N649DA) has been TACH TIME: 97.8 inspected in accordance with an Annual Inspection and PROP T.S.M.O.H.: N/A was found to be in an airworthy condition. PROP TOTAL TIME: Time in Service: 97.8 Removed spinner and inspected propeller components, blades, spinner, bulkheads, and attaching hardware. Checked blades for play. Reinstalled spinner. The aircraft, airframe, aircraft engine or appliance identified above was inspected and repaired in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this work order: WO # RMS 2018 04689 Date: 18 SEPT 2018 ERAU 9 Steve Johnson Signed: Repair Station N3XR816N. N3XR816N 7691 THIS PAGE TOTAL PREVIOUS TOTAL BROUGHT FORWARD TOTAL SINCE NEW CARRY FORWARD to Top of Next Page

## Section 4A: Propeller Service and Maintenance Record

DATE	TIME RU	JN	TOTAL SINCE OVER			
1 1	HOURS	MIN	HOURS	MIN	INSTALLATIONS, INSPECTIONS, REPAIR	S, ADJUSTMENTS MOS
BROUGHT _		-				-, MODIFI
<b>M</b> Dian	10nd AIRCRAFT		D.O.T. APPR	AIRCRAFT OVED MAIN NIZATION16	TENANCE	
Registration: Airframe Total Time: Engine LH SN: Engine LH TT: Prop LH SN: Prop LH TT:	N649DA 171.5 E4-C-00454 171.5 180211 171.5	AC Seri Work O Engine Engine Prop Ri	rder: S RH SN: E RH TT: 1 1 SN: 1	2.N334 50 072010 54-C-00455 71.5 80214 71.5		
RH Propell	er Routine Mair	ntenan	ce:			
MT Manua	p Inspection Car I E-124 eekly AD Review				Ch 5 and	
• PAA BI-We	eniy AD Neview	, 2010-	20 complied (	witti		
The Maintenance	ACA B	en perfo irworthin	ess	Applicable S		
	AMO 161-93					
Parkway Grand I	9 Tach: 267.4 and MT-propello tion and was det	52 (9) AcftTT er main	1: 267.4 Prop	<u>р ТТ: 267</u> ual. I се		
Siere o Brieffy	1		T .			
PROP MODEL (R): MTV-6-R-C-F/CF190- PROP S/N (R): 18021 REG. NO: N649DA WORK ORDER: 0168	14	Pre	emien ft Service	<b>)</b> C	Premier Aircraft Service, Inc. 3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345	DATE: 9/4/2020 A/C TSN: 362.3 PROP TT (R): 362.3 HOBBS: 77.5
Right Prop Ent • Performed 100 H		sing DA	42NG AMM a	as a guide		
DATE OWNER			/	11		Work Order: 0165
DATE: 9/4/2020			had Cox, Licen	ise: AP3782	2800	Printed by EBis 3 (datcomedia.com
PROP MODEL (R):						DATE: 12/3/2020
MTV-6-R-C-F/CF190 PROP S/N (R): 1802 REG. NO: N649DA WORK ORDER: 022	14	Pre	emie	pe	Premier Aircraft Service, Inc. 3804 Falcon Way W Hangar 18S Fort Worth, TX 76106	A/C TSN: 434.1 PROP TT (R): 434.1 HOBBS: 183.9

**Right Prop Entries** 

• Performed 100 Hour Inspection using DA42NG AMM as a guide.

I certify this propeller has been inspected IAW an Annual Inspection and was determined to be in airworthy condition.

DATE: 12/3/2020

SIGNED: David Seastead, License: AP3492477 IA

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345

Work Order: 0223

Printed by EBis 3 (datcomedia.com)

PROP MODEL (R): MTV-6-R-C-F/CF190-69 PROP S/N (R): 180214 REG. NO: N649DA WORK ORDER: 0267



#### Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345 DATE: 2/12/2021 A/C TSN: 529.7 PROP TT (R): 529.7 HOBBS: 324.5

#### **Right Prop Entries**

Performed 100 Hour Inspection using DA42NG AMM as a guide

I certify this propeller has been inspected IAW a 100 Hour Inspection and was determined to be in airworthy condition.

DATE: 2/12/2021

SIGNED:

David Seastead, License: AP3492477 IA

Work Order: 0267

Printed by EBis 3 (datcomedia.com)

PROP MODEL (R): MTV-6-R-C-F/CF190-69 PROP S/N (R): 180214 REG. NO: N649DA WORK ORDER: 0300



#### Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345 DATE: 4/2/2021 A/C TSN: 619.4 PROP TT (R): 619.4 HOBBS: 461.9

#### **Right Prop Entries**

Performed 100 Hour Inspection using DA42NG AMM as a guide

DATE: 4/2/2021

SIGNED:

David Seastead, License: AP3492477 IA

Work Order: 0300

Printed by EBis 3 (datcomedia.com)

PROP MODEL (R): MTV-6-R-C-F/CF190-69 PROP S/N (R): 180214 REG. NO: N649DA WORK ORDER: 0346



#### Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345 DATE: 6/7/2021 A/C TSN: 715.8 PROP TT (R): 715.8 HOBBS: 598.5

#### **Right Prop Entries**

Performed 100 Hour Inspection using DA42 AMM as a guide

I certify this propeller has been inspected IAW a 100 Hour Inspection and was determined to be in airworthy condition.

DATE: 6/7/2021

SIGNED: Chad Cox, License: AP3782800 IA

Work Order: 0346

Printed by EBis 3 (datcomedia.com)

PROP MODEL (R): MTV-6-R-C-F/CF190-69 PROP S/N (R): 180214 REG. NO: N649DA WORK ORDER: 0392



#### Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345 DATE: 7/29/2021 A/C TSN: 794.9 PROP TT (R): 794.9 HOBBS: 708.1

#### **Right Prop Entries**

Performed 100 Hour Inspection using DA42NG AMM as a guide

I certify this propeller has been inspected IAW a 100 Hour Inspection and was determined to be in airworthy condition.

DATE: 7/29/2021

Chad Cox, License: AP3782800 IA

Work Order: 0392

Printed by EBis 3 (datcomedia.com)

PROP MODEL (R): MTV-6-R-C-F/CF190-69 PROP S/N (R): 180214 REG. NO: N649DA WORK ORDER: 0418



SIGNED:

#### Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345 DATE: 9/15/2021 A/C TSN: 892.2 PROP TT (R): 892.2 HOBBS: 847.8

#### **Right Prop Entries**

Performed 100 Hour Inspection using DA42NG AMM as a guide

I certify this propeller has been inspected IAW a 100 Hour Inspection and was determined to be in airworthy condition.

DATE: 9/15/2021

SIGNED: Chad Cox, License: AP3782800 IA Work Order: 0418

Printed by EBis 3 (datcomedia.com)

Make: Diamond Model: DA42NG S/N:42.N334 REG NO: N649DA	Diamond.  FLEET & AVIATION SERVICES	Diamond Fleet & Aviation services LLC 5070 S. Collins suite 205, Arlington, TX 76018 Phone: 817-575-7828	Date: 12/3/2021 Hobbs: 998.7 A/C TSN: 992.0 Right prop: 992.0	NS, REPAIRS, ADJUSTMENTS, MODI		
Right prop	rmed a 100 hour inspection	using DA42NG AMM as a guide.				
		week to hour inspection and was determined to SIGNED: War I A	be in an airworthy			
Date: 12/3/2021		Austin Paden, A&P:4494928				
1	1 1			Propeller R · page 1 of 1		
wo: N649DA 2022.02.28 Se	cneduled	Diamon  FLEET & AVIATION SERVICE	N			
	Diamond Fleet & Aviation	Service - 5070 S. Collins S. Suite 205 -	Arlington, TX 76018 - 90			
N649DA TACH: 1083.4	MT Propeller, PTSN: 10	MTV-6-R-C-F/CF 190-69, \$	S/N: 180214 83.4	March 04, 2022		
		ropeller PN: MTV-6-R-C-F/0		80214, TT TACH: 1083.4		
1 100 Hour Pro	aressive Inspec	tion - R Propeller – Perforr d installation manual as a g	ned100hr Inspect			
With respect to the for return to service work order: N649D	e. Details of work	nis propeller has been found performed are on file with eduled.	DISHIONO FIEEL C	ondition and is approved A Aviation Service under		
Austin Paden A/P 4	MAIN		"-week			
Austin Paden A/P 4	494928				.1	
wo: N649DA 2022.05.09	Scheduled	Diamon FLEET & AVIATION SERVICE	nd.	Propeller R ⋅ page 1 of 1		
	Diamond Fleet & Aviati	on Service - 5070 S. Collins S. Suite 205		012474808	-	
N649DA TACH: 1160.6	PTSN:		160.6	June 01, 2022		
		Propeller PN: MTV-6-R-C-F				
removed an 6ea washer 1260 6 ACT	d reinstalled to facts (p/n C-076-A), a	our inspection completed us cilitate engine maintenance. and 1ea flange o-ring (p/n (	Replaced 6ea mo C048-A) during re	ount locknuts (p/n C-067), einstallation. Next due @		
2. <b>AD 07-26-1</b> 31 May 202	3 Leading Edge 3 or 1260.6 ACTT	Erosion Strips – Inspected	I IAW MT Propell	er SI E-112. Next due @		
With respect to the for return to service work order: N649	ce. Details of wor	this propeller has been foun k performed are on file with heduled.	d in an airworthy Diamond Fleet	condition and is approved & Aviation Service under		
Michael Smith A/F	3906663	MAN				
	/	100				
				1		
THIS PAGE TOTAL						
EVIOUS TOTAL						
UGHT FORWARD						