

1. Approving Civil Aviation Authority/Country:

FAA/United States

2.

AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:

26067

4. Organization Name and Address:

Tiffin Aire, Inc.

1778 West U.S. 224 Tiffin, Ohio 44883

(DTXR341D)

5. Work Order/Contract/Invoice Number:

W.O.# 26067

6. Item:

7. Description:

8. Part Number:

9. Quantity:

10. Serial Number:

11. Status/Work:

1

HARTZELL PROPELLER

PHC-J3YF-1RF

1

FP521A

OVERHAULED

12. Remarks:

COMPLETELY OVERHAULED PROPELLER AND INSTALLED ALCOHOL FEED SHOES IN ACCORDANCE WITH HARTZELL SERVICE MANUALS LISTED ON THE BACK SIDE OF THIS FORM. COMPLIED WITH SERVICE BULLETINS: 136I, 374R1 / SERVICE LETTERS: 177, 217, 244, 267, 278, 348, 354, 61YR14, 366.
 BLADE MODEL NUMBER: F7693DFB / BLADE SERIAL NUMBERS: K06813, K06799, K06810.
 PROPELLER TOTAL TIME SINCE NEW: 825.5
 PROPELLER TOTAL TIME SINCE OVERHAUL: 0.0
 PROPELLER TIME BETWEEN OVERHAULS: 72 CALENDAR MONTHS OR 2400 HOURS WHICHEVER OCCURS FIRST.

13a. Certifies the items identified above were manufactured in conformity to:

- Approved design data and are in a condition for safe operation.
- Non-approved design data specified in Block 12.

14a. 14 CFR 43.9 Return to Service

Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval/Authorization No.:

14b. Authorized Signature:

14c. Approval/Certificate No.:

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14d. Name (Typed or Printed):

14e. Date (dd/mm/yyyy):

Todd C. Perry

26/Sep/2022

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Propeller
TSN TSO

A/C
Hrs

Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.

6/23/2023 N845LP HARTZELL PHC-J3YF-1RF S/N FP521A TACH 825.8 SPOH 0.0 TT 825.8

PROPELLER OVERHAULED BY TIEFIN AIRE INC. WORK ORDER NUMBER 26067. AD'S THROUGH 2023-13 CHECKED FOR COMPLIANCE. W/O 12524

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION.

MATTHEW G SHOWALTER AP 3542093 IA
Matthew G Showalter A3542093IA