

Propeller Logbook



SENENICH PROPELLER SERVICE, INC.

- McCauley
- Hartzell
- MT
- Sensenich
- Dowty
- Hamilton Standard

INSTALLING AGENCY PLEASE NOTE:
Recording of Propeller Total Time Since New (TTSN)
is Required Per F.A.R. 91.417

Lancaster Airport, 519 East Airport Road, Lititz, PA 17543 (800) 462-3412 (717) 560-3711 Fax: (717) 560-4354 FAA Certified Repair Station #QV9R194N

Lee Gilmer Memorial Airport, 1245 Palmour Place, Suite A, Gainesville, GA 30501 (800) 791-7767 (770) 538-0444 Fax: (770) 538-0117 FAA Certified Repair Station #S46R346N

Windham Airport, 21 Airport Road, North Windham, CT 06256 (877) 456-7944 (860) 456-7944 Fax: (860) 456-0410 FAA Certified Repair Station #Q0PR011X

The manufacturers' FAA approved overhaul period for this propeller is 6 years/months or 2400 hours, whichever occurs first.

Limiting factors affecting time between overhaul (TBO)

Corrosion, internal

- Directly proportional to calendar time
- Unseen and potentially catastrophic

Corrosion-erosion, external

- Calendar time and operating environment
- Visible and easily corrected

Wear, Internal/External

- Function of hours in operation and types of flying, i.e., aerobatic much higher wear rates than pleasure.

Seal Life

- Deterioration and loss of resiliency affecting sealing property is proportionate to calendar time in service.
- Wear rates are commensurate to hours flown.

IT IS STRONGLY RECOMMENDED ALL PROPELLERS MINIMALLY RECEIVE AN INTERNAL CORROSION INSPECTION AND NEW SEALS AT INTERVALS NOT TO EXCEED SIX YEARS.

Propeller Model PHC-J3YF-1RF

Blade Model F7392-1

Hub Serial No. FP1903B

Blade Serial No. 1 J77180

2 J77184



3 J77186

4 _____

5 _____

6 _____

SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
			<p>Date: 12/19/2019 Hobbs: 1321.0 SPOH: 0.0</p> <p>Installed this propeller on Cirrus N498PR after overhaul by Sensenich Propeller Service, Inc WO#G25323. Performed run up and leak checked.</p> <p>Signed:  A&P 2830402 IA Martin Aircraft Services, LLC</p>	
<div style="border: 1px solid black; padding: 5px; margin: 10px auto; width: 80%;"> <div style="display: flex; justify-content: space-between; font-size: small;"> wo: WO_34 Propeller - page 1 of 1 </div> <h2 style="text-align: center; margin: 0;">BOLDAviation</h2> <p style="text-align: center; font-size: x-small; margin: 0;">BOLDAviation · 965 Airport Access Dr. · Greenwood, IN 46143 · 317-745-4422</p> <hr/> <div style="display: flex; justify-content: space-between;"> <div style="width: 30%;"> <p>N468PR FLIGHT: 1130.5</p> </div> <div style="width: 40%; text-align: center;"> <p>Hartzell 3-Bladed, PHC-J3YF-1RF/F7392-1, S/N: FP1903B HOBBS: 1444.3</p> </div> <div style="width: 25%; text-align: right;"> <p>July 07, 2022</p> </div> </div> <p>C/W Annual Inspection I.A.W. Cirrus SR20 Inspection Guide.</p> <ul style="list-style-type: none"> Inspected blades and hub, bolts, bulkhead, & spinner. Ground run up and leak checked. No issues noted. <p>I certify that this aircraft, engine, propeller, or appliance identified above was repaired and/or inspected in accordance with an annual/100-hour inspection and determined to be in an airworthy condition and approved for return to service. Details of work performed are on file with BOLDAviation under work order: WO_34.</p> <p style="text-align: right;">  Ray Hutcherson Inspection Authorization 377061269 </p> </div>				

BOLDAviation

BOLDAviation · 965 Airport Access Dr. · Greenwood, IN 46143 · 317-745-4422

N468PR**Hartzell 3-Bladed, PHC-J3YF-1RF/F7392-1, S/N: FP1903B****July 07, 2022**

FLIGHT: 1130.5

HOBBS: 1444.3

C/W Annual Inspection IAW Cirrus SR20 inspection guide. Inspected blades and hub, bolts, bulkhead, spinner. Ground run up and leak checked. No issues noted.

I certify that this aircraft, engine, propeller, or appliance identified above was repaired and/or inspected in accordance with an annual/100-hour inspection and determined to be in an airworthy condition and approved for return to service. Details of work performed are on file with BOLDAviation under work order: WO_34.

Ray Hutcheson Inspection Authorization 377061269




44050 Russia Road Elyria, Ohio 44035

440-323-7000

440-323-7098 (FAX)

N468PR**TACH: 1180.3****HOBBS: 1509.0****DATE: 07-14-23**

Complied with ANNUAL INSPECTION in accordance with FAR 43 Appx. "D". AD researched through 2023-13. *I certify that this propeller has been inspected in accordance with an annual inspection and was found to be in an airworthy condition.*

James R. Schall 3399344 IA

