

PROPELLER SERVICE AND

DATE	TIME RUN		TOTAL TIME SINCE OVERHAUL		NOTE: USE BOTH PAGES AND AS MANY LINES AS REQUIRED FOR COM
	HRS.	MIN.	HRS.	MIN.	
BROUGHT FORWARD					

wo: WO_569



Propeller 100 hour - page 1 of 1

Steel Aviation · 53 North Street Ext · Phillipsburg, Ohio 45354 · 937 332 7587

N194TS
HOBBS: 1268.0

Hartzell, HC-C2YR-1BFP, S/N: CH43744B
TACH: 1018.6

September 30, 2024

C/W 100 hour Inspection in accordance with FAR 43 Appendix D using DIAMOND AMM as a guide.

I certify that this PROPELLER has been inspected in accordance with an (100 hour) inspection and was determined to be in airworthy condition. Details of work performed are on file with Steel Aviation under work order: WO_569.

Jeff Pleiman A/P I/A 3304319

wo: WO_684



Propeller - page 1 of 1

Steel Aviation · 53 North Street Ext · Phillipsburg, Ohio 45354 · 937 332 7587

N194TS
HOBBS: 1393.7

HARTZELL, HC-C2YR-1BFP, S/N: CH43744B
TACH: 1075.5

March 12, 2025

C/W Annual Inspection in accordance with FAR 43 Appendix D using - Hartzell manual 115N as a guide.

I certify that this Propeller has been inspected in accordance with an (annual) inspection and was determined to be in airworthy condition. Details of work performed are on file with Steel Aviation under work order: WO_684.

Jeff Pleiman A/P I/A 3304319

wo: WO_869



Propeller 100 hour - page 1 of 1

Steel Aviation · 53 North Street Ext · Phillipsburg, Ohio 45354 · 937 332 7587

N194TS
HOBBS: 1503.5

Hartzell, HC-C2YR-1BFP, S/N: CH43744B
TACH: 1165.3

September 18, 2025

C/W 100 hour Inspection in accordance with FAR 43 Appendix D using DIAMOND AMM as a guide. Lubricated prop with number 5 grease.

I certify that this PROPELLER has been inspected in accordance with an (100 hour) inspection and was determined to be in airworthy condition. Details of work performed are on file with Steel Aviation under work order: WO_869.

Jeff Pleiman A/P I/A 3304319

CARRIED FORWARD

TOTAL THIS PAGE

TOTAL FROM
PREVIOUS SUMMARY

TOTAL
SINCE MFG.