

Book #2
Opened 7/16/19

N813CT



AIRMART.com

AIRCRAFT SALES & BROKERAGE

AIRCRAFT SPECIALISTS PROPELLER MAINTENANCE LOG

(812) 246-4696 • (800) 356-3723 • fax (812) 246-4365

7GEM855-0-60

S/N: 35998K

www.800projets.com

FAA Approved Repair Station No. PZ4R458M

PROPELLER MAINTENANCE LOG

DATE	RECORDER OR TACH	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS, AND ALTERATIONS
		 7/15/2019 Tach:4613.5 TSMOH:1332.2 Total time:3567.52 Sensenich Model:76EM8\$-0-60 S/N:35998K
		I Certify that this prop has been inspected IAW an Annual inspection and found to be in an airworthy condition. 3549886 IA END
		 8/11/2019 Tach:4713.2 TSMOH:1431.9 Total time:3667.22 Sensenich Model:76EM8\$-0-60 S/N:35998K
		I Certify that this prop has been inspected IAW an Annual inspection and found to be in an airworthy condition. 3549886 IA END

PROPELLER MAINTENANCE LOG



Executive Air Taxi Corporation
(701) 258-5024
2301 University Dr. Bldg 48
Bismarck, ND 58504

Municipal Airport, Bismarck, ND

Date: 9/01/2021; Aircraft: N813CT; Type: PA-28-181; S/N: 28-8590080; Tach: 4785.70; Total Time: 4797.30; Engine - Type: O-360-A4M, S/N: L-31073-36A, Time: 4797.30; Prop - Type: 76EM8S5-0-60, S/N: 35998K, Time: 3751.30

Completed propeller 100 hour inspection IAW Sensenich Props and PA-28-181 Inspection Guide.

This aircraft and/or component identified above was inspected and/or repaired IAW current FAR's and I certify it to be in an airworthy condition, and is approved for return to service, with respect to the work performed.

WO# 26257 Date 9/1/21 Signature D. Decker
Executive Air Taxi Corp. Maintenance Release - Repair Station CTR019D

Central Planes

Sauk Centre, MN 56378
(320) 352-3013

Date: 04/19/2023 Reg. #: N813CT Tach: 4809.1 Total Time: 3774.7

Make: Sensenich Model: 76EM8S5-0-60 S/N: 35998K TSMOH: Unkwn

1. Dressed blades and inspected for proper attachment.
2. I certify this propeller has been inspected in accordance with an annual inspection and determined airworthy at this time. Thomas J Wenker 3136772IA TJW

PROPELLER MAINTENANCE LOG

DATE	RECODER OR TACH	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS, AND ALTERATIONS
		<p>Executive Air Taxi Corporation Municipal Airport, Bismarck, ND</p>
		<p>Executive Air Taxi Corporation (701) 258-5024 2301 University Dr. Bldg 48 Bismarck, ND 58504</p>
		<p>Date: 5/14/2024; Aircraft: N813CT; Type: PA-28-181; S/N: 28-8590080; Hobbs:; Tach: 4837.10; Total Time: 4848.70; LG Cycles:; Engine - Type: O-360-A4M; S/N: L-31073-36A; Time: 4848.70; Prop - Type: 76EM8S5-0-60, S/N: 35998K; Time: 3802.70</p>
		<p>C/N Prop 100 Hr. Inspection IAW Piper Aircraft Inspection Report (A) Model PA28-181 and PA28-181 AMM 61-00-00.</p>
		<p>This aircraft and/or component identified above was inspected and/or repaired IAW current FAR's and I certify it to be in an airworthy condition, and is approved for return to service, with respect to the work performed.</p>
		<p>WO# <u>27088</u> Date <u>5/14/24</u> Signature  Executive Air Taxi Corp. Maintenance Release - Repair Station C7YR019D</p>



Executive Air Taxi Corporation

Executive Office
(701) 258-5024

2301 University Dr. Bldg 48
Bismarck ND 58501

Municipal Airport, Bismarck, ND

DATI

C/N prop annual/100 hour inspection IAW Piper PA-28-181 Inspection Report PN# 230-1039 and FAR 43 Appendix D.

Date: 6/13/2025; Aircraft: N813CT; Type: PA-28-181; S/N: 28-8590080; Hobbs: Tach: 4848.30; Total Time: 4859.90; LG Cycles: Engine - Type: O-360-A4M, S/N: L-31073-36A, Time: 4859.90; Prop - Type: 76EM8S5-0-60, S/N: 35998K, Time: 3813.90

This aircraft and/or component identified above was inspected and/or repaired IAW current FAR's and I certify it to be in an airworthy condition, and is approved for return to service, with respect to the work performed.

WO# 27344 Date 6/13/25 Signature 12
Executive Air Taxi Corp. Maintenance Release - Repair Station CTYR0196
