


Book 2



mt-propeller

The Winner's Propeller

PROPELLER LOGBOOK

EASA DE.21G.0003 / EASA.21J.020

INSTALLATION HISTORY

Da

PROP MODEL MTV-12-D
PROP S/N 141042
REG NO N378TT
WORK ORDER ISM10038-07-2022



CIRRUS Cirrus Factory Service Center
AIRCRAFT

4134 Aviation Drive
Kissimmee FL 34741

DATE 7/13/2022
A/C TSN ~~2849~~ 28392
PROP TT 834.5
TSPOH
TACH 249.9

Prop Entries

(21) Installed prop MTV12-D S/N1141042 on Cirrus SR20 S/N 2074 after repair by MT Propeller USA CRS#Q4MR908Y IAW MT Propeller E-124 ATA 61-01-24 and Cirrus SR20 AMM 61-00

DATE 7/13/2022

SIGNED

John Goebel A&P 3075199

Work Order: ISM10038-07-2022

Printed by EBis 3 (datcomedia.com)

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
<p>MT-Propeller USA, Inc. 1180 Airport Terminal Drive, DeLand, FL 32724 FAA Approved Repair Station Q4MR908Y Phone: (386) 736-7762 Fax: (386) 736-7696 E-mail: info@mt-propellerusa.com</p>				
<p>Propeller Model: MTV-12-D/188-59b S/N: 141042</p>				
<p>Propeller TSN: Not Provided TSO: Not Provided</p>				
<p>Repaired propeller in accordance with W/O# 22-453MT and Overhaul Manual E-220 Rev68.</p>				
<p>Installed 6 new mounting studs.</p>				
<p>Year of Manufacture: 2014</p>				
<p>I certify this propeller has been repaired and determined to be in airworthy condition at</p>				
<p>this time. Return to service this date, August 22, 2022</p>				
<p>Peter Marshall, Chief Inspector Q4MR908Y </p>				
<p> </p>				
<p> </p>				
<p> </p>				
<p> </p>				
<p> </p>				
<p> </p>				
<p> </p>				
<p>OTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12</p>				

MAINTENANCE & SERVICE HISTORY

Southeast Aero Services

St Augustine, FL.

Phone (904) 824-1899/Fax (904) 824-6334

S/N: 141042


N378TT

MTV-12-D

4/13/2023

Prop TT: 922.6hrs

Performed 100 hr inspection. Researched AD compliance through biweekly 2023-08, No ADs due to Propeller at this time.





Charles T. Bryant A&P 3290857

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

5
2
3

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
PROP MODEL MTV-12-D PROP S/N 141042 REG NO N378TT WORK ORDER ISM10421-06-2023		 CIRRUS AIRCRAFT Cirrus Factory Service Center 4134 Aviation Drive Kissimmee FL 34741 Phone 689-244-5221		DATE: 7/20/2023 A/C TSN 3000.2 PROP TT 995.5 TSPOH 0 HOBBS 3000.2
Prop Entries				
(6) Performed an annual inspection of this propeller in accordance with Cirrus Aircraft SR-20 AMM 05-20 inspection checklist and the MT Propeller MM E-124 (64) I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition.				
DATE 7/20/2023	SIGNED 		Work Order: ISM10421-06-2023	
Israel Lopez Ramos IA 3629553			Printed by EBis 3 (datcomedia.com)	
<div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12				

MAKE: Cirrus
MODEL: SR20
S/N: 2074
REG. NO: N378TT
MODEL: MTV-12-D
PROP S/N 141042

ADVANCED

flyADVANCED

FAA Cert: 5T2R901C
530 Airport Rd.
Lititz, PA 17543

W/O #: 10189-07-2024
DATE: 08-02-2024
A/C TT: 2557.4
Prop TT: 1045.5
Hobbs: 3101.4
Flight: 460.9


Propeller Entries

Annual Propeller Inspection completed IAW FAR 91.409 and the requirements outlined in FAR 43 App. D. with reference to the Cirrus AMM check list ch 5-20. Cleaned blades. Serviced hub. All ADs current through release 2024-15... Re-torqued the propeller governor head cover attach hardware, operational run-up leak check ok at this time... Removed and re-installed propeller with new o-ring IAW Cirrus AMM 61-10 after replacement of the Alternator #1 drive belt P/N: 657504, adjusted the drive belt tension IAW Cirrus AMM 24-30

I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.

DATE: 08-02-2024

SIGNED:


Joshua J. Ferry
FAA Cert: 5T2R901C

WORK ORDER: 10189-07-2024
Printed by EBIS (EBISCloud.com)

MAINTENANCE & SERVICE HISTORY

AvDyne AeroServices, LLC

MAKE: Cirrus

MODEL: SR20

SERIAL NO: 2074

REGISTRATION NO: N378TT

Date: 12/10/2024 ^{AK} ~~AP~~ 4545345

Work order: 24-11-004

Total Time: ~~3123.3~~ ~~1067.4~~ 3123.3

Tach Time: ~~4766~~ 1067.4

TSO: 4182.8

natures
Station
Numbers

Prop: MTV12-D S/N 1141042

1. Completed Annual inspection on propeller I.A.W. FAR 43 appendix D, and Cirrus maintenance manuals 05-20

2. AD research completed using AD toolbox, Dated 12/3/2024.


//////////////////////////////////////END//////////////////////////////////////

This aircraft and or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service.

Pertinent details of the repair are on file at agency under work order No: 24-11-004

Date: 12/10/2024

Signed:



For Avdyne Aeroservices LLC CRS # Y7NR985Y