




*The Standard*

# **PROPELLER LOG**

**ASA-SP-L**



*The Standard*

# **PROPELLER LOG**

**ASA-SP-L**

*The Standard Propeller Log*  
SP-L

© 2017 Aviation Supplies & Academics, Inc.

**ASA-SP-L**

ISBN 978-1-56027-418-6

All rights reserved.

Reproduction or use, without written permission,  
in any manner, is prohibited.

Published by  
Aviation Supplies & Academics, Inc.  
7005 132nd Place SE  
Newcastle, WA 98059-3153  
Website: [www.asa2fly.com](http://www.asa2fly.com)  
Email: [asa@asa2fly.com](mailto:asa@asa2fly.com)

Printed in the United States of America

TRANSPORTATION USD \$4.95

ISBN 978-1-56027-418-6



**Propeller Record** General Information

**Propeller Manufacturer**

Sensenich

**Model**

76EM 8510-0-62

**Type**

**Hub Series #**

30856K

**Blade #**

**Date of Manufacture**

**Make/Model**

Grumman American

**Serial #**

AA5B-1010

**Aircraft Installed On:**



*Fletchair Fleet Support L.L.C*  
*1409 Aviation loop, Fredericksburg Texas*  
*830-990-2252*

Registration Number: N4515L  
Make: Sensenich  
Prop M/N: 76EM8S10-0-62  
Prop S/N: 30856K  
Date: 1/12/2018

Aircraft Tach Time: 2164.3

Performed Annual inspection in accordance with FAR 43 app D, with reference to Gulfstream Aerospace Corp. Maintenance Manual, Ch. 5-2-1, pages 202 thru 214. Propeller removed for inspection, Re-installed, torqued bolts and safetied. AD's checked current this date. I certify that this propeller has been inspected IAW an annual inspection and was found to be in airworthy condition.

  
Scott Egesdahl A&P35158561A

<b>Next Inspection Due:</b>	<b>Time Since Overhaul</b>	<b>Mech. Cert. # or Repair Station #</b>
-----------------------------	----------------------------	--




*Fletchair Fleet Support L.L.C*  
 1409 Aviation loop, Fredericksburg Texas  
 830-990-2252

Registration Number: N4515L  
 Make: Sensenich  
 Prop M/N: 76EM8S10-0-62  
 Prop S/N: 30856K  
 Date: 3/4/2019

Aircraft Tach Time: 2196.69

Performed Annual inspection in accordance with FAR 43 app D, with reference to Gulfstream Aerospace Corp. Maintenance Manual, Ch. 5-2-1, pages 202 thru 214. Propeller removed for inspection, Re-installed, torqued bolts and safetied. AD's checked current this date. I certify that this propeller has been inspected IAW an annual inspection and was found to be in airworthy condition.

  
 Scott Egesdahl A&P3515856IA

Year: _____	In Service	
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
Mech. Cert. # or Repair Station # _____		



Fletchair Fleet Support L.L.C  
1409 Aviation loop, Fredericksburg Texas  
830-990-2252

Registration Number: N4515E  
Make: Sensenich  
Prop M/N: 76EM8S10-0-62  
Prop S.N. 30856K  
Date: 4/14/2020

Aircraft Tach Time: 2207.84

Performed Annual inspection in accordance with FAR 43 app D, with reference to Gulfstream Aerospace Corp. Maintenance Manual, Ch. 5-2-1, pages 202 thru 214. Propeller removed for inspection, Re-installed, torqued bolts and safetied AD's checked current this date. I certify that this propeller has been inspected IAW an annual inspection and was found to be in airworthy condition.

  
Scott Egesdahl A&P 3515856IA

Year:	In Service	
Date:		
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		




Fletchair Fleet Support L.L.C  
1409 Aviation loop, Fredericksburg Texas  
830-990-2252

Registration Number: N4515L  
Make: Sensenich  
Prop M/N: 76EM8S10-0-62  
Prop S/N: 30856K  
Date: 5/12/2021

Aircraft Tach Time: 2213.47

Performed Annual inspection in accordance with FAR 43 app D, with reference to Gulfstream Aerospace Corp. Maintenance Manual, Ch. 5-2-1, pages 202 thru 214. Propeller removed for inspection. Re-installed, torqued bolts and safetied. AD's checked current this date. I certify that this propeller has been inspected IAW an annual inspection and was found to be in airworthy condition.

  
Scott Egesdahl A&P3515856IA

<b>Year:</b> _____	<b>In Service</b>	
<b>Date:</b> _____		
<b>Next Inspection Due:</b> _____	<b>Time Since Overhaul</b>	
<b>Mech. Cert. # or Repair Station #</b> _____		

**HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS**




*Fletchair Fleet Support L.L.C*  
*1409 Aviation loop, Fredericksburg Texas*  
*830-990-2252*

Registration Number: N4515L  
Make: Sensenich  
Prop M/N: 76EM8S10-0-62  
Prop S/N: 30856K  
Date: 6/1/2022

Aircraft Tach Time: 2218.54

Performed Annual inspection in accordance with FAR 43 app D, with reference to Gulfstream Aerospace Corp. Maintenance Manual, Ch. 5-2-1, pages 202 thru 214. Propeller removed for inspection. Re-installed, torqued bolts and safetied. AD's checked current this date. I certify that this propeller has been inspected IAW an annual inspection and was found to be in airworthy condition.

  
Scott Egesdahl A&P3515856IA

<b>Next Inspection Due:</b>	<b>Time Since Overhaul</b>	
		<b>Mech. Cert. # or Repair Station #</b> _____

**HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS**



*Fletchair Fleet Support L.L.C*  
1409 Aviation loop, Fredericksburg Texas  
830-990-2252

Registration Number: N4515L  
Make: Sensenich  
Prop M/N: 76EM8S10-0-62  
Prop S/N: 30856K  
Date: 6/15/2023

Aircraft Tach Time: 2237.02

Performed Annual inspection in accordance with FAR 43 app D, with reference to Gulfstream Aerospace Corp. Maintenance Manual, Ch. 5-2-1, pages 202 thru 214. Propeller removed for inspection. Re-installed, torqued bolts and safetied. Performed propeller dynamic balance, final IPS .06. AD's checked current this date. I certify that this propeller has been inspected IAW an annual inspection and was found to be in airworthy condition.

  
Scott Egesdahl A&P35158561A

Mech. Cert. # or Repair Station # \_\_\_\_\_




Fletchair Fleet Support L.L.C  
1409 Aviation loop, Fredericksburg Texas  
830-990-2252

Registration Number: N4515L  
Make: Sensenich  
Prop M/N: 76EM8S10-0-62  
Prop S/N: 30856K  
Date: 7/15/2024

Aircraft Tach Time: 2301.5


Performed Annual inspection in accordance with FAR 43 app D, with reference to Gulfstream Aerospace Corp. Maintenance Manual, Ch. 5-2-1, pages 202 thru 214. Propeller removed for inspection. Re-installed, torqued bolts and safetied. AD's checked current this date. I certify that this propeller has been inspected IAW an annual inspection and was found to be in airworthy condition

  
Scott Egesdahl A&P35158561A

---

**N4515L**      **08/01/2025**      **Tachometer time: 2365.3**  
Performed inspection of propeller, spinner and spinner bulkhead.

**Total time: 2365.3**

  
David M. Black A&P/IA 3684300

---

PO: 231242 LOT: 30-18146



133570576

P/N: 13-32370

LOC: 21JD

ASA PROPELLER LOG, SFTCVR 24PGS

