AIRCHAFT SIN: 44.NC126

AIRCRAFT TECHNICAL RECORD

N226DA

REGISTRATION

QeroTRANSPORT® Logbooks www.aerotransport.com

Airworthiness Directive Compliance Record Chronological Listing - FAA Style

N226DA 40.NC126

AD# Effective	Subject	Date & Hours @ Compliance	Method Of Compliance	0	R	Next Comp @ Hrs/Date	Authorized Signature & Number
21-17-01 08/23/21	OIL PUMP PRESSURE LOSS/	3/3/21	MSB-E4-030/2	X		N/A	David Seastead AP3492477 IA
21-22-20 11/16/21	HIGH PRESSURE PUMP DRIVING GEAR MANUFACTURING DAMAGE/	1/6/22	MSB-E4-036/1	X		N/A	David Seastead AP3492477 IA
21-24-10 12/27/21	SAND CASTED OIL PUMP HOUSING IMPROPER CLEANING PROCESS/	1/6/22	N/A by P/N	×		N/A	David Seastead AP3492477 IA
22-03-03 02/14/22	HIGH PRESSURE PUMP DRIVING GEAR MANUFACTURE OR ASSEMBLY DAMAGE/	1/6/22	MSB-E4-036/1	X		N/A	David Seastead AP3492477 IA

2025-02

AIRCRAFT TECHNICAL RECORD

Section 1. AIRFRAME LOG





DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVED MANUFACTURER #161-93

N226DA Registration: 40.NC126 AC Serial Number: E4-A-05091 Engine Serial Number: 201372 Prop Serial Number: 3.1 HRS Airframe Total Time:

Total Time Airframe Brought forward from Flight Test Journey Log (DAI - Form Q-157): 3.1 HRS

Compass Swing Performed:

Date: Next Due: **FEBRUARY 03 2021** FEBRUARY 2022

FOR	N	30	60	E	120	150
STEER	360	030	060	088	118	148
FOR	S	210	240	W	300	330
STEER	177	208	240	271	300	330

Static Pressure system and Primary Altimeter (G1000) have been inspected and tested in accordance with CAR Standard 571, Appendix B and 14 CFR 91.411

Test Date: 0 Next Due:

JANUARY 13 2021 JANUARY 2023

Standby Altimeter:

Factory Test Date: DECEMBER 10 2020 DECEMBER 2022 Next Due:

ATC Transponder & Altitude Reporting System(s) have been tested in Accordance with CAR Standard 571,

Appendix F and 14 CFR 91.217: & 91.413:

Test Date:

JANUARY 13 2021 JANUARY 2023

Next Due: Programmed Registration:

N226DA

Hex Code:

N/A (U.S. Registration)

The ELT was tested and inspected in Accordance with CAR Standard 571, Appendix G and 14 CFR 91.207(d):

Manufacturers Cert. date: 42/20

Installation Inspected:

JANUARY 29 2021

Battery due:

AUGUST 2027

Next ELT inspection due:

JANUARY 29 2022

ELT Programmed:

REG: N226DA N/A HEX:

366 (USA) Country:

Beacon ID: ADC64999655CB81

Emergency Battery Pack: Replacement Due Date: DECEMBER 2022

Garmin G1000 NXi Installation:

Software System: 2948.11

Checklist File: N/A

Basemap Land 5.18

SafeTaxi Data: 25-FEB-2021

Terrain Data: 3.00

Obstacle Data: Expires 25-FEB-2021

Navigation Data: Expires 25D-FEB-2021

Apt Directory: Expires 25-FEB-2021

FliteCharts Data: Expires 25-FEB-2021


IFR/VFR charts: Date: 28-JAN-2021



(continued next page)

FEB 0 5 2021

Date



DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVED MANUFACTURER #161-93


Registration: AC Serial Number: Engine Serial Number: Prop Serial Number: Airframe Total Time:

N226DA 40.NC126 E4-A-05091 201372 3.1 HRS

Following limitations as per DA 40 NG AMM Chapter 4 (subject to change with revision):

Component	Hours	Years	Next Due:	
Essential Bus	1000	-N/A-	1000 hrs	
Pitot-Static System	1000	2	1000 hrs or JAN 2023	
Bonding System	1000	-N/A-	1000 hrs	
Emergency Battery Pack	-N/A-	2	DECEMBER 2022	
ECU Backup Battery	-N/A-	1	JANUARY 2022	

- The following STC's are incorporated:
 - No STC's incorporated.
- THIS AIRCRAFT WAS INSPECTED FOR CONFORMITY TO APPLICABLE COMPANY RELEASED DOCUMENTS (DRAWINGS, SPECIFICATIONS, CONCESSIONS).
- I HEREBY CERTIFY THAT THIS AIRCRAFT CONFORMS TO FAA TYPE CERTIFICATE A47CE Rev No. 16,
- AND IS IN A FIT AND SAFE STATE FOR FLIGHT. Bi-weekly AWD check carried out to current revision 2021-03 all applicable AD's complied with, see attached.
- The work described above was carried out IAW the applicable Standard of Airworthiness.



(Intentionally left blank below this point)

	U.S. Standard Airworthiness Certificate, issued: (Date) FEB 1 0 2021, has been installed in the Aircraft on behalf of FAA Farmingdale/Saddle Brook MIDO Section AIR-8A5 on: (Date) FEB 1 0 2021
--	---

Section 1: Airframe Log		LANDIN	IGS / CYCLES	OF TASK	
		RTIME	DAILY TOTAL		DETAILS OF TASK (INSPECTION, REPAIRS & REPLACEMENT)
DATE	DAILY TOTAL	TOTAL	TOTAL		(INSPECTION)
1 1	HRS MIN	HOURS MI			
DRIED					
RRIED	4	Paris	ration:	N226DA 4C.NC126	
THE P	Diamon	AC Se	rial Number. ne Total Time:	3 1 hrs	
100	Anto	Engin	B SN:	3.1 hrs	
DIA	MOND AIRCRAFT	D Engin	SN:	201372 3.1 hrs	
	MAINTENANCE	Prop	Π:		
ni-mond /	Aircraft Work Older				
		was Performed.			
		-N. E4A-50-000-BH	Y SN: 0394	N.SB-E4-030/2.	
	EASA AD NO. 20	- 14 FO 000-000 i	istalled. Eligi	ine ground run and	
	New oil pump FIN	. La conice	able.		
	Prop governor sp	d out, found services beed stop adjusted 3 filter housing fittings.	No turn out		
		K724_3 replaced			
			IAMA Applic	cable Standard of	
The Ma	aintenance Describe	ed has been performed Airworthiness	IVAA (III Abbiic		
	60	RAFTINA			
	Silv	ACA 2	MAR	0 3 2021	
AC	A:	00 >	ale:		
	1	Mary 98 END.			
		-70 161-c			
					DATE: 1/6/2022
		77			t Service, Inc. A/C TSN: 90.1 HOBBS: 122.6
L: DA40NG 0.NC126	9	Premier	e	3804 Falcon Way W	HOBBS: 122.6
: Diamond EL: DA40NG 0.NC126 NO: N226DA K ORDER: 0504	S Ai	Premier	e	3804 Falcon Way W	HOBBS: 122.6
L: DA40NG D.NC126 NO: N226DA (ORDER: 0504		Premier	e	3804 Falcon Way W Hangar 18S Fort Worth, TX 76106	HOBBS: 122.6
L: DA40NG D.NC126 NO: N226DA CORDER: 0504		Premier rcraft Service	e	3804 Falcon Way W Hangar 18S Fort Worth, TX 76106	HOBBS: 122.6
L: DA40NG 0.NC126 NO: N226DA 1. ORDER: 0504		Premier	e	3804 Falcon Way W Hangar 18S Fort Worth, TX 76106	HOBBS: 122.6
L: DA40NG 0.NC126 NO: N226DA 0 ORDER: 0504			e	3804 Falcon Way W Hangar 18S Fort Worth, TX 76106	HOBBS: 122.6 Work Order: 0504
a: DA40NG INC126 IO: N226DA ORDER: 0504 Tame Entries aced fuel filte		SIGNED:		3804 Falcon Way W Hangar 188 Fort Worth, TX 76106 Phone: 562.881.5345	Work Order: 0504
a: DA40NG INC126 IO: N226DA ORDER: 0504 Tame Entries aced fuel filte				3804 Falcon Way W Hangar 188 Fort Worth, TX 76106 Phone: 562.881.5345	HOBBS. 122.0
L: DA40NG 0.NC126 NO: N226DA 0 ORDER: 0504		SIGNED:		3804 Falcon Way W Hangar 188 Fort Worth, TX 76106 Phone: 562.881.5345	Work Order: 0504 Printed by EBis 3 (datcomedia.com)
.: DA40NG INC126 INC126 INC126DA ORDER: 0504 arme Entries aced fuel filte		SIGNED:	License: AP34	3804 Falcon Way W Hangar 188 Fort Worth, TX 76106 Phone: 562.881.5345	Work Order: 0504 Printed by EBis 3 (datcomedia.com) DATE: 3/1/2022 A/C TSN: 116.7
: DA40NG .NC126 .NC126DA ORDER: 0504 ame Entries aced fuel filte :: 1/6/2022		SIGNED:	License: AP34	3804 Falcon Way W Hangar 188 Fort Worth, TX 76106 Phone: 562.881.5345 492477 IA Premier Aircraf 3804 Falcon Way W	Work Order: 0504 Printed by EBis 3 (datcomedia.com)
EDA40NG INC126 I		SIGNED:	License: AP34	3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345 492477 IA Premier Aircraf 3804 Falcon Way W Hangar 18S Fort Worth, TX 76106	Work Order: 0504 Printed by EBis 3 (datcomedia.com) DATE: 3/1/2022 A/C TSN: 116.7
.: DA40NG .NC126 .NC126 .NC126 .NC26DA ORDER: 0504	S r	SIGNED: David Seastead	License: AP34	2804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345 192477 IA Premier Aircraf 3804 Falcon Way W Hangar 18S	Work Order: 0504 Printed by EBis 3 (datcomedia.com) DATE: 3/1/2022 A/C TSN: 116.7
.: DA40NG INC128 IO: N228DA ORDER: 0504 Ame Entries aced fuel filte :: 1/6/2022 Diamond :: DA40NG INC128 IO: N226DA ORDER: 0509 Ame Entries	S T Ai	SIGNED: David Seastead	License: AP34	3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345 492477 IA Premier Aircraf 3804 Falcon Way W Hangar 18S Fort Worth, TX 76106	Work Order: 0504 Printed by EBis 3 (datcomedia.com) DATE: 3/1/2022 A/C TSN: 116.7
E. DA40NG INC126	Ai B I Inspection using stern IAW 14 CFI	SIGNED: David Seastead	License: AP34	3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345 492477 IA Premier Aircraf 3804 Falcon Way W Hangar 18S Fort Worth, TX 76106	Work Order: 0504 Printed by EBis 3 (datcomedia.com) DATE: 3/1/2022 A/C TSN: 116.7
EDA40NG INC126 INC126 INC126 INC126DA ORDER: 0504 INCE Entries aced fuel filte E1/6/2022 Diamond EDA40NG INC126 I	Ai	SIGNED: David Seastead Premier rcraft Service g DA40NG AMM as R 91.207(d)	License: AP34	3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345 492477 IA Premier Aircraf 3804 Falcon Way W Hangar 18S Fort Worth, TX 76106	Work Order: 0504 Printed by EBis 3 (datcomedia.com) DATE: 3/1/2022 A/C TSN: 116.7
DIAMONG INC126 I	Ai Inspection using stern IAW 14 CF ackup batteries 0 Hour lubricatio	SIGNED: David Seastead Premier rcraft Service g DA40NG AMM as R 91.207(d)	License: AP34	Premier Aircraf 3804 Falcon Way W Hangar 188 Fort Worth, TX 76106 Phone: 562.881.5345 Premier Aircraf 3804 Falcon Way W Hangar 185 Fort Worth, TX 76106 Phone: 562.881.5345	Work Order: 0504 Printed by EBis 3 (datcomedia.com) DATE: 3/1/2022 A/C TSN: 116.7 HOBBS: 161.4
E. DA40NG I. DA40NG INC128 IO: N226DA ORDER: 0504 Imme Entries aced fuel filte E: 1/6/2022 Diamond E: DA40NG INC128 INC1	Ai Inspection using stern IAW 14 CF ackup batteries 0 Hour lubricatio	SIGNED: David Seastead Premier Torraft Service g DA40NG AMM as R 91.207(d) in accordance with an A	License: AP34	Premier Aircraf 3804 Falcon Way W Hangar 188 Fort Worth, TX 76106 Phone: 562.881.5345 Premier Aircraf 3804 Falcon Way W Hangar 185 Fort Worth, TX 76106 Phone: 562.881.5345	Work Order: 0504 Printed by EBis 3 (datcomedia.com) DATE: 3/1/2022 A/C TSN: 116.7 HOBBS: 161.4
EDA40NG INC126 INC126 INC126 INC126DA ORDER: 0504 INCE Entries aced fuel filte Entries Control of the control o	Ai Inspection using stern IAW 14 CF ackup batteries 0 Hour lubricatio	SIGNED: David Seastead Premier rcraft Service g DA40NG AMM as R 91.207(d) in accordance with an A SIGNED:	License: AP34	page 185 Fort Worth, TX 76106 Phone: 562.881.5345 Premier Aircraf 3804 Falcon Way W Hangar 185 Fort Worth, TX 76106 Phone: 562.881.5345	Work Order: 0504 Printed by EBis 3 (datcomedia.com) DATE: 3/1/2022 A/C TSN: 116.7 HOBBS: 161.4
EDA40NG INC126 INC126 INC126 INC126DA ORDER: 0504 INCE Entries aced fuel filte Entries Control of the control o	Ai Inspection using stern IAW 14 CF ackup batteries 0 Hour lubricatio	SIGNED: David Seastead Premier Torraft Service g DA40NG AMM as R 91.207(d) in accordance with an A	License: AP34	page 185 Fort Worth, TX 76106 Phone: 562.881.5345 Premier Aircraf 3804 Falcon Way W Hangar 185 Fort Worth, TX 76106 Phone: 562.881.5345	Work Order: 0504 Printed by EBis 3 (datcomedia.com) DATE: 3/1/2022 A/C TSN: 116.7 HOBBS: 161.4
EDA40NG INC126 INC126 INC126 INC126DA ORDER: 0504 INCE Entries aced fuel filte Entries Control of the control o	Ai Inspection using stern IAW 14 CF ackup batteries 0 Hour lubricatio	SIGNED: David Seastead Premier rcraft Service g DA40NG AMM as R 91.207(d) in accordance with an A SIGNED:	License: AP34	page 185 Fort Worth, TX 76106 Phone: 562.881.5345 Premier Aircraf 3804 Falcon Way W Hangar 185 Fort Worth, TX 76106 Phone: 562.881.5345	Work Order: 0504 Printed by EBis 3 (datcomedia.com) DATE: 3/1/2022 A/C TSN: 116.7 HOBBS: 161.4
E. DA40NG I. DA40NG INC128 IO: N226DA ORDER: 0504 Imme Entries aced fuel filte E: 1/6/2022 Diamond E: DA40NG INC128 INC1	Ai Inspection using stern IAW 14 CF ackup batteries 0 Hour lubricatio	SIGNED: David Seastead Premier rcraft Service g DA40NG AMM as R 91.207(d) in accordance with an A SIGNED:	License: AP34	page 185 Fort Worth, TX 76106 Phone: 562.881.5345 Premier Aircraf 3804 Falcon Way W Hangar 185 Fort Worth, TX 76106 Phone: 562.881.5345	Work Order: 0504 Printed by EBis 3 (datcomedia.com) DATE: 3/1/2022 A/C TSN: 116.7 HOBBS: 161.4
E. DA40NG I. DA40NG INC128 IO: N226DA ORDER: 0504 Imme Entries aced fuel filte E: 1/6/2022 Diamond E: DA40NG INC128 INC1	Ai Inspection using stern IAW 14 CF ackup batteries 0 Hour lubricatio	SIGNED: David Seastead Premier rcraft Service g DA40NG AMM as R 91.207(d) in accordance with an A SIGNED:	License: AP34	page 185 Fort Worth, TX 76106 Phone: 562.881.5345 Premier Aircraf 3804 Falcon Way W Hangar 185 Fort Worth, TX 76106 Phone: 562.881.5345	Work Order: 0504 Printed by EBis 3 (datcomedia.com) DATE: 3/1/2022 A/C TSN: 116.7 HOBBS: 161.4
L: DA40NG LNC126	Ai Inspection using stern IAW 14 CF ackup batteries 0 Hour lubricatio	SIGNED: David Seastead Premier rcraft Service g DA40NG AMM as R 91.207(d) in accordance with an A SIGNED:	License: AP34	page 185 Fort Worth, TX 76106 Phone: 562.881.5345 Premier Aircraf 3804 Falcon Way W Hangar 185 Fort Worth, TX 76106 Phone: 562.881.5345	Work Order: 0504 Printed by EBis 3 (datcomedia.com) DATE: 3/1/2022 A/C TSN: 116.7 HOBBS: 161.4
L: DA40NG L: DA40NG L: NC126 LO: N226DA ORDER: 0504 ame Entries Laced fuel filte L: 1/6/2022 Diamond L: DA40NG LNC126 L	Ai Inspection using stern IAW 14 CF ackup batteries 0 Hour lubricatio	SIGNED: David Seastead Premier rcraft Service g DA40NG AMM as R 91.207(d) in accordance with an A SIGNED:	License: AP34	page 185 Fort Worth, TX 76106 Phone: 562.881.5345 Premier Aircraf 3804 Falcon Way W Hangar 185 Fort Worth, TX 76106 Phone: 562.881.5345	Work Order: 0504 Printed by EBis 3 (datcomedia.com) DATE: 3/1/2022 A/C TSN: 116.7 HOBBS: 161.4

.

MAKE: Diamond MODEL: DA40NG S/N: 40.NC126 REG. NO: N226DA WORK ORDER: 0539



Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345 DATE: 4/20/2022 A/C TSN: 152.3 HOBBS: 215.2

Airframe Entries

· Replaced avionics switch and relay

DATE: 4/20/2022 SIGNED:	Work Order: 053 Printed by EBis 3 (datcomedia.com
David Seastead, License: AP349	4477 IA
	The state of the s