



CONTINENTAL

A E R O S P A C E T E C H N O L O G I E S

**ENGINE
LOG
BOOK**

Service Information

Consult the Continental web site at <http://www.continental.aero> for engine related news or announcements. The web site contains useful information for Continental engine owners, including service information and illustrated parts catalogs.

If Internet access is not available, contact our Customer Service Department at:
1-888-826-5465 Toll free in the United States or 1-251-436-8299 for International customers

Warranty Information

This product is covered by Continental Aerospace Technologies™ product warranty. To read or download a copy for your records, please visit the Product Warranty page on our web site at: <http://www.continental.aero/services/warranty.aspx> or scan the QR Code to the right to navigate to the page:



Instructions for Continued Airworthiness

For complete access to the engine Instructions for Continued Airworthiness, Illustrated Parts Catalogs, Service Documents, Technical Briefs, company news, and upcoming events, please take a few moments to register the serial number of your engine on our web site: <http://www.continental.aero/services/owner-registration.aspx> or scan the QR Code to the right to navigate to the page:



Engine Returns

Return engines for core credit with this log book to:
Continental Aerospace Technologies
2039 Broad Street
Mobile, AL 36615 USA

Return engines for overhaul with this log book to:
Continental Services
Factory Service Center
8600 County Road 32
Fairhope, Alabama 36532 USA

**USE ONLY FUEL SPECIFIED IN OPERATOR'S
MANUAL OR TYPE CERTIFICATE DATA SHEET
USE OF AUTOMOTIVE FUEL IS PROHIBITED**



Continental Motors

FAA PRODUCTION CERTIFICATE NO. 508

Printed:03/29/2021

Test Date03/29/2021

This engine model I0550N43B, serial number 1040348 was rebuilt by Continental Motors Inc, in accordance with approved design data and the applicable requirements of 14 CFR, Part 21 and 43 of the Federal Aviation Regulation. The approved design data for this engine incorporates all changes required by applicable Airworthiness Directives and Continental Motors Service Bulletins.


CONTINENTAL MOTORS, INC.

Form 6012-04 (Rev Sept 2014)

