

Engine Log  
Make DIAMOND  
Engine Make LYCOMING  
HOBBS 408.5

Aircraft N123TV  
Model DA40  
Engine Model IO-360-M1A

Date APR 3 2017  
S/N 40.432  
Engine S/N L-31679-51A

Performed an Annual Inspection IAW FAR Part 43 Appendix D using Diamond DA40 AMM as a guide.  
Performed compression check. Results are as follows: #1 78/80 #2 76/80 #3 74/80 #4 76/80 M/O 44/80  
Drained Oil. Removed, opened, and inspected oil filter and found no abnormalities.  
Lubricated engine controls as needed  
Installed new oil filter P/N AA48110-02. Serviced engine with 7 qts Phillips X/C 15w/50. One qt supplied to customer.  
Verified all AD's have been complied with thru APR 3 2017.  
AD compliance list is added to aircraft logs.

END

I certify that this aircraft and/or component identified above was inspected and repaired IAW current FAA regulations and determined Airworthy for return to service.

Phillip Scadden IA 400062798