

PROPELLER LOGBOOK

PROPELLER MOD	EL <u>PHC-J3YF-1N</u>	
PROPELLER S/N	FP6189B	

LOGBOOK #____

HAI	RIZELL	PROPE	LLEK IN	C Item	Number:	J3F20500			Date:	10/1/2007	
	INS	SPECTION	4865	61-2	6913	386		Work C	order #:	M604320	
Model Nu	mber PHC-J	3YF-1N/N7	•		.,,,						
Ass'y Ser FP6189		Hydr Unit NA	No.	Sulkhead No).	Valve N	o. NA				
Blade 1: A Clamp 1:	A1198 V	Blade 2: A Clamp 2:	1208	Blade 3: A1 Clamp 3:	212	Blade 4: Clamp 4:		Blade 5: Clamp 5:		Blade 6:	
Reverse	Start Lock	Low Pitch	High Pitch	Feather	Position	Orient.	Qty:Al	St	Scrw	A-2424-1	Washer
NA	NA	12.4	35.0	NA	1	L	0	2	0	0	2
Ref Radius	(inches) for	angles:	30		2	Т	1	1	0	0	3
Comments: Deice Kit:											
Packing Date: ///////D7											
nspected E	By: John Ma	artin	or this prop	eller incond	orates all c	changes requi	red by a	oplicable Ai	worthine	ess Directive	S.
The	approved de	esign data i	or trus prop	eller incope	natos an c	Jilangeo roqui					



Position	PITCH RANGE
Propeller Model PHC-J3YF-2N	High/Feather 35,0
Propeller S/NFP6/89B	Start Lock
Blade Design <u>N7605B</u>	Low17.4°
Blade S/N's	Reverse
No. 1	
No. 2 <u>A /208</u>	Aircraft Manufacturer CINERS Design
No. 3 4 1212	Aircraft Model <u>SR22</u>
No. 4	S/N2758
	Deviation NTIGED
No. 5	Registration N719ED
No. 6	Registration N FITED

Date	Pro _l TSN	peller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	.0	NA		I have Dynamically Balanced Propeller IAW Hartzell Propeller Owner's Manual 145 Rev. 4 Dated Dec. 2006 Section 61-00-45 on

IO_550_N Turl	008; Aircraft: N719ED; Type: SR2	122; S/N: 2758; Hobbs: 163.8; Total Time: 163.8; Engine - Type: .8; Prop - Type: PHC-J3YF-1N, S/N: FP6189B, Time: 163.8
Fit Hobbs: 16	3.8 Hobbs: 171.3.	
	ed an Annual inspection in accorda	ance with the Cirrus Design SR22 Inspection Form and Service
Manual. Grou	nd run for ops and leak ck good. that this propeller has been inspe	ected in accordance with an Annual inspection and was determined ———
to be in airwo	thy condition.	
A&P38976503	15 IA DOWN SAL 143891	1650JS
	in Aviation - Madison	Wisconsin Aviation - Watertown
	rben Court , WI 53704	1741 River Drive Watertown, WI 53094
608-268		920-261-4567
T 1	1 1	
		2; S/N: 2758; Hobbs: 314.5; Total Time: 314.5; Engine - Type:
I O SEONISO Turk		4.5; Prop - Type: PHC-J3YF-1N, S/N: FP6189B, Time: 314.5
Flt Hobbs: 314.5 ***Prop Work***	an Annual inspection in accords	ance with EAR 43 Annendix D
Fit Hobbs: 314.5 ***Prop Work*** Completed AD 07-26-09 (1/3		work, not pplicable by propeller blade model number.
Fit Hobbs: 314.5 ***Prop Work*** Completed AD 07-26-09 (1/3 AD 08-13-28 (7/2)	30/08) Propeller blade shank rev 17/08) Propeller hub lube hole in	work, not pplicable by propeller blade model number. nspection, not applicable by propeller model number. Prop not left
Fit Hobbs: 314.5 ***Prop Work*** Completed AD 07-26-09 (1/3 AD 08-13-28 (7/2 hand rotating. G I certify that	30/08) Propeller blade shank rev 17/08) Propeller hub lube hole in round run for ops and leak ck go this propeller has been inspect	work, not pplicable by propeller blade model number. nspection, not applicable by propeller model number. Prop not left
Fit Hobbs: 314.5 ***Prop Work*** Completed AD 07-26-09 (1/3 AD 08-13-28 (7/2 hand rotating. G I certify that be in airworthy co	30/08) Propeller blade shank rev 17/08) Propeller hub lube hole in round run for ops and leak ck go this propeller has been inspect	work, not pplicable by propeller blade model number. nspection, not applicable by propeller model number. Prop not left good.
Fit Hobbs: 314.5 ***Prop Work*** Completed AD 07-26-09 (1/3 AD 08-13-28 (7/2 hand rotating. G I certify that be in airworthy of Steven Johnson A&P 397604650	30/08) Propeller blade shank rev (7/08) Propeller hub lube hole in round run for ops and leak ck go this propeller has been inspect andition.	work, not pplicable by propeller blade model number. nspection, not applicable by propeller model number. Prop not left good.
Fit Hobbs: 314.5 ***Prop Work*** Completed AD 07-26-09 (1/3 AD 08-13-28 (7/2 hand rotating. G I certify that be in airworthy co Steven Johnson A&P 397604650 Wisconsin	30/08) Propeller blade shank rev 17/08) Propeller hub lube hole in round run for ops and leak ck go this propeller has been inspect andition. Aviation - Madison	work, not pplicable by propeller blade model number. Inspection, not applicable by propeller model number. Prop not left good. Ited in accordance with an Annual inspection and was determined to Wisconsin Aviation - Watertown
Fit Hobbs: 314.5 ***Prop Work*** Completed AD 07-26-09 (1/3 AD 08-13-28 (7/2 hand rotating. G I certify that be in airworthy co Steven Johnson A&P 397604650	30/08) Propeller blade shank rev 17/08) Propeller hub lube hole in round run for ops and leak ck go this propeller has been inspect andition. Aviation - Madison en Court	work, not pplicable by propeller blade model number. Inspection, not applicable by propeller model number. Prop not left good. Ited in accordance with an Annual inspection and was determined to

ite	F	Hobbs: 433	.5 Flight I	aft: N719ED; Type: Hobbs: 426.0	: SR22; S/N: 2758; H	obbs: 426.0; Total Time: 426.0	es, ctions.
	-	Visconsi 8606 Cor	red propelle en '8 'n Aviation ben Cou WI 537	on - Madison urt	N/N7605B s/n FP618	Wisconsin Aviation - Water 1741 River Drive Watertown, WI 53094 920-261-4567	rtown ———
1							
T							
T							
T							
+							
\dashv		1					
		+					
		6					




HARTZELL SERVICE CENTER

5465 W. St. Rt. 185

Piqua, Ohio 45356-2634 U.S.A

July 2, 2010

S/N: FP6189B TSN: 426.0 TSO: N/A




Mak Bala

Mark Baker, Repairman # 2582389 Repair Station # SJ3R843L



Date	Pro TSN	peller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directive Service Documents, Overhaul, Major or Minor Repair, and Inspec			
				719ED; Type: SR22; S/N: 2758; Hobbs: 426.0; Total Time: 426.0			
	Hobbs: 433.5 Flight Hobbs: 426.0						
		031466, dj		o/n PHC-J3Y1F-1N/N7605B, s/n FP6189B, after repair by Hartzell, CRS# SJ3R843L, //2010. Performed ground runs and operational checks - no defects noted.			
	A&P 26	36878) an fl	2636878 HAP			
	36	606 Cort	oen Cou				
		adison,)8-268-5		Watertown, WI 53094 920-261-4567			
		3					
		Ĩ					
		6					
					,		



9	Prop TSN	eller TSO	A/C Hrs			g to Airworthiness Directives, or Minor Repair, and Inspections.	
	w	Da	te: 5/31/2	012; Aircraft: N681PG; Type: 0	:IRRUS SR22; S/N: 2102; Hob	bbs: 2587.00; Total Time: 2587.00	
			Prop Wor				
				vised weight and balance dated		on N681PG. PTT: 540.8; PTSO: New. perational checks good.	
-			P 2636878	BIA () on the 2	636878IA		_
		36	606 Corl	n Aviation - Madison ben Court	17	isconsin Aviation - Watertown 741 River Drive atertown, WI 53094	_
			268-	WI 53704 5003		20-261-4567	_
		Engir 579.1 Hobb	ne - Type: 30	IO-550N42B, S/N: 1001065, Ti Flight Hobbs: 2625.5		s: 2625.50; Total Time: 2625.50; C-J3YF-1N, S/N: FP6189B, Time:	-
		Forn dete Dou	Complete n and Serv I certify the ermined to b g Seibel	d Progressive inspection Phase ice Manual. nat this propeller has been inspection.		the Cirrus Design SR22 Inspection ase III and IV inspection and was	_
		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	606 Cor	n Aviation - Madison ben Court WI 53704	Wis 174 Wa	sconsin Aviation - Watertown 41 River Drive atertown, WI 53094 D-261-4567	_

Engine - Type: IO-550N4 615.40 Hobbs: 3179.7 Flight I ***Prop Work*** Completed an Annual certify that this propelle in airworthy condition.	428, S/N: 1001065, Time: 631.80; Hobbs: 2661.6 4al inspection in accordance with F	e with an Annual inspection and was determine	ime:
☐ Wisconsin Aviati 3606 Corben Co Madison, WI 53 608-268-5003	on - Madison ourt	Wisconsin Aviation - Windows 1741 River Drive Watertown, WI 53094 920-261-4567	atertown _ -
Engine - Type: IO-550N- 653.70 Hobbs: 3229.2 Flight: ***Prop Work*** Completed a Phase	Hobbs: 2699.9 se 1 inspection in accordance with propeller has been inspected in accordance with condition. A B B B B B B B B B B B B B B B B B B	S/N: 2102; Hobbs: 2699.90; Total Time: 26; Prop - Type: PHC-J3YF-1N, S/N: FP6189B; Cirrus 400 hour Progressive inspection Proceedance with a Phase 1 inspection and ward Wisconsin Aviation - Watertown, WI 53094 920-261-4567	gram —

Date: 5/24/2013; Aircraft: N681PG; Type: CIRRUS SR22; S/N: 2102; Hobbs: 2732.20; Total Time: 2732.20; Engine - Type: IO-550N42B, S/N: 1001065, Time: 702.40; Prop - Type: PHC-J3YF-1N, S/N: FP6189B, Time: 686.00 Hobbs: 3271.1 Flight Hobbs: 2732.2 ons. ** Prop Work *** Completed a Phase 2 & 3 inspection in accordance with Cirrus Design 400 Hr Progressive Inspection Program. I certify that this propeller has been inspected in accordance with a Phase 2 & 3 inspection and was determined to be in airworthy condition. **Bobby Wangler** A&P 2702325 IA Wisconsin Aviation - Watertown Wisconsin Aviation - Madison 1741 River Drive 3606 Corben Court Watertown, WI 53094 Madison, WI 53704 920-261-4567 608-268-5003 Date: 9/06/2013; Aircraft: N681PG; Type: CIRRUS SR22; S/N: 2102; Hobbs: 2774.60; Total Time: 2774.60; Engine - Type: IO-550N42B, S/N: 1001065, Time: 744.80; Prop - Type: PHC-J3YF-1N, S/N: FP6189B, Time: Hobbs: 3323.1 Flight Hobbs: 2774.6 ***Prop Work*** Completed an Annual inspection in accordance with FAR 43, Appendix D. I certify that this propeller has been inspected in accordance with an Annual inspection and was determined to Bolly dangles AP270252A be in airworthy condition. **Bobby Wangler** A&P 2702325 IA Wisconsin Aviation - Madison 1741 River Drive 3606 Corben Court Watertown, WI 53094 Madison, WI 53704 608-268-5003 920-261-4567

Date: 10/01/2014; Aircraft: N681PG; Type: CIRRUS SR22; Engine - Type: IO-550N42B, S/N: 1001065, Time: 850.50; F834.10 Hobbs: 3458.4 Flight Hobbs: 2880.3 ***Prop Work*** Completed an Annual inspection in accordance with F/I certify that this propeller has been inspected in accordance be in airworthy condition. Dan Stammen A&P 2636878 IA	Prop - Type: PHC-J3YF-1N, S/N: FP6189B, Time: AR 43, Appendix D. e with an Annual inspection and was determined to	
Wisconsin Aviation - Madison 3606 Corben Court Madison, WI 53704 608-268-5003	Wisconsin Aviation - Watertown 1741 River Drive Watertown, WI 53094 920-261-4567	•
Date: 11/01/2015; Aircraft: N681PG; Type: CIRRUS SR22; S. Engine - Type: IO-550N42B, S/N: 1001065, Time: 920.40; Pr 904.00 Flight Hobbs: 2950.2 Hobbs: 3545.2 ****Propeller Work*** Completed an Annual inspection in accordance with FAR been inspected in accordance with an Annual inspection and Benjamin J. Pitterle A&P390747277 IA	op - Type: PHC-J3YF-1N, S/N: FP6189B, Time: 43, Appendix D. I certify that this propeller has	
Wisconsin Aviation - Madison 3606 Corben Court Madison, WI 53704 608-268-5003	Wisconsin Aviation - Watertown 1741 River Drive Watertown, WI 53094 920-261-4567	•

M. S.

P.

Date	Propel TSN	ler TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directive Service Documents, Overhaul, Major or Minor Repair, and Inspec		
	Date: 1/20/2017; Aircraft: N681PG; Type: CIRRUS SR22; S/N: 2102; Hobbs: 3028.50; Total Time: 3028.50; Engine - Type: IO-550N42B, S/N: 1001065, Time: 998.70; Prop - Type: PHC-J3YF-1N, S/N: FP6189B, Time: 982.30 ***Propeller Work*** Completed an Annual inspection in accordance with FAR 43, Appendix D. I certify that this propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition. Doug Seibel A&P389765035 IA					
	3	3606 C Madisc	nsin Avia Forben (on, WI 5 8-5003	53704 Watertown, WI 53094		
		·				

February 21, 2018

N681PG

CIRRUS SR22

S/N 2102

FLIGHT 3111.9 Hrs

Hobbs 3758.9 Hrs

Continental

IO550N42B

S/N 1001065

FLIGHT 3111.9 Hrs

TTE 1372.1 Hrs

Hartzell

PHC-J3YF-1N

S/N FP6189B

FLIGHT 3111.9 Hrs

Hobbs 3758.9 Hrs

Removed spinner. Inspected hub for cracks; no deficiency noted. Lubricated propeller hub with grease. Checked blades for free play; found satisfactory. Painted blade face as needed. Dressed leading edges.

Reinstalled spinner. (Refer to Job #681PG1for details.)

THIS AIRCRAFT ENGINE/PROPELLER COMBINATION WAS INSPECTED AND/OR WAS

REPAIRED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FAA FOR AN ANNUAL

RETURN TO SERVICE **INSPECTION** AND IS APPROVED F FED

JIM BARKER A&P/IA 2755069

Hangar (715) 822 5787

Cell (715) 491 1303

Email jim@aviationvibes.com

AVIATION RESOURCES, LLC A&P

401 Airport Ave, Hangar #7 Jumberland, WI 54829

www.aviationvibes.com

PROP MODEL: PHC-J3YF-1N PROP S/N: FP6189B REG. NO: N681PG WORK ORDER: 4808-04-2019



Classic Aviation, Inc.

2755069

501 W 15th St Pella, IA 50219 Phone: 641-628-9393

DATE: 5/24/2019 A/C TSN: 3190.8 PROP TT: 1813.2 HOBBS: 3190.8

Prop Entries

(3) Annual Inspection. Filed and dressed blades of propeller. Lubricated propeller hub with Aeroshell 6. Checked all applicable ADs and updated list in aircraft records.

I certify that this propeller has been inspected in accordance nual inspection and was determined to be in airworthy condition.

DATE: 5/24/2019

SIGNED: Wm. Haven Hick, IA: 3428785 Work Order: 4808-04-2019

Printed by EBis 3 (datcomedia.com)