



*The Standard*

**PROPELLER LOG**

ASA-SP-L

**Propeller Record** General Information

**Propeller Manufacturer** HARTZELL

**Model** PHC-53XF1RF **Type** \_\_\_\_\_

**Hub Series #** FP1609B **Blade #** \_\_\_\_\_

**Date of Manufacture** \_\_\_\_\_

**Aircraft Installed On:** S122

**Serial #** 0285



HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: <u>2017</u>	Total Time in Service	Description: <u>INSTALLED THIS PROPELLER ON N874CD.</u>
Date: <u>09/09</u>	<u>UNKNOWN</u>	<u>OVERHAUL BY PALM BEACH #10 PROPELLER</u>
Next Inspection Due:	Time Since Overhaul	<u>561.965. PROP.</u>
	<u>2.3</u>	Mech. Cert. # or Repair Station # <u>CESQW2ET4TK KDF Kowfish</u>

Year: Jonathan Bogan

Date:



Next I Due:

N874CD

Propeller Hartzell PHC-J3YF-1RF

S/N:FP1609B

12/30/2019

Hobbs Time:708.3

Prop TT:93.9

321 W. 6<sup>th</sup> Ave.  
Bristow, OK. 74010  
(918)760-8050

Year:

I certify that this propeller has been inspected in accordance with the applicable criteria in FAR Part 43 Appendix D and was determined to be in airworthy condition.

Date:

Next I Due:

Jonathan Bogan A&P3162931 IA