





PROPELLER LOGBOOK

PROPELLER MODEL PK-J34F-18F1F7693DFB

PROPELLER S/N FP4346B

LOGBOOK #____








Position	PITCH RANGE
Propeller Model <u>PHC-J34F-IRF IFF IGF3 DFR</u>	High/Feather
Propeller S/N FP 4346B	Start Lock
Blade Design	Low
Blade S/N's	Reverse
No. 1 _ K 37065	
No. 2 K 32071	Aircraft Manufacturer
No. 3 K 32061	Aircraft Model SR22
No. 4	S/N
No. 5	Registration
No. 6	
Spinner Assembly Part No	

Date	Pro TSN	peller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
1906	4	NIA	.1	
				I have Dynamically Balanced Propeller IAW Hartzell Propeller Overest's Manual 115N Bay 11 dated Day 104
				Propeller Owner's Manual 115N Rev. 11 dated Dec/04 Section: 61-00-15 on (DATE).
			m2	
a= .	我 2007	31. 9		And are 3.50 , 13.00 gram(s).
	N .30	231		MFG 218 (Sign/Stamp)
				Cirrus Design Corporation, PC 338CE
_ D	assic Avia ate: obbs Tir otal Tim	ne:	03-10- 255.6 255.6	A ' 0 C 1 No 1001
A	Annual In	spection.	Inspecte aft record	ed blades, track, hub and spinner. Lubed hub. Checked all applicable AD's and ds. I certify that this propeller has been inspected in accordance with an annual ed to be in an airworthy condition. Doug Cash A&P 484960270 IA


A STATE OF THE PARTY OF THE PAR

Classic Aviation, Inc.	501 West 15 th Street, Pella	a, IA 50219	
Date: Flight Hobbs Time: Total Time:	04-07-2008 370.6 370.6	Logbook Entry for: Aircraft Serial Number:	N981DB 1801
list in aircraft records	in an airporthy condition. Doug Cash A&F	er has been inspected in accorda P 3268592 IA	ked all applicable AD's and updated ance with an annual inspection and
Classic Aviation, Inc.	501 West 15th Street, Pel	la, IA 50219	
Date: Flight Hobbs Time: Total Time:	02-17-2009 459.8 459.8	Logbook Entry for: Aircraft Serial Number:	N981DB 1801
list in aircraft record	Inspected blades, track, his. I certify that this propele in an airworthy condition Doug Cash A&	ner nas deen mspected in decer-	cked all applicable AD's and updated lance with an annual inspection and

ate	Propallar	A/0	December 1 11	
	PROP MODEL: PROP S/N: REG. NO: 981DB WORK ORDER: 0354-12-2009		Classic Aviation, Inc. 501 W 15th St Pella, IA 50219 Phone: 641-628-9393	DATE: 1/15/2010 2 A/C TSN: 512 PROP TT: 512 - HOBBS: 512
+	Prop Entries (3) Annual Inspectupdated list in air	ction. Filed craft records	and dressed blades of propeller, labed propeller hab Checkers.	ed all applicable AD's on propeller and
+	I certify that this pro	peller has bee	en inspected in accordance with an annual inspection and was determined	ned to be in airworthy condition.
	DATE: 1/15/2010		SIGNED: Kexell and	Work Order: 0354-12-2009
			Doug Cash, IA: 3268592	Printed by EBis 3 (datcomedia.com)
t	-1			
		2		
+				
٠.				
	1			
+-				
		, ,		
\top		9		ì



e	Prop TSN	eller TSO	A/C Hrs	S	Description of all oper Service Documents, O	rations pertaining to Airworthi verhaul, Major or Minor Repa	ness ir, a
			F	LIGHTL ORW	EVEL OOD Propeller 1	Log Entry	
			e: Duggan	& Associates,	Tail # N981DB	T.T. 766.2	
		W.O.:	: 6934		Serial #: FP4346B	Hobbs 766.2	
r	, , , , , , , , , , , , , , , , , , ,		09-17-201		Model # PHC-J3YF-1BF	Prop. T.T. 766.2 V Cirrus SR22 MM & MM	
		s 5 8 4	ny at this	Flightle	Stevel Norwood Aircraft M Road, Norwood MA 0206	even Wolff A&P 16629146 aintenance 52 781-769-8686	-2 44
	_	_					



í	h	1	3	b
ļ	J	Š	2	į

DOUGLAS DUNCAN AVIATION LLC 100 TOWER DR, HGR 6 GREENVILLE, SC 29607 LOG ID# 8445 02-December-2011 WO# 5425 REF# 5425 AC TT 1034.3 HOBBS 1034.3 N981DB S/N 1801 CIRRUS SR22 Pg 1/1 TSN 1034.3 TSO 1034.3 PROPELLER *COMPLETED ANNUAL INSPECTION AND LUBRICATION IAW FAR 91.409, FAR 43 APPENDIX D, AND CIRRUS SR22 MM 5-00. ALL AD'S AND SB'S RESEARCHED THROUGH CURRENT ATP REVISION 11/28/11. NEXT ANNUAL INSPECTION DUE I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. THE AIRCRAFT, ENGINE, COMPONENT, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION AGENCY REGULATIONS AND IS HEREBY APPROVED FOR RETURN TO SERVICE WITH REGARDS TO MAINTENANCE PERFORMED. DOUGLAS DUNCAN A&P/IA 3384163 DOUGLAS DUNCAN AVIATION LLC 100 TOWER DR, HGR 6 GREENVILLE, SC 29607 LOG ID# 8490 27-January-2012 WO# 5462 REF# 5462 AC TT 1050.3 HOBBS 1050.3 Pa 1/1 CIRRUS SR22 N981DB S/N 1801 TSN 1050.3 TSO 1050.3 THE AIRCRAFT, ENGINE, COMPONENT, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED IN ACCORDANCE

PROPELLER *REMOVED PROPELLER GOVERNOR, P/N C290D3R/T23, S/N 051482, FOR OVERHAUL, AND INSTALLED OVERHAULED GOVERNOR, S/N 030064, WITH NEW GASKET, IAW CIRRUS SR22 MM 61-20. OPS/LEAK CHECK: GOOD.

WITH CURRENT FEDERAL AVIATION AGENCY REGULATIONS AND IS HEREBY APPROVED FOR RETURN TO SERVICE WITH REGARDS TO MAINTENANCE PERFORMED.

DOUGLAS DUNCAN

A&P/IA 3384163



DOUGLAS DUNCAN AVIATION LLC 100 TOWER DR, HGR 6 GREENVILLE, SC 29607 LOG ID# 8891 19-December-2012 WO# 5687 REF# 5687 AC TT 1140.1 HOBBS 1140.1 N14MK S/N 1801 CIRRUS SR22 FHM 1140.1 TSN 1140.1 TSO 1140.1

Pg 1/1

PROPELLER *COMPLETED ANNUAL INSPECTION IAW FAR 91.409, FAR 43 APPENDIX D, AND CIRRUS SR22 MM 5-00. ALL AD'S AND SB'S RESEARCHED THROUGH CURRENT ATP REVISION 12/17/12. NEXT ANNUAL INSPECTION DUE 12/31/2013.

I CERTIFY THAT THIS AIRCRAFT, ENGINE, OR PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.
THE AIRCRAFT, ENGINE, COMPONENT, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION AGENCY REGULATIONS AND IS HEREBY APPROVED FOR RETURN TO SERVICE WITH REGARDS TO MAINTENANCE PERFORMED.

DOUGLAS DUNCAN

A&P/IA 3384163

DATE

DOUGLAS DUNCAN AVIATION LLC 100 TOWER DR, HGR 6 GREENVILLE, SC 29607 LOG ID# 9310 27-November-2013 WO# 5907 REF# 5907 AC TT 1258.7 HOBBS 1258.7 N14MK S/N 1801 CIRRUS SR22

Pg 1/1

FHM 1258.7 TSN 1258.7 TSO 1258.7

PROPELLER *COMPLETED ANNUAL INSPECTION IAW FAR 91.409, FAR 43 APPENDIX D, AND CIRRUS SR22 MM 5-00. ALL AD'S AND SB'S RESEARCHED THROUGH CURRENT ATP REVISION 11/15/2013. NEXT ANNUAL INSPECTION DUE 11/2014.

I CERTIFY THAT THIS AIRCRAFT, ENGINE, OR PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

THE AIRCRAFT, ENGINE, COMPONENT, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION AGENCY REGULATIONS AND IS HEREBY APPROVED FOR RETURN TO SERVICE WITH REGARDS TO MAINTENANCE PERFORMED.

DOUGLAS DUNCAN

A&P/IA 3384163

DATE

8/25/11	1200-	1300 Para 1 0 0 11 11 11	ons.
725/14	1350.5	Sensenich Propeller Service, Inc. 1142 Aviation Boulevard Gainesville, Ga. 30501 Phone (770)538-0444 Fax (770)538-0117 www.sensenichpropellers.com 24 Sep 2014 Propeller Model: PHC-J3YF-1RF/F7693DFB Blade S/N's: K32065 K32071 K32061	str!ke
		Blade Angles: Low: 13.9 Propeller TSN: 1350.5 Propeller TSO: -0- Disassemble, Service, Zyglo, Magnaflux, Assemble, Set Angles, Cl., 1, T., 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,	
		Balanced - Overhaul. All Work Done In Accordance With Hartzell Specifications. Daniel Landis Repair Station S46R346N	

PROPELLER PN:PHC GOVERNOR PN:C290	EMOVED PROPELLER AND GOVERNOR FOR LIGHTENING STRIKE INSPECTION PERFORMED BY SENSE INSTALLED SAME PROPPELLER, GOVERNOR AND GROUND RUN AND ADJUSTED AS NEEDED. OPELLER PN:PHC-J3YF-1RF,SN: FP4346B VERNOR PN:C290D3R/T23 SN: 030064 OPELLER NEXT OVERHAUL DUE ACTT 3750.5 E AIRCRAFT, ENGINE, COMPONENT, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIR THE CURRENT FEDERAL AVIATION AGENCY REGULATIONS AND IS HEREBY APPROVED FOR RETURN GARDS TO MAINTENANCE PERFORMED. OF A STATE OF THE COMPONENT OF THE C	SENICH PROPELLER,		
WITH CURRENT FEDI REGARDS TO MAINTE	ER NEXT OVERHAUL DUE ACTT 3750.5 CRAFT, ENGINE, COMPONENT, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED REPORTED FOR RETURN TO MAINTENANCE PERFORMED.	AIRED IN ACCORDANCE UN TO SERVICE WITH		
DOUGLAS DUNCAN	UGLAS DUNCAN AVIATION LLC 100 TOWER DR, HGR 6 GREENVII			
OG ID# 10014 09 14MK S/N 1801	i-October-2015 WO CIRRUS SR22	# 6265 REF# 6265 2		3.4 Pg 1 / 1
OPELLER OMPLETED ANNUAL I O SB'S RESEARCHEI	DUNCAN AVIATION LLC 100 TOWER DR, HGR 6 GREENVILLE, SC 29607 014 05-October-2015 WO# 6265 REF# 6265 AC TT 1423.4 HOBBS 1423.4 S/N 1801 CIRRUS SR22	M 5-00. ALL AD'S ON DUE 10/2016.		
E AIRCRAFT, ENGING TH CURRENT FEDERA CARDS TO MAINTENA	L AVIATION AGENCY R	LLER OR APPLIANCE I EGULATIONS AND IS F	DENTIFIED ABOVE WAS REPARENCE EREBY APPROVED FOR RETURE	IRED IN ACCORDANCE N TO SERVICE WITH
0,0,0	32878	11-5-15		

ate	Prop TSN	eller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
				RainAir Aircraft Services, LLC
				Located at the Albertville Airport, Albertville, AL 35950
				Ph.# (256) 660-1311
				Propeller Log Entry
1				N14MK
	Performance A.D.'s according to ser	eference s checked dance wit vice. 11/03/20	Inspected for compath an Annual 16 Signa	ection in accordance with FAR 43 Appd. D, using Cirrus SR22 Scheduled Inspection Report, chapter 05-20, ed and lubed hub. Inspected spinner and back plate and dressed minor nicks in blades, as needed. All pliance thru T Data revision# 2016-22, dated 10/31/2016. I certify this Propeller has been inspected in inspection and was found to be in an Airworthy condition at this time. Propeller approved for return Michael R. Manderson
				•
+		V 200		







RainAir Aircraft Services, LLC Located at the Albertville Airport, Albertville, AL 35950

Ph.# (256) 660-1311

Propeller Log Entry

N14MK


01/11/18 W/O# 1625 Hartzell Model: PHC-J3YF-1RF S/N#: FP4346B Hobbs: 1451.3 TTP: 1451.3 SPOH: 100.8 Performed Annual inspection I/A/W FAR 43 Appendix D, using Cirrus SR22 Scheduled Inspection Report, chapter 05-20 as a reference. Cleaned and inspected blades, hub, spinner and backing plate, dressed minor nicks in blades. Performed dynamic balance on propeller using Dynamic Solutions Systems, Inc. MicroVib II unit. Found an initial vibration level of .446 IPS, installed 15.3 gr. @ 270° and 8.3 gr. @ 295° from index, resulting in a vibration level of .076 IPS. All A.D's checked for compliance thru T-data revision 2017-26, dated 12/25/2017. I certify that this Propeller has been inspected in accordance with an Annual Inspection and was found to be in an Airworthy condition at this time. Propeller approved for return to service.

Michael R. Manderson

Date	: 01/11/20	18 Signat	ture: Milye R Mandyson Certificate #: A&P 3450465 I.A.
		28.5	

reference. Cleaned and inscompliance thru T-data revant Annual Inspection and warden Date: 02/08/2019 Signatur	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.	Deller A/C TSO Hrs
Performed Annual inspecting reference. Cleaned and inspection compliance thru T-data revian Annual Inspection and when the Date: 02/08/2019 Signature.		
Performed Annual inspecting reference. Cleaned and inspection compliance thru T-data revian Annual Inspection and when the Date: 02/08/2019 Signature.	RainAir Aircraft Services, LLC	
Performed Annual inspecting reference. Cleaned and inspection compliance thru T-data revian Annual Inspection and when the Date: 02/08/2019 Signature.	Located at the Albertville Airport, Albertville, AL 35950	
Performed Annual inspecting reference. Cleaned and inspection compliance thru T-data revian Annual Inspection and when the Date: 02/08/2019 Signature.	Ph.# (256) 660-1311	
Performed Annual inspecting reference. Cleaned and inspection compliance thru T-data revian Annual Inspection and when the Date: 02/08/2019 Signature.	Propeller Log Entry	
	Hartzell Model: PHC-J3YF-1RF S/N#: FP4346B Hobbs: 1489.6 TTP: 1489.6 SPOH: 139.1 ection I/A/W FAR 43 Appendix D; using Cirrus SR22 Scheduled Inspection Report, chapter 25-20 as a linspected blades, hub, spinner and backing plate, dressed minor nicks in blades. All A.D's checked for revision 2019-03, dated 02/04/2019. I certify that this Propeller has been inspected in accordance with it was found to be in an Airworthy condition at this time. Propeller approved for return to service. Mark Sutton Certificate #: A&P 548046776 I.A.	rence. Cleaned and pliance thru T-data in nual Inspection and 02/08/2019 Signa
	·	0

The state of the s



RainAir Aircraft Services, LLC Located at the Albertville Airport, Albertville, AL 35950 Ph.# (256) 660-1311 Propeller Log Entry

N14MK

O2/08/20 W/O# 1814 Hartzell Model: PHC-J3YF-1RF S/N#: FP4346B Hobbs: 1496.4 TTP: 1496.4 SPOH: 145.9 Performed Annual inspection I/A/W FAR 43 Appendix D, using Cirrus SR22 Scheduled Inspection Report, chapter 05-20 as a reference. Cleaned and inspected blades, hub, spinner and backing plate, dressed minor nicks in blades. All A.D's checked for compliance thru T-data revision 2020-03, dated 02/03/2020. I certify that this Propeiler has been inspected in accordance with an Annual Inspection and was found to be in an Airworthy condition at this time. Propeiler approved for return to service.

Michael R. Manderson

Date: 02/08/2020 Signature: Mills R Mandie Certificate #: A&P 3450465 I.A.

Propeller A/C
TSN TSO Hrs

Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.

RainAir Aircraft Services, £LC
Located at the Albertville Airport, Albertville, AL 35950
Ph.# (256) 660-1311
Propeller Log Entry

N14MK

O3/22/21 W/O# 1931 Hartzell Model: PHC-J3YF-1RF S/N#: FP4346B Hobbs: 1501.8 TTP: 1501.8 SPOH: 151.3 Performed Annual inspection I/A/W FAR 43 Appendix D, using Cirrus SR22 Scheduleu inspection Report, chapter 05-20 as a reference. Cleaned and inspected blades, hub, spinner and backing plate: dressed minor nicks in blades. All A.D's checked for compliance thru T-data revision 2021-06, dated 03/15/2021. I certify that this Propeller has been inspected in accordance with an Annual Inspection and was found to be in an Airworthy condition at this time. Propeller approved for return to service.

Date: 03/22/2021 Signature:

Certificate #: A&P 548046776 I.A.

A CONTRACTOR OF THE PROPERTY O