

# mt-propeller

*The Winner's Propeller*

## PROPELLER LOGBOOK

EASA DE.21G.0008 / EASA.21J.020

# MT-Propeller Warranty Policy

Dear Customer,

Congratulations on the purchase of your new MT-Propeller. Engineered with the customer in mind, it is designed to provide years of reliable and trouble-free service.

Scheduled maintenance or servicing of your MT-propeller should be accomplished at your nearest **MT-Propeller Approved Service Station**.



For location of the MT-Propeller Approved Service Station nearest you, please call us and ask for Produkt Support.

---

## **NOTE**


Having work performed at a facility other than a MT-Propeller Approved Service Station may void your warranty.

# MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
Jul 16 2019	∞:00	/	Manufactured	
6-4-2021	Hdds: 2689.9		Installed this propeller on N234PD.	
			Torqued mount nuts to proper spec.	
			Aircraft approved for return to service	
				AP543250162IA

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

# MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
	N234PD	Make: MT	Model: MTV-9-D/198-52 S/N: 190680	
	Hobbs: 2855.0		Date: 3-17-2022	
	Complied with annual inspection. inspected hub and blades for condition.			
	Checked all AD's through bi-weekly 2022-05. I certify this Propeller has			
	been inspected in accordance with an Annual Inspection and was			
	determined to be in airworthy condition.			
	Geoffrey J. Carson			AP543250162 IA
NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12				

N234PD SR22 S/n 1167 4/11/2023 Hobbs/AFTT: 3012.6  
Engine Continental IO-550-N(41B) S/n 1040344 TSN: 322.7  
Propeller MT MTV-9 S/n 190680 TSN: 322.7

**Propeller Log** Complied with an Annual Inspection in accordance with FAR 43 Appendix D

All applicable AD's checked and complied with through this date

Performed ground run, operation/leak checks good

I certify that this Propeller has been inspected in accordance with a 100HR/Annual Inspection and was determined to be in an Airworthy Condition

Ronald Laskey AF31442061A

Key West Aircraft Maintenance



res  
tion  
rs

Dat				res tion rs

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

**MT-Propeller USA, Inc. 1180 Airport Terminal Drive, DeLand, FL 32724**

**FAA Approved Repair Station Q4MR908Y**

**Phone: (386) 736-7762 Fax: (386) 736-7696 E-mail: info@mt-propellerusa.com**

**Aircraft Model: Cirrus SR22 N234PD S/N: 1167 Hobbs: 3104.7**

**Propeller Model: MTV-9-D/198-52**

**S/N: 190680**

**Propeller TSN: 414.8 Hrs**

Removed propeller from aircraft for repair. Repaired and resealed propeller in accordance with W/O: 24-150MT and overhaul manual E-220Rev69.

Blade SN: 1) AKD-75829 2) AKD-75830 3) AKD-75831

Installed propeller on aircraft in accordance with operations and installation manual E-124, revision 72.

Ground run, operational check and leak check satisfactory.

Year of manufacture: 2019


I certify this propeller has been repaired and inspected, and determined to be in airworthy condition at this time. Return to service this date, March 5, 2024

**Peter Marshall, Chief Inspector Q4MR908Y**




# MAINTENANCE

N234PD SR22 S/n: 1167 4/4/2024 Hobbs/AFTT: 3114.3  
Engine: Continental IO-550-N(41B) S/n: 1040344 TSN: 424.4  
Propeller: MT MTV-9 S/n: 190680 TSN: 424.4

**Propeller Log:** Complied with an Annual Inspection in accordance with FAR 43 Appendix D.  
All applicable AD's checked and complied with through this date.  
Performed ground run, operation/leak checks good.  
I certify that this Propeller has been inspected in accordance with an 100HR/Annual Inspection and was determined to be in an Airworthy Condition.  
Ronald Laskey AP3144206IA  
Key West Aircraft Maintenance 

N234PD SR22 S/n: 1167 5/7/2025 Hourmeter/AFTT: 3275.8  
Engine: Continental IO-550-N(41B) S/n: 1040344 TSN: 585.9  
Propeller: MT MTV-9 S/n: 190680 TSN: 585.9

**Propeller Log:** Complied with an Annual Inspection in accordance with FAR 43 Appendix D.  
All applicable AD's checked and complied with through this date.  
-Performed ground run, operation/leak checks good.  
I certify that this Propeller has been inspected in accordance with a 100HR/Annual Inspection and was determined to be in an Airworthy Condition.  
Ronald Laskey AP3144206IA  
Key West Aircraft Maintenance 

Dat

NC

res  
ion  
's

12

N234PD SR22 S/n: 1167 3/15/2026 Hourmeter/AFTT: 3306.8

Engine: Continental IO-550-N(41B) S/n: 1040344 TSN: 616.9

Propeller: MT MTV-9 S/n: 190680 TSN: 616.9

**Propeller Log:** Complied with an Annual Inspection in accordance with FAR 43 Appendix D.

All applicable AD's checked and complied with through this date.

-Performed ground run, operation/leak checks good.

I certify that this Propeller has been inspected in accordance with a 100Hour/Annual Inspection and was determined to be in an Airworthy Condition.

Ronald Laskey AP3144206IA

Key West Aircraft Maintenance




NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12