



**3861 Co. Rd. 140
Findlay, Ohio 45840
1-800-553-7767
Fax 419-299-3244**

Propeller Log Book

Owner Name Mike Weber

Address 212 Wall Street

Port Jefferson, Ohio 45360

Propeller Make McCauley

Propeller Model 1C172/EM7653

Blade Model —

Hub Serial No. E4049

Blade Serial No. 1 —

2 —

3 —

4 —

PITCH RANGE

High — Low —

Feather — Reverse —

Maximum Hours or Service Life between overhaul required by Mfg. — Hrs. or —

years interval between overhauls. At Engine Overhaul

SERVICEABLE

Propeller
UNIT

McCawley
MAKE

IC172/EM7653
MODEL

E4049
SERIAL NUMBER

The component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.

Pertinent details of the repair are on file at this repair station under:

OWNER Mike Weber

WORK ORDER NO. 12420

DATE 09/17-95

[Signature]
SIGNED FOR

Priebe Propeller and Avionics, Inc.
3861 County Road 140
Findlay, Ohio 45840
419-299-3562
800-553-7767
FAX 419-299-3244

F.A.A. Repair Station Number IC5R930M

Work Performed by Priebe Propeller and Avionics, Inc. Repair Station #IC5R930M. Work Order/Invoice # 12420

Signature

[Signature]

Blade #1 _____

Ser. No. _____

Blade #2 _____

Ser. No. _____

Blade #3 _____

Ser. No. _____

Blade #4 _____

Ser. No. _____

~~Overhaul~~

~~Repair~~

Recond.

~~A.D. Only~~

Service Letters

83-7, 83-8, 83-8-1 CW

Service Bulletins

137F, 195 CW

Date CR 45

Date 08-17-95

Propeller Total Time 976.0

Tach/Hobbs Time 976.0

Propeller Time Since Overhaul 0.0

Completely Recondition Propeller In Accordance
With McCauley Service Manual 730720. Comply
With Service Letters - 83-7, 83-8, 83-8-1 And Service
Bulletins - 137F, 195.

Work Performed By Priebe Propeller Shop, Inc. Repair
Station #IC5R930M. Work Order/Invoice # 12420

Signature

 End.

