



**H and H PROPELLER
SERVICE, INC.**

FAA -PS4R451M

**Burlington - Alamance Regional Airport
Burlington, NC 27215**

**Propeller Logbook
(336) 227-1467
1-800-334-6437**

SERVICEABLE PART

MANUFACTURER *Hartzell*
PART NAME *Dove*
MODEL *F-4-21*
PART NO. _____
SERIAL NO. *D185511J*
REMARKS: *Overhauled, C/W SB 148, 176, 57, 61-61, 129 bench checked and listed*

ACCOMPLISHED BY *Mark Blanchard*

THE AIRCRAFT PROPELLER OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER:

Order No. *715759* Date *Sept 07*
Signed *Joe Long*
Signature of Authorized Representative

FOR: **H & H PROPELLER SERVICE**
Burlington Municipal Airport
Burlington, NC 27215

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
6 Sept 07		Overhauled propeller m/w HC-F2YR-1RF	
		s/w CM 793, c/w SB 118F, 136E, SL 61-61R1	
		223, 217, 229, 117, 154, 5I 152A, AD(02-09-08)	
		Greased painted and balanced by	
		H & H Propeller Service	<i>Elmer Munder</i>
		WO# 15759.	<i>Prothman fac camp</i>
		H & H PROPELLER SERVICE, INC.	
		8439 SOUTH AVIATION DRIVE	
		BURLINGTON MUNICIPAL AIRPORT	
		BURLINGTON, N. C. 27215	
		FAA REPAIR STATION PS4B451M	
		1-800-334-6437	

SERVICEABLE PART

MANUFACTURER Hartzel
 PART NAME Propeller
 MODEL HC-F24K-1RF
 PART NO. CP1793
 SERIAL NO. C/W5B 118F
 REMARKS: Overhauled, C/W5B 118F
136I, SL61-61R1, 223, 217
229, 117, 154, SL152A, AD
Note (92-09-08) cleared & granted
and balanced Bldg # F8468A-4R
#1) F25076 #2) F25061


ACCOMPLISHED BY Bob Evans

THE AIRCRAFT PROPELLER OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER:

Order No. 715789 Date Sept 10 07
 Signed William Leo Long
 Signature of Authorized Representative

FOR: **H & H PROPELLER SERVICE**
 Burlington Municipal Airport
 Burlington, NC 27215

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		 <p>FULL-SERVICE FBO • AIRCRAFT LEASING • MANAGEMENT</p> <p>Reg :N4311W Tach: 3070.8 Smoh: 0.0</p> <p>Prop: Hartzell Model: HC-F2YR-1RF S/N: CM-793</p> <ol style="list-style-type: none"> 1) Aircraft propeller Re-Installed after Major Overhaul by H&H Propeller Service(Reference H&H W/O No. 715759). 2) Re-Installed Prop Governor after ovhl.(Reference H&H W/O No. 715759). 3) I certify that this aircraft propeller has been inspected in accordance with an annual/100hr inspection and was determined to -be in airworthy condition. Approved for return to service. 	
		<p><i>Rick Gardner</i> 9/20/2007 Rick Gardner A&P 3146802 I/A</p>	

