

# PROPELLER MAINTENANCE RECORD

AIRCRAFT SERIAL AND REGISTRATION	17280015 70E/SFA7658	N 364ES TL:005
PROPELLER MODEL AND SERIAL	235/LFA 7570	06020
HUB SERIAL Wa BLADE SERIALS	; wa,	
7551Q-1-13		•

		16	MAINTENANCE RECORD	
DATE 19 <u>97</u>	TOTAL IN SERV		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
1497	5	6	Propeller SN QG020 has been installed on engine SN L-26918-51A on aircroft 17280015.	
			N# 364ES Hobbs 80.3 Date 6-26-97  Propeller Log  Midwest Corporate Aviation. Propeller TT: 80.3 Airframe TT: 80.3	
		100 m	Completed Annual inspection by complying with items A, B, C, D, E, F, and L in accordance with Cessna 172R Maintenance Manual.  All ADs were checked through this date, see compliance record and recurring sheets. I certify that this Propeller was inspected in accordance with Annual inspection and was determined to be in an airworthy condition.  Pertinent details of the maintenance are on file at this repair station under W/O 18511.  for Midwest Corporate Aviation CRS BVYR-657C.	

TOTAL IN SER		Fanta Av	iation, Inc.	12.11	Prop		ified Repair	r Station FEH	R859D	RIZED SIGI
HOURS	10ths	Eddie us	idilon, The			THE WAT			E	& NUMBE
		Customer Shop Wor 25	Name: Flight rk Order 77886	Reg. No.	Maint Rese Make CESSNA	rve Model 172	Serial 80015	Tach Time 195.50	Closed	
		OPR	Descri	100 (00 (000)	10.00				age 1	
		11	COMPLIED WITH #2-77/80, #3	H 100 H -78/80,	DUR/ANNUAL \$4-77/80	INSPECTION	. COMPRESS	SION CHECK:#1	-77/80,	-
		98	THE AIRCRAFT ABOVE WAS RE	PATRETI A	AME, AIRCE	CTETL IN ACC	, PROPELLER ORDANCE WITH	H LUKKENI FEI	EKHL	D
			AVIATION REGI DETAILS OF TI #77886	IN ATTOM	E AND TO A	SPPROUFN FOI	R RETURN TO	SERVICE. PI	KIINENI	
			DATE:6-9-98 EAGLE AVIATIO	ON INC.	IGNED BY	FAA A	PPROVEN REP	AIR STATION F YOUR PERMA	FOR FEHR859II	ns ——
			2861 AVIATION WEST COLUMBIA	A, SC 25	7170	LE I MI	K NO FMAI U	a individual	11m111 11mm011	- <del></del>



TAL TIM SERVIC

IRS

Eagle Avi	iation, Inc.			το <b>ρ</b> . FAA Cert	ified Repair	r Station FEH	IR859D	^UT (
	Name: Flight k Order 78072	Reg.No.		ve Model 172	Serial 80015	Tach Time 280.30	Closed	
OPR	Descri	ptio	n			Pa	age 1	
	ETI TED CHA	19110 CHA	NGF. COMP	PRESSION C	FCK:#1 75/8	TH OIL AEROS 0. \$2 78/80, ITEMS ON INS	#3 /8/8V;	
98	ABOVE WAS RE	PAIRED A BULATIONS THE REPAI S SI	ME, AIRCR	PPROVED FO	PROPELLER ORDANCE WITH R RETURN TO IS AGENCY UN	AIR STATION	ERTINENT DER NUMBER.	

&

AL TIM

ERVICE

Prop **UTHORIZ** Eagle Aviation, Inc. FAA Certified Repair Station FEHR8591 CERTII Customer Name: Flight Dept. Maint Reserve Reg.No. Make N364ES CESSNA Tach Time Closed 385.40 Serial 80015 Shop Work Order Model 78273 172 OPR Description Page 1 COMPLIED WITH 100 HOUR & ANNUAL INSPECTION. COMPRESSION CHECK: \$1 78/8 \$2 78/80, \$3 76/80, \$4 77/80. COMPLIED WITH OIL CHANGE SERVICED WITH 8 QTS. 15W50, CHANGE OIL FILTER CH48110. COMPRESSION CHECK:#1 78/80, MAINTENANCE RELEASE

THE AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER WORK ORDER NUMBER. 98 **‡**78273 DATE: 11-05-98 S EAGLE AVIATION INC. SIGNED BY: FAA APPROVED REPAIR STATION #FEHR859D 2861 AVIATION WAY RETAIN AS PART OF YOUR PERMANENT RECORDS WEST COLUMBIA, SC 29170

**PROPELLER ENTRY** 

Reg N: 364ES

Make: CESSNA

Model: 172R

Serial: 17280015

Hobbs Time: 686.9

UTHOR CER

1. REMOVED PROPELLER MODEL 1C235/LFA7570 SN: QG020. INSTALLED PROPELLER MODEL 1A170E/JFA7658 SN: TL005 PER AIR PLAINS SERVICES CORP. STC #SA4428SW.

#### MAINTENANCE RELEASE

THE AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, PROPELLER OR APPLICANCE IDENTIFIED ABOVE WAS REPARIED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER WORK ORDER NUMBER #80161.

DATE: 10/13/2000

SIGNED BY:

**EAGLE AVIATION INC** 

Suan FAL APPROVED REPAIR STATION #FEHR859D

**2861 AVIATION WAY** 

RETAIN AS PART OF YOUR PERMANENT RECORDS

WEST COLUMBIA, SC 29170

		(41)					
ragic av	lation, inc.	a	TAA CET	LILIEG KEPALI	prarion LFU	D DECON	ITUOD
Customer Shop Wo 025	Name: Eagle West ork Order Reg.No. 80161 N364ES	Maint Custome Make CESSNA	er Model 172	Serial 80015	Tach Time 686.90	Closed	JTHOR CERT
0. P. R	Descripti	o n			Pa	ige 1	
11	COMPLIED WITH ANY DRAINED OIL, SERV CLEANED, RAN UP,	TUAL INSPECTION ICED WITH 8 QU LEAK AND OPS (	N. COMPRES JARTS AERO CHECKED GO	SSION: 1) 76/ DSHELL 15W50 DOD.	80, 2) 77/80 OIL. ENGINE	), 4) 77/80 WAS	
98	THE AIRCRAFT, AIR ABOVE WAS REPAIRE AVIATION REGULATION THE RE\$80161 DATE:10/20/2000 EAGLE AVIATION IN 2861 AVIATION WAY WEST COLUMBIA, SC	FRAME, AIRCRAID AND INSPECTIONS AND IS APPAIR ARE ON FINE SIGNED BY	ED IN ACCEPROVED FOR	PROPELLER OF CORDANCE WITH RETURN TO SEE AGENCY UNI	CURRENT FED SERVICE. PE DER WORK ORD IR STATION	ERAL RTINENT ER NUMBER. FOR FEHR859D	



'THORIZE CERTIFI

& N

TOTAL TIME IN SERVICE PROPELLER ENTRY OURS 10tl Model: 172 Serial No: 80015 Total Time: 765.1 Make: Cessna Reg: N364ES COMPLIED WITH ANNUAL INSPECTION IN ACCORDANCE WITH CESSNA 172 MAINTENANCE MANUAL CHAPTER 5 MAINTENANCE RELEASE THE AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER WORK ORDER NUMBER #81316. AA APPROVED REPAIR STATION #FEHR859D SIGNED BY: DATE: 10/22/01 EAGLE AVIATION INC RETAIN AS PART OF YOUR PERMANENT RECORDS 2861 AVIATION WAY WEST COLUMBIA, SC 29170

OTAL TIME SERVICE

JRS 10

Reg: N364ES

Make: CESSNA

Model: 172R

PROPELLER ENTRY

Serial No: 17280015

Total Time: 864.8

ITHO

CE

COMPLIED WITH ANNUAL INSPECTION PER CESSNA 172R INSPECTION GUIDE AND APPENDIX D TO PART 43.

MAINTENANCE RELEASE

THE AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER WORK ORDER NUMBER #82100.

DATE: 7/22/02

SIGNED BY:

VED REPAIR STATION #FEHR859D

EAGLE AVIATION, INC. **2861 AVIATION WAY** 

FAA APPRO AS PART OF YOUR PERMANENT RECORDS RETAIN

**WEST COLUMBIA, SC 29170** 

N#: 364ES

WO#: 202586

DATE: 7/15/03

TACH: 417.1

TOTAL TIME: 417.1

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy

condition. KNO

Signature:

FAA REPAIR STA. #RSUR804H

**VARS-115** 

ATE	TOTAL IN SER			N#. 364ES WO#: 203350 DATE: 7/26/04	<b>WaVirgin</b> Avia	PEROTI	PAIR STA RSUR804 VARS-11	н –		A	UTHORIZED SIGI
	HOURS	10ths		TACH: 569.9							& NUMBE
				TOTAL TIME: 569 I certify that this prian annual inspection condition!	opeller has been in:	spected in accorded to be in airv	rdance wi	th			
			ă .	Signature/V		ON THE CONTROL OF THE	We have distributed to the	All parameters and the second			
			Air Virg	<u>l<b>inia</b></u> 1607 Tec	NOTES CONTRACTOR OF THE PARTY O						,
- 1		05-00: 8/3/2		N 364ES HOBBS:	MAKE: C		MODEL:			1000	172280015 719.0
ir	nnual Insp	ection:	Dressed n 13-1b, and	ninor leading edge of all current Federal A	lamage. All work p	erformed IAW C					
10	ouna airwa		RINT	ed to service.		SIGNED			C	ERTIFIC	CATE No.
	Will	iam F	. Hook	Jr.	William V.	THAS	2		Α	P271	56911A
ᆣ					MINIST IS	N.L.					

Air Virginia, LLC 1607 Tech Center DR. Blacksburg, VA. 24060

(540) 961-0047

Brendan Carroll

A&P2967776IA<><

Reg: <u>N364ES</u> <u>Make: Cessna</u> <u>Model: 172R</u> <u>Serial No: 17280015</u> <u>Tach: 1518.0</u> <u>Hobbs: 1727.9</u> Propeller model: <u>1A170E/JFA7658</u> <u>Serial No: TL005</u>

Date: 8-25-06

Performed Annual inspection I/AW FAR part 43 Appendex D - dress and painted prop. I certify that this aircraft has been inspected in accordance with an annual inspection and is ok for return to service.

16-Sep-2008

1750.5 TTAF&E: 1063.6 TTP 1063.6 tach: Performed Annual inspection IAW FAR part 43 Appendix D. Dressed leading edge with no other discrepancies noted at this time. I certify this propeller has been inspected in accordance with an ANNUAL inspection and found to be in airworthy

condition.

New River Aero Blacksburg, VA 24060 540-951-0080

Nathan Ostermann A&P2896768IA



22-Oct-2009

1168.3 tach:

1855.2 TTAF&E: 1168.3 TTP

Performed Annual inspection IAW FAR part 43 Appendix D. Dressed leading edge with no other discrepancies noted at this time. I certify this propeller has been inspected in accordance with an ANNUAL inspection and found to be in airworthy condition.

**New River Aero** Blacksburg, VA 24060 540-951-0080

Nathan Ostermann A&P2896768IA

2-Dec-2010

1238.5 tach: 1925.4 TTAF&E: 1238.5 TTP

Performed Annual inspection IAW FAR part 43 Appendix D. Dressed leading edge with no other discrepancies noted at this time. I certify this propeller has been inspected in accordance with an ANNUAL inspection and found to be in airworthy

condition.

*New River Aero* Blacksburg, VA 24060 540-951-0080

Nathan Ostermann A&P2896768IA

13-Feb-2012

1300 tach: 1986.9 TTAF&E: 1300 TTP
Performed Annual inspection IAW FAR part 43 Appendix D. Dressed leading edge with no other discrepancies noted at this time. I certify this propeller has been inspected in accordance with an ANNUAL inspection and found to be in airworthy

condition.

**New River Aero** Blacksburg, VA 24060 540-951-0080

Jeffrey S. Hoprich A&P212562013IA

12-Mar-2013

1368.3 tach:

2055.2 TTAF&E:

1368.3 TTP

1. C/W: AD 82-27-01, DNA by propeller model #.

2. C/W: AD 03-13-07, DNA, Not serviced by T & W Propellers

3. C/W: AD 05-14-11, DNA, Not serviced by Southern California Propeller

4. Performed Annual inspection IAW FAR part 43 Appendix D. Dressed leading edge with no other discrepancies noted at this time. I certify this propeller has been inspected in accordance with an ANNUAL inspection and found to be in airworthy condition.

**New River Aero** Blacksburg, VA 24060 540-951-0080

Nathan Ostermann A&P2896768IA

5-Mar-2014

HOL

1416.9 tach:

2103.8 TTAF&E:

1416.9 TTP

Performed Annual inspection IAW FAR part 43 Appendix D. Dressed leading edge with no other discrepancies noted at this time. I certify this propeller has been inspected in accordance with an ANNUAL inspection and found to be in airworthy condition.

**New River Aero** Blacksburg, VA 24060 540-951-0080

Jeffrey S. Hoprich A&P212562013IA

1-Feb-2015

1555.9 tach:

2242.8 TTAF&E:

1555.9 TTP

Performed Annual inspection IAW FAR part 43 Appendix D. Dressed leading edge with no other discrepancies noted at this time. I certify this propeller has been inspected in accordance with an ANNUAL inspection and found to be in airworthy Jeffrey J Hopen condition.

New River Aero Blacksburg, VA 24060 540-951-0080

Jeffrey S. Hoprich A&P212562013IA



**AUTHORIZED SI** 

CERTIFICATI & NUME

with no other discrepancies noted at this time. I certify this propeller has been inspected in accordance with an ANNUAL inspection and found to be in airworthy condition. The & Hoprich New River Aero Blacksburg, VA 24060 Jeffrey S. Hoprich A&P212562013IA 540-951-0080 1812.3 TSNew: 1812.3 TTP: 27-Feb-2017 1812.3 tach: Removed McCauley propeller (Mod # 1A170E/JFA7658; S/N: TL005) for overhaul by Jeffey 5 Hobrick Piedmont Propulsion Systems, LLC. New River Aero Blacksburg, VA 24060 Jeffrey S. Hoprich A&P212562013IA 540-951-0080

2369.5 TTAF&E:

Performed Annual inspection IAW FAR part 43 Appendix D. Dressed leading edge

1682.6 tach:

19-Feb-2016

1682.6 TTP



PROPULSION SYSTEMS, LLC

PIEDMONT PROPULSION SYSTEMS 4400 Lansing Drive WINSTON-SALEM, N.C. 27105 REPAIR STATION NO.3FSR595B

M.F.G. - McCauley

MODEL - 1A170E/JFA7658

S/N - 11.005

DATE 04-07-2017 W.O. P27814

Overhauled in accordance with McCauley manuals 730720/R6, Dec 15, 2002 and SPM100/R6, Oct. 19, 2015. No Service Bulletins complied with at this shop visit. No Airworthiness Directives apply at this time. T.S.O. 00.0; T.S.N. Unknown ---End----

APPROVED BY RULLI INSPECTOR FOR
PIEDMONT PROPULSION SYSTEMS Winston-Salem, N.C. Repair Station no. 3PSR595B

15-Apr-2017

1812.3 tach:

1812.3 TTP

0.0 TSPOH

Installed McCauley propeller (Mod # 1A170E/JFA7658; S/N: TL005) after overhaul by Piedmont Propulsion Systems, LLC. Ref: W.O. P27814 per Cessna Service Manual Propeller installation instructions.

**New River Aero** Blacksburg, VA 24060 540-951-0080

Jeffrey S. Hoprich A&P212562013IA







23-Mar-2019

1905.9 tach:

1905.9 TTP

**93.6 TSPOH** 

Performed Annual inspection IAW FAR part 43 Appendix D. Dressed leading edge with no other discrepancies noted at this time. I certify this propeller has been inspected in accordance with an ANNUAL inspection and found to be in airworthy condition.

New River Aero Blacksburg, VA 24060

540-951-0080

1986.01 TTP

173.7 TSPOH


1986.01 tach: Performed Annual inspection IAW FAR part 43 Appendix D. Dressed leading edge with no other discrepancies noted at this time. I certify this propeller has been inspected in accordance with an ANNUAL inspection and found to be in airworthy condition.

New River Aero Blacksburg, VA 24060 540-951-0080

Jeffug 5 Hopinich Jeffrey S. Hoprich A&P212562013IA

Jeffres Hoperch

ffrey S. Hoprich A&P212562013IA



Date: 2/01/2020; Aircraft: N364ES; Type: 172R; S/N: 17280015; Tach: 2069.70; Total Time: 2756.60; Prop - Type: 1A170E/JFA7658, S/N: TL005, Time: 257.40, SMOH:

257.40

Shop Order #: F20-0160

### PROPELLER ENTRY

Complied with annual / 100 hour inspection i/a/w Cessna 172R 5-00-00 AMM par. 2 B (1).

### Maintenance Release

The aircraft or appliance identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service. Pertinent details are on file at this Repair Station

Signed:

CRS# BGSR439C

... T 3 É E