









Date	Description of all operations pertaining to Airworthiness Directives, Service Documents, and Inspections.
	<p>December 1 2018 N420SE S/N 2293 Hartzell PHC-J3YF-1N S/N: FP8848B Flight meter: 1239.8 Prop TSO: 94.1</p> <p style="text-align: right;">  VectorAir Aircraft Inspection & Repair Erie Municipal Airport 395 Airport Drive Erie, Colorado 80516 </p> <p>Performed a 100hr inspection of propeller for annual of N420SE in accordance with FAR 43 appendix D and Hartzell Manual 145 and a checklist as a guide. Visual inspection blades, hub and spinner o.k. A list of AD's may be found in aircraft records. I certify this propeller has been inspected in accordance with a 100hr inspection and determined to be in airworthy condition.</p> <p style="text-align: center;">-----END-----</p> <p style="text-align: right;">  Terrill Shafer AP2860279IA </p>
	<p>December 1 2018 <i>Jan 10 2020</i> N420SE S/N 2293 Hartzell PHC-J3YF-1N S/N: FP8848B Flight meter: 1240.4 Prop TSO: 106.83</p> <p style="text-align: right;">  VectorAir Aircraft Inspection & Repair Erie Municipal Airport 395 Airport Drive Erie, Colorado 80516 </p> <p>Performed a 100hr inspection of propeller for annual of N420SE in accordance with FAR 43 appendix D and Hartzell Manual 145 and a checklist as a guide. Visual inspection blades, hub and spinner o.k. A list of AD's may be found in aircraft records. I certify this propeller has been inspected in accordance with a 100hr inspection and determined to be in airworthy condition.</p> <p style="text-align: center;">-----END-----</p> <p style="text-align: right;">  Paul D Randall AP3081341IA </p>

	<p>February 17 2021 N420SE S/N 2293 Hartzell PHC-J3YF-1N S/N: FP8848B Flight meter: 1256.0 Prop TSO: 122.43</p> <p style="text-align: right;">  VectorAir Aircraft Inspection & Repair Erie Municipal Airport 395 Airport Drive Erie, Colorado 80516 </p> <p>Performed a 100hr inspection of propeller for annual of N420SE in accordance with FAR 43 appendix D and Hartzell Manual 145 and a checklist as a guide. Visual inspection blades, hub and spinner o.k. A list of AD's may be found in aircraft records. I certify this propeller has been inspected in accordance with a 100hr inspection and determined to be in airworthy condition.</p> <p style="text-align: center;">-----END-----</p> <p style="text-align: right;">  Joel Burkholder AP3277608IA </p>
	<p>March 15 2022 N420SE S/N 2293 Hartzell PHC-J3YF-1N S/N: FP8848B Flight meter: 1267.4 Prop TSO: 133.83</p> <p style="text-align: right;">  VectorAir Aircraft Inspection & Repair Erie Municipal Airport 395 Airport Drive Erie, Colorado 80516 </p> <p>Performed a 100hr inspection of propeller for annual of N420SE in accordance with FAR 43 appendix D and in reference to Hartzell Manual 145 and a checklist as a guide. Visual inspection blades, hub and spinner o.k. A list of AD's may be found in aircraft records. I certify this propeller has been inspected in accordance with a 100hr inspection and determined to be in airworthy condition.</p> <p style="text-align: center;">-----END-----</p> <p style="text-align: right;">  Terrill Shafer AP2860279IA </p>