


It is important to understand that the existence of this Document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer work in accordance with the national regulations of an Airworthiness Authority different than the Airworthiness Authority of the country specified in block 1 it is essential that the user/installer ensures that his/her Airworthiness Authority accepts parts/components/assemblies from the Airworthiness Authority of the country specified in block 1. Statements in block 14 and 19 do not constitute an installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Airworthiness Approval Tag
User/Installer Responsibilities

2. FAA FORM 8130-3 AIRWORTHINESS APPROVAL TAG U.S. Department of Transportation Federal Aviation Administration		3. System Tracking Ref. No. FPS 3616	
4. Manufacturer Foster's Propeller Service, Inc. - 26650 Highway 62 - Boynton, OK 74422		5. Work Order, Contract or Invoice No. 3616-1 page	
6. Part Number 12322490		11. Serial/Batch Number 880280	
7. Description McAuley Prop		12. Status/Work Newly Overhauled	
8. Part Number 12322490		10. Quantity 1	
9. Eligibility* 70P476L		19. Return to Service in Accordance with FAR 43.9 Certifies that the work specified in block 13 (or attached) above was carried out in accordance with FAA airworthiness regulations and in respect to the work performed the part(s) is(are) approved for return to service.	

16. FAA Authorization No. _____
 17. Date _____
 18. Date _____
 19. **Return to Service in Accordance with FAR 43.9**
 Certifies that the work specified in block 13 (or attached) above was carried out in accordance with FAA airworthiness regulations and in respect to the work performed the part(s) is(are) approved for return to service.

20. Authorized Signature

 21. Certificate Number
F3PRO14N
 22. Name (Typed or Printed)
JERRY D. FOSTER
 23. Date
05-07-02

16. FAA Authorization No. _____
 17. Date _____
 18. Date _____
 19. **Return to Service in Accordance with FAR 43.9**
 Certifies that the work specified in block 13 (or attached) above was carried out in accordance with FAA airworthiness regulations and in respect to the work performed the part(s) is(are) approved for return to service.

* (Optional) Installer must cross check eligibility with applicable technical data.

FOSTER'S PROPELLER SERVICE, INC.

26650 HIGHWAY 62
BOYNTON, OKLA. 74422
F.A.A. APPROVED REPAIR STATION NO. F3PR014N

Phone 918-733-2131

FAX 918-474-367

=
= POWERMASTER A/C ENGINES
= 9027 S. AIRPORT WAY
= TULSA, OK. 91096
=

=
= WORK ORDER NO.3616
= CUSTOMER P.O.
= DATE 05/08/02
=

MAKE: McCAULEY
MODEL: D3A32C409C
SER. NO.: 880280
SER. NO.:

AIRPLANE 'N' NO.

WORK DESCRIPTION

OVERHAULED PROP PER S/M 761001, SPM100-1 & BOM100-1. C/W ALL SB'S THROUGH SB227
ALL SL'S THROUGH SL02-5 THAT APPLY. ASSEMBLED, BALANCED & TESTED.


PARTS LIST

1 EA. 100% REPLACEABLE PARTS KIT.

>DO NOT DETACH<

MAKE---McCAULEY MODEL--D3A32C409C
SERIAL NO.----880280

THE COMPONENT IDENTIFIED ABOVE WAS REPAIRED/OVERHAULED
AND INSPECTED IN ACCORDANCE WITH CURRENT CIVIL
AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR
RETURN TO SERVICE. PERTINENT DETAILS OF THE
REPAIR ARE ON FILE AT THIS AGENCY UNDER
WORK ORDER NUMBER---3616 DATE---05/08/02

SIGNED  FOR
FOSTER'S PROPELLER SERVICE, INC.
CERTIFICATE NO F3PR014N
26650 HIGHWAY 62 BOYNTON, OK. 74422 PH 918-733-2131

(This copy to be inserted in proper log book)