


PROP

LOGS

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
12-17-09	0.0	N/A	4.0	<p>I have Dynamically Balanced Propeller IAW Hartzell Propeller Owner's Manual 145 Rev. 6 Dated Dec. 2008 Section 61-00-45 on <u>Dec 17, 2009</u> (DATE). The location of the Weight(s) are <u>190</u> degree And are <u>7.2</u> gram(s).</p> <p><u>Dave Cook</u>  (Sign/Stamp) Cirrus Design Corporation, PC 338CE</p>

Mass Aviation Services, LLC
 Worcester Regional Airport
 375 Airport Drive, Worcester, MA 01602

4-12-11 WO# 4908 Reg. N488CD Flight Hobbs: 281.3

Propeller: Serviced hub with grease. Painted blade faces black. Updated the airworthiness directives through Bi-weekly issue 2011-07. I certify that this propeller has been inspected in reference with an annual inspection and is determined to be in airworthy condition and approved for return to service.

B. G. H.

AP315893661A

PROP MODEL:
PROP S/N:
REG. NO: 488CD
WORK ORDER:
0545-03-2015



81 Kenosia Ave
Danbury, CT 06810
Phone: 203-702-7192

DATE: 4/21/2015
A/C TSN: 686.9
PROP TT: 686.9
TSPOH: 686.9
FLIGHTTIME: 686.9

Prop Entries

Performed 100hr. inspection on propeller I/AW FAR part 43, appendix D, and manufactures service manuals.

Maintenance Release:

I certify that this aircraft and/or component(s) on 488CD was repaired and inspected in accordance with an Annual and/or 100hr. inspection and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this maintenance shop under Work Order No. 0545-03-2015, Dated 4/21/2015.

DATE: 4/21/2015

SIGNED:

Work Order: 0545-03-2015

Devon Chapin, IA: A&P67484333IA

Printed by EBis 3 (datcomedia.com)

Date 4/19/2016

W/O# 14998



Propeller Logbook Entry

AIRCRAFT: N488CD

CRS AWKR298C

S/N 3577

25170 Aviation Ave., Davis, CA 95616

Tach / Flight 795.2 COMPLIED WITH AN ANNUAL INSPECTION THIS DATE PER FAR 43 APPENDIX D. ALL WORK
 TTAF 795.2 COMPLETED IN ACCORDANCE WITH APPLICABLE MANUALS. PREPPED AND REPAINTED PROPELLER
 BLADE FACES FLAT BLACK.

Prp TSN 795.2 *I certify that this Aircraft/Engine/Propeller has been inspected IAW an Annual inspection and
 was determined to be in an airworthy condition. Signed*

Prp TSO N/A

A handwritten signature in blue ink, appearing to read 'Shawn Matthies', is written over a horizontal line.

Shawn Matthies AWKR298C

The Aircraft and/or component identified above was repaired and inspected IAW FAA regulations and was found airworthy to return to service only for the work performed.

Pertinent details of the repair are on file at this agency: Signed:

Shawn Matthies AWKR298C

Date 4/24/2017

W/O# 15922



Propeller Logbook Entry

AIRCRAFT: N488CD

CRS AWKR298C

S/N 3577

25170 Aviation Ave., Davis, CA 95616

Tach / Flight 900.3 COMPLIED WITH AN ANNUAL INSPECTION THIS DATE PER FAR 43 APPENDIX D. ALL WORK COMPLETED
 IN ACCORDANCE WITH APPLICABLE MANUALS.

TTAF 900.3

Prp TSN 900.3

Prp TSO N/A

I certify that this Aircraft/Engine/Propeller has been inspected IAW an Annual inspection and was determined to be in an airworthy condition. Signed

Shawn Matthies AWKR298C

The Aircraft and/or component identified above was repaired and inspected IAW FAA regulations and was found airworthy to return to service only for the work performed.

Pertinent details of the repair are on file at this agency: Signed:

Shawn Matthies AWKR298C