

AIRFRAME MAINTENANCE RECORDS

Log No. 2

Aircraft Registration No. N986CD

Aircraft Mfg. CIRRUS DESIGN Model SR22 Serial No. 1862

Engine Mfg. CONTINENTAL Model IO-550-N Serial No. 689102

Engine Mfg. _____ Model _____ Serial No. _____

Propeller Mfg. HATZEL Model PHC-J3YF-1RF Serial No. FP4453B

Hub Design No. _____ Hub Serial No. _____

Blade Design No. _____ Blade Serial No's. _____

Propeller Mfg. _____ Model _____ Serial No. _____

Hub Design No. _____ Hub Serial No. _____

Blade Design No. _____ Blade Serial No's. _____

(All applicable information must be filled in)



AEROTECH PUBLICATIONS INC.

www.adlog.com
P.O. Box 1359 / Southold, NY 11971-0965
(631) 765-9375
1-800-235-6444
FAX: (631) 765-9359

DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
TOTAL brought forward from previous page			
6/12/09	746.0	746.0	This log opened this date. S. Vander Valk A&P 2919106

Airframe Log

June 16, 2009

N986CD

Flight Time: 0.00, Total Time: 747.7, Hobbs: 747.7
C/W SB 2X-31-01, installed flight hobbs meter for recording total time by installing kit# 70150-001. Total time will now be tracked by the Flight Hobbs.

S. Vander Valk
Steven Vander Valk A&P 2919106
Paragon Aircraft Service

Airframe Log

July 20, 2009

N986CD

Flight Time: 31.8, Total Time: 779.5, Hobbs: 790.9
Replaced pilots push to talk switch. Installed overhauled roll trim motor assembly part# 12546-003S serial# EO 180.

S. Vander Valk
Steven Vander Valk A&P 2919106
Paragon Aircraft Service

Airframe Log

September 18, 2009

N986CD

Flight Time: 46.0, Hobbs: 809.1
Replaced aircraft battery.

S. Vander Valk
Steven Vander Valk A&P 2919106
Paragon Aircraft Service

Airframe Log

October 14, 2009

N986CD

Tach: 65.3

Removed and replaced left fuel tank quick drain P/N C100191.

Michael Kastner
Michael Kastner A&P 157829388 IA
Paragon Aircraft Service

Airframe Log

November 13, 2009

N986CD

Flight Hobbs: 80.1, Total Time: 827.1, Hobbs: 850.7

All systems checked for condition and proper operation. Wheel bearings cleaned and repacked. Battery and brakes serviced. Replaced left aft nav light lens, bracket air filter, rebound bumper, interconnect bungee and brake caliper o-rings. Checked and weighed cockpit fire extinguisher. Adjusted aileron cable tensions. All AD's checked thru 09-23. ELT inspected per FAR 91.207(d).

I certify that this aircraft has been inspected in accordance with an annual inspection and determined to be in an airworthy condition.

S. Vander Valk
Steven Vander Valk A&P 2919106 IA
Paragon Aircraft Service

DATE

TOTAL TIME IN SERVICE

TACH OR RECORDING METER TIME

DESCRIPTION OF WORK PERFORMED—
SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK

TOTAL brought forward from previous page

Airframe Log

January 29, 2010

Flight Time: 106.7 Hobbs Time: 889.4

N 986CD

Installed new lower door latch P/N 21889-001. Door Striker Pin. Ops check good. *Adjusted Cabin*

John L. Longaker
John L. Longaker A&P 138848254
Paragon Aircraft Service

Airframe Log

March 9, 2010

Flight Hobbs: 129.8 Hobbs: 917.7

N 986CD

Removed and replaced damaged rebound bumper on nose landing gear. Removed and replaced broken left outboard exhaust spring

John L. Longaker
John L. Longaker A&P 138848254
Paragon Aircraft Service

6/1/10

920.2

173.2

Airframe Log

June 1, 2010

Flight Hobbs: 173.2, Total Time: 920.2, Hobbs: 974.8

N986CD

All systems checked for condition and proper operation. Wheel bearings cleaned and repacked. Battery and brakes serviced. Replaced BA-24 bracket air filter, nose gear rebound bumper part# 18380-001, defroster control rod part# 12111-001 and brake caliper o-rings. Checked and weighed cockpit fire extinguisher. All AD's checked thru 10-11. ELT inspected per FAR 91.207(d).

I certify that this aircraft has been inspected in accordance with an annual inspection and determined to be in an airworthy condition.

Steven Vander Valk
Steven Vander Valk A&P 2919106 IA
Paragon Aircraft Service

6/1/10

920.2

173.2

Replaced #2 batteries, next due 6/2012 or 1420.2 T.T. *Steven Vander Valk A&P 2919106*

SUB-TOTAL this page

TOTAL-Carry forward to next page

C&W Aero Services, Inc. CRS# HX1R208K

19 Wright Way, Suite #3, Fairfield, NJ 07004 (973) 227-5750

WO# 24502	Hobbs: 974.8	Aircraft TT:	Model: SR22
Reg #: N986CD	Ser #: 1862	Manuf: Cirrus	

The ATC Transponder tests and inspection required by FAR 91.413 were performed this date and found to comply with FAR 43, Appendix F. The Pitot/Static System has been inspected in accordance with FAR 91.411 and found to be AIRWORTHY. Details of these inspections are on file at this Repair Station.

Transponder #1 Make/Model: Garmin GTX327

SN: 83723100

Authorized Signature: _____



Date: 5/27/2010

C&W Aero Services, Inc. CRS #HX1R208K

I certify that the following tests were performed on Altimeter Model 5934D-3

S/N 451950 in accordance with FAR Part 43 Appendix E as outlined

In Tables I, II, III, and IV. Altimeter tested to 20,000 ft.

Work Order # 24379 Date 5-26-10

Performed By: Mike J. Smith

Form# CWF-014

C&W Aero Services, Inc. CRS #HX1R208K

I certify that the following tests were performed on Altimeter Model EXP5000 (27.1)

S/N 20065118 in accordance with FAR Part 43 Appendix E as outlined

In Tables I, II, III, and IV. Altimeter tested to 20,000 ft.

Work Order # 24380 Date 5-27-10

Performed By: Charles Reiche

Form# CWF-014

C&W Aero services Inc. 19 Wright Way, Suite 3 Fairfield, NJ 07004 FAA Repair Station HX1R208K		
Master Reads	Altimeter Reads	
	Encoder	Altimeter
-1000		-1,000
0		0
500		500
1000		1,000
1500		1,510
2000		2,020
3000		3,020
4000		4,020
6000		6,000
8000		8,000
10000		9,990
12000		11,980
14000		13,980
16000		15,990
18000		18,000
20000		20,020
22000		
25000		
30000		
35000		

Altimeter Make: UNITED INSTRUMENT
 Altimeter Model: 5934D-3
 Altimeter S/N: 451950
 Tested By: Mike J. Smith
 Date: 5-26-10 Work order No. 24379
 Form No. CWF-013

Master Reads	Altimeter Reads	
	Encoder	Altimeter
-1000		-1000
0		0
500		500
1000		1000
1500		1500
2000		2000
3000		3000
4000		4000
6000		6000
8000		8000
10000		10000
12000		12000
14000		14000
16000		16000
18000		18000
20000		20000
22000		
25000		
30000		
35000		

C&W Aero services Inc.
19 Wright Way, Suite 3
Fairfield, NJ 07004
FAA Repair Station HX1R208K

Altimeter Make: AVIATION CORP
 Altimeter Model: EXP5000 (27.1)
 Altimeter S/N: 20065118
 Tested By: Charles Reiche
 Date: 5-27-10 Work order No. 24380
 Form No. CWF-013

DESCRIPTION OF WORK PERFORMED—
SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK

DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK			
TOTAL brought forward from previous page						
Paragon Aircraft Service, Inc. 19 Wright Way, Fairfield, NJ 07004 Phone: (973)575-0364 Fax (973)244-1884					Authorized Cirrus Service Center	
Airframe Logbook Entry		Hobbs			Total Time	
4/11/2012		1308.4			1178.8	
Date	N' Number	Make/Model	Serial#	Flight	W. O.	
4/11/2012	986CD	Cirrus SR22	1862	431.8	7101	
Removed and replaced ELT battery with new. Next due change MAR/2018. Complied with FAR91.207d inspection. Found to be satisfactory						
I certify that the work described above was performed satisfactorily and in accordance with approved/acceptable data and is approved for return to service with regard to work performed.						
Authorized Signature: <i>[Signature]</i>					John L Longaker A&P 3532411	

C&W Aero Services, Inc. CRS# HX1R208K
 19 Wright Way, Suite #3, Fairfield, NJ 07004 (973) 227-5750
 An Authorized **Hawker Beechcraft** Service Center

WO# 26617	Hobbs: 1329.3	Aircraft TT:	
Reg. #: N986CD	Ser #: 1862	Manuf: Hawker Beechcraft	Model: SR22

ATC Transponder tests and inspection required by FAR 91.413 were performed this date and found to comply with FAR 43, Appendix F. The Pitot/Static System has been inspected in accordance with FAR 91.411 and found to be AIRWORTHY. Details of these inspections are on file at this repair station.

Transponder #1 Make/Model: Garmin GTX327 SN: 83723100
 Data Computer Make/Model: Avidyne EXP5000 SN: 20065118

Authorized Signature: *[Signature]* Date: 5/10/2012

Master Reads	Encoder	No	Altimeter
-1000			-1010
0			-15
500			485
1000			985
1500			1485
2000			1985
3000			2985
4000			3980
6000			5980
8000			7980
10000			9980
12000			11970
14000			13965
16000			15960
18000			17960
20000			19960
22000			
25000			
30000			
35000			

Master Reads	Encoder	No	Altimeter
-1000			-1010
0			0
500			500
1000			1005
1500			1505
2000			2010
3000			3010
4000			4010
6000			6000
8000			7990
10000			9980
12000			11970
14000			13965
16000			15940
18000			17990
20000			20000
22000			
25000			
30000			
35000			

Altimeter Make: **United Instruments**
 Altimeter Model: **5934 D-3**
 Altimeter S/N: **451950**
 Tested By: **Charles Reiche**
 Date: **5/10/12** Work Order No. **26457**
 Form No. CWF-013

C&W Aero Services, Inc. CRS #HX1R208K

I certify that the following tests were performed on Altimeter Model **EXP5000**
 S/N **20065118** in accordance with FAR Part 43 Appendix E as outlined
 in Tables I, II, III, and IV. Altimeter tested to **20,000** ft.
 Work Order # **26457** Date **5/10/2012**
 Performed By: **Charles Reiche** Form#CWF-014

C&W Aero Services, Inc. CRS #HX1R208K

I certify that the following tests were performed on Altimeter Model **5934D-3**
 S/N **451950** in accordance with FAR Part 43 Appendix E as outlined
 in Tables I, II, III, and IV. Altimeter tested to **20,000** ft.
 Work Order # **26458** Date **5/10/2012**
 Performed By: **Charles Reiche** Form#CWF-014

DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
TOTAL brought forward from previous page			

Airframe Logbook Entry	Paragon Aircraft Service, Inc. 19 Wright Way, Fairfield, NJ 07004 Phone: (973)575-0364 Fax (973)244-1884						Authorized Cirrus Service Center
Date	N' Number	Make/Model	Serial#	Flight	Hobbs	Total Time	W. O.
6/27/2012	N986CD	Cirrus SR22	1862	466.8	1351.9	1213.8	7192
<p>All systems checked for condition and proper operation. Wheel bearings cleaned and repacked. Battery and brakes serviced. Replaced induction filter. ELT inspected in accordance with FAR 91.207(d). Battery due for replacement Mar/2018. # 2 batteries due for replacement 5/2013. Replaced left wheel farring bracket. Replaced both aileron gap seals. Resealed rear window. Replaced both door rescue placards. Replaced fire extinguisher. Replaced left brake linings. Replaced both upper main wheel farring mounts. Next 100 hour inspection due at flight time 566.1</p> <p>I certify that this Aircraft has been inspected in accordance with an Annual Inspection and determined to be in an airworthy condition.</p> <p><i>I certify that the work described above was performed satisfactorily and in accordance with approved/acceptable data and is approved for return to service with regard to work performed.</i></p> <p>Authorized Signature:  Steve Vander Valk A&P 2919106 IA</p>							


Airframe Logbook Entry	Paragon Aircraft Service, Inc. 19 Wright Way, Fairfield, NJ 07004 Phone: (973)575-0364 Fax (973)244-1884						Authorized Cirrus Service Center
Date	N' Number	Make/Model	Serial#	Flight	Hobbs	Total Time	W. O.
7/26/2012	N986CD	Cirrus SR22	1862	480.6	1369.1	1227.6	7238
<p>Replaced #2 batteries P/N 50979-001.</p> <p><i>I certify that the work described above was performed satisfactorily and in accordance with approved/acceptable data and is approved for return to service with regard to work performed.</i></p> <p>Authorized Signature:  Steven VanderValk A&P 2919106</p>							

Airframe Logbook Entry	Paragon Aircraft Service, Inc. 19 Wright Way, Fairfield, NJ 07004 Phone: (973)575-0364 Fax (973)244-1884						Authorized Cessna Service Center
Date	N' Number	Make/Model	Serial#	Flight	Hobbs	Total Time	W. O.
11/16/2012	N986CD	^{Cirrus SR22} [REDACTED]	1862	521.7	1422.8	1284.7	7272
<p>Removed push to talk switch and installed a new P/N=50339-001 switch as req. Done I/A/W Cirrus SR22 wiring manual Chap 20-10 standard practices. Ops check satisfactory.</p> <p><i>I certify that the work described above was performed satisfactorily and in accordance with approved/acceptable data and is approved for return to service with regard to work performed.</i></p> <p>Authorized Signature:  Steven Festa A+P 3440693</p>							


	SUB-TOTAL this page
	TOTAL -Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
TOTAL brought forward from previous page			

Airframe Logbook Entry		Paragon Aircraft Service, Inc. 19 Wright Way, Fairfield, NJ 07004 Phone: (973)575-0364 Fax (973)244-1884					Authorized Cirrus Service Center	
Date	N' Number	Make/Model	Serial#	Flight	Hobbs	Total Time	W. O.	
3/1/2012	N986CD	Cirrus SR22	1862	1148.1	1268.9	1148.1	7046	
Replaced inoperative #3 Egt probe 16579-002, ran up checked OK.								
I certify that the work described above was performed satisfactorily and in accordance with approved/acceptable data and is approved for return to service with regard to work performed.								
Authorized Signature: 				Steven VanderValk A&P 2919106				

Airframe Logbook Entry		Paragon Aircraft Service, Inc. 19 Wright Way, Fairfield, NJ 07004 Phone: (973)575-0364 Fax (973)244-1884					Authorized Cirrus Service Center	
Date	N' Number	Make/Model	Serial#	Flight	Hobbs	Total Time	W. O.	
6/14/2013	N986CD	Cirrus SR22	1862	562.6	1477.6	1309.6	7556	
All systems checked for condition and proper operation. Wheel bearings cleaned and repacked. Battery and brakes serviced. Replaced induction air filter, throttle control rod end, left tailpipe outboard spring and bracket, right brake linings, nose gear rebound bumper, lower cowl close out seals, cabin step treads and left passenger reading light switch. Replaced remote ELT switch battery next due 3/2020. Installed new EMA controller next due 5/2020. Checked and weighed cockpit fire extinguisher. Replaced ELT batteries next due 12/2022. ELT checked I/AW FAR 91.207(d). All AD's checked thru 13-11.								
I certify that this aircraft has been inspected in accordance with an Annual Inspection and determined to be in an airworthy condition.								
I certify that the work described above was performed in accordance with approved/acceptable data and is approved for return to service with regard to work performed.								
Authorized Signature: 				Steven VanderValk A&P 2919106 IA				

Airframe Logbook Entry		Paragon Aircraft Service, Inc. 19 Wright Way, Fairfield, NJ 07004 Phone: (973)575-0364 Fax (973)244-1884					Authorized Cirrus Service Center	
Date	N' Number	Make/Model	Serial#	Flight	Hobbs	Total Time	W. O.	
3/17/2014	986CD	Cirrus SR22	1862	637.4	1573.7	1384.4	7736	
Replaced left upper gear leg farring with new. Replaced both aileron gap seals.								
I certify that the work described above was performed satisfactorily and in accordance with approved/acceptable data and is approved for return to service with regard to work performed.								
Authorized Signature: 				John L. Longaker A&P 3532411				

Airframe Logbook Entry		Paragon Aircraft Service, Inc. 19 Wright Way, Fairfield, NJ 07004 Phone: (973)575-0364 Fax (973)244-1884					Authorized Cirrus Service Center	
Date	N' Number	Make/Model	Serial#	Flight	Hobbs	Total Time	W. O.	
6/19/2014	N986CD	Cirrus SR22	1862	652	1592.5	1399	7918	
All systems checked for condition and proper operation. Wheel bearings cleaned and repacked. Battery and brakes serviced. Replaced induction air filter, nose gear rebound bumper, alternator air valve and bolt, left entry step and #2 batteries. Installed overhauled left muffler, see 8130 from Aerospace Welding. C/W SB 2X-27-16R2 flap actuator modification. Adjusted nose fork tension per manual. Checked and weighed cockpit fire extinguisher. ELT checked I/AW FAR 91.207(d). All AD's checked thru 14-11.								
I certify that this aircraft has been inspected in accordance with an Annual Inspection and determined to be in an airworthy condition.								
I certify that the work described above was performed in accordance with approved/acceptable data and is approved for return to service with regard to work performed.								
Authorized Signature: 				Steven VanderValk A&P 2919106 IA				

TOTAL-Carry forward to next page

D, Airframe Logbook Entry


Paragon Aircraft Service, Inc.
 19 Wright Way, Fairfield, NJ 07004
 Phone: (973)575-0364 Fax (973)244-1884

Authorized
 Cirrus Service
 Center

Date	N' Number	Make/Model	Serial#	Flight	Hobbs	Total Time	W. O.
6/10/2015	N986CD	Cirrus SR22	1862	698.6	1651.2	1455.6	8343

All systems checked for condition and proper operation. Wheel bearings cleaned and repacked. Battery and brakes serviced. Replaced induction air filter, main tires, left brake disc and linings, upper cabin door hinge eye-bolts and nose wheel bearings and races. Checked and weighed cockpit fire extinguisher. ELT checked I/A/W FAR 91.207(d). All AD's checked thru 15-11. I certify that this aircraft has been inspected in accordance with an Annual Inspection and determined to be in an airworthy condition.

I certify that the work described above was performed in accordance with approved/acceptable data and is approved for return to service with regard to work performed.

Authorized Signature:  Steven VanderValk A&P 2919106 IA

Airframe Logbook Entry

Paragon Aircraft Service, Inc.
 19 Wright Way, Fairfield, NJ 07004
 Phone: (973)575-0364 Fax (973)244-1884

Authorized
 Cirrus Service
 Center

Date	N' Number	Make/Model	Serial#	Flight	Hobbs	Total Time	W. O.
2/19/2016	N986CD	Cirrus SR22	1862	741.9	1705	1488.9	8591

Removed CAPS Parachute PN 20331-001, SN 02133 and installed CAPS Parachute PN 25574-004-REB, SN 02079R1 next replacement due 01/27/2026. Removed CAPS Rocket Motor Assy PN 15047-001, SN 2467 and installed CAPS Rocket Motor Assy. PN 29500-003, SN 1508. Next replacement due 01/26/2026. Complied with SB 2X-95-13 CAPS Strap Inspection And Grommet Installation. Complied with SB 2X-95-18R2 CAPS Rocket Motor Assembly Replacement. Reinstalled original CAPS line cutters due 4/2017.

I certify that the work described above was performed satisfactorily and in accordance with approved/acceptable data and is approved for return to service with regard to work performed.

Authorized Signature:  Steven VanderValk A&P 2919106

Airframe Logbook Entry


Paragon Aircraft Service, Inc.
 19 Wright Way, Fairfield, NJ 07004
 Phone: (973)575-0364 Fax (973)244-1884

Authorized
 Cirrus Service
 Center

Date	N' Number	Make/Model	Serial#	Flight	Hobbs	Total Time	W. O.
6/20/2016	N986CD	Cirrus SR22	1862	762.9	1729.7	1519.9	8766

All systems checked for condition and proper operation. Wheel bearings cleaned and repacked. Battery and brakes serviced. Replaced induction air filter and NO PUSH placards on elevators. C/W SB 2X-52-08R1 gast strut and divertor replacement. Checked and weighed cockpit fire extinguisher. ELT checked I/A/W FAR 91.207(d). All AD's checked thru 16-12. I certify that this aircraft has been inspected in accordance with an Annual Inspection and determined to be in an airworthy condition.

I certify that the work described above was performed in accordance with approved/acceptable data and is approved for return to service with regard to work performed.

Authorized Signature:  Steven VanderValk A&P 2919106 IA

Airframe Logbook Entry

Paragon Aircraft Service, Inc.
 19 Wright Way, Fairfield, NJ 07004
 Phone: (973)575-0364 Fax (973)244-1884

Authorized
 Cirrus Service
 Center

Date	N' Number	Make/Model	Serial#	Flight	Hobbs	Total Time	W. O.
1/30/2017	N986CD	Cirrus SR22	1862	780.7	1751.2	1537.7	9032

Removed and replaced Main battery. Installed new Gill G-243 S/N G02897723. Operational check satisfactory.

I certify that the work described above was performed satisfactorily and in accordance with approved/acceptable data and is approved for return to service with regard to work performed.

Authorized Signature:  John L. Longaker A&P 3532411

DA Airframe Logbook
Entry

Paragon Aircraft Service, Inc.
19 Wright Way, Fairfield, NJ 07004
Phone: (973)575-0364 Fax (973)244-1884

Authorized
Cirrus Service
Center

Date	N' Number	Make/Model	Serial#	Flight	Hobbs	Total Time	W. O.
6/23/2017	N986CD	Cirrus SR22	1862	797.7	1770.5	1554.7	9156

All systems checked for condition and proper operation. Wheel bearings cleaned and repacked. Battery and brakes serviced. Installed customr supplied Bendix KLR 10 AOA indicator per installation manual, this is considered a minor alteration. Note system needs inflight calibration before it can be used. Replaced induction air filter, cowl screw placards, cowl edge seals and alternate air hose support. Checked and weighed cockpit fire extinguisher. Installed new ELT batteries, next due 12/2025. ELT checked I/A/W FAR 91.207(d). All AD's checked thru 17-12.

I certify that this aircraft has been inspected in accordance with an Annual Inspection and determined to be in an airworthy condition.

I certify that the work described above was performed in accordance with approved/acceptable data and is approved for return to service with regard to work performed.

Authorized Signature:



Steven VanderValk A&P 2919106 IA

MAKE Cirrus
MODEL SR22
S/N 1862
REG NO N986CD
WORK ORDER:
5394-09-2017

ADVANCED Fly Advanced

Repair Station No. 5T2R901C
530 Airport Rd.
Lititz, PA 17543
Phone: 717-735-5176

DATE: 9/15/2017
A/C TSN:
HOBS: 1808

Airframe Entries

Installed the #1 WAAS antenna ONLY on the top of the fuselage IAW SB 2X-34-24 R1 WAAS Antenna Installation on PFD Equipped Aircraft.

Maintenance Release

The aircraft and/or component(s) on N986CD was repaired and inspected in accordance with the current rules and regulations of Title 14 of the Code of Federal Regulations, was found airworthy and was returned to service.

DATE: 9/15/2017

SIGNED


Joel A. Glover
Certified Repair Station No. 5T2R901C

Work Order: 5394-09-2017

Printed by EBis 3 (datcomedia.com)

Airframe Logbook
Entry

Paragon Aircraft Service, Inc.
19 Wright Way, Fairfield, NJ 07004
Phone: (973)575-0364 Fax (973)244-1884

Authorized
Cirrus Service
Center


Date	N' Number	Make/Model	Serial#	Flight	Hobbs	Total Time	W. O.
6/22/2018	N986CD	Cirrus SR22T	1862	865.3	1851.6	1622.3	9503

All systems checked for condition and proper operation. Wheel bearings cleaned and repacked. Battery and brakes serviced. ELT checked I/A/W FAR 91.207(d). Battery replacement due 12/2025. Replaced induction air filter. Cleaned and adjusted nose fork to proper tension. Replaced wellnut for upper left gear faring. Replaced damaged cowl seal. Installed new cabin fire extinguisher. Complied with SB2X-95-24R1 by installing ground wire. Removed and replaced parachute reefing line cutters. Installed new cutters S/N's 13333, 13270. Next due 5/2024. Removed and replaced #2 batteries. Removed and replaced pilot and copilots seat belt inflators. Next due Feb/2026. All AD's checked thru 18/12.

I certify that this aircraft has been inspected in accordance with an Annual Inspection and determined to be in an airworthy condition.

I certify that the work described above was performed satisfactorily and in accordance with approved/acceptable data and is approved for return to service with regard to work performed.

Authorized Signature:



John L. Longaker A&P 3532411 IA


SUB-TOTAL this page

TOTAL-Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
------	-----------------------	------------------------------	---

TOTAL brought forward from previous page

Airframe Logbook Entry	Paragon Aircraft Service, Inc. 19 Wright Way, Fairfield, NJ 07004 Phone: (973)575-0364 Fax (973)244-1884						Authorized Cirrus Service Center
Date	N' Number	Make/Model	Serial#	Flight	Hobbs	Total Time	W. O.
7/2/2019	N986CD	Cirrus SR22	1862	886.6	1879.4	1643.6	9840
All systems checked for condition and proper operation. Wheel bearings cleaned and repacked. Battery and brakes serviced. ELT checked I/A/W FAR 91.207(d). Battery replacement due 12/2025. Replaced induction air filter. Replaced damaged cowl seal. Installed new CAPS safety pin. Replaced gascolator quick drain. Replaced spindle cup, steering fork bushings, thrust washer, and hold down nut. Set nose steering to proper tension. Replaced nose gear pivot bushings and bearings. Replaced all no push placards on the tail. Replaced rescue placards. Replaced clamp for alternate air support tube. Set proper tension on left exhaust forward ball joint. Rotated tires on rim to extend tire life. Replaced right brake disk and linings. Adjusted timing on copilots door latches and adjusted lower door pin. All AD's checked thru 19-12.							
I certify that this aircraft has been inspected in accordance with an Annual Inspection and determined to be in an airworthy condition.							
I certify that the work described above was performed satisfactorily and in accordance with approved/acceptable data and is approved for return to service with regard to work performed.							
Authorized Signature:				 John L. Longaker A&P 3532411 IA			

Airframe Logbook Entry	Paragon Aircraft Service, Inc. 19 Wright Way, Fairfield, NJ 07004 Phone: (973)575-0364 Fax (973)244-1884						Authorized Cirrus Service Center
Date	N' Number	Make/Model	Serial#	Flight	Hobbs	Total Time	W. O.
7/24/2020	N986CD	Cirrus SR22	1862	898	1897.8	1655	10138
All systems checked for condition and proper operation. Wheel bearings cleaned and repacked. Battery and brakes serviced. ELT checked I/A/W FAR 91.207(d). Battery replacement due 12/2025. Replaced induction air filter. Replaced ELT remote switch battery, next due 7/2025. Replaced #2 batteries, next due 8/2022. Resealed rear window. Resecured wing aerodynamic firings. Replaced aileron/rudder interconnect bungee, next due 7/2025. Replaced right muffler. Rebuilt right brake caliper, installed new temperature stickers. Per FAR 91.213(d) EMA removed for service, AMsafe seatbelts disabled, panel placarded. All AD's checked thru 20-13.							
I certify that this aircraft has been inspected in accordance with an Annual Inspection and determined to be in an airworthy condition.							
I certify that the work described above was performed satisfactorily and in accordance with approved/acceptable data and is approved for return to service with regard to work performed.							
Authorized Signature:				 John L. Longaker A&P 3532411 IA			

Airframe Logbook Entry	Paragon Aircraft Service, Inc. 19 Wright Way, Fairfield, NJ 07004 Phone: (973)575-0364 Fax (973)244-1884						Authorized Cirrus Service Center
Date	N' Number	Make/Model	Serial#	Flight	Hobbs	Total Time	W. O.
8/20/2020	N986CD	Cirrus SR22	1862	904.7	1907.5	1661.7	10138
Installed overhauled EMA controller, P/N 508358-421 S/N RA05AUG20-18. Replacement due 08/27. Replaced #1 alternator installed overhauled unit P/N 646843 S/N 016DA033. Operational and leak check satisfactory.							
I certify that the work described above was performed satisfactorily and in accordance with approved/acceptable data and is approved for return to service with regard to work performed.							
Authorized Signature:				 John L. Longaker A&P 3532411			


SUB-TOTAL this page

TOTAL-Carry forward to next page

TOTAL brought forward from previous page

Airframe Logbook Entry	Paragon Aircraft Service, Inc. 19 Wright Way, Fairfield, NJ 07004 Phone: (973)575-0364 Fax (973)244-1884						Authorized Cirrus Service Center	
	Date	N' Number	Make/Model	Serial#	Flight	Hobbs		Total Time
	5/21/2021	N986CD	Cirrus SR22	1862	913.5	1920.3	1670.5	10556
Removed #1 alternator for repair P/N 646843 S/N 016DA033, reinstalled same alternator after repair. Operational and leak check satisfactory.								
I certify that the work described above was performed satisfactorily and in accordance with approved/acceptable data and is approved for return to service with regard to work performed.								
Authorized Signature: 						John L. Longaker A&P 3532411		

Airframe Logbook Entry	Paragon Aircraft Service, Inc. 19 Wright Way, Fairfield, NJ 07004 Phone: (973)575-0364 Fax (973)244-1884						Authorized Cirrus Service Center	
	Date	N' Number	Make/Model	Serial#	Flight	Hobbs		Total Time
	4/5/2022	N986CD	Cirrus SR22	1862	917.7	1927.1	1665.6	10645
All systems checked for condition and proper operation. Wheel bearings cleaned and repacked. Battery and brakes serviced. Replaced induction air filter, #5 EGT probe, 1 RH exhaust tailpipe spring, RH inboard wheel fairing bracket, annunciator panel, all flap hinges and LH mid flap hinge brackets. Checked and weighed cockpit fire extinguisher. ELT checked I/AW FAR 91.207(d). All AD's checked thru 22-06.								
I certify that this Aircraft has been inspected in accordance with an Annual Inspection and determined to be in an airworthy condition.								
I certify that the work described above was performed in accordance with approved/acceptable data and is approved for return to service with regard to work performed.								
Authorized Signature: 						Steven VanderValk A&P 2919106 IA		

Airframe Logbook Entry	Paragon Aircraft Service, Inc. 19 Wright Way, Fairfield, NJ 07004 Phone: (973)575-0364 Fax (973)244-1884						Authorized Cirrus Service Center	
	Date	N' Number	Make/Model	Serial#	Flight	Hobbs		Total Time
	9/5/2022	N986CD	Cirrus SR22	1862	930.1	1942.8	1677.8	11129
Installed overhauled alternator #1 646843 serial# 008HA105R, see 8130 from Aerotech of Louisville in aircraft records. Installed new #1 FCM and alt 1 circuit breaker. Installed new aircraft battery. Ran up and found charging system working normally.								
I certify that the work described above was performed satisfactorily and in accordance with approved/acceptable data and is approved for return to service with regard to work performed.								
Authorized Signature: 						Steven VanderValk A&P 2919106		

SUB-TOTAL this page

