

406 Yellowbird Road • Portland International Airport • Portland, ME 04102 (207) 780-1811 • Fax (207) 772-6900

CRS FSER011E

Next Due: Annual

Date	WO#	Registration	Type/Model	SN	Tach	ACTT
A STATE OF THE PARTY OF THE PAR				41044	849.3	849.3
12-09-13	37328	N611RJ	LC41-550FG	41044	04918	047.3

Inspected iaw Cessna Model 400 Annual Inspection Guide

The following airworthiness directives were complied with:

AD 07-07-06 R1 "Linear Bearing Inspection"—inspected aileron and elevator control system linear bearings per the AD Next Due: Annual No defects noted.

AD 13-11-10 "Maximum Braking Procedures"—inserted a copy of the AD in the aircraft AFM

Battery Due: Dec 2015 Complied with FAR 91.207(d) ELT Inspection

Complied with Aerospace Systems TKS System Annual Inspection Requirements

The following discrepancies were noted and corrected:

- Replaced dirty induction filter with new p/n BA345E Filter
- Replaced inop It. nav light bulb with new p/n 900-328-06 Bulb-ops check ok
- Resafety-wired right aft engine mount bolt lock tab as required
- Replaced deteriorated chafe tape on rt. flap as required
- Rebonded cabin interior trim attach bracket as required
- Replaced expired ELT battery with new p/n 452-3063 Battery
- Inspected It, fuel quantity indicating system components and wiring due to erratic operation—no defects noted. Cleaned wiring connectors and terminals. Reinstalled items removed for access. Refueled lt. wing-ops check ok
- Serviced brake reservoir
- Replaced worn lt. brake linings with new p/n 066-06200 Linings
- Replaced deteriorated It. brake caliper shim with new p/n 068-01100 Shim
- Repainted landing light lens border as required

I certify that this Aircraft has been inspected in accordance with an Annual Inspection, and was determined to be in airworthy condition. All applicable AD Notes have been completed with and this aircraft is approved for return to service.

Signature

Signature Such Maintenance, L.L.C, PORTLAND, MAINE

REPAIR STATION FSER011E



406 Yellowbird Road • Portland International Airport • Portland, ME 04102 (207) 780-1811 • Fax (207) 772-6900

CRS FSEROTTE

Date	WO#	Registration	Type/Model			
12-29-14	38280	N6IIRJ	LCAL SERVIC	SN	Tach	ACTT
Inspected iaw Cessna Model 400 Annual Inspection C			Juide	41044	933.2	933.2

The following airworthiness directives were complied with:

AD 07-07-06 R1 "Linear Bearing Inspection"—inspected aileron and elevator control system linear bearings per the AD

Complied with FAR 91 207(d) ELT Inspection Next Due: Annual Battery Due: Dec 2015 Complied with Aerospace Systems TKS System Annual Inspection Requirements Next Due: Annual The following discrepancies were noted and corrected:

- Replaced dirty induction filter with new p/n BA345E Filter
- Removed and reinstalled #2-4-6 exhaust riser assembly after repair by Dawley Aviation (WO 111326) Touched up paint on landing light lens frame, windshield and lt. wing tip
- Rebonded I cabin side wall attach bracket to cabin floor
- Replaced It. and rt. entry step tread with new p/n 09-31675 Non-skid Tape
- Removed intermittent lt. outboard fuel quantity transmitter. Cleaned potentiometer contacts and reinstalled—ops check ok Removed and reinstalled oxygen bottles s/n NN0621732, NN0621936, and NN0623158. Hydrostatic Test performed by SEMCO Aerospace,
- Replaced unserviceable audio panel s/n 96269234 with overhauled p/n 011-00401-10 GMA340P Audio Panel s/n 96295555—ops check ok
- Repaired cosmetic cracks around It. and rt. cockpit door windows iaw Cessna LC41-550FG SRM

I certify that this Aircraft has been inspected in accordance with an Annual Inspection, and was determined to be in airworthy condition.

All applicable AD Notes have been completed with and this aircraft is approved for return to service.

MAINE AVIATION AIRCRAFT MAINTENANCE, L.L.C, PORTLAND, MAINE