wo: GA 2844 Airframe · page 1 of 2



Glencoe Aviation · 6253 Airport Industrial Blvd · GONZALES, LA 70737 · 225-460-3636

N52MK CIRRUS DESIGN CORP, SR22T, S/N: 2468 March 13, 2025

Flight: 197.5 Hobbs: 244.9

- 1. Performed annual inspection IAW 14CFR43 and Cirrus SR AMM 5-20 as a guide.
- 2. Performed ELT test IAW 91.207 with satisfactory results. * Battery Due Replacement 12/2027*
- 3. Removed inspection panels. Inspected, operated, and lubricated flight controls and control surfaces. Inspected fuselage and wings for defects with non found. Installed inspection panels.
- 4. Operated and inspected all lighting with no defects noted.
- 5. Researched AD's SB's and Life Limited components. All AD's and SB's are complied with thru DRS Bi-Weekly 2025-04. Inspected life limited components and found to be current
- 6. Weight check fire extinguisher and found to be within limits.
- Removed MLG Fairings and inspected wheels and brakes and found brake pads to be within serviceable limits. Jacked A/C performed NLG inspection and tension test and found to be within limits. Installed removed fairings.
- 8. Completed SB2X-76-05, removal of the upper power lever with a visual inspection & a fluorescent dye penetrant and developer, no cracks.
- 9. Removed and replaced RH & LH intake air filters P/N AA27166-001
- 10. Operated and inspected Precise Flight O2 System with satisfactory results
- 11. Operated and inspected TKS system with satisfactory results. 12 Battery #2 Due Replacement 1/2026

I CERTIFY THAT THIS AIRFRAME HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL IN-SPECTION AND IS IN AIRWORTHY CONDTION AT THIS TIME.



Glencoe Aviation · 6253 Airport Industrial Blvd · GONZALES, LA 70737 · 225-460-3636

With respect to the work performed, this airframe is approved for return to service. Details of work performed are on file with Glencoe Aviation under work order: GA 2844.

Ian Crump I/A 4507777 _____