ENGINEERING RECORD

INSPECTION, REPAIRS & REPLACEMENT DRAW A DIAGONAL LINE THROUGH ANY UNUSED LINES IN DATE AND TIME COLUMNS.		SIGNATURE	LICENCE	
Inspected and teste Replaced ELT Batt Main battery failed Replaced Emergent Replaced main batt Verified all AD's ha AD list is attached I certify that this air	d ELT IAW FAR Part 9 ery. Next due DEC 2021. capacity check. Replace by backup battery with never air duct eve been complied with the aircraft logs.	END identified above was inspected and repaired I	2025. R 2019	ions and
		3000		