N 3695 F



## ENGINE LOG BOOK

Publication ELB-01 JUN 2019

ď

nd 35.



Steel Aviation - 53 North Street Ext - Phillipsburg, Ohio 45354 - 937 332 7587

N369SF HOBBS: 2582.9

Continental, IO-550-N(43), S/N: 1041851

March 01, 2023

TACH: 2203.9

IO-550-N(43), ENGINE PN: IO-550-N(43), SN: 1041851,

1. R&R Engine s/n 691694 WITH FACTORY REMANUFACTURED ENGINE S/N 1041851 Installed (2) P/N 15077-003 - Weldment, Tailpipe SR22 Black, Installed P/N AE3663163G0100 - HOSE, TYPE D, RETURN FROM FUEL PUMP, Installed P/N AE3663163H0137 - HOSE, TYPE D, FIREWALL TO BOOST PUMP, Installed P/N AE3663161E0070 - HOSE, TYPE D, BAFFLE TO XDUCER, Installed P/N AE3663162E0106 - HOSE, TYPE D, SDILCER TO AE3663163E0106 - HOSE, TYPE D, SDILCER TO AE366316 - HOSE, XDUCER TO METERING BLOCK, Installed P/N AE3663162G0106, 51018-001 - HOSE, TYPE D, FUEL PUMP TO BAFFLE ID STATE OF THE PUMP T TO BAFFLE, Installed P/N 19815-016 - MCU To Alternator 2, Shielded, Installed P/N 19815-004 - MCU To Alternator 1, Shielded, Installed P/N 19815-020 - MCU To Battery, Installed P/N 19815-030 - MCU To Starter, Installed P/N 20140-003 P/N 20140-003 - Engine Mount Attach Plate, Installed (3) P/N 11314-003 - Rod End, Female, Installed (6) P/N AEC-169-380098-1, 13386-001 - NLG PUCKS, SR22, Installed (2) P/N NAS77-10-013 - BUSHING, FLANGED, PRESS FIT, Installed (2) P/N 13705-003 - SPACER, BUSHING, NLG, Installed (6) P/N 96301-01 - BARRY MOUNT Installed (2) P/N 13705-003 - SPACER, BUSHING, NLG, Installed (6) P/N 96301-01 - BARRY MOUNT, Installed P/N AE3663163H0180 - HOSE, TYPE D, GASCOLATOR TO ENGINE PUMP, Installed P/N AN178-45A - Bolt, Installed P/N 38562-001, AE3660001B0120 - Oil Pressure Sensor, 12", Straight To Straight Fittings Installed P/N 105120 - Oil Pressure Sensor, 12", Straight To Straight Straight To Straight To Straight To Straight Straight To Straight Straig Fittings, Installed P/N 38562-001, AE3660001B0120 - OII Pressure Sensor, 12 , Straight to Straight Fittings, Installed P/N 16546-001 - Frame, Engine Mount, S/N 6 Point S/N: 3052, Installed P/N NAS1523-8B - GASCOLATOR, Stat-O-Seal, Installed P/N MS29513-015 - O RING, Installed P/N MS29513-137 - O RING, P/N 656802 - ALTERNATOR SALTERNATOR HARTZFIL 70 AMP P/N 656802 - ALTERNATOR S/N: H-U010777, Installed P/N ES-7024-14 - ALTERNATOR, HARTZELL, 70 AMP S/N: H-W071931, Installed P/N 18841-002 - Seal Duct Recognition Light, Installed P/N 20153-002 - Collector, Exhaust, SR22, Installed P/N 50908-001 - Gascolator Filter, Installed P/N 646655 - ALTERNATOR DRIVE COU-PLING, elastomeric, Installed P/N 50908-001 - Gascolator Filter, Installed P/N 640000 - ALI EDINATOR DRIVE COORDING, elastomeric, Installed P/N C290D3-R/T23 - PROP GOV. S/N: 072016, Installed P/N 657970 - V BELT, ALT 2, W/PERSPECTIVE, Installed (2) P/N 51021-001 - SPRING EXTENSION, ENG BAFFLE, Installed P/N SI 6 - BELE BROWN ALT 2008 - CARRIED SL6 - REIFF PRE HEATER, STANDARD, IO 550, Installed P/N A14836-001 - CIRRUS MUFFLER S/N: 226823,

wo: WO\_76

Engine · page 2 of 2



Steel Aviation  $\cdot$  53 North Street Ext  $\cdot$  Phillipsburg, Ohio 45354  $\cdot$  937 332 7587

Installed P/N A14837-001, 14837-001 - Heat Exchanger, SR22, Inconel, S/N 0320-2437, Installed P/N 18892-003 - Insulation sleeve, NACA Duct To Mixing Box, Installed P/N RG24-15M - MAIN BATTERY, CONCORD, 24V S/N: 41269857, Installed P/N SCEET-12 - SCEET DUCTING, Installed P/N SCEET-10 X 27 WITH CUFFS - SCEET DUCT, 2.5 DIA X 27 W/SEALED ENDS, Installed P/N SCEET-10 X14" WITH CUFFS - SCEET DUCT, 2.5 DIA X 27 W/SEALED ENDS, Installed P/N SCEET-10 X14" WITH CUFFS - SCEET DUCT, 2.5 DIA X 14 M/SEALED ENDS, Installed P/N SCEET-10 X14" WITH CUFFS - SCEET DUCT, 2.5 DIA X 14 M/SEALED ENDS, Installed P/N SCEET-10 X14" WITH CUFFS - SCEET DUCT, 2.5 DIA X 14 M/SEALED ENDS, Installed P/N SCEET-10 X 14 M/SEALED ENDS, Installed P/N SCEET-10 X 14 M/SEALED ENDS, Installed P/N SCEET-10 X 14 WITH CUFFS - SCEET DUCT, 2.5 DIA X 14 M/SEALED ENDS, Installed P/N SCEET-10 X 14 WITH CUFFS - SCEET DUCT, 2.5 DIA X 14 M/SEALED ENDS, Installed P/N SCEET-10 X 14 WITH CUFFS - SCEET DUCT, 2.5 DIA X 14 M/SEALED ENDS, Installed P/N SCEET-10 X 14 WITH CUFFS - SCEET DUCT, 2.5 DIA X 14 M/SEALED ENDS, Installed P/N SCEET-10 X 14 WITH CUFFS - SCEET DUCT, 2.5 DIA X 14 M/SEALED ENDS, Installed P/N SCEET-10 X 14 WITH CUFFS - SCEET DUCT, 2.5 DIA X 14 M/SEALED ENDS, Installed P/N SCEET-10 X 14 WITH CUFFS - SCEET DUCT, 2.5 DIA X 14 M/SEALED ENDS, Installed P/N SCEET-10 X 14 WITH CUFFS - SCEET DUCT, 2.5 DIA X 14 M/SEALED ENDS, INSTALLED ENDS, INST 2.5 DIA. X 14 W/SEALED ENDS, Installed P/N SCEET-10 X 12.5 WITH CUFFS - SCEET DUCT, 2.5 DIA. X 12.5

- 2. Serviced engine with 20/50M. Adjusted Fuel System IAW Continental M-0 Installed (8) P/N Mineral SAE20W50
- 3. Muffler and heat exchanger C/W with at engine install.

With respect to the work performed, this Engine is approved for return to service. Details of work performed are on file

Brad Helman A&P 3939968	
	_



Steel Aviation · 53 North Street Ext · Phillipsburg, Ohio 45354 · 937 332 7587

N369SF

Continental, IO-550-N(43), S/N: 1041851

March 01, 2023

HOBBS: 2582.9

TACH: 2203.9

IO-550-N(43), ENGINE PN: IO-550-N(43), SN: 1041851,

C/W Annual Inspection in accordance with FAR 43 Appendix D using Cirrus AMM as a guide.

I certify that this ENGINE has been inspected in accordance with an (annual) inspection and was determined to be in airworthy condition. Details of work performed are on file with Steel Aviation under work order: WO\_76.

ff Pleima	an A/P I/A	3304319	p	1/_	S Muc	