USE ONLY FUEL CONFORMING TO ASTM D910 USE OF AUTOMOTIVE GAS IS NOT APPROVED.



Teledyne Continental Motors, Inc. A Teledyne Technologies Company

Printed: 03/18/2008

This engine model 10360ES21, Serial No. 360663 was manufactured on 03/17/2008 by Teledyne Continental Motors in accordance with approved design data and the applicable requirements of Part 21 of the Federal Aviation Regulation. The approved design data for this engine incorporates all changes required by applicable Airworthiness Directives and Teledyne Continental Motors Service Bulletins.

TELEDYNE CONTINENTAL MOTORS

A TELEDYNE TECHNOLOGIES COMPANY PRODUCTION CERTIFICATE NO. 508

	Hrs. Min. Hrs. Min. Installations, Inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins July 11, 2008 N184PG S/N 1965 31.6 Elizabeth Main.
-	July 11, 2008 N184PG S/N 1965 31.6 Flight Hobbs
	Performed first 25 hour inspection in accordance with Cirrus check list
	OK. END.
	The maintenance amounting () I is a
4	The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to a second or secon
	with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details
	are on file under work order 4723.
	- /1-4
111	- Hiller
	Brian A. Smith
	Repair Station MYNR748K
	11329 East State Road 32 Zionsville, IN 46077
	317 - 769 - 4487 Certified Repair Station No. MYNR748K
- Marie	
Contraction of the Contraction o	
1000	
	August 12, 2008 N#184PG S/N 1965 FLT Time 49.9
	August 12, 2008 N#184PG S/N 1965 FLT Time 49.9
	Changed engine oil and filter. Serviced engine with Aeroshell 100W. Washed engine
	Changed engine oil and filter. Serviced engine with Aeroshell 100W. Washed engine and lubed controls. Run-up and leak check goodEND
	Changed engine oil and filter. Serviced engine with Aeroshell 100W. Washed engine and lubed controls. Run-up and leak check goodEND The maintenance operation(s) described above were inspected in accordance with current
	Changed engine oil and filter. Serviced engine with Aeroshell 100W. Washed engine and lubed controls. Run-up and leak check goodEND The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found
	Changed engine oil and filter. Serviced engine with Aeroshell 100W. Washed engine and lubed controls. Run-up and leak check goodEND The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 4768.
	Changed engine oil and filter. Serviced engine with Aeroshell 100W. Washed engine and lubed controls. Run-up and leak check goodEND The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 4768. Paul Jlan
	Changed engine oil and filter. Serviced engine with Aeroshell 100W. Washed engine and lubed controls. Run-up and leak check goodEND The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 4768. Paul W. Enlow
	Changed engine oil and filter. Serviced engine with Aeroshell 100W. Washed engine and lubed controls. Run-up and leak check goodEND The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 4768. Paul Jlan
	Changed engine oil and filter. Serviced engine with Aeroshell 100W. Washed engine and lubed controls. Run-up and leak check goodEND The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 4768. Paul W. Enlow
	Changed engine oil and filter. Serviced engine with Aeroshell 100W. Washed engine and lubed controls. Run-up and leak check good.———END————END——————————————————————————
	Changed engine oil and filter. Serviced engine with Aeroshell 100W. Washed engine and lubed controls. Run-up and leak check goodEND The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 4768. Paul W. Enlow

/2008

icable

cone

for this ledyne

ate	Total Time Time Since	
Annu	ball 100W. Washed engine	. Changed oil and filter. Serviced engine with abed controls. Compression cks. #1 77/80 #2 #6 72/80. Cleaned fuel screen, and oil screen. od thru 2008-19END
	and with respect to work perform	ove were inspected in accordance with current med, the aircraft and/or component was found
Paul W.	y and is approved for return to servi	ice. Details are on file under work order 4883.
Paul W.	y and is approved for return to servi	ice. Details are on file under work order 4883. MONTGOMER' AVIATION, INC.
Paul W.	y and is approved for return to servi	ice. Details are on file under work order 4883. MONTGOMER

N184PG S/N 1965 FLT Time 138.5 December 30, 2008 Changed oil and filter. Cut filter open and found no metal. Serviced engine with 8 qts. Aeroshell 80W. Washed engine and lubed controls. Run-up and leak check good.-END-The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Detail(s) are on file under work order 5000. Paul W. Enlow Repair Station MYNR748K MONTGOMERY 11329 East State Road 32 Zionsville, IN 46077 317 - 769 - 4487 Certified Repair Station No. MYNR748K

	July 7 2000 Magazo		cord		
	3419 7, 2009 N184PG S/N 196	55 FLT and Total Time 202.7 Hobbs Time 261.6	pections		
t F	Completed annual inspection this date. Changed oil and filter, cut filter open and found no metal. Serviced engine with 8qts. Aeroshell 100W. Washed engine and lubed controls. Cleaned oil screen. Cleaned fuel screen. Compression cks. #1 76/80 #2 77/80 #3 77/80 #4 76/80 #5 75/80 #6 78/80. Run-up and leak check good. AD's good thru 2009-11ENDEND				
	regulations and Mith Lespect to Mork	ibed above were inspected in accordance with current performed, the aircraft and/or component was found to service. Details are on file under work order 5251 .			
		MONTGOMER AVIATION, I			
		11329 East State Road			
		Zionsville IN 460			
		Zionsville, IN 460 317 - 769 - 44 ——————————————————————————————————	187		

TES

September 3, 2009 N184PG S/N 1965 FLT Time 255.2 Hobbs Time 322.3

Changed oil and filter, cut oil filter open and found no metal. Serviced engine with Aeroshell 100W. Washed engine and lubed controls. Run-up and leak check good.

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 5326.

Paul W. Enlow

Repair Station MYNR748K



MONTGOMERY AVIATION, INC.

11329 East State Road 32 Zionsville, IN 46077 317 - 769 - 4487

Brought Forw	November 11, 2009 N184PG S/N 1965 FLT and Total Time 304.0 Hobbs 383.7 Completed annual inspection this date. Changed oil and filter, cut filter open and found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and lubed found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and lubed found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and lubed found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and lubed found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and lubed found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and lubed found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and lubed found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and lubed found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and lubed found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and lubed found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and lubed found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and lubed found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and lubed found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and lubed found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and lubed found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and lubed found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and lubed found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and lubed found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and lubed found no metal. Serviced engine with 8qts. Aeroshell 80W. Washed engine and 8qts. Aeroshell 80W. Wa			
	The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 5432. Paul W. Enlow			
	airworthy and is approved for return to service. Details are on file under work order 5432. Paul W. Enlow			
	airworthy and is approved for return to service. Details are on file under work order 5432.	Ċ.		
	airworthy and is approved for return to service. Details are on file under work order 5432. Paul W. Enlow Repair Station MYNR748K MONTGOMERY AVIATION, INC. 11329 East State Road 3 Zionsville, IN 4607	c. 2 7		
	airworthy and is approved for return to service. Details are on file under work order 5432. Paul W. Enlow Repair Station MYNR748K MONTGOMERY AVIATION, INC. 11329 East State Road 3	c. 2 7		

April 28, 2010 N184PG S/N 1965 FLT Time 368.5

Changed oil and filter, cut filter open and found no metal. Serviced engine with 8qts. Aeroshell 100W. Washed engine and lubed controls. Run-up and leak check good. Inspected left and right mufflers. Checked good.

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 5635.

Paul W. Enlow

Repair Station MYNR748K



MONTGOMERY AVIATION, INC.

11329 East State Road 32 Zionsville, IN 46077 317 - 769 - 4487

August 31, 2010 N184PG S/N 1965 Flight Time 449.2 Changed oil and filter, cut filter open and found no metal. Serviced engine with 8qts. Aeroshell 100W. Washed engine and lubed controls. Run-up and leak check good. -----FND-----The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 5858. Paul W. Enlow Repair Station MYNR748K MONTGOMERY AVIATION, INC. 11329 East State Road 32 Zionsville, IN 46077 317 - 769 - 4487 Certified Repair Station No. MYNR748K

Completed 100HR per Cirrus Ch. 5 Scheduled Maintenance Report. Changed oil and Completed 100HR per Cirrus Cir. 5 Schedules in the Report. Changed oil and filter, cut filter open and found no metal. Serviced engine with 8qts. Aeroshell 80W. filter, cut filter open and round no medical screen. Cleaned fuel screen. Installed Washed engine and lubed controls. Cleaned Compression checker. #4 75 (c). Washed engine and Jupea Controls. Closed Good. Compression checks- #1 76/80 #2 77/80 all new spark plugs. Timings checked good. Run-up and operational checks. Brought For all new spark plugs. Timings checked 30. Run-up and operational check good. AD's #3 77/80 #4 76/80 #5 76/80 #6 75/80. Run-up and operational check good. AD's good thru 2011-03.-----END-----The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 6098. Paul W. Enlow Repair Station MYNR748K 11329 East State Road 32 Zionsville, IN 46077 317-769-4487 Certified Repair Station No. MYNR748K ENGINE MODEL: 10360FS Commander Aero, Inc. DATE: 6/7/2011 ENGINE S/N: 360663 REG NO: N184PG A/C TSN: 541 Repair Station No. GA5R-876M ENG TT: 541 WORK ORDER 10570 Springboro Pike 28630-05-2011 FLIGHTTIME: 541 Miamisburg, Ohio 45342 USA Phone: 888-881-5580 **Engine Entries** (2) Complied with 100 Hour Engine Inspection. Changed oil and filter. Serviced with Aeroshell 100W.... (5) Checked Compression -1) 75/80; 2) 76/80; 3) 76/80; 4) 74/80; 5) 76/80; 6) 70/80.... (6) Took oil sample.... (17) Cleaned, gapped, and tested spark plugs. Rotated plugs and installed new gaskets.... (18) Replaced induction system filter.... (17) Removed cleaned and reinstalled nozzles.... (20) Removed baffle on left side of engine. Replaced with new baffle... (22) Removed mags and sent out for 500 hr mag inspection. Reinstalled in same position after 500 inspection was completed.... (24) Washed down engine and ran for leak check. I certify that this engine was inspected in accordance with a 100 hour inspection and found to be airworthy. The aircraft and/or component(s) on N184PG was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for setup to second provided in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 28630-05-2011. DATE: 6/7/2011 SIGNED: Kromer, Gary Work Order: 28630-05-2011

Certified Repair Station No. GA5R-876M

March 1, 2011 N184PG SR-20 S/N 1965 FLT and ENG/TT 493.7 Hobbs Time 602.5

Date

ord

ions.

Printed by EBis 3 (datcomedia.com)

Broug

DATE: 6/7/2011

SIGNED:

Kromer, Gary
Certified Repair Station No. GASR-876M

Certified Repair Station No. GASR-876M

Certified Repair Station No. GASR-876M

June 5, 2012 N184PG S/N 360663 Flight Time 603.0 ETT 100hr/Annual Inspection Completed This Date. Inspected IAW Cirrus Inspection Report ATA 05-20. Compression test 1)75/80 2)78/80 3)74/80 4)75/80 5)76/80 6)74/80.

Changed oil and filter, opened filter, OK, serviced with Aeroshell W100.

Lubed per lube chart items due. Installed new air filter element. Installed new boots on "P" leads. Cleaned Hi Tension lead spark plug ends. Installed new spark plug #6 top.

Post run /leak check IAW 05-30 normal.


ADs checked thru BW 2012-10 no ADs due at this time.

See AD list for full details.

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service.

Details are on/file under work order 6801

Ed Hobelman MYNR748K



11329 East State Road 32 Zionsville, IN 46077 317-769-4487

mught For


ord

tions.

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 7387.

Paul W. Enlow

Repair Station MYNR748K



11329 East State Road 32 Zionsville, IN 46077 317-769-4487

August 15, 2014 N184PG M/N IO-360-ES S/N 360663 FLT and ENG Total Time 643.3 Hobbs Time 752.9

Annual inspection completed I/A/W Cirrus SR20 AMM Ch.5 Scheduled Inspection Report. Changed oil and filter, cut filter open and found no metal. Serviced engine with 8qts. Aeroshell 100W. Washed engine and lubed controls. Cleaned oil screen. Cleaned, gapped and rotated spark plugs. Cleaned fuel screen. Compression checks-#1 79/80, #2 74/80, #3 76/80, #4 74/80, #5 74/80, #6 74/80. Master Orifice 46 psi. Cleaned all fuel injectors, next due cleaning at 943. FLT Time. Installed new gasket for oil service cap. Adjusted idle to 750 rpm's. Run-up and operational checks good. Reviewed AD's thru 2014-07-28.-----END------

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 7904.

Paul W. Enlow

Repair Station MYNR748K



11329 East State Road 32 Zionsville, IN 46077 317-769-4487

Time Since Total Time Last Overhaul Date Min. Hrs.

Hrs.

Engine Service and Maintenance Reco

Installations, Inspections, Airworthiness Directives, Special Inspect Modifications and Service Bulletins

aht Fol

S/N 360663 M/N 10-360-ES 9/04/2015 N184PG FLT and Engine Total Time 673.2 Hobbs Time 782.8

Complied with Annual inspection I/A/W Cirrus SR20 AMM chapter 5 scheduled inspection report. Profiled blades. Drained engine oil. Removed oil filter. Cut open filter. No metals found. Installed new filter. Cleaned oil screens. Serviced with 8 qts of Aeroshell W100 oil. Compression tests #1 72/80 #2 70/80 #3 68/80 #4 72/80 #5 74/80 #6 76/80 Master Orifice 45 psi. Cleaned fuel screen. Cleaned engine and lubed controls. Cleaned, gapped and rotated spark plugs. Run-up and operational checks good.Ads good thru 2015/9

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service,

Details are on file under work order 8371.

Donald Brown MYNR748K

11329 East State Road 32 Zionsville, IN 46077 317-769-4487

S/N:360663 Hobbs Time: 840.0 M/N:10-360-ES N184PG Date: October 26, 2016

FLT Time and Engine Total Time: 730.4

Completed Annual Inspection IAW Cirrus SR20 CH 05-20 Scheduled Inspection Report. Changed engine oil and filter. Obtained oil sample and sent to Blackstone Laboratories for oil analysis. Serviced engine with Aeroshell 100W oil. Installed new filter P/N CH48108-1. Inspected old filter and no visible metal was noted. Performed engine compression check. Results are as follows: 1)75/80 2)75/80 3)74/80 4)72/80 5)73/80 6)74/80 master orifice: 43/80. Cleaned, gapped, and rotated spark plugs. Washed engine with solvent and lubricated engine controls. Re-adjusted cyl #2 drain line so that it isn't chaffing into baffle spring. Installed new seals for cylinder 1, 4, 6, and 5 push rod tubes. Leak check ok. AD's reviewed thru 10/26/2016. Final Run-up ops and leak check ok.

The maintenance operation(s) described above were inspected in accordance with current FAA regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service.

Details are on file at this agency under work order 8797.

1MYR828C



11329 East State Road 32 Zionsville, IN 46077