N427KG



## ENGINE MAINTENANCE RECORDS

wo: WO\_338

D . . . . M.



Flightlogix · 4510 Airport Road · Cincinnati, OH 45226 · 513-321-1200

N427KG

Continental, IO-550-N51B, S/N: 691745

August 1, 2019

Engine · page 1 of 1

Tach: 1571.8 Hobbs: 1902.2

1. Inspected this engine I/A/W a 100hour/Annual inspection per 14 CFR 43 Appendix D and Cirrus SR22 AMM rev. B5 Chapter 5-20.

2. Cleaned and gapped spark plugs Installed (12) P1003 - Spark Plug Washer, Installed (1) URHB32E - Spark Plug.

3. Engine compressions taken. Master orifice: 43, Cylinder #1: 68, #2: 60, #3: 75, #4: 70, #5: 65, #6:62.

4. Removed, cleaned, oiled and re-installed Induction air filter.

5. Oil change completed. Drained engine oil. Serviced with (8) 15W50 - Aeroshell.

6. Cut open old filter and inspected for metal debris. None found.

7. Installed (1) AA48108-2 - Oil Filter.

8. Oil sample taken (1) 1151 - Kit: oil analysis, AOA.

9. Added 12.8 ounces 08-07097-1 - camguard.

10. Post maintenance run up and leak checks good.

11. Adjusted engine idle and fuel flow.

12. Installed new LH exhaust header assembly and exhaust dump tube. Installed (1) 22-6100031 - Exhaust dump tube, Installed (1) 22-6850011 - Exhaust manifold left, Installed (1) MGKC - Gasket Kit.

With respect to the work performed, this engine is approved for return to service. Details of work performed are on file with Flightlogix under work order: WO\_338.

Greg Herrmann A&P IA 406901563 \_

