

PROP

LOGS



McGregor Executive Airport
 355 McGregor Airport Road
 McGregor, TX 76657
 Phone: 254-848-2345
 Fax: 254-848-2555

N#:	<u>N721KK</u>	Make:	<u>Cirrus</u>
H/M:	<u>184.7</u>	Model:	<u>SR22T</u>
Date:	<u>10-5-12</u>	S/N:	<u>0193</u>

PTT: 147.7

Performed an **Annual Inspection** as required by FAR 91.409 in accordance with the Cirrus SR22T service manual, and FAR 43 Appendix D. I certify that this propeller was inspected in accordance with an **Annual Inspection** and was determined to be in an airworthy condition.

(Authorized Signature)

for CRS# U9RR733J

Details of the work performed are on file at this station, reference Work Order #: AA12-0435



Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		



McGregor Executive Airport
 355 McGregor Airport Road
 McGregor, TX 76657
 Phone: 254-848-2345
 Fax: 254-848-2555

N#: N721KK Make: Cirrus
 H/M: 388.6 Model: SR22T
 Date: 11-11-13 S/N: 0193


PTT: 322.9

Performed an **Annual Inspection** as required by **FAR 91.409** in accordance with the Cirrus SR22T service manual, and FAR 43 Appendix D. I certify that this **propeller** was inspected in accordance with an **Annual Inspection** and was determined to be in an airworthy condition.

(Authorized Signature)

for CRS# U9RR733J

Details of the work performed are on file at this station, reference Work Order #: AA13-0158



**Glendale Aero Services**

6841 N. Glen Harbor Blvd
Glendale, AZ 85309
623-414-4930

Registration: **N721KK****PROPELLER LOG**

Date: 12/5/2014

W/O: 6001034

Model: PHC-J3YF-1N

Flt Hobbs: 421.9

S/N: NJ501B

TSMOH: 421.9

Complied with annual inspection IAW 14 CFR 43 Appendix D using the Cirrus Aircraft annual inspection checklist CH 5-20.

AD's researched thru T-Data content revision 2014-24, see attached AD compliance list for details.

Serviced propeller with Aeroshell 6 grease. Inspected and profiled minor nicks in blades as required.

Post maintenance ground run-up and operational checks performed with no leaks or defects noted.

I certify this propeller has been inspected in accordance with an Annual / 100 Hr. inspection and was determined to be in airworthy condition

SIGNATURE: Kenneth Morgan III

FAA AUTHORIZATION:

322829269 IA



Glendale Aero Services

6841 N. Glen Harbor Blvd
Glendale, AZ 85309
623-414-4930

Registration: **N721KK**

Date: 12/9/2015

Model: PHC-J3YF-1N

S/N: NJ501B

PROPELLER LOG

W/O: 6001430

Flt Hobbs: 517.4

TSMOH: 517.4

Complied with an Annual inspection IAW 14 CFR 43 Appendix D in reference to the Cirrus Aircraft annual inspection checklist CH 5-20 & Precise Flight ICA.

AD's researched thru T-Data content revision 2015-24, see attached AD compliance list for details.

Serviced propeller with Aeroshell 6 grease. Inspected and profiled minor nicks in blades as required.

Post maintenance ground run-up and operational checks performed with no leaks or defects noted.

I certify this propeller has been inspected in accordance with an Annual / 100 Hr. inspection and was determined to be in airworthy condition

SIGNATURE: John Fisher

FAA AUTHORIZATION:

2734397/ IA



Glendale Aero Services

6841 N. Glen Harbor Blvd
Glendale, AZ 85309
623-414-4930

Registration: **N721KK**

Date: 9/28/2016

Model: PHC-J3YF-1N

S/N: NJ501B

W/O: 6001726

Flt Hobbs: 563.9

TSMOH: 563.9

PROPELLER LOG

Complied with an Annual inspection IAW 14 CFR 43 Appendix D in reference to the Cirrus Aircraft annual inspection checklist CH 5-20 & Precise Flight ICA.

AD's researched thru T-Data content revision 2016-19, see attached AD compliance list for details.

Removed propeller assembly. Removed crankshaft seal and propeller o-ring. Installed new crankshaft seal p/n 641250 and prop o-ring p/n C-3317-228. Removed and replaced alternator belt with new p/n 657970, tensioned to specified limits. Re-installed propeller and torqued to specified limits. Blade track checked and found within limits. MX performed IAW Cirrus AMM Chapter 61 and Hartzell Manual 115N.

Serviced propeller with Aeroshell 6 grease. Inspected and profiled minor nicks in blades as required.

Post maintenance ground run-up and operational checks performed with no leaks or defects noted.

I certify this propeller has been inspected in accordance with an Annual / 100 Hr. inspection and was determined to be in airworthy condition

SIGNATURE: James Butler

FAA AUTHORIZATION:

2833700 IA

**Glendale Aero Services**

6841 N. Glen Harbor Blvd
Glendale, AZ 85309
623-414-4930

Registration: **N721KK**

Date: 10/5/2017

Model: PHC-J3YF-1N

S/N: NJ501B

W/O: 6002146

Fit Hobbs: 646.7

TSMOH: 646.7

PROPELLER LOG

Complied with an Annual inspection IAW 14 CFR 43 Appendix D in reference to the Cirrus Aircraft annual inspection checklist CH 5-20 & Precise Flight ICA.

AD's researched thru T-Data content revision 2017-19, see attached AD compliance list for details.

Serviced propeller with Aeroshell 6 grease. Inspected and profiled minor nicks in blades as required.

Adjusted propeller governor ¼ turn CW to increase RPM to specified limits at full rated power IAW SR22 AMM Chapter 61.

Post maintenance ground run-up and operational checks performed with no leaks or defects noted.

I certify this propeller has been inspected in accordance with an Annual / 100 Hr. inspection and was determined to be in airworthy condition

SIGNATURE: James Butler

FAA AUTHORIZATION:

2833700 IA



Glendale Aero Services

6841 N. Glen Harbor Blvd
Glendale, AZ 85309
623-414-4930

Registration: **N721KK**

Date: 11/9/2018

Model: PHC-J3YF-1N

S/N: NJ501B

W/O: 6002598

Flt Hobbs: 723.8

TSMOH: 723.8

PROPELLER LOG

Complied with an Annual inspection IAW 14 CFR 43 Appendix D in reference to the Cirrus Aircraft annual inspection checklist CH 5-20 & Precise Flight ICA.

AD's researched thru T-Data content revision 2018-22, see attached AD compliance list for details.

Serviced propeller with Aeroshell 6 grease. Inspected and profiled minor nicks in blades as required.

Post maintenance ground run-up and operational checks performed with no leaks or defects noted.

I certify this propeller has been inspected in accordance with an Annual / 100 Hr. inspection and was determined to be in airworthy condition

SIGNATURE: James Butler

FAA AUTHORIZATION:

2833700 IA