

**HARTZELL**

# PROPELLER LOGBOOK

PROPELLER MODEL PHC-J3Y1F-1W

PROPELLER S/N NJ1240B

LOGBOOK # \_\_\_\_\_

# PROPELLER MAINTENANCE RECORD

Position One

PITCH RANGE

Propeller Model PHC-J3Y1F-1N

High/Feather \_\_\_\_\_

Propeller S/N NJ1240B

Start Lock \_\_\_\_\_

Blade Design N7605CB

Low \_\_\_\_\_

Blade S/N's

Reverse \_\_\_\_\_

No. 1 B1954

No. 2 B1956

Aircraft Manufacturer Cirrus Design Corp.

No. 3 B1936

Aircraft Model SR22T

No. 4 \_\_\_\_\_

S/N 1249

No. 5 \_\_\_\_\_

Registration N153AT

No. 6 \_\_\_\_\_

Spinner Assembly Part No. \_\_\_\_\_





Hangar 1 Aeropuerto Internacional Miguel Hidalgo Guadalajara, Jalisco, México  
Phone: 01 3332842300 C.P. 45659

# PROPELLER MAINTENANCE LOGBOOK

Pag: 1/1

Date: MAY 23, 2017	Register: XA-GTS	Model CIRRUS SR22T		
MFD: MAR 04-2016	TT: 99.0	TC: 94	WO: 05	249
Propeller Model PHC-J3Y1F-1N	TT: 99.0	TC: 94	S/N M1240B	

### INSPECTIONS:

- 100 Hr. Propeller Inspection was performed IAW CH 05-20.

I certify that this Aircraft has been inspected in accordance with CIRRUS SR 22 AMM, and determined to be in Airworthy condition. AD's and SB's were research up to date.

The Aircraft, airframe or appliance identified above was maintained and/or altered and inspected in accordance with current Regulations issue by the DGAC and Maintenance Manual Recommendations is approved for return to service./ DGAC Repair Station No. 132

Sign: \_\_\_\_\_

Insp. Alvaro Espejo Rodriguez.

Lic. Dgac 200106971.

**AEROTRON**  
CORPORATIVOS S.A. DE CV.  
J, AUTORIZACION DGAC N° 132


Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		



Hangar 1 Aeropuerto Internacional Miguel Hidalgo Guadalajara, Jalisco, México  
 Phone: 01 3332842300 C.P. 45659

## PROPELLER MAINTENANCE LOGBOOK

Pag: 1/1


<b>Date: JAN 25, 2018</b>	<b>Register: XA-GTS</b>	<b>Model CIRRUS SR22T</b>		<b>S/N 1249</b>
<b>MFD: MAR 04-2016</b>	<b>TT: 144.4</b>	<b>TC: 127</b>	<b>WO: 0118-15</b>	
<b>Propeller Model PHC-J3Y1F-1N</b>	<b>TT: 144.4</b>	<b>TC: 127</b>	<b>S/N NJ1240</b>	

**INSPECTION:**

- Propeller Inspection 100/Annual was performed: IAW, CH 05-20.

I certify that this Aircraft has been inspected in accordance with CIRRUS SR 22T AMM, and determined to be Airworthy condition. AD's and SB's were research up to date.

The Aircraft, airframe or appliance identified above was maintained and/or altered and inspected in accordance with current Regulations issue by the DGAC and Maintenance Manual Recommendations is approved for return to service./  
 DGAC Repair Station No. 132

Sign:   
**Insp. Alvaro Espejo Rodriguez.**  
**Lic. DGAC 200106971.**

**AEROTRON**  
**SERVICIOS AERONAUTICOS CORPORATIVOS, S.A DE CV**  
**TALLER AERONAUTICO. AUTORIZACION**  
**DGAC No.132 FAA 8ET811C**




Hangar 1 Aeropuerto Internacional Miguel Hidalgo Guadalajara, Jalisco, México  
Phone: 01 3332842300 C.P. 45659

# PROPELLER MAINTENANCE LOGBOOK

Pag: 1/1

Date: Mar 05, 2018	Register: XA-GTS	Model CIRRUS SR22T	Registration No. 1240
MFD: MAR 04-2016	TT: 152.9	TC: 136	WO: 0318/15
Propeller Model PHC-J3Y1F-1N	TT: 152.9	TC: 136	S/N NJ1240B

**INSPECTION:**

- Propeller inspection 100/Annual Was Performed: IAW, CH 05-20.


I certify that this Aircraft has been inspected in accordance with CIRRUS SR 22T AMM and determined to be in Airworthy condition. AD's and SB's were research up to date.

The Aircraft, airframe or appliance identified above was maintained and/or altered and inspected in accordance with current Regulations issue by the DGAC and Maintenance Manual Recommendations is approved for return to service by DGAC Repair Station No. 132/ Repair Station FAA8ETY811C

Sign: \_\_\_\_\_

Insp. Alvaro Espejo Rodriguez.  
Lic. DGAC 200106971.

AEROTRON  
AEROS CORPORATIVOS, S.A DE C.V.  
SERVICIOS AERONÁUTICOS, AUTORIZACIÓN  
TALLER AERONÁUTICO, AUTORIZACIÓN  
DGAC No. 132 FAA8ETY811C


Date	Propeller TSN    TSO		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	April 12, 2019			
	N5411			TT:235.0
	Hartzell			Model: PHC-J3Y1F-1N                      SN: NJ1240B
	Completed annual propeller inspection, cleaned blades, sinner and hub. INspected hub, blades, spinner and spinner			
	bulkhead, No defects noted. Lubricated hub with Aeroshell 6 grease. Check blade track and blades for movement in hub.			
	NO defects noted.			
	I certify this propeller was inspected IAW an annual inspection and found to be in an airworthy condition.			
	Ian Simpkins A&P 3681524 IA 			

# PROPELLER LOG

N5411



23 June 2020  
Make: Cirrus  
Hobbs: 358.6

Prop S/N: NJ1240B  
Model: PHC-J3Y1F-1N  
Tach: 276.1  
TTSOH:

1. CW ANNUAL INSPECTION in accordance with FAR 43 APPENDIX D - Using Hartzell /Cirrus AMM as a guide.

I certify that this propeller has been inspected in accordance with (annual) inspection and was determined to be in airworthy condition.

A/P 3343189IA

Signed 