

# Propeller Service & Maintenance Record

Date	Total Time	Time Since Last Overhaul	Installations, Inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins.
------	------------	--------------------------	---

**HARTZELL**

## PROPELLER LOGBOOK

PROPELLER MODEL PHC-J3YF-1RF

PROPELLER S/N FP5272B

LOGBOOK # \_\_\_\_\_

### PROPELLER MAINTENANCE RECORD

Position \_\_\_\_\_

PITCH RANGE

Propeller Model PHC-J3YF-1RF

High/Feather \_\_\_\_\_

Propeller S/N FP5272B

Start Lock \_\_\_\_\_

Blade Design F7693DFB

Low \_\_\_\_\_

Blade S/N's

Reverse \_\_\_\_\_

No. 1 K46017

Aircraft Manufacturer Cessna Design

No. 2 K46015

Aircraft Model SR22

No. 3 K46023

S/N 2288

No. 4 \_\_\_\_\_

Registration N335A


No. 5 \_\_\_\_\_

No. 6 \_\_\_\_\_

Spinner Assembly Part No. \_\_\_\_\_



# Propeller Service & Maintenance Record

Date	Total Time	Time Since Last Overhaul	Installations, Inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins.
12-05-06	.0	N/A 1.2	<p>I have Dynamically Balanced Propeller IAW Hartzell Propeller Owner's Manual 115N Rev. 12 dated April/05 Section: 61-00-15 on <u>12-05-06</u> (DATE). The location of the Weight(s) are <u>N/A</u> degree And are <u>N/A</u> gram(s).</p> <p><u>Dean Johnson</u> (Sign/Stamp)  PC 338CE</p> <p>Cirrus Design Corporation,</p>



AVIATION SERVICES

469 Airport Road, Johnstown PA 15904  
Phone: 814-361-3500 Fax: 814-361-3498

Registration: N335A	Time: TT 306.9	W/O: 0712-4	Date: 12-14-2007
---------------------	----------------	-------------	------------------

Hartzell PHC-J3YF-1RF, S/N FP5272B Flight Hobbs: 194.7, Hobbs: 424.4

Performed Annual Inspection IAW Cirrus Inspection guide 05-20. and Hartzell M/M. AD's C/W thru 2007-24 Biweekly. Compliance record provided in aircraft logs. Lubricated propeller assembly. FOD, leak and functional checks - good.

*This Propeller has been inspected in accordance with an Annual inspection and is approved for return to service. Further details are on file under work order referenced above.*

Signature: Richard A. Barnhart II Certificate: CRS # N64R483Y

PROP MODEL:  
PHC-J3YF-1RF  
PROP S/N: FP5272B  
REG. NO: N335A  
WORK ORDER: 782

## Advanced Aircraft Services LP

500 Airport Rd. Suite D  
Lititz, PA 17543  
Phone: 717-735-5179

DATE: 11/7/2008  
A/C TSN: 516.5  
PROP TT: 516.5  
HOBBS: 658.4

### Prop Entries

Completed an Annual Inspection using the Cirrus AMM check list ch. 5-20.... C/W AD 08-13-28 Prop Hub Lube Holes, N/A by design/part number... Dressed all prop blades and serviced hub. All AD's current thru 08-22 -END-

I certify that this PROPELLER has been inspected IAW an Annual inspection and was found to be in Airworthy condition.

DATE: 11/7/2008

SIGNED

Richard A. Barnhart II, IA: 3124994

Work Order: 782

Printed by EBis 3 (datcomedia.com)



## Propeller Service & Maintenance Record

Date	Total Time	Time Since Last Overhaul	Installations, Inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins.
<b>SENENICH PROPELLER SERVICE, INC.</b> DATE: <u>11-10-08</u> CRS: QV9R194N Hobbs/Time: <u>576.9</u> A/C Reg: <u>N335A</u> Hub Model: _____ Hub S/N: _____ Propeller TTSN: _____ Propeller TTSO: _____			
Summary of work performed <i>Dynamic Balanced Propeller IAW.</i> <i>Chadwick Helmutt Smith Propeller Co.</i> <i>Starting IPS.21 at 2500rpm.</i> <i>Adjusted static balance weights.</i> <i>Ending IPS.02 at 2500rpm.</i> <i>End</i>			
<small>Pertinent details of this repair or overhaul are on file at this repair station under work order # <u>119707</u>            Signed <u>[Signature]</u> for Senenich Propeller Service, Inc., 519 E. Airport Rd. Lititz, PA 17543            *This signature constitutes approval for return to service of this aircraft ONLY FOR THE WORK WE HAVE PERFORMED.            We have not performed nor been authorized to perform any inspection of this aircraft nor have we reviewed or been authorized to review the maintenance records, including Part 39 compliance.</small>			
<b>Advanced Aircraft Services LP</b> PROP MODEL: PHC-J3YF-1RF PROP S/N: FP5272B REG. NO: N335A WORK ORDER: 1012 500 Airport Rd. Suite D Lititz, PA 17543 Phone: 717-735-5179 DATE: 7/30/2009 A/C TSN: 593.7 PROP TT: 593.7 HOBBS: 755.5			
<b>Prop Entries</b> Completed an Annual Inspection using the Cirrus AMM check list ch. 5-20.... Dressed all prop blades and serviced hub. All AD's current thru 09-15. END- I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition. DATE: 7/30/2009 SIGNED: <u>[Signature]</u> Work Order: 1012 Richard A. Barnhart II, IA: 3124994 Printed by EBis 3 (datcomedia.com)			
<b>Advanced Aircraft Services LP</b> PROP MODEL: PHC-J3YF-1RF PROP S/N: FP5272B REG. NO: N335A WORK ORDER: 1385 500 Airport Rd. Suite D Lititz, PA 17543 Phone: 717-735-5179 DATE: 23 July, 2010 A/C TSN: 1018 PROP TT: 745 FLIGHTTIME: 939			
<b>Prop Entries</b> Completed an Annual Inspection using the Cirrus AMM check list ch. 5-20. Dressed all blades and serviced hub. All AD's current thru 2010-15. I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition. DATE: 23 July, 2010 SIGNED: <u>[Signature]</u> Work Order: 1385 Richard A. Barnhart II, IA: 3124994 Printed by EBis 3 (datcomedia.com)			



#



PROP MODEL:  
HC-J3YF-1RF  
PROP S/N: FP5272B  
REG. NO: N335A  
WORK ORDER:  
659-11-2014



Advanced Lancaster LP  
530 Airport Rd.  
Lititz, PA 17543  
Phone: 717-735-5179

DATE: 11/12/2014  
A/C TSN: 1689 7  
PROP TT: 1689 7  
HOBBS: 1984 8

#### Prop Entries

Cirrus Propeller Annual Inspection completed using the Cirrus AMM check list ch. 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2014-22.

I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.

DATE: 11/12/2014

SIGNED:

Richard A. Bernhart II, IA: 41249944P

Work Order: 3659-11-2014

Printed by EBis 3 (datcomedia.com)

#### Service Record

#### Business Modifications and

PROP MODEL:  
PHC-J3YF-1RF  
PROP S/N: FP5272B  
REG. NO: N335A  
WORK ORDER:  
4275-12-2015



Fly Advanced  
530 Airport Rd.  
Lititz, PA 17543  
Phone: 717-735-5179

DATE: 1/7/2016  
A/C TSN: 1824 5  
PROP TT: 1689 7  
HOBBS: 2135 5

#### Prop Entries

Cirrus Propeller Annual Inspection completed using the Cirrus AMM check list ch. 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2015-26.

I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.

DATE: 1/7/2016

SIGNED:

Derrick S. Miller, IA: 3221608

Work Order: 4275-12-2015

Printed by EBis 3 (datcomedia.com)

PROP MODEL:  
PHC-J3YF-1RF  
PROP S/N: FP5272B  
REG. NO: N335A  
WORK ORDER:  
4920-01-2017



Fly Advanced  
Repair Station No. 5T2R901C  
530 Airport Rd.  
Lititz, PA 17543  
Phone: 717-735-5179

DATE: 1/18/2017  
A/C TSN: 2174 9  
PROP TT: 2174 9  
HOBBS: 2328 3

#### Prop Entries

Annual Propeller Inspection completed IAW FAR 91.409 and the requirements outlined in FAR 43 App. D. with reference to the Cirrus AMM check list ch 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2017-01.

I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.

DATE: 1/18/2017

SIGNED:

Joel A. Glover  
Certified Repair Station No. 5T2R901C

Work Order: 4920-01-2017

Printed by EBis 3 (datcomedia.com)

PROP MODEL:  
PHC-J3YF-1RF  
PROP S/N: FP5272B  
REG. NO: N335A  
WORK ORDER:  
5569-01-2018



Fly Advanced  
Repair Station No. 5T2R901C  
530 Airport Rd.  
Lititz, PA 17543  
Phone: 717-735-5179

DATE: 1/12/2018  
A/C TSN: 2270 4  
PROP TT: 2270 4  
HOBBS: 2435 9

#### Prop Entries

Annual Propeller Inspection completed IAW FAR 91.409 and the requirements outlined in FAR 43 App. D. with reference to the Cirrus AMM check list ch 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2018-01.

I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.

DATE: 1/12/2018

SIGNED:



Derrick S. Miller  
Certified Repair Station No. 5T2R901C

Work Order: 5569-01-2018

Printed by EBis 3 (datcomedia.com)



## Propeller Service & Maintenance Record

Date	Total Time	Time Since Last Overhaul	Installations, Inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins.
	<b>ADVANCED</b> Fly Advanced PROP MODEL: PHC-J3YF-1RF PROP S/N: FP5272B REG. NO: N335A WORK ORDER: 6133-10-2018	Repair Station No. 5T2R901C 530 Airport Rd. Lititz, PA 17543 Phone: 717-735-5179	DATE: 2/13/2019 A/C TSN: 2314 PROP TT: 2314 HOBBS: 2486
	<b>Prop Entries</b> Annual Propeller Inspection completed IAW FAR 91.409 and the requirements outlined in FAR 43 App. D. with reference to the Cirrus AMM check list ch 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2019-03. I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.		
	DATE: 2/13/2019  SIGNED: Josh Ferry Certified Repair Station No. 5T2R901C Work Order: 6133-10-2018 Printed by EBis 3 (datcomedia.com)		
	<b>ADVANCED</b> Fly Advanced PROP MODEL: PHC-J3YF-1RF PROP S/N: FP5272B REG. NO: N335A WORK ORDER: 7079-02-2020	Repair Station No. 5T2R901C 530 Airport Rd. Lititz, PA 17543 Phone: 717-735-5179	DATE: 2/19/2020 A/C TSN: 2339.9 PROP TT: 2339.9 HOBBS: 2523.1
	<b>Prop Entries</b> Annual Propeller Inspection completed IAW FAR 91.409 and the requirements outlined in FAR 43 App. D. with reference to the Cirrus AMM check list ch 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2020-04. I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.		
	DATE: 2/19/2020  SIGNED: Joshua J. Ferry Certified Repair Station No. 5T2R901C Work Order: 7079-02-2020 Printed by EBis 3 (datcomedia.com)		