




HARTZELL


PROPELLER LOGBOOK


PROPELLER MODEL PHC-S3YF-1RF


Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
MAINTENANCE RECORD				
May 7, 2003		Page 1 of 1		N41XP
Aircraft Total: 105.2				Hartzell
Engine TSN: 105.2				PHC-J3YF-1RF
Engine TSO: N/A				S/N: FP1673B
Work Orders: PG-03-06775				
<p>The below listed items were accomplished in accordance with approved or acceptable data as applicable. Details are on file under the above work order number(s). Work order discrepancy numbers are shown in brackets [], followed, in bold, directly by AD notes and SB's. Task codes listed at end of corrective action as applicable.</p> <p>[500] Annual/100 Hour Inspection performed in accordance with Cirrus SR22 AMM Scheduled Inspection Report, Chapter 5-20 p/n 13773-001.</p> <p>I certify that this propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.</p> <p>Signed </p> <p>Central Flying Service, Inc. CRS# HBKR587E 1501 Bond Street, Little Rock, AR 72202 Phone: (501) 375-3245, (800) 888-5387 FAX (501) 374-2150</p>				


Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
MAINTENANCE RECORD				
May 10, 2004		Page 1 of 1		N41XP
Aircraft Total: 206.7				Hartzell
Engine TSN: 206.7				PHC-J3YF-1RF
Engine TSO: N/A				S/N: FP1673B
Work Order(s): PG-04-08866				
<p>The below listed items were accomplished in accordance with approved or acceptable data as applicable. Details are on file under the above work order number(s). Work order discrepancy numbers are shown in brackets [], followed, in bold, directly by AD notes and SB's. Task codes listed at end of corrective action as applicable.</p> <p>[500] Annual Inspection performed in accordance with 14 CFR Appendix D to Part 43 using Cirrus Design SR22 A.M.M. p/n 13773-001 as an aid.</p> <p>I certify that this propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.</p> <p>Signed </p> <p>Central Flying Service, Inc. CRS# HBKR587E 1501 Bond Street, Little Rock, AR 72202 Phone: (501) 375-3245, (800) 888-5387 FAX (501) 374-2150</p>				


Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.	
	TSN	TSO			
MAINTENANCE RECORD <i>6 May 05 DJS</i>					
Date:	May 6, 2005		Page 1 of 1 Pages		Reg. No: N41XP
Aircraft:	Cirrus SR22		Serial #:	206	Total time / HM: 279.7 / 279.7
Propeller:	PHC-J3YF-1RF		Serial #:	FP1673B	Total time: 279.7
<p>The below listed items were accomplished in accordance with the Cirrus Design SR22 Airplane Maintenance Manual and other approved or acceptable data as applicable. Work order discrepancy numbers are shown in brackets [], followed, in bold, directly by AD notes and SB's.</p> <p><u>Work Order PG-05-11014</u> [500] Annual Inspection completed this date.</p> <p>I certify that the above listed items have been completed, and with regard to the above items, that this aircraft has been approved for return to service.</p> <p>Signed  Central Flying Service, Inc. 1501 Bond Street, Little Rock, AR 72202</p> <p style="text-align: right;">Phone: (501) 375-3245, (800) 888-5387 CRS No. HBKR587E FAX (501) 374-2150</p>					


Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.	
	TSN	TSO			
MAINTENANCE RECORD					
Date:	June 2, 2006		Page 1 of 1 Pages		Reg. No: N41XP
Aircraft:	Cirrus SR22		Serial #:	206	Total time / HM: 350.6 / 350.6
Propeller:	PHC-J3YF-1RF		Serial #:	FP1673B	Total time: 350.6
<p>The below listed items were accomplished in accordance with the Cirrus Design SR22 Airplane Maintenance Manual and other approved or acceptable data as applicable. Work order discrepancy numbers are shown in brackets [], followed, in bold, directly by AD notes and SB's.</p> <p><u>Work Order PG-06-13253</u> [500] Annual Inspection performed in accordance with 14 CFR Part 43, Appendix D. [457] AD 2005-14-11, To prevent blade failure that could result in separation of a propeller blade & loss of control of the airplane, N/A, prop has not been returned to service by Southern California Propeller Service.</p> <p>I certify that this <i>propeller</i> has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.</p> <p>Signed  Central Flying Service, Inc. 1501 Bond Street, Little Rock, AR 72202</p> <p style="text-align: right;">Phone: (501) 375-3245, (800) 888-5387 CRS No. HBKR587E FAX (501) 374-2150</p>					


Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.	
MAINTENANCE RECORD				
Date:	July 9, 2007	Page 1 of 1 Pages	Reg. No: N41XP	
Aircraft:	Cirrus SR22	Serial #: 206	Total time / HM: 409.8 / 409.8	
Propeller:	PHC-J3YF-1RF	Serial #: FP1673B	Total time: 409.8	
<p>The below listed items were accomplished in accordance with the Cirrus Design SR22 Airplane Maintenance Manual and other approved or acceptable data as applicable. Work order discrepancy numbers are shown in brackets [], followed, in bold, directly by AD notes and SB's.</p> <p><u>Work Order PG-07-15350</u> [500] Annual Inspection performed in accordance with 14 CFR Part 43, Appendix D.</p> <p>I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.</p> <p>Signed  Central Flying Service, Inc. 1501 Bond Street, Little Rock, AR 72202 Phone: (501) 375-3245, (800) 888-5387 CRS No. HBKR587E FAX (501) 374-2150</p>				


Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.	
MAINTENANCE RECORD				
Date:	July 11, 2008	Page 1 of 1 Pages	Reg. No: N41XP	
Aircraft:	Cirrus SR22	Serial #: 0206	Total Time / HM: 451.3 / 451.3	
Propeller:	PHC-J3YF-1RF	Serial #: FP1673B	Total Time: 451.3	
<p>The below listed items were accomplished in accordance with the Cirrus Design SR22 Airplane Maintenance Manual and other approved or acceptable data as applicable. Work order discrepancy numbers are shown in brackets [], followed, in bold, directly by AD notes and SB's.</p> <p><u>Work Order PG-08-17281</u> [500] Annual Inspection performed in accordance with 14 CFR Part 43, Appendix D. [462] AD 2007-26-09 (effective 1/30/08) <i>Initial Blade Inspections</i> - No action required per paragraph (h) (1). All blades serial numbers are above D47534. Propeller is considered to be in compliance with the one-time inspection and rework requirements of this AD. Blade serial numbers are J71891, J71884, and J71890.</p> <p>I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.</p> <p>Signed  Central Flying Service, Inc. 1501 Bond Street, Little Rock, AR 72202 Phone: (501) 375-3245, (800) 888-5387 CRS No. HBKR587E FAX (501) 374-2150</p>				


Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.		
	TSN	TSO				
MAINTENANCE RECORD						
Date:	August 12, 2009 <i>jsl</i>		Page 1 of 1 Pages		Reg. No:	N41XP
Aircraft:	Cirrus SR22		Serial #:	0206	Total Time / HM:	496.8 / 496.8
Propeller:	PHC-J3YF-1RF		Serial #:	FP1673B	Total Time:	496.8
<p>The below listed items were accomplished in accordance with the Cirrus Design SR22 Airplane Maintenance Manual and other approved or acceptable data as applicable. Work order discrepancy numbers are shown in brackets [], followed, in bold, directly by AD notes and SB's.</p> <p><u>Work Order PG-09-19215:</u> [500] Annual Inspection performed in accordance with 14 CFR Part 43, Appendix D.</p> <p>I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.</p> <p>Signed _____ Central Flying Service, Inc. 1501 Bond Street, Little Rock, AR 72202</p> <p style="text-align: center;"> James E. Schofield Phone: (501) 375-3245, (800) 888-5387</p> <p style="text-align: right;">CRS No. HBKR587E FAX (501) 374-2150</p>						

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.		
	TSN	TSO				
MAINTENANCE RECORD						
Date:	September 3, 2010		Page 1 of 1 Pages		Reg. No:	N41XP
Aircraft:	Cirrus SR22		Serial #:	0206	Total Time / HM:	538.4 / 538.4
Propeller:	PHC-J3YF-1RF		Serial #:	FP1673B	Total Time:	538.4
<p>The below listed items were accomplished in accordance with the Cirrus Design SR22 Airplane Maintenance Manual and other approved or acceptable data as applicable. Work order discrepancy numbers are shown in brackets [], followed, in bold, directly by AD notes and SB's.</p> <p><u>Work Order PG-10-20992:</u> [500] Annual Inspection performed in accordance with 14 CFR Part 43, Appendix D. [400] 6-month, 100-hour and 300-hour lubrication requirements complied with.</p> <p>I certify that this PROPELLER has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.</p> <p>Signed _____ Central Flying Service, Inc. 1501 Bond Street, Little Rock, AR 72202</p> <p style="text-align: center;"> John White Phone: (501) 375-3245, (800) 888-5387</p> <p style="text-align: right;">CRS No. HBKR587E FAX (501) 374-2150</p>						

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.	
MAINTENANCE RECORD				
Date:	October 5, 2011	Page 1 of 1 Pages		Reg. No: N41XP
Aircraft:	Cirrus SR22	Serial #:	0206	Total Time / HM: 626.6 / 626.6
Propeller:	PHC-J3YF-1RF	Serial #:	FP1673B	Total Time: 626.6
The below listed items were accomplished in accordance with the Cirrus Design SR22 Airplane Maintenance Manual and other approved or acceptable data as applicable. Work order discrepancy numbers are shown in brackets [], followed, in bold, directly by AD notes and SB's.				
<u>Work Order 041101156</u>				
[500] Annual Inspection performed in accordance with 14 CFR Part 43, Appendix D.				
I certify that this PROPELLER has been inspected in accordance with an Annual/100 Hour inspection and was determined to be in airworthy condition.				
Signed				
Central Flying Service, Inc. 1501 Bond Street, Little Rock, AR 72202		John White Phone: (501) 375-3245, (800) 888-5387		CRS No. HBKR587E FAX (501) 374-2150

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.	
MAINTENANCE RECORD				
Date:	November 9, 2012	Page 1 of 1 Pages		Reg. No: N41XP
Aircraft:	Cirrus SR22	Serial #:	0206	Total Time / HM: 691.3 / 691.3
Propeller:	PHC-J3YF-1RF	Serial #:	FP1673B	Total Time: 691.3
The below listed items were accomplished in accordance with the Cirrus Design SR22 Airplane Maintenance Manual and other approved or acceptable data as applicable. Work order discrepancy numbers are shown in brackets [], followed, in bold, directly by AD notes and SB's.				
<u>Work Order 041202782</u>				
[500] Annual Inspection performed in accordance with 14 CFR Part 43, Appendix D.				
I certify that this propeller has been inspected in accordance with a 100 Hour Annual Inspection and was determined to be in airworthy condition.				
Signed				
Central Flying Service, Inc. 1501 Bond Street, Little Rock, AR 72202		Gregory A Scher Phone: (501) 375-3245, (800) 888-5387		CRS No. HBKR587E FAX (501) 374-2150

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
MAINTENANCE RECORD			
Date:	December 05, 2013	Page 1 of 1 Pages	Reg. No: N41XP
Aircraft:	Cirrus SR22	Serial #: 0206	Total Time / HM: 759.8 / 759.8
Propeller:	PHC-J3YF-1RF	Serial #: FP1673B	Total Time: 759.8
<p>The below listed items were accomplished in accordance with the Cirrus Design SR22 Airplane Maintenance Manual and other approved or acceptable data as applicable. Work order discrepancy numbers are shown in brackets [], followed, in bold, directly by AD notes and SB's.</p> <p><u>Work Order 041304421</u></p> <p>[500] Annual Inspection performed in accordance with 14 CFR Part 43, Appendix D.</p> <p>I certify that this propeller has been inspected in accordance with a 100 Hour/Annual Inspection and was determined to be in airworthy condition.</p> <p>Signed _____ Central Flying Service, Inc. 1501 Bond Street, Little Rock, AR 72202</p> <p style="text-align: center;"> Gregory A Scher Phone: (501) 375-3245, (300) 888-5387</p> <p style="text-align: right;">CRS No. HBKR587E FAX (501) 374-2150</p>			


Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
MAINTENANCE RECORD			
Date:	January 9, 2015	Page 1 of 1 Pages	Reg. No: N41XP
Aircraft:	Cirrus SR22	Serial #: 0206	Total Time / HM: 800.7 / 800.7
Propeller:	PHC-J3YF-1RF	Serial #: FP1673B	Total Time: 800.7
<p>The below listed items were accomplished in accordance with the Cirrus Design SR22 Airplane Maintenance Manual and other approved or acceptable data as applicable. Work order discrepancy numbers are shown in brackets [], followed, in bold, directly by AD notes and SB's.</p> <p><u>Work Order 041505675</u></p> <p>[500] A 100 Hour Inspection was performed in accordance with 14 CFR Part 43, Appendix D.</p> <p>I certify that this propeller has been inspected in accordance with a 100 Hour Inspection and was determined to be in airworthy condition.</p> <p>Signed _____ Central Flying Service, Inc. 1501 Bond Street, Little Rock, AR 72202</p> <p style="text-align: center;"> Gregory A Scher Phone: (501) 375-3245, (800) 888-5387</p> <p style="text-align: right;">CRS No. HBKR587E FAX (501) 374-2150</p>			

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
MAINTENANCE RECORD				
Date:	January 20, 2016		Page 1 of 1 Pages	Reg. No: N41XP
Aircraft:	Cirrus SR22		Serial #: 0206	Total Time / HM: 848.1 / 848.1
Propeller:	PHC-J3YF-1RF		Serial #: FP1673B	Total Time: 848.1
<p>The below listed items were accomplished in accordance with the Cirrus Design SR22 Airplane Maintenance Manual and other approved or acceptable data as applicable. Work order discrepancy numbers are shown in brackets [], followed, in bold, directly by AD notes and SB's.</p> <p><u>Work Order 041606963</u></p> <p>[500] 100 Hour Inspection complied with in accordance with 14 CFR Part 43, Appendix D.</p> <p>I certify that this propeller has been inspected in accordance with a 100 Hour Inspection and was determined to be in airworthy condition.</p> <p>Signed _____ Central Flying Service, Inc. 1501 Bond Street, Little Rock, AR 72202</p> <p style="text-align: center;"><i>Gregory A. Seyer</i> Gregory A. Seyer Phone: (501) 375-3245, (800) 888-5387</p> <p style="text-align: right;">CRS No. HBKR587E FAX (501) 374-2150</p>				

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
MAINTENANCE RECORD				
Date:	February 08, 2017		Page 1 of 1 Pages	Reg. No: N41XP
Aircraft:	Cirrus SR22		Serial #: 0206	Total Time / HM: 902.1 / 902.1
Propeller:	PHC-J3YF-1RF		Serial #: FP1673B	Total Time: 902.1
<p>The below listed items were accomplished in accordance with the Cirrus Design SR22 Airplane Maintenance Manual and other approved or acceptable data as applicable. Work order discrepancy numbers are shown in brackets [], followed, in bold, directly by AD notes and SB's.</p> <p><u>Work Order 041707967</u></p> <p>[500] 100 Hour Inspection complied with in accordance with 14 CFR Part 43, Appendix D.</p> <p>[054] Dressed propeller as required ,IAW Hartzell POM.</p> <p>I certify that this propeller has been inspected in accordance with a 100 Hour Inspection and was determined to be in airworthy condition.</p> <p>Signed _____ Central Flying Service, Inc. 1501 Bond Street, Little Rock, AR 72202</p> <p style="text-align: center;"><i>Thomas Joe Papka</i> THOMAS JOE PAPKA Phone: (501) 375-3245, (800) 888-5387</p> <p style="text-align: right;">CRS No. HBKR587E FAX (501) 374-2150</p>				

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.	
MAINTENANCE RECORD				
Date:	March 02, 2018	Page 1 of 1 Pages	Reg. No: N41XP	
Aircraft:	Cirrus SR22	Serial #: 0206	Total Time / HM: 954.7 / 954.7	
Propeller:	PHC-J3YF-1RF	Serial #: FP1673B	Total Time: 954.7	
<p>The below listed items were accomplished in accordance with the Cirrus Design SR22 Airplane Maintenance Manual and other approved or acceptable data as applicable. Work order discrepancy numbers are shown in brackets [], followed, in bold, directly by AD notes and SB's.</p> <p><u>Work Order 041808903</u></p> <p>[500] 100 Hour Inspection complied with in accordance with 14 CFR Part 43, Appendix D.</p> <p>I certify that this propeller has been inspected in accordance with a 100 Hour Inspection and was determined to be in airworthy condition.</p> <p>Signed _____</p> <p>Central Flying Service, Inc. Thomas Papka CRS No. HBKR587E 1501 Bond Street, Little Rock, AR 72202 Phone: (501) 375-3245, (800) 888-5387 FAX (501) 374-2150</p>				

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.	
MAINTENANCE RECORD				
Date:	April 1, 2019	Page 1 of 1 Pages	Reg. No: N41XP	
Aircraft:	Cirrus SR22	Serial #: 0206	Total Time / HM: 992.2 / 992.2	
Propeller:	PHC-J3YF-1RF	Serial #: FP1673B	Total Time: 992.2	
<p>The below listed items were accomplished in accordance with the Cirrus Design SR22 Airplane Maintenance Manual and other approved or acceptable data as applicable. Work order discrepancy numbers are shown in brackets [], followed, in bold, directly by AD notes and SB's.</p> <p><u>Work Order 041909799</u></p> <p>[500] 100 Hour Inspection complied with in accordance with 14 CFR Part 43, Appendix D.</p> <p>I certify that this propeller has been inspected in accordance with a 100 Hour Inspection and was determined to be in airworthy condition.</p> <p>Signed _____</p> <p>Central Flying Service, Inc. <i>THOMAS PAPKA</i> CRS No. HBKR587E 1501 Bond Street, Little Rock, AR 72202 Phone: (501) 375-3245, (800) 888-5387 FAX (501) 374-2150</p>				

 Glendale Aero Services 6841 N. Glen Harbor Blvd Glendale, AZ 85307 623-414-4930	Registration: N41XP	ENGINE LOG	
	Date: 10/18/2019		W/O: 6002949
	Model: SR22		Hobbs: 1032.0
	S/N: 0206		
Adjusted prop governor for maximum RPM IAW the Cirrus SR22 Chapter 61-20. Ground run-up and operational checks normal with no leaks or defects noted.			
Adjusted maximum fuel flow to specified limits IAW the CMI M-O standard practices MM Chapter 6-4.10.2.1.			
SIGNATURE: <i>Ron Scarborough</i>		FAA AUTHORIZATION: 3546789 A&P	

Date	Propeller TSN TSO		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
------	----------------------	--	------------	---



Glendale Aero Services

6841 N. Glen Harbor Blvd
Glendale, AZ 85307
623-414-4935

Registration: *N41XP*

PROPELLER LOG

Date: 4/20/2020

W/O: 8000253

Model: PHC-J3YF-1RF

Hobbs: 1065.4

S/N: FP7694

TSMOH: 1065.4

Complied with an annual inspection IAW 14 CFR 43 Appendix D & in reference to the Cirrus Aircraft annual inspection checklist CH 5-20. AD's researched thru T-Data content revision 2020-09, see attached AD compliance list for details.

Serviced propeller with Aeroshell 6 grease. Inspected and profiled minor nicks in blades as required.

I certify this propeller has been inspected in accordance with an Annual / 100 Hr. inspection and was determined to be in airworthy condition

SIGNATURE: *Matthew Hatfield*

FAA AUTHORIZATION:

2766522 IA

