



HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-J34F-1RF/F7693PFB

PROPELLER S/N FP3490B

LOGBOOK # 1

PROPELLER MAINTENANCE RECORD

Position One

Propeller Model PHC-J34F-1RF/F7693DFB

Propeller S/N FP3490B

Blade Design F7693DFB

Blade S/N's

No. 1 K16820

No. 2 K16819

No. 3 K16821

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____

Reverse _____

Aircraft Manufacturer Cirrus

Aircraft Model SR-22

S/N SR22-1335

Registration N228MM

[illegible]

N228MM
March 7, 2006

Hobbs 107.9
TTPROP 107.9

1. Performed Annual Inspection in accordance with Cirrus Design SR22 "Scheduled Inspection Report".
2. Lubricated propeller and dressed each blade leading edge as necessary.
3. A.D.'s checked through 2006-04.

All work performed by Auburn Flight Service, an Authorized Cirrus Design Service Center under work order numbers- 5640, 5641 and 5642.

I certify that this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in an airworthy condition.

Gregory T. Woodruff
Gregory T. Woodruff A&P 553697406 I.A.

N228MM
May 1, 2007



Hobbs 151.0
TTPROP 151.0

1. Performed Annual Inspection in accordance with Cirrus Design SR22 Series Maintenance Manual (applicable Chapters).
2. Lubricated propeller per Hartzell guidelines.
3. A.D.'s checked through 2007-08, Service Bulletins through May 1, 2007.

All work was performed by Auburn Flight Service, an Authorized Cirrus Design Service Center under Work Order numbers- 6169 and 6170.

I certify that this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in an airworthy condition.

Gregory T. Woodruff
Gregory T. Woodruff A&P 553697406 I.A.

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	N228MM		Hobbs 187.2
	January 23, 2008		TTPROP 187.2
			<ol style="list-style-type: none"> 1. Performed an Annual Inspection in accordance with Cirrus Design SR22 Series Maintenance Manual (applicable Chapters). 2. Lubricated the propeller as required. 3. Hartzell A.D. #2007-26-09 is not applicable per each blade serial number. 4. A.D.'s checked through 2008-01. Service Bulletins checked through January 18, 2008.
			All work was accomplished by Auburn Flight Service, an Authorized Cirrus Design Service Center under Work Order numbers- 6568 and 6575.
			I certify that this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in an airworthy condition.
			 Gregory T. Woodruff A&P 553697406 I.A.
	N228MM		Hobbs 202.4
	February 10, 2009		TTPROP 202.4
			<ol style="list-style-type: none"> 1. Performed an Annual Inspection in accordance with Cirrus Aircraft SR22 Series Maintenance Manual (applicable Chapters). 2. Lubricated the propeller hub as required. 3. A.D.'s checked through 2009-03. Service Bulletins checked through February 10, 2009.
			All work (unless otherwise specifically stated) was performed by Auburn Flight Service, an Authorized Cirrus Aircraft Service Center under Work Order #7135.
			I certify that this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in an airworthy condition.
			 Gregory T. Woodruff A&P 553697406 I.A.

PROP MODEL:
PHC-J3YF-1RF/F7693DFB
PROP S/N: FP3490B
REG. NO: N228MM
WORK ORDER:
6068-03-2010

Kalamazoo Aircraft, Inc.

Repair Station No. K9AR289N
2729 E Milham Rd.
Kalamazoo, MI 49002
Phone: (269) 381-0790

DATE: 3/13/2010
A/C TSN: 352.7
PROP TT: 352.7
HOBBS: 352.7

Prop Entries

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

The above work was performed in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Details are on file at this certified repair station.

DATE: 3/13/2010

SIGNED:

James R Michalka
Certified Repair Station No. K9AR289N

Work Order: 6068-03-2010

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-1RF/F7693DFB
PROP S/N: FP3490B
REG. NO: N228MM
WORK ORDER:
6429-03-2011

Kalamazoo Aircraft, Inc.

Repair Station No. K9AR289N
2729 E Milham Rd.
Kalamazoo, MI 49002
Phone: (269) 381-0790

DATE: 4/13/2011
A/C TSN: 512.7
PROP TT: 512.7
HOBBS: 512.7

Prop Entries

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

The above work was performed in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Details are on file at this certified repair station.

DATE: 4/13/2011

SIGNED:

James R Michalka
Certified Repair Station No. K9AR289N

Work Order: 6429-03-2011

Printed by EBis 3 (datcomedia.com)

Prop
TSN

PROP MODEL:
PHC-J3YF-1RF/F7693DFB
PROP S/N: FP3490B
REG NO: N228MM
WORK ORDER:
6761-05-2012

Kalamazoo Aircraft, Inc.

Repair Station No. K9AR289N
2729 E Milham Rd.
Kalamazoo, MI 49002
Phone: (269) 381-0790

DATE: 5/11/2012
A/C TSN: 673.8
PROP TT: 673.8
HOBBS: 673.8

Prop Entries

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

The above work was performed in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Details are on file at this certified repair station.

DATE: 5/11/2012

SIGNED:


James R. Michalski
Certified Repair Station No. K9AR289N

Work Order: 6761-05-2012

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-1RF/F7693DFB
PROP S/N: FP3490B
REG NO: N228MM
WORK ORDER:
7073-05-2013

Kalamazoo Aircraft, Inc.

Repair Station No. K9AR289N
2729 E Milham Rd.
Kalamazoo, MI 49002
Phone: (269) 381-0790

DATE: 6/7/2013
A/C TSN: 821.4
PROP TT: 821.4
HOBBS: 821.4


Prop Entries

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

The above work was performed in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Details are on file at this certified repair station.

DATE: 6/7/2013

SIGNED:


James R. Michalski
Certified Repair Station No. K9AR289N

Work Order: 7073-05-2013

Printed by EBis 3 (datcomedia.com)

Propeller Maintenance Entry for N228MM


DATE: 06/26/2014

PTT: 951.6

HOBBS: 951.6

1. REMOVED THIS PROPELLER MODEL NO: PHC-J3YF-1RF/F7693DFB, S/N: FP3490B FROM CIRRUS SR 22, N228MM, S/N: 1335 FOR OVERHAUL BY AIRCRAFT PROPELLER.

Michael S. Lawson

Signature: 

Page 1 of 1

Certificate No. AP3057235331A

Wings Aviation Inc 4601 Murvihill Rd, Valparaiso IN 46383 219-462-6622 wingsaviationvpz.com

[illegible]

Propeller Maintenance Entry for N228MM

DATE: 07/16/20

PTT: 951.6

TSOH: 0000.0


HOBBS: 951.6

1. COMPLIED WITH AN ANNUAL INSPECTION THIS DATE USING CIRRUS MANUAL AS A GUIDE.
2. INSTALLED THIS HARTZELL PROPELLER MODEL NO: PHC-J3YF-1RF/F7693DFB, S/N: FP3490B AFTER OVERHAUL BY AIRCRAFT PROPELLER ON CIRRUS SR22 N228MM, S/N: 1335.
3. ADS CHECKED THRU 2014-14. SEE AD COMPLIANCE REPORT THIS DATE.

MAINTENANCE RELEASE:

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED I/A/W AN ANNUAL/100 HOUR INSEPTION AND HAS BEEN FOUND TO BE IN AN AIRWORTHY CONDITION. THIS PROPELLER IS BEING RETRUNED TO SERVICE THIS DATE.

Michael S. Lawson

Signature: 

Page 1 of 1

Certificate No. AP3057235331A

Wings Aviation Inc 4601 Murvihill Rd. Valparaiso IN 46383 219-462-6622 wingsaviationvpz.com

[illegible]

DATE: 08/01/2015

Propeller Maintenance Entry for N228MM
TSOH: 101.5 ETT: 1053.1

ACTT: 1053.1

1. COMPLIED WITH AN ANNUAL/100 HOUR INSPECTION THIS DATE USSING CIRRUS MAINTENANCE MANUAL AS A GUIDE.
2. LUBRICATED PROPELLER AS PER MAINTENANCE MANUAL
3. AD'S CHECKED THRU 2015-015. SEE AD COMPLIANCE REPORT THIS DATE.

MAINTENANCE RELEASE:




I CERTIFY THIS PROPELLER HS BEEN INSPECTED I/A/W AN ANNUAL/100 HOUR INSPECTION AND HAS BEEN FOUND TO BE IN AN AIRWORHTY CONDION. THIS PROPELLER IS BEING RETURNED TO SERVICE.

Michael S. Lawson

Signature: 

Wings Aviation Inc. 4601 Murvhill Rd. Vaiparakeo IN 46383 219-462-6622 wingsaviationvpz.com

Certificate No. AP3057235331A

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
				 <p>EXECUTIVE AIR TRANSPORT, INC. 103 Sinclair Drive • Muskegon, MI 49441</p> <p>DATE: 9/15/2016 HOBBS: 1134.0 TSMOH: 182.4 TAIL #: N228MM TYPE: PHC-J3YF-1RF S/N: FP3490B</p> <ol style="list-style-type: none"> 1. Performed 100-hour inspection referencing Cirrus SR22 scheduled inspection report. 2. Inspected spinner and spinner bulkhead. 3. Inspected de-ice boots and slinger ring for security and wear. 4. Lubricated propeller with Aeroshell #6 as required. 5. See AD list for times and compliance. <p>Complied with the above listed items, referenced SR22 Maintenance Manual.</p> <p> Kim J. Corley Jr. AP 3674557</p> <ol style="list-style-type: none"> 6. Performed annual inspection referencing Cirrus SR22 scheduled inspection report. <p>I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition. This propeller is approved for return to service.</p> <p> Victor Grahn AP 3015259 IA</p>

Propeller Maintenance Entry for N228MM

DATE: 10/01/2017
ETT: 1213.2
PTT: 1213.2

HOBBS: 1213.2

ACTT: 1213.2
ETSOH: 1213.2
PTSOH: 261.6

1. COMPLIED WITH AN ANNUAL/100 HOUR INSPECTION I/AW FAR43 APPENDIX D THIS DATE USING CIRRUS MAINTENANCE MANUAL AS A GUIDE.
2. AD'S CHECKED THRU 2017-020. SEE AD COMPLIANCE REPORT THIS DATE.

MAINTENANCE RELEASE:

I CERTIFY THIS PROPELLER HS BEEN INSPECTED I/A/W AN ANNUAL/100 HOUR INSPECTION AND HAS BEEN FOUND TO BE IN AN AIRWORHTY CONDION. THIS PROPELLER IS BEING RETURNED TO SERVICE.

Michael S. Layson
Signature

Wings Aviation Inc 4601 Murvill Rd. Vaiparso IN 46383 219-462-6622 wingsaviationvpz.com

Certificate No. AP3057235331A