

HARTZELL

N818RN

PROPELLER LOGBOOK

PROPELLER MODEL PHC-334F-1RF

PROPELLER S/N FP6682B

LOGBOOK #

PROPELLER MAINTENANCE RECORD

Position ONE

PITCH RANGE

Propeller Model PHC-33YF-1RF

High/Feather

Propeller S/N FP6682B

Start Lock

Blade Design F7392-1

Low

Blade S/N's

Reverse

No. 1 K72444

No. 2 K72450

No. 3 K72445

No. 4

No. 5

No. 6




Aircraft Manufacturer CIRRUS DESIGN CORP.

Aircraft Model SR-20

S/N 1990

Registration N531PG

Spinner Assembly Part No.

Date	Propeller TSN TSO	A/C HTS	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
GA Maintenance, Inc Fort Lauderdale Executive Airport – FXE 1635 NE 51 st Place – Building 31A Fort Lauderdale, FL 33309			
GA Cirrus Design Model: SR20 Tail Number: N531PG SN: 1990 Hobbs: 136.8 Flight: 96.5 1) Complied with Cirrus 100 hour interval inspection program and oil change (Cirrus Maintenance Program)			
March 04, 2009 Humphrey Lemmers  2010282 - IA			
GA Maintenance, LLC 1635 N.W. 51st Place, Bldg. 31 - A Fort Lauderdale, FL 33309 Phone: 954-202-5995 June 2, 2009			
Propeller Log Cirrus Design Model: SR20 Serial: 1990 Tail: N818RN Flight: 164.7 Hobbs: 232.2			
Propeller Maintenance Notes 1 - Complied with Propeller 100 Hr Inspection			
I certify that this propeller has been inspected in accordance with 100 hour inspection and was determined to be in airworthy condition. 			
Humphrey Lemmers  AP2010282			

PLATINUM

1635 NW 51 PLACE
HANGAR 31-A
FORT LAUDERDALE, FL 33309
(954) 771-1288

Make: CIRRUS Model: SR20 Serial: 1990 Registration: N818RN Tach: 267.2 Hobbs: 368.4


PERFORMED HARTZELL 100 HOUR INSPECTION

I CERTIFY THAT THE ABOVE PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH 100
HOUR INSPECTION AND IS DETERMINED TO BE IN AIRWORTHY CONDITION.

W/O: 09-222

Date AUGUST 14, 2009

Humphrey Lemmers



AP2010282

PROP MODEL:
PHC-J3YF-IRF
PROP S/N: FP6682B
REG. NO: N818RN
WORK ORDER: 0172

PLATINUM

Platinum Aviation Service

1635 NW 51st Place - Hangar 31
Fort Lauderdale, FL 33309
Phone: (954) 771-1288

DATE: 25 June, 2010
A/C TSN: 4579
PROP TT: 4579
FLIGHTTIME: 4579


Prop Entries

Completed annual propeller inspection IAW Cirrus SR20 MM & MM checklist. AD's current through issue 2010-14. Lubricated with Aeroshell #6.

I certify that this airframe has been inspected IAW an annual inspection and is found airworthy at this time.

DATE: 25 June, 2010

SIGNED:



Work Order: 0172

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-IRF
PROP S/N: FP6682B
REG. NO: N818RN
WORK ORDER: 0616

PLATINUM Service
AVIATION

Platinum Aviation Service

1635 NW 51st Place - Hangar 31
Fort Lauderdale, FL 33309
Phone: (954) 771-1288

DATE: 30 June, 2011
A/C TSN: 6162
PROP TT: 6162
FLIGHTTIME: 6162


Prop Entries

Completed annual propeller inspection IAW Cirrus SR20 MM & MM checklist. Lubricated with Aeroshell #6. AD's current through issue 2011-13. I certify this propeller has been inspected IAW an annual inspection and is airworthy at this time.

I certify that this airframe has been inspected IAW an Annual inspection and is found airworthy at this time.

DATE: 30 June, 2011

SIGNED:



Work Order: 0616

Glenn Juber, IA: 3438378

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-IRF
PROP S/N: FP6682B
REG. NO: N818RN
WORK ORDER: 0172

PLATINUM

Platinum Aviation Service

1635 NW 51st Place - Hangar 31
Fort Lauderdale, FL 33309
Phone: (954) 771-1288

DATE: 25 June, 2010
A/C TSN: 457.9
PROP TT: 457.9
FLIGHTTIME: 457.9

Prop Entries

Completed annual propeller inspection IAW Cirrus SR20 MM & MM checklist. AD's current through issue 2010-14. Lubricated with Aeroshell #6.

I certify that this airframe has been inspected IAW an Annual inspection and is found airworthy at this time.

DATE: 25 June, 2010

SIGNED:

Glenn Juber, IA: 3438373

Work Order: 0172

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-IRF
PROP S/N: FP6682B
REG. NO: N818RN
WORK ORDER: 0616

PLATINUM Service
AVIATION

Platinum Aviation Service

1635 NW 51st Place - Hangar 31
Fort Lauderdale, FL 33309
Phone: (954) 771-1288

DATE: 30 June, 2011
A/C TSN: 616.2
PROP TT: 616.2
FLIGHTTIME: 616.2

Prop Entries

Completed annual propeller inspection IAW Cirrus SR20 MM & MM checklist. Lubricated with Aeroshell #6. AD's current through issue 2011-13. I certify this propeller has been inspected IAW an annual inspection and is airworthy at this time.

I certify that this airframe has been inspected IAW an Annual inspection and is found airworthy at this time.

DATE: 30 June, 2011

SIGNED:

Glenn Juber, IA: 3438378

Work Order: 0616

Printed by EBis 3 (datcomedia.com)

Date	Propeller TSN	TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
JULY 20	2012			HOBBS: 991.2 FLT 745.1
			HUMPHREY LEMMERS	I Certify that this PROPELLER Has Been Inspected In Accordance
			A&P 2010282 1A	With 100 HR Inspection And Was Determined To Be In Airworthy Condition.
7/20/2013				I certify that this PROPELLER HAS BEEN INSPECTED IN ACCORDANCE
FLT	930.0			WITH A 100 HR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY
HOBBS	1230.5		CONDITION	A. Lemmers A&P 2010282 1A



Cirrus Factory Authorized Service Center
CRS#9ESR403B
2580 SE Aviation Way Ste 102
Stuart, FL 34996 PH (772) 781-0610
rick@eastcoastaviationservice.com

8/11/14 N818RN Hartzell PHC-J3YF-1RF SN#PF6682B H.M.1440.6 FLH.M. 1103.5 T.T.1103.5 T.S.N.1103.5
100HR/Annual Inspection Completed

Inspected this propeller in accordance with FAR 43 Appendix D, blades inspected and hub lubricated, checked and found all AD's to have been C/W thru this date I certify this propeller to have been inspected in accordance with an 100HR inspection and was determined to be in a airworthy condition.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with the current requirements of the Federal Aviation administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS 9ESR403B, under W/O#19514B

Date: 8/11/14

Signed 
Richard Epler
Certified Repair Station No. 9ESR403B

W/O#19514B

PROPELLER LOGBOOK ENTRY

RFN Holdings LLC	Tail # N818RN PHC-J3YF-1RF	Tach: 1202.4 Total time: 1202.4
Date: 02/10/2015	Serial # FP6682B	TSMOH: N/A

Completed 100 hr propeller inspection IAW Cirrus Design SR20 MM checklist. Lubricated hub w/Aeroshell #6. AD's current through issue 2015-03. I certify that this propeller has been inspected IAW a 100 hr inspection and is found airworthy at this time.

Signature: 

Glenn Juber A&P IA 3438378
5115 NW 98th Dr, Coral Springs, FL 33076

operations pertaining to Airworthiness Directives

PROPELLER LOGBOOK ENTRY

RFN Holdings LLC	Tail # N818RN PHC-J3YF-1RF	Tach: 1299.3 Total time: 1299.3
Date: 07/18/2015	Serial #FP6682B	TSMOH: N/A

Completed annual propeller inspection IAW Cirrus Design SR20 MM checklist. Lubricated hub w/Aeroshell #6. AD's current through issue 2015-14. I certify that this propeller has been inspected IAW an annual inspection and is found airworthy at this time.

Signature: 

Glenn Juber A&P IA 3438378, 5115 NW 98th Dr, Coral Springs, FL 33076

PROPELLER LOGBOOK ENTRY

RFN Holdings LLC	Tail # N818RN PHC-J3YF-1RF	Tach: 1379.1 Total time: 1379.1
Date: 08/03/2016	Serial #FP6682B	TSMOH: N/A

Completed annual propeller inspection IAW Cirrus Design SR20 MM checklist. Lubricated hub w/Aeroshell #6. AD's current through issue 2016-16. I certify that this propeller has been inspected IAW an annual inspection and is found airworthy at this time.

Signature: 

Glenn Juber A&P IA 3438378, 5115 NW 98th Dr, Coral Springs, FL 33076

PROPELLER LOGBOOK ENTRY

RFN Holdings LLC	Tail # N818RN PHC-J3YF-1RF	Tach: 1380.1 Total time: 1380.1
Date: 09/15/2017	Serial #FP6682B	TSMOH: N/A

Completed annual propeller inspection IAW Cirrus Design SR20 MM checklist. Lubricated hub w/Aeroshell #6. AD's current through issue 2017-18. I certify that this propeller has been inspected IAW an annual inspection and is found airworthy at this time.


Signature: 

Glenn Juber A&P IA 3438378, 5115 NW 98th Dr, Coral Springs, FL 33076

PROPELLER LOGBOOK ENTRY

RFN Holdings LLC	Tail # N818RN PHC-J3YF-1RF	Tach: 1388.3 Total time: 1388.3
Date: 11/04/2018	Serial #FP6682B	TSMOH: N/A


Completed annual propeller inspection IAW Cirrus Design SR20 MM checklist. Lubricated hub w/Aeroshell #6. AD's current through issue 2018-22. I certify that this propeller has been inspected IAW an annual inspection and is found airworthy at this time.

Signature: 
Glenn Juber A&P IA 3438378, 5115 NW 98th Dr, Coral Springs, FL 33076

PROPELLER LOGBOOK ENTRY

RFN Holdings LLC	Tail # N818RN PHC-J3YF-1RF	Tach: 1380.1 Total time: 1380.1
Date: 09/15/2017	Serial #FP6682B	TSMOH: N/A

Completed annual propeller inspection IAW Cirrus Design SR20 MM checklist. Lubricated hub w/Aeroshell #6. AD's current through issue 2017-18. I certify that this propeller has been inspected IAW an annual inspection and is found airworthy at this time

Signature: 

Glenn Juber A&P IA 3438378, 5115 NW 98th Dr, Coral Springs, FL 33076

PROPELLER LOGBOOK ENTRY

RFN Holdings LLC	Tail # N818RN PHC-J3YF-1RF	Tach: 1388.3 Total time: 1388.3
Date: 11/04/2018	Serial #FP6682B	TSMOH: N/A

Completed annual propeller inspection IAW Cirrus Design SR20 MM checklist. Lubricated hub w/Aeroshell #6. AD's current through issue 2018-22. I certify that this propeller has been inspected IAW an annual inspection and is found airworthy at this time.


Glenn Juber A&P IA 3438378, 5115 NW 98th Dr, Coral Springs, FL 33076

PROPELLER LOGBOOK ENTRY

RFN Holdings LLC	Tail # N818RN PHC-J3YF-1RF	Tach: 1393.2 Total time: 1393.2
Date: 05/23/2019	Serial #FP6682B	TSMOH: N/A

Completed annual propeller inspection IAW Cirrus Design SR20 MM checklist. Lubricated hub w/Aeroshell #6. AD's current through issue 2019-10. I certify that this propeller has been inspected IAW an annual inspection and is found airworthy at this time.

 Glenn Juber A&P IA 3438378, 5115 NW 98th Dr, Coral Springs, FL 33076

5/27/2020 PHC-J3YF-1RF \$FP6682B N818RN SR20 TACH 1563.0 HM 1994.5

Date


Complied with Annual inspection IAW 14CFR43 Appx D. Corrosion on prop leading edges: cleaned corrosion, dressed prop and recovered with paint. Prop balance: prop balanced and found to be 0.13 IPS: acceptable.




Matthew Hood AP3267745IA

I certify that this propeller has been inspected IAW 14CFR43 Appx D for annual inspection has been found airworthy at this time, and is returned to service. All applicable AD's noted to have been complied with at this time.




Matthew Hood AP3267745IA

