

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-13YF-1RF1F7693DFB

PROPELLER S/N FP2792B

LOGBOOK # _____

PROPELLER MAINTENANCE RECORD

Position _____

Propeller Model PHC-234F-1RF/F7693DFB

Propeller S/N FP 2792B

Blade Design _____

Blade S/N's

No. 1 K 01354

No. 2 K 01372

No. 3 K 01370

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____

Reverse _____

Aircraft Manufacturer Cirrus Design

Aircraft Model SR-22

S/N 0899

Registration N8225C

PROP MODEL:
PROP S/N
REG NO: 822sc
WORK ORDER: 1204-04-2004



Cirrus Design Factory Service Center

4515 Taylor Circle
Duluth, MN 55811

Repair Station No. YD5R855Y

DATE: 4/29/2004
TTA:
TTP:
HOBBS: 5.9

Prop Entries

Installed polished spinner (P/N 13978-001) IAW AMM 61-10.....

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CR# YD5R855Y.

DATE: 4/29/2004

SIGNED:

Mitch Knase
Certified Repair Station No. YD5R855Y

WORK ORDER: 1204-04-2004

Printed by EBis (<http://www.datcomedia.com>)



Leading Edge Aviation Services

Vandenberg Airport

Tampa, FL 33610

(813)-626-1515

11 June 2005

N822SC

Hobbs: 182.2

Hartzell M/N PHC-J3YF-1RF

Serviced Propeller and inspected with reference to AMM CH. 5-20... I certify this propeller has been inspected in accordance with a 100 hour inspection and is found to be in airworthy condition.

Ryan Donahue A&P #3015609



Propeller TSN TSO		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
-------------------------	--	------------	---

Destin Air Charters

Aircraft Reg
Manufacturer
Model

N822SC
Hartzell
PHC-J3YF-1RF

Date 06-09-2006
Page 1 of 1

Serial #

FP2792B

Engine
Total 260.0
Time
Hobbs 260.0

1. Complied with annual inspection.
2. Complied with 12 month / 100 hour lube of propeller hub.
3. All airworthiness directives and service bulletins / instructions complied with through this date.

I CERTIFY THIS PROPELLER WAS INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION.

The aircraft, airframe, equipment, or engine identified above was repaired and inspected in accordance with the current manufacturers maintenance manual and the current regulations of the Federal Aviation Administration and is approved for return to service.

Signed:  Kelly D Smith AP2922165IA

Destin Air Charters, 4460 Legendary Dr, Destin, FL 32541

Destin Air Charters

Aircraft Reg
Manufacturer
Model

N822SC
Hartzell
PHC-J3YF-1RF

Serial #

FP2792B

Date
Page

07-19-2006
1 of 1

Engine
Total
Time

308.1
17.1

1. Complied with 50 hour inspection, ~~100~~ hour inspection due @ 67.1 Hobbs, 358.1 Acft TT.
2. All airworthiness directives and service bulletins / instructions complied with through this date.

The aircraft, airframe, equipment, or engine identified above was repaired and inspected in accordance with the current manufacturers maintenance manual and the current regulations of the Federal Aviation Administration and is approved for return to service.

Signed: _____

[Signature]
Kelly D Smith AP2922165IA

Destin Air Charters, 4466 Legendary Dr, Destin, FL 32541

Propeller

A/C

Description of all

Destin Air Charters

Aircraft Reg
Manufacturer
Model

N822SC
Hartzell
PHC-J3YF-1RF

Date
Page

08-30-2006
1 of 1

Serial #

FP2792B

Prop
Total
Time
Hobbs

393.4
102.4

1. Complied with annual inspection.
2. All airworthiness directives and service bulletins / instructions complied with through this date.

I CERTIFY THIS PROPELLER WAS INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION.

The aircraft, airframe, equipment, or engine identified above was repaired and inspected in accordance with the current manufacturers maintenance manual and the current regulations of the Federal Aviation Administration and is approved for return to service.

Signed: _____

Kelly D Smith AP2922165IA

Destin Air Charters, 4460 Legendary Dr, Destin, FL 32541

Miracle Strip Aviation, Inc.
FAA Certified Repair Station
DZJR423D

Destin Airport
1001 Airport Road
P. O. Box 159
Destin, Florida 32540
Anti-Drug/Alcohol Plan # B-S0-00156S

N# 8225C

Date: 9-25-06

Tach/~~Hobbs~~ 136.0

Description of work performed: Removed & Replaced Prop Deice

Boots on all Blades IAW MFR Service
Manual

Maintenance Release: The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance was Repaired and Inspected in Accordance with Current Regulations of the FAA Administration and is Approved for Return To Service.

Signed: 

For Miracle Strip Aviation CRS # DZJR423D

WO# 06766

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		

Destin Air Charters

Aircraft Reg
Manufacturer
Model

N822SC
Hartzell
PHC-J3YF-1RF

Serial #

FP2792B

Date
Page

10-03-2006
1 of 1


Prop
Total
Time
Hobbs

439.0
148.0

1. This aircraft and all associated installed equipment must be maintained in accordance with Destin Air Charters Approved Aircraft Inspection Program, as revised.

The aircraft, airframe, engine, propeller, or equipment identified above was repaired and inspected in accordance with the current manufacturers maintenance manual and the current regulations of the Federal Aviation Administration and is approved for return to service.

Signed: _____



Kelly D Smith AP2922165IA

Destin Air Charters, 4460 Legendary Dr, Destin, FL 32541

Destin Air Charters

Aircraft Reg
Manufacturer
Model

N822SC
Hartzell
PHC-J3YF-1RF

Serial #

FP2792B

Date
Page

10-03-2006
1 of 1

Prop
Total
Time
Hobbs

439.0
148.0

1. Complied with 50 hour / Phase I inspection, Phase II due @ 198.0 Hobbs, 489.0 Acft TT.
2. All airworthiness directives and service bulletins / instructions complied with through this date.

I certify that a PHASE I inspection was complied with in accordance with the Destin Air Charters Approved Aircraft Inspection Program and all work was completed in accordance with the manufacturers maintenance manual. The Aircraft is approved for return to Service.

Signed: _____

Kelly D Smith AP2922165IA

Destin Air Charters, 4460 Legendary Dr, Destin, FL 32541


Date	T

Destin Air Charters

Aircraft Reg Manufacturer Model	N822SC Hartzell PHC-J3YF-1RF	Date Page WO# Prop Total Time Hobbs	10-26-2006 1 of 1 506 480.8 189.8
Serial #	FP2792B		

- Phase II inspection, Phase III due @ 239.8 Hobbs, 530.8 Acft TT.
- All airworthiness directives and service bulletins / instructions complied with through this date.

I certify that a PHASE II inspection was complied with in accordance with the Destin Air Charters Approved Aircraft Inspection Program and all work was completed in accordance with the manufacturers maintenance manual. The Aircraft is approved for return to Service.


Signed:  Kelly D Smith AP2922165IA

Destin Air Charters

Aircraft Reg Manufacturer Model	N822SC Hartzell PHC-J3YF-1RF	Date Page WO# Prop Total Time Hobbs	11-29-2006 1 of 1 519 531.3 240.3
Serial #	FP2792B		

- Complied with Phase III inspection, Phase II due @ 289.8 Hobbs, 580.8 Acft TT.
- All airworthiness directives and service bulletins / instructions complied with through this date.

I certify that a PHASE III inspection was complied with in accordance with the Destin Air Charters Approved Aircraft Inspection Program and all work was completed in accordance with the manufacturers maintenance manual. The Aircraft is approved for return to Service.

Signed:  Kelly D Smith AP2922165IA


Destin Air Charters, 4120 Legendary Dr, Destin, FL 32541

Destin Air Charters

Aircraft Reg	N822SC	Date	01-08-2007
Manufacturer	Hartzell	Page	1 of 1
Model	PHC-J3YF-1RF	WO#	524
Serial #	FP2792B	Prop	
		Total Time	573.2
		Hobbs	282.2

1. Phase II inspection, Phase IV due @ 332.2 Hobbs, 623.2 Acft TT.
2. All airworthiness directives and service bulletins / instructions complied with through this date.

I certify that a PHASE II inspection was complied with in accordance with the Destin Air Charters Approved Aircraft Inspection Program and all work was completed in accordance with the manufacturer's maintenance manual. The Aircraft is approved for return to Service.

Signed:  Kelly D Smith AP2922165IA

Destin Air Charters

Aircraft Reg	N822SC	Date	02-20-2007
Manufacturer	Hartzell	Page	1 of 1
Model	PHC-J3YF-1RF	WO#	528
Serial #	FP2792B	Prop TT	621.1
		Hobbs	336.2

1. Complied with phase IV inspection, Phase II due @ 382.2 Hobbs, 673.2 Acft TT.
2. All airworthiness directives and service bulletins / instructions complied with through this date.

I certify that a PHASE IV inspection was complied with in accordance with the Destin Air Charters Approved Aircraft Inspection Program and all work was completed in accordance with the manufacturer's maintenance manual. The Aircraft is approved for return to Service.

Signed:  Kelly D Smith AP2922165IA

Date	T

Destin Air Charters

Aircraft Reg
Manufacturer
Model
Serial #

N822SC
Hartzell
PHC-J3YF-1RF
FP2792B

Date 03-18-2007
Page 1 of 1
WO# 533
Prop TT 672.6
Hobbs 381.6

1. Complied with phase II inspection, Phase V due @ 431.6 Hobbs, 722.6 Acft TT.
2. All airworthiness directives and service bulletins / instructions complied with through this date.

I certify that a PHASE II inspection was complied with in accordance with the Destin Air Charters Approved Aircraft Inspection Program and all work was completed in accordance with the manufacturer's maintenance manual. The Aircraft is approved for return to Service.

Signed:  Kelly D Smith AP2922165IA

Destin Air Charters, 4460 Legendary Dr, Destin, FL 32541

Destin Air Charters

Aircraft Reg
Manufacturer
Model
Serial #

N822SC
Hartzell
PHC-J3YF-1RF
FP2792B

Date 04-10-2007
Page 1 of 1
WO# 538
Prop TT 720.6
Hobbs 429.6

1. Complied with phase V inspection, Phase II due @ 479.6 Hobbs, 770.6 Acft TT.
2. All airworthiness directives and service bulletins / instructions complied with through this date.

I certify that a PHASE V inspection was complied with in accordance with the Destin Air Charters Approved Aircraft Inspection Program and all work was completed in accordance with the manufacturer's maintenance manual. The Aircraft is approved for return to Service.

Signed:  Kelly D Smith AP2922165IA

Destin Air Charters


Aircraft Reg
Manufacturer
Model
Serial #

N822SC
Hartzell
PHC-J3YF-1RF
FP2792B

Date 05-08-2007
Page 1 of 1
WO# 541
Prop TT 765.5
Hobbs 474.5

1. Complied with phase II inspection, Phase I due @ 524.5 Hobbs, 815.5 Acft TT.
2. All airworthiness directives and service bulletins / instructions complied with through this date.

I certify that a PHASE II inspection was complied with in accordance with the Destin Air Charters Approved Aircraft Inspection Program and all work was completed in accordance with the manufacturer's maintenance manual. The Aircraft is approved for return to Service.

Signed:  Kelly D Smith AP2922165IA

Destin Air Charters

Aircraft Reg
Manufacturer
Model
Serial #

N822SC
Hartzell
PHC-J3YF-1RF
FP2792B

Date 07-02-2007
Page 1 of 1
WO# 549
Prop TT 815.5
Hobbs 524.5

1. Complied with phase I inspection, Phase II due @ 574.5 Hobbs, 865.5 Acft TT.
2. All airworthiness directives and service bulletins / instructions complied with through this date.

I certify that a PHASE I inspection was complied with in accordance with the Destin Air Charters Approved Aircraft Inspection Program and all work was completed in accordance with the manufacturer's maintenance manual. The Aircraft is approved for return to Service.

Signed:  Kelly D Smith AP2922165IA

Date	Propeller TSN TSO		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
1-27-09	1440.1		<small>Notes</small> 220.1	<p>Complied with PHASE II inspection / All Airworthiness directives and Service Bulletins Instructions up thru this date. I certify that a Phase II inspection was complied with IAW the DCAI Air Charters AAIP Inspection program and all work was completed IAW the MPF Maintenance Manual. This Aircraft is Approved for Return to Service <i>[Signature]</i> 267906423</p>
12-15-11				SEE AIRFRAME LOG FOR PROP ENTRY.

	HOBBS	22433
	FLT	1121.7
2-18-13		

DOUGLAS DUNCAN AVIATION LLC 100 TOWER DR, HGR 6 GREENVILLE, SC 29607
LOG ID# 8944 18-February-2013 WO# 5709 REF# 5709 AC TT 1121.7 HOBBS 2293.3
N822SC S/N 0899 CIRRUS SR22
FHM 1121.7 TSN 493.6 TSO 493.6

PROPELLER
*COMPLETED ANNUAL INSPECTION IAW FAR 91.409, FAR 43 APPENDIX D, AND CIRRUS SR22 MM 5-00. ALL AD'S AND SB'S RESEARCHED THROUGH CURRENT ATP REVISION 2/14/2013. NEXT ANNUAL INSPECTION DUE FEB 2014.

I CERTIFY THAT THIS AIRCRAFT, ENGINE, OR PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.
THE AIRCRAFT, ENGINE, COMPONENT, PROPELLER OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION AGENCY REGULATIONS AND IS HEREBY APPROVED FOR RETURN TO SERVICE WITH REGARDS TO MAINTENANCE PERFORMED.

Douglas Duncan 2-18-13
DOUGLAS DUNCAN A&P/IA 3384163 DATE

Date	TS

Destin Air Charters

Aircraft Reg
Manufacturer
Model
Serial #

N822SC
Hartzell
PHC-J3YF-1RF
FP2792B


Date
Page
WO#
Prop TT
Hobbs

08-11-2007
1 of 1
555
860.5
570.7

IS.

1. Complied with phase II inspection, Phase III due @ 620.7 Hobbs, 910.5 Acft TT.
2. All airworthiness directives and service bulletins / instructions complied with through this date.

I certify that a PHASE II inspection was complied with in accordance with the Destin Air Charters Approved Aircraft Inspection Program and all work was completed in accordance with the manufacturer's maintenance manual. The Aircraft is approved for return to Service.

Signed:  Kelly D Smith AP2922165IA

Destin Air Charters

Aircraft Reg
Manufacturer
Model
Serial #


N822SC
Hartzell
PHC-J3YF-1RF
FP2792B

Date
Page
WO#
Prop TT
Hobbs

09-25-2007
1 of 1
560
908.0
617.0

1. Complied with phase III inspection, Phase II due @ 667.0 Hobbs, 958.0 Acft TT.
2. Dressed prop blades to remove minor nicks.
3. All airworthiness directives and service bulletins / instructions complied with through this date.

I certify that a PHASE II inspection was complied with in accordance with the Destin Air Charters Approved Aircraft Inspection Program and all work was completed in accordance with the manufacturer's maintenance manual. The Aircraft is approved for return to Service.

Signed:  Kelly D Smith AP2922165IA

1001 Airport Road
Destin, Florida 32540
CRS DZJR423D

**MIRACLE STRIP
AVIATION
AVIAT DESTIN**

N# 822SC Hobbs: 1132.5 except as stated below, no other work, inspection,
Corrective action or determination of
Airworthiness was made at this time.

Description of work performed:

C/W PHASE II INSPECTION,
PHASE III DUE AT 1182.5 HOBBS,
ALL AD AND SB/INSTRUCTIONS C/W
THROUGH THIS DATE, INSTALLED NEW
SPINNER PIN C3532-5P I
CERTIFY THAT A PHASE II WAS C/W
I/A/W DESTIN AIR CHARTERS PHASE
II INSPECTION GUIDE.

Maintenance Release: The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance was Repaired and Inspected
In Accordance With Current Regulations of the FAA Administration and is approved for return to service.

Signed: [Signature] CRS#DZJR423D

WO# 50-08-0480 Date: 11-7-08

**Blue Angel
Aviation**

Cirrus SR22 S/N 0899 N8225C
Propeller Hartzell PHC-J3Y-1RF SN FP2792B
1370.2 Hobbs \1631.1 TT

15 July 2009 - Completed Phase III Inspection per Destin Air Charters AAIP dated 08-01-2006, pgs. 79-104. Complied with all requirements of checklist & propeller found to be in an **Airworthy Condition**.

Cirrus Air 2875543

8/10/09		1599.4	Completed Phase II + III Inspection per Destin Air Charters AAIP dated 08-01-2006. Complied with all requirements of checklist & propeller found to be in an Airworthy Condition. Hobbs 1370.2 TT 1631.1	
8/10/09		1599.4	Completed Phase I Inspection per Destin Air Charters AAIP dated 08-01-2006. Complied with all requirements of checklist. This was a End of Cycle Inspection next is a Phase II AT 429.1 Hobbs 1370.2 TT 1631.1	

Propeller
TSN TSO

A/C
Hrs

Description of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspections.

Prop

1001 Airport Road
Destin, Florida 32540
CRS DZJR423D

MIRACLE STRIP
AVIATION
AVIAT DESTIN

Fit. 270.5

N# 829JC Hobbs: 1853.1 except as stated below, no other work, inspection,
Corrective action or determination of
Airworthiness was made at this time.

Description of work performed:

Removed & Reinstalled Prop cov. After
Outside Repair by South Coast Prop Service
Run & Op's checked good See 8130-3

Maintenance Release: The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance was Repaired and Inspected
In Accordance With Current Regulations of the FAA Administration and is approved for return to service.

Signed:

[Signature]

CRS#DZJR423D

WO#

50-01-0085

Date:

8/30/09

NOT IN SERVICE

9/29/09	1651.8			Completed Phase I Inspection per Destin Air Charter AAIP CK List Completed All requirements of Check List AND propeller no faults noted J. M. Hill # AAIP 262906423
11/13/09	1699.1			Completed Phase II Inspection per Destin Air Charter AAIP CK List Completed All requirements of CK List AND ops CK no faults noted J. M. Hill # AAIP 262906423

Propeller
TSO

A/C
Hrs

Description of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspections.

Heart of Virginia Aviation
11152 Airpark Rd
Ashland, VA 23005



Phone (804) 798-6500
Fax (804) 798-6544
WO # A10-0449

N822SC

Sept 20, 2010

Aircraft Hobbs: 1544.2 Aircraft Total Time: 1835.2

Prop Total time: 1835.2

I certify this prop has been inspected in accordance with an annual inspection was
determined to be in airworthy condition.

Daniel McSherry AP3110300IA




Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair and	3.
	TSN	TSO			

Premier Aviation Services, LLC dba **Flying Moose Aviation** (HGR 1A4 KPJC)

12/10/2013 N822SC SR22 s/n 0899 Hobbs: 2618.9 FHM: 1395.6 Prop:

100 hour propeller inspection IAW Cirrus SR22 maintenance manual, section 5-20 inspection checklist. Inspected Hartzell propeller blades for nicks and cracks. Inspected spinner, bulkhead and attaching bolts. Inspected hub and governor. Greased hub with aeroshell #5 grease. Operational and leak check OK. I certify this propeller has been inspected in accordance with a 100 hour inspection and has been determined to be in airworthy condition.



Steven C. Hurd A&P2685696

12/12/2013 N822SC Hobbs: 2618.9 FHM: 1395.6 Annual Inspection completed for security and condition this date. I certify this propeller has been inspected IAW Annual Inspection and was Determined to be in Airworthy Condition.



A&P 1674145 IA

--	--	--	--	--	--



Hangar 23, Tulsa International Airport-Tulsa, OK 74115
(918)836-6418

Date: 12/16/2014; Aircraft: N822SC
Hartzell Propeller 100 Hour Inspection. PHC-J3YF-1 s/n: FP2792B.
WO: MA14-04633 Flt. Hour: 1504.4 Hobbs: 2772.7 TSPOH: 970.0

Inspected and lubricated this propeller using the Cirrus Aircraft and Hartzell maintenance forms.

I certify this Propeller has been inspected in accordance with a 100 Hour/Annual inspection and was determined to be in airworthy condition this date.

Signature *Steve Collins*
Autopilots Central, Inc. CRS CM2R747K

Twelve Stone Aviation 802 Airport Ave. Hangar 5 Springdale, AR 72764 479-799-8065
N822SC SN.FP2792B HOBBS: 3042.0 TSPOH: 1239.3 01/15/2016

INSPECTED PROPELLER HUB, BLADES AND SPINNER ASSEMBLY I.A.W. CIRRUS MM FOR ANNUAL INSPECTION.NO DEFECTS NOTED. I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IAW ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

KEVIN S. DAVIS

K. S. Davis
AP431476148IA

PROP MODEL:
PHC-J3YF-IRFIF7693DFB
PROP S/N: FP2792B
REG. NO: N822SC
WORK ORDER: 200639

Clear Star Aviation
Repair Station No. 5CSR009B
4765 Frank Luke Dr
Addison, TX 75001
Phone: 972-267-2376

DATE: 8/1/2017
A/C TSN: 1945.4
PROP TT: 1945.4
TACH: 1945.4

Prop Entries

Performed propeller 100 HR inspection in accordance with current Cirrus Design Aircraft Maintenance Manual 5-20 and 5-30.

Researched AD's through bi-weekly issue of this date, all AD's are in compliance at this time. I certify that this propeller has been inspected in accordance with a 100HR inspection and was determined to be in airworthy condition. I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station 5CSR009B.

DATE: 8/1/2017

SIGNED:

Longaker, Doug
Certified Repair Station No. 5CSR009B

Work Order: 200639

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PROP S/N:
REG. NO: N822SC
WORK ORDER:
5143-01-2018



Houston Aviation Center, LLC
12888 Hwy 6 S Ste 113
Sugar Land, TX 77498 USA
Phone: 281-494-5800

DATE: 1/24/2018
A/C TSN: 3491.4
PROP TT: 58.8
HOBBS: 3491.4

Prop Entries

Removed propeller, installed new propeller o-ring P/n C-3317-228, and re-installed propeller in proper orientation.

Maintenance Release

The aircraft and/or component(s) on N822SC was repaired and/or inspected in accordance with current requirements of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at Houston Aviation Center, LLC under Work Order No. 5143-01-2018.

DATE: 1/24/2018

SIGNED:

Elijah Derbecker, A&P: 3757478

Work Order: 5143-01-2018

Printed by EBis 3 (datcomedia.com)

N98HH Hartzell Prop PHC-J3YF-1RF s/n FP2792B HOBBS 3567.5 FL 218.8



5410 OPERATIONS ROAD, MONROE, LA 71203
(318) 387-0222 Repair Station #3MIR878B

DATE 9-4-18-18

100 hour inspection completed per Cirrus MM inspection guide 5-20 and Hartzell Owners Manual 115N

I certify that this propeller has been inspected in accordance with an annual inspection and found to be in airworthy condition.

JPS AVIATION LLC, FAA APPROVED REPAIR STATION #3MIR878B
REGIONAL AIRPORT MONROE LA

SIGNED [Signature] WO# 14839

N98HH Hartzell Prop PHC-J3YF-1RF s/n FP2792B HOBBS 3520.6 FL 348



5410 OPERATIONS ROAD, MONROE, LA 71203
(318) 387-0222 Repair Station #3MIR878B

DATE 10-24-19

100 hour inspection completed per Cirrus MM inspection guide 5-20 and Hartzell Owners Manual 115N

I certify that this propeller has been inspected in accordance with an annual inspection and found to be in airworthy condition.

JPS AVIATION LLC, FAA APPROVED REPAIR STATION #3MIR878B
REGIONAL AIRPORT MONROE LA

SIGNED Thomas Ciles WO# 15142

Description Service Done														
A/C Hrs														

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP2792B
REG. NO: N822SC
WORK ORDER:
5942-10-2020



Houston Aviation Center, LLC

12888 Hwy 6 S Ste 113
Sugar Land, TX 77498 USA
Phone: 281-494-5800

DATE: 12/8/2020
A/C TSN: 3865.6
PROP TT: 3865.6
TSPOH: 2062.9
FLIGHTTIME: 470.7

Prop Entries

Completed a 100 HR/Annual Inspection this date Ref. CDC SR22 AMM 5-20 and Propeller Owner's Manual No. 115N. Inspected and dressed propeller blade leading edges. Inspected and lubricated propeller hub. Checked blade track. Checked ADs thru BW 2020-25.... I certify that this Propeller has been inspected in accordance with a 100 HR/Annual Inspection and was determined to be in Airworthy condition

Maintenance Release

The aircraft and/or component(s) on N822SC was repaired and/or inspected in accordance with current requirements of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at Houston Aviation Center, LLC under Work Order No. 5942-10-2020.

DATE: 12/8/2020

SIGNED:

Fouad Hussain, A&P: 3204861 IA

Work Order: 5942-10-2020



Printed by EBis 3 (datcomedia.com)

6-4-2021

Prop tsMOH : 1795.4

Remove this prop from N822SC @ PCT: 2524.9

ATP 3343185FP

Propeller TSN TSO		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
			<div style="text-align: right; margin-bottom: 10px;">  </div> <p>HARTZELL SERVICE CENTER One Propeller Place Piqua, Ohio 45356 U.S.A.</p> <p>July 9, 2021 W/O:19127 S/N: FP2792B TSN: 2524.9 TSO: 0.0</p> <p>Pertinent details of the work performed are specified on the provided FAA Form 8130-3, Tracking Number MM43160, Dated 7-9-21.</p> <div style="text-align: center; margin: 20px 0;">  </div> <p>Dan Davis Repairman # Repair Station # SJ3R843L</p>