

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-534F-1RF

PROPELLER S/N FP5063B

LOGBOOK # 1

PROPELLER MAINTENANCE RECORD

Position One

PITCH RANGE

Propeller Model PHC-534F-1RF

High/Feather _____

Propeller S/N FP5063B

Start Lock _____

Blade Design F7693DF

Low _____

Blade S/N's

Reverse _____

No. 1 K40815

No. 2 K40813

Aircraft Manufacturer Cirrus

No. 3 K40754

Aircraft Model SR22

No. 4 _____

S/N 2202

No. 5 _____

Registration N677CP

No. 6 _____

Spinner Assembly Part No. _____

Date	Propeller TSN	TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
12/11 2008	146.7		146.7	<p>Removed Spinner, inspected BACKPLATE AND Propeller, NO Defects. Replaced Spinner. NO AD'S THIS PERIOD. I CERTIFY THIS Propeller WAS INSPECTED IAW AN ANNUAL INSPECTION per Cirrus Service Manual, SR22, AND FOUND AIRWORTHY AND APPROVED FOR RTS. END</p> <p><i>Berry Mosley AP 2731840 IA</i></p>

Make: Hartzell
 Model: PHC-J3YF-1RF
 Serial No.: FP5063B



TCM CUSTOMER SUPPORT CENTER

Date: 01/07/2010
 Hobbs Time: 280.1
 Flight Time: 236.3

TCM Mattituck Service Center, 8600 County Rd 32, Fairhope, AL 36532 251-990-5080 FAA Repair Station No. ID4R254M

I certify that this propeller has been inspected in accordance with an annual inspection and determined to be in airworthy condition.

Work Performed: Completed an ANNUAL inspection in accordance with the Cirrus SR22 maintenance manual 100hr/annual inspection checklist. Completed ground operational checks and leak check. -----END-----

Authorized Signature For Repair Station ID4R254M: *Michael O. Lindsay*
 Details of the work performed is on file under Work Order No. 4438

8/19/2017 TTSN: 744.7 (H) 638.5 (T)

Removed spinner. Cleaned and inspected IAW Cirrus SR-22 maintenance manual 100 hr/annual inspection checklist. Re-installed spinner. I certify that this propeller has been inspected in accordance with an annual inspection and determined to be in an airworthy condition.


Neal George A&P 2877828 IA

12/07/2019 TTSN: 836.7 (H) 718.7 (T)

Removed spinner. Cleaned and inspected with reference to the Hartzell manual 100 hr/annual inspection checklist. Re-installed spinner


Neal George A&P 2877828 IA

10/01/2018 TTSN: 787.8 (H) 675.9 (T)

Removed spinner. Cleaned and inspected IAW manufacturer's 100 hr checklist. Re-installed spinner.


Neal George A&P 2877828 IA

03/04/21 TTSN: 857.2 (H) 735.6 (T)


Removed spinner. Cleaned and inspected IAW Cirrus SR-22 maintenance manual 100 hr/annual inspection checklist. Re-installed spinner. I certify that this propeller has been inspected in accordance with an annual inspection and determined to be in an airworthy condition.


Neal George A&P 2877828 IA

04 May 2022

Hartzell PAC J3YF-1RF S/N: FPG063B TTSN: 751.2 Tach: 751.2 Hobbs: 877.2

Inspected and serviced propeller referencing the manufacturer's instructions for 100-hr/Annual inspection and the scope and detail of 14 CFR Part 43, Appendix D. I certify that this propeller has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy condition.


Neal E. George, A&P/IA 2877828

