

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-J3YF-1RF/F7693DFB

PROPELLER S/N FP3565B

LOGBOOK # 1

PROPELLER MAINTENANCE RECORD

Position One

Propeller Model PHC-13 YF-1RF/F7693DFB

Propeller S/N FP3565B

Blade Design F7693DFB

Blade S/N's

No. 1 K17794

No. 2 K17792

No. 3 K17793

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____

Reverse _____

Aircraft Manufacturer Cirrus

Aircraft Model SR-22

S/N SR22-1401

Registration N485CD

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP3565B
REG. NO: N483CD
WORK ORDER:
2024-04-2007



Twin Cities Aviation, Inc.

8891 Airport Rd #A-2
Blaine, Minnesota 55449
Phone: 763-784-9165

DATE: 4/13/2007
A/C TSN: 302 2
PROP TT: 302 2
HOBBS: 302 2

Prop Entries

CW a annual Propeller inspection IAW Cirrus SR 22 MM and IG. AD's researched to date. See AD listing for pertinent details. All Cirrus SB's researched to date. Ground run, ops and leak check satisfactory. I certify that I have inspected this propeller IAW a annual inspection and it was determined to be airworthy with respect to work performed at this date and time. The following discrepancies were addressed:

The aircraft, airframe, engine, propeller, or appliance above was repaired and / or inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.

DATE: 4/13/2007

SIGNED:

Jeff Iskierka, IA: 470046442

Work Order: 2024-04-2007

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP3565B
REG. NO: N483CD
WORK ORDER:
2569-04-2008



Twin Cities Aviation, Inc.

8891 Airport Rd #A-2
Blaine, Minnesota 55449
Phone: 763-784-9165

DATE: 4/17/2008
A/C TSN: 416.5
PROP TT: 416.5
HOBBS: 416.5

Prop Entries

CW a annual Propeller inspection IAW Cirrus SR 22 MM and IG. Dressed and painted blades. AD's researched to date. See AD listing for pertinent details. All Cirrus SB's researched to date. Ground run, ops and leak check satisfactory. I certify that I have inspected this propeller IAW a annual inspection and it was determined to be airworthy with respect to work performed at this date and time. The following discrepancies were addressed:

The aircraft, airframe, engine, propeller, or appliance above was repaired and / or inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.

DATE: 4/17/2008

SIGNED:

Andrew Bougetz, IA: 2656245

Work Order: 2569-04-2008

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
 PHC-J3YF-1RF
 PROP S/N: FP3565B
 REG. NO: N483CD
 WORK ORDER:
 3880-02-2011



Twin Cities Aviation, Inc.

8891 Airport Rd #A-2
 Blaine, Minnesota 55449 USA
 Phone: 763-784-9165

DATE: 3/1/2011
 A/C TSN: 726
 PROP TT: 726
 HOBBS: 726

Prop Entries

CW an Annual Propeller Inspection IAW Cirrus SR 22 MM and IG. Dressed and painted blades. AD's researched to date. See AD listing for pertinent details. All Cirrus SB's researched to date. Ground run, ops and leak check satisfactory. I certify that I have inspected this propeller IAW an Annual Inspection and it was determined to be airworthy with respect to work performed at this date and time. The following discrepancies were addressed:—CW AD 08-13-28, Propeller Hub Lubrication Holes, DNA by Model Number, No further action required.

The aircraft, airframe, engine, propeller, or appliance above was repaired and / or inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.

DATE: 3/1/2011

SIGNED:

Andrew Bougetz, IA: 2656245

Work Order: 3880-02-2011

Printed by EBis 3 (datcomedia.com)

5-2-12	T7m	890	Dressed & Painted Prop	R. Soehl 476668220 AZ
6-4-13	H-1000.1		Dressed & Trnst Prop	R. Soehl 476668220 AZ

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
	7-1	-14		Hw 1137
				Dressed and Insp Prop
				A. Soehn 47668220A2
	-8	1-15		Hw 1235
				Dressed Painted & Insp Prop
				A. Soehn 47668220A2
	8-12	-16		Hw 1324
				Insp'd Dressed & Painted Prop
				A. Soehn 47668220A2

PROP MODEL: PHC-J3YF-1RF
PROP S/N: FP3565B
REG NO: N483CD
WORK ORDER: 8817-08-2018



Repair Station No: 5TCR105B
8891 Airport Road A2
Blaine, MN 55449
Phone: 763-784-9165

DATE: 9/4/2018
A/C TSN: 1465.4
PROP TT: 1465.4
HOBBS: 1465.4

Prop Entries

C/W an Annual Propeller Inspection IAW Cirrus SR 22 MM and IG. Dressed and painted blades. AD's researched to date. Cirrus SB's researched to date. Ground run, ops and leak check satisfactory. I certify that I have inspected this propeller IAW an Annual Inspection and it was determined to be airworthy with respect to work performed at this date and time. The following discrepancies were addressed:

The aircraft, airframe, engine, propeller, or appliance above was repaired and / or inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.

DATE: 9/4/2018

SIGNED:

Josh Shea
Certified Repair Station No. 5TCR105B

Work Order: 8817-08-2018

Printed by EBis 3 (datcomedia.com)

Date	Propeller TSN TSO		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
				<p style="text-align: center;">Ozark Airworks, Inc. 185 Taxiway Place Midway, AR. 72651 (870) 481-5456</p> <p>Date: 10/14/2019 Propeller: Hartzell Model: PHC-J2YF-1RF Serial No. FP3565B Tach: 1612.1, Total time: 1612.1 Annual inspection completed this date. This inspection procedure meets the requirements of FAR 43.13 appendix (d) and Hartzell PHC-J3YF series propeller maintenance, service and inspection data.</p> <p>All AD note pertinent to this propeller have been complied with and are listed in the Compliance Report. Details of the work completed regarding the above inspection are on file at this agency under work order Number OZA-3447.</p> <p>I certify that this propeller has been inspected in accordance with an annual inspection and has been determined to be in an airworthy condition and returned to service.</p> <p style="text-align: right;"><i>Les Ives</i> Les Ives 489486318 A/P - I/A</p>
				<p><i>12-1-2019</i></p> <p><i>Removal Prop for OH @ Howard 3126242</i></p> <p><i>Hobbs 16306</i></p>

HARTZELL SERVICE CENTER
One Propeller Place
Piqua, Ohio 45356 U.S.A



January 20, 2020

W/O:16700 S/N: FP3565B TSN: Not Provided TSO: 0.0
1630.6

Pertinent details of the work performed are specified on the provided FAA Form 8130-3, Tracking Number MK54340, Dated 1-20-20.

A handwritten signature in blue ink, appearing to be "D. Davis", written over a horizontal line.

Dan Davis Repairman #
Repair Station # SJ3R843L

PROPELLER LOG

06/18/2020



N18SA
Make: CIRRUS
Hobbs: 1630.6

S/N: 1401
Model: SR22
Tach:
TTSOH: 0

All operations pertaining to Airworthiness Directives,
Alerts, Overhaul, Major or Minor Repair, and Inspections.

1. C/W ANNUAL INSPECTION in accordance with FAR 43 APPENDIX D - Using Hartzell /Cirrus AMM as a guide.
2. Re installed Prop P/NPHC-J3YF-1RF S/N FP3565B after O/H from Hartzell. TTSN 1630.6 TTSMOH 0.

I certify that this propeller has been inspected in accordance with (annual) inspection and was determined to be in airworthy condition.

A/P3343189I/A Kevin Pierron

Signed _____



3430 Old Columbus Road Carroll, Ohio 43130
Phone Number: 1-740-777-2191

Date:

Prop

ENGINE TACH: 1693 TTP: Unknown

TSMOH: 63

N Number: N18SA

Annual Inspection

Completed the following:

1. Aircraft propeller inspected following scope and detail of FAR 43 Appendix D and manufactures service manual
2. Inspected propeller bolts for proper torque and safety.
3. Checked surfaces for nicks and scratches.
4. Review Bi-Weekly T-Data 2021-23 and complied with where required.
5. Operational checks completed after inspection

I certify that this aircraft **Propeller** has been inspected in accordance with an **Annual** inspection and was determined to be in airworthy condition.

Aircraft returned to service.


James A. Shadd A&P 4120371 IA

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
------	----------------------	------------	---

3430 Old Columbus Road Carroll, Ohio 43130
 Phone Number: 1-740-777-2191
 Date: 12-8-2022



Prop

ENGINE TACH: 1743.4 TTP: Unknown

TSMOH: 113.4

N Number: N18SA

Annual Inspection

Completed the following:

1. Aircraft propeller inspected following scope and detail of FAR 43 Appendix D and manufactures service manual
2. Inspected propeller bolts for proper torque and safety.
3. Checked surfaces for nicks and scratches.
4. Review Bi-Weekly T-Data 2022-25 and complied with where required.
5. Operational checks completed after inspection

I certify that this aircraft **Propeller** has been inspected in accordance with an **Annual** inspection and was determined to be in airworthy condition.

Aircraft returned to service.

James A. Shadd A&P 4120371 IA
